

2-8-18

King's Auto Spray Paint Pte Ltd

160 Sin Ming Drive #05-10 Sin Ming Autocity

Singapore 575722

TAN SHUHUI GERALDING

Not Attracted  
Murray B. G. P. M.

Re: Estimate cost for SLG 8464m mitsudishi outlander

SUPPLY OF PARTS:

|                                        |   |                   |   |
|----------------------------------------|---|-------------------|---|
| 1pc rear bumper                        | R | \$ 916.00         | ✓ |
| 1pc rear bumper beam                   |   | 480.00            | ? |
| 2pc rear bumper brackets @ 71.00       |   | 142.00            | ? |
| 1pc rear bumper center garnish         | R | 289.00            | ✓ |
| 8pc rear bumper clips @ 3.50           | M | 28.00             | ✓ |
| 2pc rear bumper side reflector @ 90.00 | M | 180.00            | X |
| 1pc rear center panel                  |   | 369.00            | ? |
| 2pc rear bumper side retainer @ 28.00  | M | 56.00             | X |
|                                        |   | <u>\$ 2460.00</u> |   |
|                                        |   | 246.00            |   |
|                                        |   | <u>\$ 2214.00</u> |   |

Less 10%

LABOUR:

1 set rear bumper sensor

2005  
Shen \$ 300.00

To dismantle & rear panel top trim & side fender inner trim

\$ 60.00 ?

Renew the above mentioned parts

knocking, cutting, welding & straighten rear damaged parts

\$ 700.00 ?

spray paintings

600 \$ 700.00

\$ 3974.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

HUAT