

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1138P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (CONSISTENT)	DEFORMED	811.11	811.11
1	REAR BUMPER SPONGE (CONSISTENT)	NOT NECESSARY	79.20	-
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	NOT NECESSARY	815.64	-
1	REAR BUMPER REINFORCEMENT CENTRE (CONSISTENT)	NOT NECESSARY	79.20	-
2	REAR BUMPER N/S & O/S SIDE BRACKET @\$52.20 (CONSISTENT)	O/S NOT NECESSARY / N/S DEFORMED	104.40	52.20
1	REAR BUMPER N/S REFLECTOR (CONSISTENT)	NOT NECESSARY	107.50	-
1	REAR N/S RIM @\$246.00 (CONSISTENT)	CUT	246.00	246.00
	LESS 20% DISCOUNT		-448.61	-221.86
			1,794.44	887.45
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	48.00	48.00
1	SET REVERSE SENSOR (SN) (CONSISTENT)	NOT NECESSARY	280.00	-
1	REAR N/S FENDER STICKER (SN) (CONSISTENT)	NECESSARY	60.00	60.00
1	TYRE (MAXXIS) (80%) (SN) (CONSISTENT)	PUNCTURE	200.00	160.00
1	SUNDRY (SN) (CONSISTENT)	NECESSARY	50.00	20.00
			638.00	288.00
	LABOUR			
	TOWING FEE.		50.00	50.00
	TO CHECK FOR REAR N/S WHEEL ALIGNMENT.		80.00	80.00
	TO DISMANTLE AND REPLACE REVERSE SENSOR AND TEST SYSTEM.		80.00	30.00
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING TO KNOCK - OUT ,STRAIGHTEN ,REPAIR,RESHAPE OF THE SAME ,ETC.		700.00	300.00
	TO PUTTY AND SPRAY PAINTING ON THE REAR BUMPER ,REAR N/S FENDER .		400.00	400.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	120.00	-
			1,430.00	860.00

Report Ref No. CC4/ASM18014859/T1pa3q2



Page No.:2 of 2

GRAND TOTAL	3,862.44	2,035.45
RECOMMENDED COST OF REPAIRS		2 035 45

Report Ref No. CC4/ASM18014859/T1pa3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

Amonto

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.