



Your Ref: DMCV1700042H

Date: 18th October 2018

Our Ref: CS1/ICS18014912/T1vd3s2

M/s ECICS Ltd
10 Eunos Road 8
Singapore Post Centre #09-04A
Singapore 408600
(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:
SJY 5289B INSURED VEHICLE: GY 5601T ACCIDENT DATE: 18/04/2017**

We thank you for your instruction on 26/07/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJY 5289B from M/s Performance Motors Ltd.
- b) Singapore Accident Statement of Vehicles SJY 5289B and GY 5601T.
- c) Colour damaged vehicle photographs of SJY 5289B.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SJY 5289B
Make & Model	: B.M.W X5 XDRIVE35I
Year of Registration	: 2010
Chassis Number	: WBAZV42080LL57581
Engine Capacity	: 2979 cc
2. We recommend that the repairs of the entire damage require about 10 (Ten) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.