

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way,

AIG Building #09-16

Singapore 079120

Attn: Motor Claims Department

Date : 14/08/2018

Vehicle No : SKG8275D

Veh Make/Model : Citroen Grand C4 Picasso 1.6

YOM : 2012

Chassis No : VF7UA5FV8CJ619994

Date of Accident : 13/08/2018

No	Qty	Description	Amount \$	
		List Items:-		
1	1	Front bumper	\$ 1,296.00	X
2	1	Front bumper side retainer (LH)	\$ 162.00	X
3	1	Front LH fender	\$ 604.80	X
4	1	Front LH fender splash shield	\$ 129.60	X
5	1	LH side mirror assy	\$ 788.40	X
6	1	Front LH door assy	\$ 2,400.00	X
7	1	Front LH door windscreen outer moulding	\$ 288.00	X
8	1	Front LH door pillar frame black sticker	\$ 140.40	X
9	1	Front LH door oute handle	\$ 97.20	X
10	1	Front LH door protector	\$ 162.00	✓
11	1	Rear LH door assy	\$ 1,296.00	X
12	1	Rear LH door windscreen outer moulding	\$ 288.00	X
13	1	Rear LH door protector	\$ 162.00	✓
14	1	Rear LH fender	\$ 3,080.00	X
15	1	Rear LH fender splash shield	\$ 129.60	X
16	1	Rear bumper	\$ 993.60	X
		Total - List Item	\$ 12,017.60	
		Less 10%	\$ 1,201.76	
		Total	\$ 10,815.84	
		Special Nett Items:-		
1	10	Front bumper clip	\$ 120.00	X
2	10	Front LH fender splash shield clip	\$ 120.00	X
3	10	Rear LH fender splash shield clip	\$ 120.00	X
4	6	Front LH door protector clip	\$ 102.00	X
5	6	Rear LH door protector clip	\$ 102.00	X
6	1	Front LH wheel rim	\$ 680.00	X
7	1	Rear LH wheel rim	\$ 680.00	X
		Total - SN Item	\$ 1,924.00	
		Balance b/f	\$ 12,739.84	

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way,
AIG Building #09-16
Singapore 079120
Attn: Motor Claims Department

Date : 14/08/2018
Vehicle No : SKG8275D
Veh Make/Model : Citroen Grand C4 Picasso 1.6
YOM : 2012
Chassis No : VF7UA5FV8CJ619994
Date of Accident : 13/08/2018

No	Qty	Description	Amount \$
		Balance c/f	\$ 12,739.84
		Labour Charges:-	
1		Spray painting on all affected area.	\$ 1,600.00
2		Labour remove/refix accident damages parts to knock, jack, cut weld and realign accident affected area.	\$ 1,500.00
3		To apply anti rust treatment.	\$ na 180.00
4		To check wiring system & light.	\$ 80.00
5		To check & adjust wheel alignment.	\$ na 80.00
6		To transfer front LH door mechanism.	\$ na 100.00
7		To transfer rear LH door mechanism.	\$ na 100.00
8		To remove and reinstall interior upholstery.	\$ na 120.00
9		To remove and reinstall front and rear door windscreen glass.	\$ na 150.00
		Total - L/C	\$ 3,910.00

9001
4001
X
201
X
X
X
X
X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Sub-Total \$ 16,649.84
7% GST \$ 1,165.49
Total \$ 17,815.33