

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

15 AUG 2018

E S T I M A T EEstimate No. : b1 48027
Date Estimated : 14/08/2018
Prepared By : Han Kwan Yong

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -Sam Han Mun
802 Thomson Road
#11-08

Singapore 298187

- ACCOUNT - 40000Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGJ313L	D284493	30/09/2013	528iA	0

DESCRIPTION

To replace rear bumper & attachments including to knock out rear boot lid and dented area caused by the accident

1275 2,550.00

To respray rear bumper and boot lid

1868 2,076.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

Sundries.

80.00

Total Labour 1: 4,883.00

DESCRIPTION

DESCRIPTION	QTY	PRIC	VALUE
BODY NUT	10	1.15	11.50
BODY NUT	10	0.90	9.00
RR BUMPER CARRIER	1	714.25	714.25
ADAPTOR	1	68.45	68.45
REAR BUMPER CENTRE GUIDE	1	60.05	60.05
REAR BUMPER PRIMED (PDC)	1	1,467.20	1,467.20
REAR BUMPER TOWING EYE COVER PRIMED	1	46.45	46.45
EMBLEM GROMMET	2	0.80	1.60
# MODEL LETTERING 528i	1	62.55	62.55
BMW EMBLEM	1	69.50	69.50
PLUG	10	1.05	10.50
PLUG BLACK D=5MM	10	0.90	9.00
EXPANDING NUT	6	0.55	3.30

Total Parts : 2,533.35

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X**E S T I M A T E**

Estimate No. : **b1 48027**
Date Estimated : **14/08/2018**
Prepared By : **Han Kwan Yong**

Page No. : **2 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGJ313L	D284493	30/09/2013	528ia	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Claims OD / <u>3rd Party</u> / Uninsured losses / Direct Settlement	
Regn No. _____	Claim No. _____
Date&Time <u>04/09/18 10/30</u>	Excess S\$ _____
Surveyor's Name <u>TEAM</u>	Sign _____
Surveyor's Tel <u>90010068</u>	Authorised <u>Yes / No</u>
Authorised Date _____	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No <u>Yes</u> PML Yes / No <u>No</u>	
Surveyor's E-mail _____	
No. of Working Days Recommend <u>4 days</u>	

Labour 1	:	4,883.00
Parts	:	2,533.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	519.14
Grand Total	:	<u>7,935.49</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **