

ASS. REC. BY:

REF:

es/AWA18014961/Alvoban

Special Instruction:

Surveyor:

Taufik

ASSIGNMENT (Office)

From (Person):

Ben Tang

of

AWAC

Date/Time:

16/8/18 @ 11:39am

Estimated Cost:

Bill to:

OD/TP WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

YN 4838D

Insured:

GBF 5638Y

at Workshop m/s

Ryder Auto

Tel:

9792 4673

of

1 Kaki Bukit Ave 6 # 01-56 Autobay

Policy No:

AVCP8B0084171701

Claim No:

GBF 5638Y/1BT

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

14/08/2018

CA / REV / REP. / REV 24 HRS

1wp

20/8/18 @

H.O.D. Endorsement:

Date/Time:

1:49pm @ 16/8/18

Person Contacted:

Mr-Sun

Vehicle-IN/OUT

| Date/Time | Action/Instruction (✓) Estimate                                  |
|-----------|--|
|           | YN 4838D - X   |
|           | GBF 5638Y - X  |
| 2/10/18   | Con firm with Ryder \$ 5600 .00 @ 5 days<br>(Red: \$ 5970 , 52%. |

REF:

AWAC

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
| N/S | O/S |
|     | X   |

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rport: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

Veh No: **3N4838D** Yr Regn: **2014 / Jan.**  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: **Hino XZ4900R.** C.C. **4009**  
 Colour: **white** A/C: Insured / Std / NI / NA  
 Sp. Reading: **115039** T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: **JHHTCS3H60K001785**  
 Gen. Cond: **Good** / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modi: **NH** / S/Rim / STD A/Rim or  
 Tyre Size: F: **7.00 R16**  
 R: **n n (0)**  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR **(SUMI)**  
 TOYO / YOKO or **Sumi**  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. **6** mm R/Bal. **6/6** mm  
 L/Bal. **6** mm L/Bal. **6/6** mm  
 D.O.A. \_\_\_\_\_ D.O.I. **20/8/18.**  
 Survey held at **Ryder Auto**  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
**Rear o/s**  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

p/p ~~450~~ 5600, 5 days

RECEIVED 03 OCT 2018

*[Signature]*  
2/10/2018

Date/Time, File Pass to?  : Preli. Report  
 : Final Report

Days Of Repair: **5**  
 Resurvey No. of Trip: **1**

|                         |     |
|-------------------------|-----|
| Survey Fee:             | 250 |
| Transportation:         |     |
| _____ \$ + PS, _____ \$ |     |
| ) Photos                |     |
| ) Others                |     |
| TOTAL                   | 250 |

Date/Time, File Return to?

3/10 - typist

Add Fee:  : Site Insp (\$)  
 : Interview (\$)  
 : Tech. Invs (\$)  
 : Weekend (\$)

Report Format : **TP**  
 Lump Sum / I.B.I: (\$) **5600/3**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED VEHICLE INSURANCE COMPANY LTD Ref : CS/AWA18014961/T1vd3

(SINGAPORE BRANCH)  
60 ANSON ROAD #08-01 (8th FLOOR)  
MAPLETRAIL LANSION  
SINGAPORE 439614

Date : 16-08-2018



Code : AWA

## 1. Policy Particulars :- THIRD PARTY CLAIM

|     |                  |                |            |
|-----|------------------|----------------|------------|
| Ins | GBF 5638Y        | Veh. Inspected | YN 4838D   |
| Pol | AVCPSB0084171701 | Coverage (\$)  | 0.00       |
| Cl  | ORF5638Y/BT      | Excess (\$)    | 0.00       |
| Ass | TANG BEN         | Assign Date    | 16/08/2018 |

## 2. Vehicle Particulars & Condition

|    |        |              |   |
|----|--------|--------------|---|
| Ma | M      | c.c          | 0 |
| En | HIDDEN | Year of Reg. |   |
| Ch |        | Colour       |   |
| Od |        | Steering     |   |
| Br |        | Modification |   |
| Ge |        |              |   |

## 3. Conditions of Tyres

|     | Make | Balance |
|-----|------|---------|
| R/F |      | mm      |
| L/F |      | mm      |
| R/R |      | mm      |
| L/R |      | mm      |

## 4. Description of Damages

|  |  |
|--|--|
|  |  |
|--|--|

## General Information

|   |                       |                 |            |
|---|-----------------------|-----------------|------------|
|   | 20/08/2018            | Inspection Date | 20/08/2018 |
| S | LKK AUTO WORKSHOP LLP |                 |            |
|   | 111 BUKIT AVE 6       |                 |            |
|   | SINGAPORE 417883      |                 |            |

## Remarks

|  |  |
|--|--|
|  | CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.          |
|  | YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |

## Nivitha (LKK Auto)

---

**From:** Tang, Ben <Ben.Tang@awac.com> on behalf of Motorsurvey <Motorsurvey@awac.com>  
**Sent:** Thursday, 16 August 2018 11:39 AM  
**To:** 'assignments'  
**Cc:** 'SUR'; 'Ryder Auto workshop'  
**Subject:** TP Survey assignment for YN 4838D - DOA: 14/08/2018 Our ref: GBF 5638Y/BT

The above captioned accident refers.

Pursuant to the Practice Directions Amendment No. 1 of 2016 which was effective on 1 April 2016, we like to advise that the third party claimant and us **do** have consensus in the appointment of **Mr Adrian Ling** as the Single Joint Expert to conduct the pre-repair survey of the third party claimant's vehicle.

Please conduct "THIRD PARTY" survey on without prejudice basis. The information as are follows:

|                               |   |                                    |
|-------------------------------|---|------------------------------------|
| 3 <sup>rd</sup> Party Vehicle | : | YN 4838 D                          |
| Insured Vehicle               | : | GBF 5638 Y (Accident not Reported) |
| Policy Number                 | : | AVCPSB0084171701                   |
| Name of Workshop              | : | Ruder Auto Pte Ltd                 |
| Contact Number                | : | 9792 4673                          |
| Person to Contact             | : | San Choon                          |
| Estimated Cost of repairs     | : | \$ NA                              |

Copy to Ruder Auto Pte Ltd via Email

Note -

- ( x )
1. This is to keep you informed that we have appointed surveyors to conduct inspection to your client's damaged vehicle on a without prejudice basis.
  2. **Please keep our motor surveyor and us informed so as to enable the surveyor to conduct a post repair inspection once your client's vehicle has been repaired and before returning the repaired vehicle to your customer.**
  3. Please quantify your client's claim with all relevant supporting documents once your client's vehicle has been repaired.
  4. Please do not construe this appointment of surveyor and our above request as an admission of liability.

Regards  
Motor Claims  
Claims Group  
Global Market

The information contained in this e-mail and any attachments hereto is confidential. If you are not the intended recipient, you must not use or disseminate any of this information. If you have received this e-mail in error, please immediately notify the sender by reply e-mail and permanently delete the original e-mail (and any attachments hereto) and any copies or printouts thereof. Although this e-mail and any attachments hereto are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by Allied World Assurance Company Holdings, GmbH or its subsidiaries or affiliates, either jointly or severally, for any loss or damage arising in any way from its use.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |   |
|----------------------------|---|
| Date Of Report             | 15/08/2018 11:10                        |
| Date Of Accident           | 14/08/2018 16:20                        |
| Exact Location Of Accident | AYE TOWARDS TUAS (BEFORE NORMATON EXIT) |
| Country/State of Loss      | SINGAPORE                               |

### DETAILS OF OWN VEHICLE

|                             |                               |
|-----------------------------|-------------------------------|
| Vehicle Registration Number | YN4838D                       |
| <b>Insured/Policyholder</b> |                               |
| Name Of Registered Owner    | HUARONG ARTS & CRAFTS PTE LTD |
| Co Reg No                   | 200210461H                    |
| Email Address               | NOEMAIL                       |
| Mobile Phone No             | (LOCAL) +65-93799559          |
| Alternative Phone No        | OFFICE-93799559               |

### Vehicle Particulars

|  |                    |
|--|--------------------|
| Manufacturer   | HINO               |
| Model  | LORRY              |
| Exact Purpose for which vehicle was being used at time of accident           |                    |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO                 |
| If No, Please state action to be taken                                       | THIRD PARTY        |
| Vehicle Category   | COMMERCIAL VEHICLE |

### Insurance Company

|                           |  |
|---------------------------|--|
| Name of Insurance Company | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Type Of Coverage          | COMPREHENSIVE                          |
| Fleet Policy              | NO                                     |
| Policy Number             | 5069005004-03                          |
| Cover Note Number         |  |

### Driver

|                      |                      |
|----------------------|----------------------|
| Name of Driver       | LIN ZHANWEN          |
| NRIC No              | G5452856L            |
| Date Of Birth        | 19/01/1973           |
| Occupation           | OUTDOOR              |
| Date Of Driving Pass | 27/12/2013           |
| Driving Experience   | 4 YEARS AND 7 MONTHS |
| Gender               | MALE                 |
| Mobile Number        | (LOCAL) +65-93799559 |
| Fax Number           |                      |
| Contact Number       | OFFICE-93799559      |
| E-Mail Address       | NOEMAIL              |

|   |  |
|---|--|
| Address   | 1 BUKIT BATOK CRESCENT<br>#06-40 WCEGA PLAZA |
| Postcode  | S658064                                      |
| Was driver an employee of the Insured's Company     | YES  |
| If No, Relationship of the Driver with the Insured  |  |
| Vehicle Registration Number of Driver's Own Vehicle | -  |
|   | -  |
|   | -  |
| Insurance Company of Driver's Own Vehicle           | -  |
|   | -  |
|   | -  |

#### General Information of the Accident

|                    |                          |
|--------------------|--------------------------|
| Type Of Accident   | COLLISION - HEAD TO REAR |
| Weather Conditions | CLEAR                    |
| Road Surface       | DRY                      |

#### Other Information

|   |     |
|---|-----|
| Was any foreign vehicle involved in this accident?  | NO  |
| Number of vehicles involved in the accident   |     |
| Was any body injured in the Accident?   | NO  |
| Was any injured conveyed to hospital by ambulance?  |     |
| Was any other material or property damaged?   | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO  |
| Number of Passengers (Including Driver)   | 1   |

#### Details of Police Action

|   |    |
|---|----|
| Was the accident reported to the police?  | NO |
| If Yes, Please state which Police Station |    |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom?                     |    |

#### Circumstances of Accident

I WAS TRAVELLING ALONG AYE GOING TOWARDS TUAS (BEFORE NORMANTON EXIT), A LORRY THAT WAS BEHIND ME WAS TRYING TO OVERTAKE ME FROM THE RIGHT. AS THE RESULT, THE LEFT SIDE PORTION OF THE SAID LORRY HIT ONTO THE REAR RIGHT PORTION OF MY VEHICLE.

#### Attachment(s)

|   |     |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera?   | NO  |
| Was there any audio recorded?                 | NO  |

#### DETAILS OF OTHER VEHICLE PROPERTY 1

|                                     |                    |
|-------------------------------------|--------------------|
| Vehicle Registration Number         | GBF5638Y           |
| Vehicle Make/Model/Colour           | TOYOYA             |
| Details Of Properties               |                    |
| Vehicle Category                    | COMMERCIAL VEHICLE |
| Name of Driver                      | XU XINCHUN         |
| NRIC/Passport Number                | 0 74026656         |
| Contact Number                      |                    |
| Address                             |                    |
| Postcode                            |                    |
| Insurance Company Name              |                    |
| Nature Of Damage                    |                    |
| No. Of Passenger (Including Driver) |                    |

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



林斌文

Policyholder's Signature  
Date & Time:

(Co. Reg. No: 200210461H)  
 No. 1 Bukit Batok Crescent #05-49  
 VIC/GA, LAZA Singapore 659545  
 Tel: 6277 9717 / 6275 0709 Fax: 6278 1071  
 Email: busin@vic.com.sg

林斌文

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

**IDAC BUKIT BATOK (VAC)**  
 511 Bukit Batok Street 23  
 Singapore 659545  
 Tel: 6560 3312 Fax: 6569 0722  
 Email: vacbb@singnet.com.sg

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



# Ryder

 Auto Pte Ltd

1 Kaki Bukit Ave 6, #01-56, Autobay @ Kaki Bukit, Singapore 417883

Email: [ryderautoworkshop@gmail.com](mailto:ryderautoworkshop@gmail.com)

Fax: 64815390

## ESTIMATE OF REPAIR

(Without Prejudice)

Veh # : YN4838D Model : HINO XZU700R-HKFMS3

Date Of Accident: 14/8/2018

Location : AYE TOWARDS TUAS (BEFORE NORMANTON EXIT)

| Qty    | Description                               | Surveyor<br>Remarks | Surveyor<br>Adj | Amount \$        |           |
|--------|---|---------------------|-----------------|------------------|-----------|
|        | <u>Special Nett Items</u>                 |                     |                 |                  |           |
| 1 pc   | Rear o/s tail-gate plywood cover          |                     |                 | 200.00           | X un      |
| 1 pc   | Rear o/s tail-gate                        |                     |                 | 3,800.00         | 2800 bt ✓ |
| 2 pcs  | Rear o/s tail-gate hinges (Upper & Lower) |                     |                 | 400.00           | 300 bt ✓  |
| 1 pc   | Rear o/s tail-gate lock                   |                     |                 | 600.00           | 400 bt ✓  |
| 1 pc   | Rear o/s tail-gate rubber stopper         |                     |                 | 20.00            | X un      |
| 1 pc   | Rear o/s tail-gate pillar                 |                     |                 | 1,800.00         | 1200 bt ✓ |
| 1 pc   | O/s aluminium cover                       |                     |                 | 1,200.00         | X un      |
| 50 pcs | O/s aluminium cover rivets                |                     |                 | 50.00            | X un      |
| 1 pc   | O/s plywood cover X                       |                     |                 | 300.00           | X un.     |
|        | Sub-Total                                 |                     |                 | <b>8,370.00</b>  | 4700      |
|        | <u>Labour</u>                             |                     |                 |                  |           |
| 1      | To straighten and welding                 |                     |                 | 3,200.00         | 900       |
|        | Sub-Total                                 |                     |                 | <b>3,200.00</b>  |           |
|        | Total                                     |                     |                 | <b>11,570.00</b> |           |
|        | After -20%                                |                     |                 | <b>9,256.00</b>  |           |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$5600 #

5 days.

Tanpin 92495749

## Janice Lee (LKKAuto)

---

**From:** Ryder Auto workshop <ryderautoworkshop@gmail.com>  
**Sent:** Wednesday, October 03, 2018 9:02 AM  
**To:** Janice Lee (LKKAuto)  
**Subject:** Re: YN 4838D  
**Attachments:** image001.jpg

will do



1 Kaki Bukit Ave 6, #01-56, Autobay @ Kaki Bukit, Singapore 417883  
Fax: 64815390



5 Tuas Ave 3 BS Logistics Hub Singapore 639405  
Fax: 64815390



On Wed, Oct 3, 2018 at 8:58 AM Janice Lee (LKKAuto) <[JaniceLee@lkkauto.com](mailto:JaniceLee@lkkauto.com)> wrote:

Hi,

LOD you may submit to insurance.

Thank you.

Best Regards,

**Jannice Lee (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [janicelee@lkkauto.com](mailto:janicelee@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Janice Lee (LKKAuto)

---

**From:** Janice Lee (LKKAuto)  
**Sent:** Tuesday, October 02, 2018 5:55 PM  
**To:** ryderautoworkshop@gmail.com  
**Cc:** SUR  
**Subject:** YN 4838D

Dear Sir,

Confirm \$5,600 @ 5 days

Thank you.

Best Regards,

**Jannice Lee (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [janicelee@lkkauto.com](mailto:janicelee@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |  |                              |   |
|--|--|------------------------------|---|
| ALLIED WORLD ASSURANCE COMPANY LTD   |  | Ref : CS/AWA18014961/T1vd3e2 |   |
| (SINGAPORE BRANCH)<br>60 ANSON ROAD #08-01 (8th FLOOR)<br>MAPLETREE ANSON<br>SINGAPORE 079914  |  | Date : 01-11-2018            |  |
| Code : AWA   |  |                              |   |
| 1. Policy Particulars :- THIRD PARTY CLAIM   |  |                              |   |
| Insured Veh.   | GBF 5638Y  | Veh. Inspected               | YN 4838D  |
| Policy No.   | AVCPSB0084171701   | Coverage (\$)                | 0.00  |
| Claim No.  | GBF5638Y/BT  | Excess (\$)                  | 0.00  |
| Assign From  | TANG BEN   | Assign Date                  | 16/08/2018  |
| 2. Vehicle Particulars & Condition   |  |                              |   |
| Make & Model   | HINO XZU700R   | c.c                          | 4009  |
| Engine No.   | HIDDEN   | Year of Reg.                 | 2014  |
| Chassis No.  | JHHTCS3H60K001785  | Colour                       | WHITE   |
| Odometer   | 115039   | Steering                     | IN ORDER  |
| Brakes   | IN ORDER   | Modification                 | NIL   |
| General  | GOOD   |                              |   |
| 3. Conditions of Tyres   |  |                              |   |
|  | Size   | Make                         | Balance   |
| R/H Front Tyre   | 7.00 R16   | SUMITOMO                     | 6 mm  |
| L/H Front Tyre   | 7.00 R16   | SUMITOMO                     | 6 mm  |
| R/H Rear Tyre  | 7.00 R16 (D)   | SUMITOMO                     | 6/6 mm  |
| L/H Rear Tyre  | 7.00 R16 (D)   | SUMITOMO                     | 6/6 mm  |
| 4. Description of Damages  |  |                              |   |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.<br>DAMAGES SEE DETAILS.   |  |                              |   |
| 5. General Information   |  |                              |   |
| Accident Date  | 14/08/2018   | Inspection Date              | 20/08/2018  |
| Survey held at   | RYDER AUTO WORKSHOP LLP<br>1 KAKI BUKIT AVE 6<br>#01-56 SINGAPORE 417883 |                              |   |
| 5a. Remarks  |  |                              |   |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |                              |   |
| 5b. Estimate Days of Repair  |  |                              |   |
| ESTIMATED NORMAL PERIOD FOR REPAIR:  |  | <b>5 Working Days</b>        |   |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YN 4838D

| Qty                                | Description of Parts                           | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|--|---------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b>        |  |               |                           |                   |
| 1                                  | REAR O/S TAIL-GATE PLYWOOD COVER (SN)          | NOT NECESSARY | 200.00                    | -                 |
| 1                                  | REAR O/S TAIL-GATE (SN)                        | BENT          | 3,800.00                  | 2,800.00          |
| 2                                  | REAR O/S TAIL-GATE HINGES (UPPER & LOWER) (SN) | BENT          | 400.00                    | 300.00            |
| 1                                  | REAR O/S TAIL-GATE LOCK (SN)                   | BENT          | 600.00                    | 400.00            |
| 1                                  | REAR O/S TAIL-GATE RUBBER STOPPER (SN)         | NOT NECESSARY | 20.00                     | -                 |
| 1                                  | REAR O/S TAIL-GATE PILLAR (SN)                 | BENT          | 1,800.00                  | 1,200.00          |
| 1                                  | O/S ALUMINIUM COVER (SN)                       | NOT NECESSARY | 1,200.00                  | -                 |
| 50                                 | O/S ALUMINIUM COVER RIVETS (SN)                | NOT NECESSARY | 50.00                     | -                 |
| 1                                  | O/S PLYWOOD COVER (SN)                         | NOT NECESSARY | 300.00                    | -                 |
|                                    |  |               | 8,370.00                  | 4,700.00          |
| <b>LABOUR</b>                      |  |               |                           |                   |
|                                    | TO STRAIGHTEN AND WELDING.                     |               | 3,200.00                  | 900.00            |
|                                    |  |               | 3,200.00                  | 900.00            |
| <b>GRAND TOTAL</b>                 |  |               | <b>11,570.00</b>          | <b>5,600.00</b>   |
| <b>RECOMMENDED COST OF REPAIRS</b> |  |               |                           | <b>5,600.00</b>   |

Report Ref No. CS/AWA18014961/T1vd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.