LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd. From: LKK Auto Consultants Pte Ltd

AIG Building

51 Ubi Ave 1 #01-25 78 Shenton Way #07-16 Paya Ubi Industrial Park Singapore 079120 Singapore 408933

Attn: Mohd Zawaye, Norsazani 17 Aug 2018 Date:

Preliminary Advice

Vehicle No : SKH5019S Accident Date : 15/08/2018 Make : AUDI A4 Policy No. : 2100495291-01

Assignment Date : 17/08/2018 **Excess** : S\$0.00 Date of Inspection: 17/08/2018 Est. Duration of Repair : 8.00

Inspection At : PREMIUM AUTOMOBILES PTE LTD (UBI)

> 55 UBI ROAD 1 SINGAPORE 408699

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	24,855.00
Revised Amount	:S\$	12,875.00
Check Items (Estimated)	:S\$	5,502.00
Total	:S\$	18,377.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 130,000.00 COE / PARF Rebate :S\$ 63,050.00

Salvage Value :S\$

Margin for Repair :S\$ 66,950.00

Remarks

(>	()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
()	Other comments :