

INVOICE

INS. CASE OWNER:

CC 6/EQ1801

5116, 72663/

LKK:

IDAC:

Surveyor:

Amfikh

DOI:

ASSIGNMENT

21/8/18

Date / Time:

20/8/18

Registered in Merimen:

Pre-assign / CCU / FTE

sfw 8500u



Insured Vehicle No.:

Name of Insured:

DELTA LOGISTICS VIL

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

20/8/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: MA NA

Driver Tel No.:

(V/L YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

DMPMELT-104458

BMW

POMM PUYOVER SUP KO
HEADING MYE THAS

OI GIA REPORT YES / NO : TP GIA REPORT YES / NO

Insured Liability:

Final ? Yes / No

SGJ 9A5T

INSRS:
WSP:
Tel:
Liability:
RMKS:

modern

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time:

24/8/18

TH

22.1.19 #12PM

SGJ 9A5T - 4 SFW 8500u - 2

TRUCK ORO CONFIRMED ACCIDENT. ORO REAL EXCEED TO INFORM TP CLAIM
AGREED TO SETTLE AND AWARD ABOUT 100 VALUE.

STAGE

DATE / PIC

Non-Reporting Itr (1st)

Non-Reporting Itr (2nd)

Non-Reporting Itr (Final)

Notification Itr (if non-pickup)

Call OI:

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act:

Release Voucher: (No HRO)

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

SS 3,200

1

5 days) Reduction:

40 %

Email

Call

FINAL SETTLEMENT

Date/Time: 13.2.19

Confirm with: (N/A)

Email

Cal

Final Liability:

SS 100

(Agreed / Assessed) BOLA S/N No.:

31

If NO or B 28, Ass. Lia:

Repair Cost:

SS 3,424.00

Loss of Rental (LOR):

SS -

1

days)

Loss of Use (LOU):

SS 368.00

(5.0

x 5 days)

Loss of Income (LOI):

SS -

(5

x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

SS 2.00

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost:

SS -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

400

Total:

SS 3,726.00

Global Sum SS:

FINAL PAYMENT

Date/Time: 13.2.19

Confirm with: (N/A)

Email

Cal

Payee 1:

SS 3,726.00

Name 1:

MODERN AUTOMOTIVE PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

OLV
14/1
OK



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD		Ref : CC6/EQ18015116/T1ub3		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 20-08-2018		
		Code : EQI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKW 8500U	Veh. Inspected	SGJ 995T	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	20/08/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	20/08/2018	Inspection Date	21/08/2018	
Survey held at	MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

31 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC6/EQ118015116/T1ub3

Date: 23.08.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SGJ995T

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 21.08.2018 at the premises of M/s Modern Automotive Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	5,348.75
Revised Estimate Amount	: S\$	4,198.75
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5 days

Yours faithfully,

MOHD. TAUFIKH
Licensed Appraiser

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

EQ Insurance Co. Ltd

22 Gemmill Lane
Singapore 069257
Tel : 6223 - 9433
Fax : 6224 - 3903

Quotation

DATE : 21.08.2018
VEH NO : SGJ 995T
MODEL : Toyota Vios
D O A : 20.08.2018
YR REF : SKW8500U

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SGJ995T (TOYOTA VIOS)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Boot	1	de ✓ 505.00
2	Toyota Emblem	1	new ✓ 83.00
3	Vios Emblem	1	new ✓ 72.00
4	1.5e Emblem	1	new ✓ 74.00
5	vvti Emblem	1	new ✓ 73.00
6	Rear Boot Lock	1	bt ✓ 189.00
7	Rear Boot Hinges - LH & RH	2	Rx 190.00
8	Rear Bumper	1	de ✓ 326.00
9	Rear Bumper Bracket - LH & RH	2	new ✓ 230.00
10	Rear Bumper Side Retainer - LH & RH	2	new ✓ 190.00
11	Rear Bumper Clips	1 set	new ✓ 20.00
12	Rear End Panel	1	bt ✓ 640.00 <i>plus to.</i>
13	Rear End Panel Top Garnish	1	de ✓ ? 221.00
14	Tail Lamp - RH	1	can ✓ 189.00
15	Tail Lamp Panel - RH	1	bt ✓ 223.00
			\$ 3,225.00
Less 25%			(806.25)
			\$ 2,418.75
<u>S/NET ITEMS</u>			
1	Reverse Sensor	4	new ✓ 250.00 <i>200</i>
2	Rear End Panel Sealant	1	new ✓ 60.00 <i>40</i>
			\$ 310.00
Total Parts			
			\$ 2,728.75

LABOUR CHARGE

RE : ESTIMATE FOR ACCIDENT REPAIR SGJ995T (TOYOTA VIOS)

1	To knocking & pull out rear portion & renew above parts	\$ 700	1,200.00
2	To putty & spray up paint works	\$ 700	1,100.00
3	To check wiring	\$ ✓	20.00
4	To under seal	\$ ✓	30.00
5	To remove reverse sensor	\$ 30	120.00
6	To transfer bootlid fittings	\$ 60	150.00
Total Labour		\$	2,620.00
Grand Total		\$	5,348.75

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

62563561

Taufik 97495779

LAK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

wp'
21/8/18 @ 1150
Repairing after repair
surv R/Insurance Co. m.
5 days.

Asher Sng (LKKAUTO)

From: Chin <chin@modernautomotive.com.sg>
Sent: Friday, 1 February 2019 10:44 AM
To: Asher Sng (LKKAUTO)
Subject: RE: LOD SGJ995T (EQ)

Dear Asher

We accept your offer and please forward us your DV.

Thank you

Regards,
Grace Chin
Modern Automotive Pte Ltd
Blk 3023-A, Ubi Road 1 #01-61
Singapore 408717

Tel: 6748 4422
Fax: 6747 6720

From: Asher Sng (LKKAUTO) [mailto:AsherSng@lkkauto.com]
Sent: Friday, February 1, 2019 10:33 AM
To: Chin <chin@modernautomotive.com.sg>
Subject: RE: LOD SGJ995T (EQ)

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Hi Sir,

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair(w/GST)	\$ 3,424.00
2. Loss of Use (5 days x \$60)	\$ 300.00
3. LTA/GIA search fee	\$ 2.00

TOTAL

\$ 3,726.00

Kindly let us have your acceptance.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: Chin <chin@modernautomotive.com.sg>

Sent: Friday, 11 January 2019 3:18 PM

To: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>

Subject: Re: LOD SGJ995T (EQ)

Dear Asher

Please find our LOD for your perusal.

Thank you

Regards,

Grace Chin

Modern Automotive Pte Ltd

Blk 3023-A, Ubi Road 1 #01-61

Singapore 408717

Tel: 6748 4422

Fax: 6747 6720

MODERN AUTOMOTIVE PTE LTD

BLK 3023A UBI ROAD 1 # 01 - 61

SINGAPORE 408717

GST REG. NO : 200501102H

TEL : 6748 4422 / 6745 4422 FAX : 6747 6720

Email: chin@modernautomotive.com.sg

YOUR REF : SKW8500U

OUR REF : SGJ995T

Date : 05.10.2018

The Claims Manager

EQ Insurance Co. Ltd

5 Maxwell Road #17-00

Tower Block , MND Complex

Singapore 069110

Tel : 6223 - 9433

Fax: 6224 - 3903

**RE : ACCIDENT INVOLVING SGJ995T & SKW8500U ON 20.08.2018
ALONG CLEMENTI AVE 6 TOWARDS AYE (TUAS)**

We refer to the above matter.

We have been authorized by our client Mr Ho Hin Neng to make claim against your insured vehicle No.SKW8500U in respect of the above accident for the following :

Repair Cost	\$	3,424.00	(Incl GST)
Loss of use (5 days x \$100)	\$	500.00	
Search fee	\$	2.00	
Total :	\$	3,926.00	

Enclosed herewith a copy each of the supporting documents for your perusal.
Kindly process the above and remit the payment to us asap.

Yours faithfully



Modern Automotive Pte Ltd

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Tuesday, 22 January 2019 12:15 PM
To: 'MANA@DELTA LOG.COM.SG'
Subject: ACCIDENT INVOLVING SKW 8500U AND SGJ 995T ON 20/08/2018

Our Ref: CC6/EQI18015116/T1eb3

22 JAN 2019

DELTA LOGISTICS PTE LTD

Dear Sir/Madam,

ACCIDENT INVOLVING SKW 8500U AND SGJ 995T ON 20/08/2018

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Asher
Case Handler
DID: 6841 6051
FAX: 6741 4108
Email: Ashersng@lkkauto.com

c.c. **EQ INSURANCE COMPANY LIMITED**
(Motor Claims Dept)

LETTER OF AUTHORIZATION

Date: 20/8/18

TO WHOM IT MAY CONCERN

Dear Sir,

RE: ACCIDENT INVOLVING VEHICLE

SGJ 9957 & SKW 8500 U

ON 20/8/18 ALONG Clementi Ave 6 twds

AYE (Tuas)

This letter is to authorize **MODERN AUTOMOTIVE PTE LTD** at Block 3023A, Ubi Road 1, #01-61, Singapore 408717 to resolve the above matter.

In respect of this authorization, **MODERN AUTOMOTIVE PTE LTD** has my/our authority to decide on my/our behalf whether to accept any offer of settlement from the third party insurers. I/we also agreed that all payments include Loss of Use to make in favour of **MODERN AUTOMOTIVE PTE LTD**.

MODERN AUTOMOTIVE PTE LTD is also authorized to sign all the required documents include Discharge Voucher from the third party insurers on my/our behalf.

Yours Faithfully



Signature of Owner

Ho Hin Neng 51334614 C

Name / NRIC

MODERN AUTOMOTIVE PTE LTD

BLK 3023A UBI ROAD 1 # 01- 58 / 61 SINGAPORE 408717
TEL : 67474422, 67454422 FAX : 67476720
GST REG. NO : 200501102H

EQ Insurance Company Ltd
5 Maxwell Road #17-00 Tower Block
MND Complex 069110

Attention : Motor Claim Department

Tax Invoice : TP001258

Date : 05/10/2018
Vehicle Num. : SGJ 995T
Make/Model : TOYOTA VIOS-2006
Chassis/Eng# :
Accident Date : 20/08/2018
Claim No. :
Reference :
Policy No. : 5057433089-05

S/N	Quantity	Particular	Unit Price	Amount S\$
LABOUR :				
ACCIDENT REPAIR (LUMPSUM)				3,200.00
Labour Total S\$:				<u>3,200.00</u>

Total S\$:	3,200.00
GST @ 7% S\$:	224.00
Amount Due S\$:	<u>3,424.00</u>


MODERN AUTOMOTIVE PTE LTD



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

8 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-127577

Date of Request: 20/08/2018

Your Ref No: Online Purchase

Modern Automotive Pte Ltd
Blk 3023A Ubi Road 1
#01-61 & #01-58
Singapore 408717

Dear Sir/Madam,

Enquiry Date 20/08/2018
Enquiry By Ho Meei Huey
TP Vehicle No. SKW8500U
Accident Date 20/08/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SKW8500U	EQ Insurance Company Ltd	30/09/2017-29/09/2018	6223 9433

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-127577

Date of Request: 20/08/2018

Your Ref No: Online Purchase

Modern Automotive Pte Ltd
Blk 3023A Ubi Road 1
#01-61 & #01-58
Singapore 408717

Dear Sir/Madam,

Enquiry Date 20/08/2018
Enquiry By Ho Meei Huey
TP Vehicle No. SKW8500U
Accident Date 20/08/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 28/02/2019

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	SKW 8500U	(Insd Veh)	Your Ref. No. : DMPPHQ17-004458
	SGJ 995T	(TP Veh)	Our Ref. No. : CC6/EQI18015116/T1eb3q2
Date of Accident	20/8/2018		

Liability	100%	
Final Repair Cost	: \$ 3,424.00	
Loss of Use	: \$ 300.00	5 days
Rental (If any)	: \$	days
Others:	: \$ 2.00	
	: \$	
	3,726.00	
Final Settlement Sum	: \$ 3,726.00	
Remarks	:	

<u>Payment Instruction: Payee's Breakdown</u>		
1)	MODERN AUTOMOTIVE PTE LTD	: \$ 3,726.00
		: \$

JOANNE LEE
LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CC6/EQ18015116/T1eb3q2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 28-02-2019	
			Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKW 8500U	Veh. Inspected	SGJ 995T	
Policy No.	DMPPHQ17-004458	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	21/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VIOS	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	MR053HY4204190936	Colour	RED	
Odometer	212905	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	YOKOHAMA	6 mm	
L/H Front Tyre	185/60 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/08/2018	Inspection Date	21/08/2018	
Survey held at	MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGJ 995T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT	DEFORMED	505.00	505.00
1	TOYOTA EMBLEM	NECESSARY	83.00	83.00
1	VIOS EMBLEM	NECESSARY	72.00	72.00
1	1.5E EMBLEM	NECESSARY	74.00	74.00
1	VVTI EMBLEM	NECESSARY	73.00	73.00
1	REAR BOOT LOCK	BENT	189.00	189.00
2	REAR BOOT HINGES -LH & RH	TO REPAIR SEE LABOUR	190.00	-
1	REAR BUMPER	DEFORMED	326.00	326.00
2	REAR BUMPER BRACKET -LH & RH	NECESSARY	230.00	230.00
2	REAR BUMPER SIDE RETAINER -LH & RH	NECESSARY	190.00	190.00
1	SET REAR BUMPER CLIPS	NECESSARY	20.00	20.00
1	REAR END PANEL	BENT	640.00	640.00
1	REAR END PANEL TOP GARNISH	DEFORMED	221.00	221.00
1	TAIL LAMP -RH	CRACKED	189.00	189.00
1	TAIL LAMP PANEL -RH	BENT	223.00	223.00
	LESS 25% DISCOUNT		-806.25	-758.75
			2,418.75	2,276.25
SPECIAL NETT ITEMS				
4	REVERSE SENSOR (SN)	NOT WORKING	250.00	200.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	60.00	40.00
			310.00	240.00
LABOUR				
	TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS .INCLUSIVE OF THE REPAIR OF REAR BOOT HINGES -LH & RH.		1,200.00	700.00
	TO PUTTY & SPRAY UP PAINT WORKS.		1,100.00	700.00
	TO CHECK WIRING.		20.00	20.00
	TO UNDER SEAL .		30.00	30.00
	TO REMOVE REVERSE SENSOR .		120.00	30.00

Report Ref No. CC6/EQI18015116/T1eb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER BOOTLID FITTINGS.		150.00	60.00
			2,620.00	1,540.00
GRAND TOTAL			5,348.75	4,056.25
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,200.00

Report Ref No. CC6/EQI18015116/T1eb3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.