

22/03/2007

ASS. REC. BY:

REF:

CS/EGII8015142/Urd3

n2

Special Instruction:

Surveyor:

Motas

ASSIGNMENT (Office)

From (Person):

Siti A'fikah

of

EGI

Date/Time:

17/8/18 @ 6:13pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKP 60342

Insured:

SFH 2833L

at Workshop n/s

Soc Leon Motor

Tel:

67477 858

of

1 Kaki Bkt Ave G # B1K D # 01-91

Policy No:

Claim No:

CDMPG18000219

Sum Insured:

Excess:

Make of Veh:

D.O.A.

16/08/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

10:20am 20/8/18

Person Contacted:

Irene

Vehicle

IN/OUT

Date/Time

Action/Instruction

(✓) Estimate

SKP 60342-x

SFH 2833L - CS/AXA17060429/Ugh 3m2 DOA: 30/12/16

Perut thm email.

claim

(08/11/13) wef

REF:

ASS. REC. BY: *Marcus*

ER1/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: *SKP60342*at Workshop m/s *Soc Leon*

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: *77k.*

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: *2* Consistent?: Yes or NoEst. Repairs: *8* days Res.: Yes or NoLum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

L1A60772
Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: *SKP60342* Yr Regn: *9, 14*Type: *M.Car* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or *CA*Make: *Audi A4* c.c. *1798*Colour: *Black* A/C: Insured / Std / NI / NASp. Reading: *62244* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *W A U T T X S K 4 F A O 2 8 5 7*Gen. Cond: *Good* / Fair / Poor / BurntSteering: *In order* / Jammed / Leaked / Burnt orBrake: *In order* / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: *245 / 35 ZR19*BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / *PIR* / SUMI /

TOYO / YOKO or _____

Front *6* mm Rear *6* mmR/Bal. *6* mm L/Bal. *6* mmD.O.A. *16/8/18* D.O.I. *20/8/18*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

*Vehicle can't start. Rep 11k byrs Inl.
with 16228**30/8/18 conf. with 1/5 @ 11700 with new.**Ad: \$ 8282.60, 411.*

RECEIVED

13/9/18 claim not received

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: *8*1) *typist*☒ : Final ReportResurvey No. of Trip: *3*

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$) *S + RS* \$☐ : Interview (\$) Photos☐ : Tech. Invs (\$) Others☐ : Weekend (\$)Report Format: *TP*Lump Sum / I.B.I. (\$) *11,700.00*

Survey Fee:

Transportation:

350

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI18015142/Urd3

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 20-08-2018



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SFH 2833L	Veh. Inspected	SKP 6034Z
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	SITI A THIKAH	Assign Date	20/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	16/08/2018	Inspection Date	20/08/2018
Survey held at	SOC LEON MOTOR WORKS 1 KAKI BUKIT AVE 6 BLK D #01-91 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Your Ref: TBA
Our Ref: CS/EGH18015142/Urd3

The Motor Claims Department
ERGO Insurance Pte Ltd

Without Prejudice

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SKP 6034Z .


We thank you for the instruction on 20/08/2018.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 20/08/2018 at the premises of M/s SOC LEON MOTOR and have the following to report:-

Workshop Estimate Amount	: S\$ 19,982.60 .
Revised Estimate Amount	: S\$ 14,682.70 .
"Check" Items Amount	: S\$.
Market Value	: S\$.
LTA Reimbursement Value	: S\$.
Nett Value	: S\$.

Description of Damage:

The vehicle sustained damages
at the rear portion.



Comments/ Present Status:
Damages Consistent.

Yours faithfully

MARCUS CHUA
Automotive Assessor

Janice Lee (LKKAuto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Thursday, September 13, 2018 2:20 PM
To: Janice Lee (LKKAuto)
Cc: SUR
Subject: RE: SKP6034Z / TP : SFH2833L/LKK / DOA : 16/08/2018

CDMPG18000219

From: Janice Lee (LKKAuto) [mailto:JaniceLee@lkkauto.com]
Sent: Tuesday, September 11, 2018 1:00 PM
To: Survey Report (ERGO Insurance Pte. Ltd.)
Cc: SUR
Subject: RE: SKP6034Z / TP : SFH2833L/LKK / DOA : 16/08/2018

Dear Pei Li,

Kindly send us the claim reference.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janice Lee (LKKAuto)
Sent: Monday, September 03, 2018 10:50 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SKP6034Z / TP : SFH2833L/LKK / DOA : 16/08/2018

Dear Sir/ Madam,

Enclosed preliminary revised **SKP 6034Z**.

Kindly let us have your claim reference.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Nivitha (LKK Auto)

From: Siti A Thikah AB Rahman <siti.rahman@ergo.com.sg>
Sent: Friday, 17 August 2018 6:13 PM
To: Catherine Chong (LKK Auto) (admin-d@lkkauto.com)
Cc: assignments@lkkauto.com; Survey Report (ERGO Insurance Pte. Ltd.)
Subject: OI: SFH2833L | TP: SKP6034Z | DOA: 16.08.2018 | PRS | ERGO CLAIM REF: TBA
Attachments: SKP6034est.pdf; SKP6034report.pdf

Dear Nivitha / Catherine,

Please conduct this survey request on without prejudice basis and try to finalize with the repairer on the repairs (Note: Our insured has yet to lodge the accident report to us).

Details of the workshop is as below email.

Attached are the necessary documents for your further actions and kindly let us have an update of the survey status.

Kindly acknowledge receipt of this email.

NOTE: Please assist to quote our ref as the subject matter, when forwarding the Preliminary Reports / Survey Reports.

Thank you.

Regards,
Siti A' thikah

DID +65 6829 9170

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

EMAIL DISCLAIMER

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message. Any views expressed in this email communication are those of the individual sender. ERGO Insurance Pte. Ltd. does not represent, warrant or guarantee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference. ERGO Insurance Pte. Ltd. asserts copyright in respect to this email including any attachment. No part may be reproduced by any process or for any purpose without prior written permission.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

From: slmoi [mailto:slmoi@singnet.com.sg]
Sent: Friday, 17 August, 2018 1:57 PM
To: Siti A Thikah AB Rahman
Subject: Accident involving SKP6034Z & SFH2833L on 16/08/2018

Hi,

Please find attached repair estimate and accident report and kindly arrange for survey at your earliest convenience.
Our client's vehicle is now lying at our workshop premises.

Thanks & Regards,
Irene Leong
SOC LEON MOTOR WORKS
Tel : 67477858



Virus-free. www.avg.com

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 65551

Vehicle Details

Vehicle No.: SKP6034Z
Vehicle to be Exported: No
Intended De-registration Date: 20 Aug 2018
Vehicle Make: AUDI
Vehicle Model: A4 1.8 TFSI MU (EU6)
Primary Colour: Black
Manufacturing Year: 2014
Engine No.: CJE085463
Chassis No.: WAUZZZ8K4FA008657
Maximum Power Output: 125.0 kW (167 bhp)
Open Market Value: \$28,952.00
Original Registration Date: 25 Sep 2014
First Registration Date: 25 Sep 2014
Transfer Count: 0
Actual ARF Paid: \$22,533.00 11266

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 24 Sep 2024
PARF Rebate Amount: \$16,899.00

Intended COE Rebate Details

COE Expiry Date: 24 Sep 2024
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$74,801.00
COE Rebate Amount: \$43,873.00
Total Rebate Amount: \$60,772.00

The information contained herein is correct as at 17 Aug 2018

OK



SELL YOUR CAR BY BIDDING
HIGHEST SELLING PRICE GUARANTEED!
OR GET \$100 CASH!



Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

2018 Lotus Exige Sport 380.



Only One In Singapore. The
 Most Raw, Powerful Car For Its
 Price.
 Direct Owner StarAd

- * Free VICOM evaluation
- * Free grooming and 6 months maintenance
- * In-house workshop ensures quality service
- * Member of SYTA and hire purchase association
- * 100% deposit refund for unapproved loan


YONG LEE SENG MOTOR PTE LTD

Browse by Category

Sort by Date Posted 20 results/page

10 vehicles

Audi A4

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Audi A4		Any	Any	2014	Any	Any	Any	Available
	Audi A4	1.8A TFSI MU	<u>\$80,888</u>	\$11,000 /yr	17-Dec-2014	1,798 cc	72,000 km	Luxury	Available
New Arrival With No Repair Needed! Well Maintained By 1 Owner. Servicing Done Regularly, Road Tax Till Dec 2018. 6 Months Engine & Gearbox Warranty. Enjoy A Comfortable And Serene Ride In The Cabin Of... Euro Performance Asia Pte Ltd Posted: 20-Aug-2018 Tags: 2014 Audi A4, Audi A4, Audi, A4, Used Audi									
	Audi A4	1.8A TFSI MU	<u>\$83,999</u>	\$12,060 /yr	30-Aug-2014	1,798 cc	61,000 km	Luxury	Available
Beautiful Black On Black Interior. Premium Pre-Owned 110 Points Certification. Flexible Finance Package And Trade In, Please SMS/Call Now For Viewing Appointment And More Details. Premium Automobiles Posted: 20-Aug-2018 Tags: 2014 Audi A4, Audi A4, Audi, A4, Used Audi									
	Audi A4	1.8A TFSI MU	<u>\$88,999</u>	\$12,550 /yr	28-Oct-2014	1,798 cc	71,000 km	Luxury	Available
Modern Grey Exterior/Black Interior. Premium Pre-Owned 110 Points Certification. Flexible Finance Package And Trade In, Please SMS/Call Now For Viewing Appointment And More Details. Premium Automobiles Posted: 17-Aug-2018 Tags: 2014 Audi A4, Audi A4, Audi, A4, Used Audi									
	Audi A4	1.8A TFSI MU	<u>\$75,800</u>	\$11,010 /yr	30-Jun-2014	1,798 cc	-	Luxury	Available
Graded B by STA Up To 90% Loan! Flexible Repayment With In House Financing. Our Vehicle Inspected By Professional Team For Highest Quality With An Option To Extend Warranty Available. Owning A Car Is So Much Easy. Universe Motoring Posted: 16-Aug-2018 Tags: 2014 Audi A4, Audi A4, Audi, A4, Used Audi									
Car Buying Car Aftermarket Car Selling On The Move Car Ownership Lifestyle Buying a pre-owned car, but Unsure of its Condition? Get, STA Car Evaluation									
	Audi A4	1.8A TFSI MU	<u>\$75,800</u>	\$11,070 /yr	18-Jun-2014	1,798 cc	36,000 km	Luxury	Available
Very Well Maintained By Meticulous Lady Owner, Excellent Condition, Low Mileage, 3 Digit Number Plate 567. Posted: 16-Aug-2018 Tags: 2014 Audi A4, Audi A4, Audi, A4, Used Audi									
	Audi A4	1.8A TFSI MU	<u>\$81,500</u>	\$11,770 /yr	28-May-2014	1,798 cc	58,000 km	Luxury	Available
1 Owner, Low Mileage. Maintained And Serviced By Agent. 100% Accident Free. Like New. Trade In Welcome. Bank/ In House Loan Available. GST Included. Call Us To Make An Appointment For Viewing. Posted: 15-Aug-2018 Tags: 2014 Audi A4, Audi A4, Audi, A4, Used Audi									
Compare	Audi A4	1.8A TFSI MU	<u>\$81,800</u>	\$11,700 /yr	29-Aug-2014	1,798 cc	43,000 km	Luxury	Available

67418430

REPAIRING OF
MOTOR VEHICLES,
PANEL BEATING,
WELDING, SPRAYING,
INSURANCE AGENT,
CLAIMS
DEALING IN 2ND
HAND VEHICLE.

速良摩哆 SOC LEON MOTOR WORKS

AUTOBAY @ KAKI BUKIT

1 Kaki Bukit Ave 6, Blk D, #01-91, Singapore 417883

Tel: 6747 7858, 6747 2343 Fax: 6742 0012

E-mail: slmoi@singnet.com.sg

Reg No. 206639/00K

修理汽車貨車兼
打嗎甲燒奸噴漆
代理保險：車禍
賠償及買賣汽車

MR ONG CHENG HWA ROGER

DATE: 17/08/2018

DOA: 16/08/2018

ESTIMATE REPAIR FOR VEHICLE NO. SKP 6034Z (AUDI A4)

	Description	List Price
1 pc	Bootlid <i>02/14C</i>	\$ 1,450.00 ✓
2 pcs	Bootid hinge @SS205.00 <i>11</i>	\$ 410.00 X
1 pc	Bootlid lock <i>7w1</i>	\$ 165.00 ✓
1 pc	Lower catch <i>11</i>	\$ 58.00 X
1 pc	Weatherstrip <i>1w1</i>	\$ 185.00 ✓
1 pc	Logo <i>rec</i>	\$ 98.00 ✓
1 pc	A4 emblem <i>rec</i>	\$ 85.00 ✓
1 pc	TFSi emblem <i>rec</i>	\$ 105.00 ✓
2 pcs	Reflector @SS550.00 <i>one</i>	\$ 1,100.00 ✓
1 pc	Rear bumper <i>Dis</i>	\$ 1,230.00 ✓
2 pcs	Bumper side retainer @SS38.00 <i>help</i>	\$ 76.00 ✓
1 pc	Bumper reinforcement <i>DD</i>	\$ 380.00 ✓
2 pcs	Bumper bracket @SS50.00 <i>11</i>	\$ 100.00 ✓
1 pc	Lower centre garnish <i>Dis</i>	\$ 190.00 ✓
10 pcs	Bumper clips @SS12.50 <i>rec</i>	\$ 125.00 ✓
4 pcs	Reverse sensor @SS198.00 <i>544</i>	\$ 792.00 <i>3pc</i>
2 pcs	Taillamp @SS610.00 <i>one</i>	\$ 1,220.00 ✓
1 pc	Rear end panel (inner) <i>3.1500</i>	\$ 440.00 ✓
1 pc	Rear end panel (outer) <i>body</i>	\$ 300.00 ✓
1 pc	End panel top garnish <i>one</i>	\$ 140.00 ✓
1 pc	Spare tyre top board <i>11</i>	\$ 550.00 X
1 pc	Spare tyre panel <i>cramped/gul 1745</i>	\$ 2,090.00 ✓
1 pc	Tool box sponge <i>To.1</i>	\$ 90.00 ✓
1 pc	Tool box sponge top cover <i>one</i>	\$ 100.00 ✓
1 pc	Rear silencer box <i>11</i>	\$ 1,190.00 X
3 pcs	Silencer box mounting @SS85.00 <i>one</i>	\$ 255.00 <i>2pc</i>
2 pcs	Silencer box chrome @SS285.00 <i>11</i>	\$ 570.00 ✓
1 pc	Floor pan cover (lh) <i>11</i>	\$ 390.00 X
		\$ 13,884.00
		\$ (1,388.40)
		\$ 12,495.60

Less: 10%

not full amount
h/s \$11,700/-
8 day
2018/18
7th place after repair

P-13103
102
11792.7
14682.7

<u>Special Nett Items</u>			
	Towing fee	\$	110.00
1 pc	Battery <i>me</i>	\$	750.00
1 set	No. plate & housing <i>sup</i>	\$	60.00
	To diagnose by computer	\$	160.00
	To spray anti-rust	\$	180.00
	To remove & fix rear silencer box	\$	150.00
	Labour charges for knocking & replacing parts.	\$	2,200.00
	Spraypainting	\$	1,600.00
TOTAL :		\$	17,705.60
			<i>19982.60 2890</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIRING OF
MOTOR VEHICLES,
PANEL BEATING,
WELDING, SPRAYING,
INSURANCE AGENT,
CLAIMS
DEALING IN 2ND
HAND VEHICLE

速 良 摩 哆
SOC LEON MOTOR WORKS

AUTOBAY @ KAKI BUKIT
1 Kaki Bukit Ave 6, Blk D, #01-91, Singapore 417883
Tel: 6747 7858, 6747 2343 Fax: 6742 0012
E-mail: slmoi@singnet.com.sg
Reg No. 206639/00K

修理汽車貨車兼
打嗎甲燒奸噴漆
代理保險：車禍
賠償及買賣汽車

MR ONG CHENG HWA ROGER

DATE: 24/08/2018

DOA : 16/08/2018

SUPPLEMENTARY PARTS FOR VEHICLE NO. SKP 6034Z (AUDI A4)

	Description	List Price
1 pc	Rear end panel (lower)	\$ 650.00
1 pc	Battery terminal	\$ 380.00
2 pcs	Safety belts @S\$750.00	\$ 1,500.00
		\$ 2,530.00
	Less : 10%	\$ (253.00)
		\$ 2,277.00

Attn: Marcus



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI18015142/Urd3n2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 17-09-2018		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SFH 2833L	Veh. Inspected	SKP 6034Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	CDMPG18000219	Excess (\$)	0.00	
Assign From	SITI A THIKAH	Assign Date	17/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	AUDI A4 (A)	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	WAUZZZ8K4FA008657	Colour	BLACK	
Odometer	62244	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/35 ZR19	PIRELLI	6 mm	
L/H Front Tyre	245/35 ZR19	PIRELLI	6 mm	
R/H Rear Tyre	245/35 ZR19	PIRELLI	6 mm	
L/H Rear Tyre	245/35 ZR19	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/08/2018	Inspection Date	20/08/2018	
Survey held at	SOC LEON MOTOR WORKS 1 KAKI BUKIT AVE 6 BLK D #01-91 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKP 6034Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOTLID	DENTED / BUCKLED	1,450.00	1,450.00
2	BOOTLID HINGE @\$205.00	NOT NECESSARY	410.00	-
1	BOOTLID LOCK	TWISTED	165.00	165.00
1	LOWER CATCH	NOT NECESSARY	58.00	-
1	WEATHERSTRIP	TWISTED	185.00	185.00
1	LOGO	NECESSARY	98.00	98.00
1	A4 EMBLEM	NECESSARY	85.00	85.00
1	TFSI EMBLEM	NECESSARY	105.00	105.00
2	REFLECTOR @\$550.00	CRACKED	1,100.00	1,100.00
1	REAR BUMPER	DISTORTED	1,230.00	1,230.00
2	BUMPER SIDE RETAINER @\$38.00	BENT	76.00	76.00
1	BUMPER REINFORCEMENT	DENTED	380.00	380.00
2	BUMPER BRACKET @\$50.00	BENT	100.00	100.00
1	LOWER CENTRE GARNISH	DISTORTED	190.00	190.00
10	BUMPER CLIPS @\$12.50	NECESSARY	125.00	125.00
4	REVERSE SENSOR @\$198.00	SHORTED (3 PCS ONLY)	792.00	594.00
2	TAILLAMP @\$610.00	CRACKED	1,220.00	1,220.00
1	REAR END PANEL (INNER)	BADLY DENTED	440.00	440.00
1	REAR END PANEL (OUTER)	BADLY DENTED	300.00	300.00
1	END PANEL TOP GARNISH	CRACKED	140.00	140.00
1	SPARE TYRE TOP BOARD	NOT NECESSARY	550.00	-
1	SPARE TYRE PANEL	CRUMPLED / BUCKLED	2,090.00	1,745.00
1	TOOL BOX SPONGE	TORN	90.00	90.00
1	TOOL BOX SPONGE TOP COVER	CRACKED	100.00	100.00
1	REAR SILENCER BOX	TO REPAIR SEE LABOUR	1,190.00	-
3	SILENCER BOX MOUNTING @\$85.00	CRACKED (1 PC ONLY)	255.00	85.00
2	SILENCER BOX CHROME @\$285.00	BENT	570.00	570.00

Report Ref No. CS/EGI18015142/Urd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FLOOR PAN COVER (LH)	NOT NECESSARY	390.00	-
1	REAR END PANEL (LOWER)(ADDITIONAL)	BADLY DENTED	650.00	650.00
1	BATTERY TERMINAL (ADDITIONAL)	ACTIVATED / DAMAGED	380.00	380.00
2	FRONT SAFETY BELTS @\$750.00 (ADDITIONAL)	ACTIVATED / JAMMED	1,500.00	1,500.00
	LESS 10% DISCOUNT		-1,641.40	-1,310.30
			14,772.60	11,792.70
	SPECIAL NETT ITEMS			
1	BATTERY (SN)	CRACKED	750.00	250.00
1	SET NO PLATE & HOUSING (SN)	BENT	60.00	40.00
			810.00	290.00
	LABOUR			
	TOWING FEE.		110.00	60.00
	TO DIAGNOSE BY COMPUTER.		160.00	100.00
	TO SPRAY ANTI-RUST.		180.00	60.00
	TO REMOVE & FIX REAR SILENCER BOX.		150.00	80.00
	LABOUR CHARGES FOR KNOCKING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR SILENCER BOX.		2,200.00	1,200.00
	SPRAYPAINTING.		1,600.00	1,100.00
			4,400.00	2,600.00
	GRAND TOTAL		19,982.60	14,682.70
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			11,700.00

Report Ref No. CS/EGI18015142/Urd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.