



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 11/12/2018

Survey Details:

Date of loss	16-Aug-18
Date of appointment	17-Aug-18
Date of survey	20-Aug-18
Location of survey	CONNECT 3

Vehicle Details:

Claim Type:	Third party
Vehicle number	CB 7614L
Make and Model	KING LONG XMQ6117K5 - 6691cc
Date of registration	15-Jul-15
Excess	
Market Value (est)	\$50,000.00
Parf Rebate (est)	\$0.00
Nett Loss (est)	\$50,000.00

Repair details:

Initial Estimate	\$ 8,208.00
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 3,346.20
Check items (estimate)	\$ -
Labour	\$ 1,600.00
Total	\$ 4,946.20
Lump Sum(if applicable)	\$ 3,950.00

Number of days for repair	<u>4 DAYS</u>
---------------------------	---------------



Remarks:

We have not authorized repairs. Based on TP video footage, TP vehicle was within lane while turning. Insured vehicle swerved in when collision happened. A letter and email were sent out to the Insured to notify TP claim and NCD. TP LOD IN. For mandate approval.

Mandate:

Liability(TP)		100%
Proposed Repair Cost	\$	3,950.00
Loss of Use	\$	600.00
Loss of Rental	\$	-
Loss of Income	\$	-
GIA/LTA search fees	\$	-
Others	\$	-
Proposed Total	\$	4,550.00