

### CONNECT 3

566 Woodlands Road ( Mandai Estate ) Singapore 728697

Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L

QT18/CB7614L/TPC-289

AXA Insurance Singapore Pte Ltd  
8 Shenton Way, #27-01 AXA Tower  
Singapore 068811

### QUOTATION

Dear Sir,  
Cost of Repair to Vehicle CB7614L  
With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)	
1.	RH compartment covers	2	1,650.00	3,300.00	DD
2.	RH reflector lamp assy	1	118.00	118.00	Brot
3.	RH compartment lamp	1	410.00	410.00	CRA
4.	RH rear wheel cover	1	1,300.00	1,300.00	X R
5.	RH rim cover	1	580.00	580.00	scr
6.	Spray painting	1	1,000.00	<del>1,000.00</del> 700	
7.	Labour charges	1	1,500.00	<del>1,500.00</del> 900	
SUB-TOTAL				SS8,208.00	

Thank you.

Part less 10%.

Yours faithfully,



Winnie Chai  
HP: 9850-9666

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No modification(s) is allowed
- Any supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Approved by: \_\_\_\_\_

Signature

Date:

NAZ LKK

20/8/18 0930

L/S

4 days

AFTER REPAIR PHOTO

6741 8434

NAZ@lkkauto.com