

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

## **Immediate Advice**

To: AXA Insurance Pte Ltd Date: 09/03/2020

## **Survey Details:**

Date of loss	16-Aug-18
Date of appointment	21-Aug-18
Date of survey	21-Aug-18
Location of survey	SK AUTOMOBILE PTE LTD

## **Vehicle Details:**

Claim Type:	Third party
Vehicle number	SKU 2545R
Make and Model	CITROEN GRAND C4 PICASSO 1.6 TURBO P.ROOF AT
Date of registration	23-Mar-10
Excess	
Market Value (est)	\$22,000.00
Parf Rebate (est)	\$16,552.00
Nett Loss (est)	\$5,448.00

# **Repair details:**

Initial Estimate	\$	46,086.75
------------------	----	-----------

## **Proposed/Revised repair cost:**

Lump Sum(if applicable)	\$ 4,800.00
Total	\$ 9,707.05
Labour	\$ 2,040.00
Check items (estimate)	\$ -
Parts	\$ 7,667.05



 $51\; UBI\; AVE\; 1,\, \#02-25\; PAYA\; UBI\; INDUSTRIAL\; PARK, SINGAPORE\; 408933\;\; TEL: \\ (065)\; 62563561\;\; FAX: \\ (065)\; 62564315\;\; PAYA\; UBI\; INDUSTRIAL\; PARK, SINGAPORE\; 408933\;\; TEL: \\ (065)\; 62563561\;\; PAYA\; UBI\; INDUSTRIAL\; PARK, SINGAPORE\; 408933\;\; TEL: \\ (065)\; 62563561\;\; PAYA\; UBI\; INDUSTRIAL\; PARK, SINGAPORE\; 408933\;\; TEL: \\ (065)\; 62563561\;\; PAYA\; UBI\; INDUSTRIAL\; PARK, SINGAPORE\; 408933\;\; TEL: \\ (065)\; 62563561\;\; PAYA\; UBI\; INDUSTRIAL\; PARK, SINGAPORE\; 408933\;\; TEL: \\ (065)\; 62563561\;\; PAYA\; UBI\; INDUSTRIAL\; PARK, SINGAPORE\; 408933\;\; TEL: \\ (065)\; 62563561\;\; PAYA\; UBI\; UBI\; PARK, SINGAPORE\; 408933\;\; TEL: \\ (065)\; 62563561\;\; PAYA\; UBI\; UBI\; PARK, SINGAPORE\; 408933\;\; TEL: \\ (065)\; 62563561\;\; PAYA\; UBI\; UBI\; PARK, SINGAPORE\; 408933\;\; TEL: \\ (065)\; 62563561\;\; PAYA\; UBI\; UBI\; PARK, SINGAPORE\; 408933\;\; TEL: \\ (065)\; 62563561\;\; PAYA\; UBI\; UBI\; PARK, SINGAPORE\; 408933\;\; TEL: \\ (065)\; 62563561\;\; PAYA\; UBI\; UBI\; PARK, SINGAPORE\; 408933\;\; TEL: \\ (065)\; 62563561\;\; PAYA\; UBI\; UBI\; PAYA\; UBI\; P$ 

#### **Remarks:**

We have not authorized repairs. It was reported that Insured vehicle was travelling straight on the left most side when TP vehicle reversed to park and the collision occured. We had requested for evidence from TP but no evidence provided till date. If TP is unable to provide evidence, we would like to deny the TP claim since TP vehicle was reversing. TP LOD in.

### **Mandate:**

Liability(TP)	0%	
Proposed Repair Cost	\$ 5,136.00	w/gst
Loss of Use	\$ -	no. of days
Loss of Rental	\$ 600.00	(\$100 x 6 days)
Loss of Income	\$ -	no. of days
GIA Search Fees	\$ 2.00	
Others (Medical Bills)	\$ -	
Proposed Total	\$ 5,738.00	
***TBC - To Be Confirmed		