

KIM KEAT MOTOR CO
Blk 10 Ang Mo Kio Industrial Park 2A
Avenue5 #05-34 AMK Autopoint
Singapore 568047

20 Aug 2018

AXA Insurance Pte Ltd.
Survey Dept.

Re: Quotation for damaged to FP8522C

<u>Item</u>	<u>Description of Parts</u>	<u>Qty</u>	<u>Amount</u>
1.	Mirror RH	1pc	38.00
2.	Brake Lever	1pc	15.00
3.	Handle Bar RH	1pc	85.00
4.	Weight RH	1pc	15.00
5.	Meter Assy Comp.	1pc	680.00
6.	Stay	1pc	85.00
7.	Top Cowl Assy	1pc	185.00
9.	Front Signal Lamp RH	1pc	38.00
10.	Fork Tube L&R	2pcs	280.00
11.	Fork Seal Set L&R	2set	55.00
12.	Steering Stem	1pc	185.00
13.	Steering Cone Bearing Assy	1set	55.00
14.	Brake Disc Front	1pc	280.00
15.	Fuel Tank	1pc	580.00
16.	Brake Pedal	1pc	55.00
17.	Footrest Assy Front RH	1pc	38.00
18.	Muffler	1pc	685.00
19.	Tail Cowl	1pc	125.00
20.	Tail Lamp Comp.	1Pc	98.00
21.	Mudguard	1pc	135.00
Total			\$ 3712.00
Less 10%			- 371.20
Sub-total			\$ 3340.80
<u>Nett Item</u>			
22.	Number Plate Front	1pc	\$ 12.00
23.	Number Platte Rear	1pc	15.00
24.	Fork Oil	1bottle	10.00
25.	To Repspray Top Cowl, Fuel Tank and Tail Cowl		280.00
26.	Transport Fee		30.00
27.	Labour		280.00
Grand Total			<u>\$ 3967.80</u>