



Your ref: TBA
Our ref: CC4/EQH18015234/T1ua3

Date: 04.09.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

PRELIMINARY ADVICE OF VEHICLE NO.

SLX 414X


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 03.09.2018 at the premises of M/s Performance Motors Limited (Alexandra) have the following to report:-

Workshop Estimate Amount	: S\$	<u>14,323.40</u>
Revised Estimate Amount	: S\$	<u>11,166.25</u>
"Check" Items Amount	: S\$	<u>2,007.15</u>
Total (Including Check Items)	: S\$	<u>13,173.40</u>
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the Front O/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4-7 days

Yours faithfully,

MOHD. TAUFIKH
Licensed Appraiser

Mon 03/09 @ 10am
S&R

SLX414X

A1



BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

260, Kampong Arang Road
East Coast Centre
Singapore 438190
Tel. 63190888 (AfterSales)
Fax. 63449777

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
64796501 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

15 AUG 2018

ESTIMATE

Estimate No. : b1 48023	Page No. : 1 of 5
Date Estimated : 14/08/2018	
Prepared By : Han Kwan Yong	

- ESTIMATE REPAIR FOR - Edwin Lee Jim Chiap 6 Lincoln Road #04-11 Singapore 308345	- ACCOUNT - 40000 Cash Sales - Service Singapore
--	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLX414X	BC98672	08/02/2018	640i xDrive GT	0

DESCRIPTION	VALUE
To replace front bumper & attachments, right headlight inner support including to knock out dented area caused by the accident	1700 2,550.00
To respray front bumper and front right fender	1730 1,923.00
To replace right headlight including program and conduct tests for proper function.	451 531.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150 177.00
Sundries. <i>NU</i>	7 150.00
Total Labour 1:	5,331.00

DESCRIPTION	QTY	PRIC	VALUE
FRT RH GRILLE (SPORT)	1	151.80	? 151.80
GUIDE BUMPER RH	1	17.00	? 17.00
GUIDE TOP RH	1	33.50	? 33.50
FRT BUMPER BOTTOM CARRIER (ACC)	1	441.55	? 441.55
# Air inlet fi	1	69.95	? 69.95
RH GRILLE AIR INLET OPEN (M)	1	70.85	? 70.85
RH COVER GRILLE (M)	1	56.50	? 56.50
RH FOG LAMP SUPPORT (M)	1	71.15	? 71.15
FRT BUMPER PANEL PRIMED (M/PDC/PMA)	1	1,870.60	del ? 1,870.60
# Grill, air i	1	99.70	? 99.70
AIR FLAPS TOP	1	273.65	? 273.65
EMBLEM (M)	1	79.95	neu ? 79.95
PLUG	10	1.05	neu ? 10.50
RH HEADLIGHT MOUNTING	1	134.30	? 134.30
# RH BRAKE AIR DUCT	1	51.50	? 51.50
RH HEADLIGHT LED AHL HIGH (ICON LIG)	1	5,174.20	mt ? 5,174.20
# Ultrasonic s	1	380.65	? 380.65
DECOUPING RING PDC TORQUE CONVERTER	1	5.05	? 5.05

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747772

290, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

118, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190628 (AfterSales)
63190833/538 (Motorrad)
Fax. 64796801 (AfterSales)
64796824 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 48023
Date Estimated : 14/08/2018
Prepared By : Han Kwan Yong

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLX414X	BC98672	08/02/2018	640i xDrive GT	0

Total Parts : 8,992.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a 'Without prejudice' basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Third Party / Uninsured losses / Direct Settlement

Claim No. _____
 Date: 3/9/18 @ 1220
 Excess \$: _____
 Signature: *Tan Jiah*
 Signature: *[Signature]*
 Authorized: Yes / No
 Type: _____
 Signature: *Tan Jiah @ lkkauto.com*
 4 days

Labour 1	:	5,331.00
Parts	:	8,992.40
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,002.64
Grand Total	:	15,326.04

14322.40

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401599W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 48023
Date Estimated : 14/08/2018
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Edwin Lee Jim Chiap
6 Lincoln Road
#04-11

Singapore 308345

- ACCOUNT - 45912
EQ Insurance Company Limited
5 Maxwell Road, #17-00 Tower Block
MND Complex
Singapore 069110

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SLX414X	BC98672	08/02/2018	640i xDrive GT	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace front bumper and attachments include making good the front RH fender and knocking out dents caused by the accident	1700.00		1,700.00 ✓	
To respray front bumper and front RH fender	1730.00		1,730.00 ✓	
To replace RH LED AHL headlight include programming and conducting tests for proper function	451.00		451.00 ✓	
To check electrical wiring systems at the front section for proper function	150.00		150.00 ✓	
Sundries.	150.00		150.00 ✓	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
FRT BUMPER PANEL PRIMED (MPDC/PMA)	1,870.60	1.00		1,870.60 ✓
EMBLEM (M)	79.95	1.00		79.95 ✓
PLUG	1.05	10.00		10.50 ✓
RH HEADLIGHT LED AHL HIGH (ICON LIG)	5,174.20	1.00		5,174.20 ✓

SUPPLEMENTARY ITEMS

Total Labour :	4,181.00
Total Parts :	7,135.25
Total Labour & Parts :	11,316.25
Deduction for Excess :	0.00
Total Repair Costs less Excess:	11,316.25
GST @7%:	792.14
Grand Total :	12,108.39

Hsiao Tong (LKKAuto)

From: Thin Thin (LKKAuto)
Sent: Tuesday, 30 October 2018 4:54 PM
To: PBSP; Taufikh (LKKAuto)
Subject: RE: FINAL REPORT / SLX414X

"Without Prejudice"

Dear Caroline,

We refer to the below matter.

Our surveyor have finalise COR at \$ 11,316.25 (exclude gst) 4 days and **subject to our principal approval**.

The days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

In order to expedite the claim process, please forward all relevant documents for us to proceed on negotiate settlement.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Best Regards,

Thin Thin Hlaing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2360 | email: thinthin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Tuesday, 30 October 2018 4:47 PM
To: Thin Thin (LKKAuto) <thinthin@lkkauto.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Subject: Fw: FINAL REPORT / SLX414X

URGENT REMINDER

From: PBSP
Sent: Monday, 22 October 2018 3:41 PM
To: taufikh@lkkauto.com; CS A Team
Subject: FINAL REPORT / SLX414X

Dear Taufikh

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 4,181.00

Total Parts : 7,135.25

Total Labour & Parts : 11,316.25

Repair days: 4

Thank you.

Regards,
Caroline

C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Monday, 20 August 2018 9:34 AM
To: assignments
Subject: FW: Our ref: SKW2733D -REQ FOR DIRECT SETTLEMENT - SLX414X & SKW2733D ON 12.08.2018
Attachments: SKM_558e18081518290.pdf; EQIC-MARS00002624-SKW2733D-gia.pdf

11 am @ 2018/11/16
person @ caroline
vehicle not in

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | 5(408933)

From: Janet Tan <janet.tan@eqinsurance.com.sg>
Sent: Sunday, 19 August 2018 2:34 PM
To: assignments <assignments@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: Our ref: SKW2733D -REQ FOR DIRECT SETTLEMENT - SLX414X & SKW2733D ON 12.08.2018

Dear all,

Attach the estimate and both parties' report.

Liability is clear. Proceed to direct settle if possible.

Regards,

Janet Tan

Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190

www.eqinsurance.com.sg

 A Member of Citystate



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: PBSP [<mailto:pml-pbsp@simedarby.com.sg>]

Sent: Friday, August 17, 2018 5:41 PM

To: Janet Tan <janet.tan@eqinsurance.com.sg>; EQI PRS <EQIPRS@eqinsurance.com.sg>
Subject: Re: Our ref: SKW2733D -REQ FOR DIRECT SETTLEMENT - SLX414X & SKW2733D ON 12.08.2018

Dear Sirs

We are agreeable to use a common surveyor below as the SJE.

LKK Auto Consultants Pte Ltd

LL

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: Janet Tan <janet.tan@eqinsurance.com.sg>
Sent: Thursday, 16 August 2018 9:24:03 AM
To: PBSP
Subject: Our ref: SKW2733D -REQ FOR DIRECT SETTLEMENT - SLX414X & SKW2733D ON 12.08.2018

***Without Prejudice
Save As To Costs***

Dear Caroline,

For pre repair survey request, please email to eqiprs@eqinsurance.com.sg

Liability is cleared. We can agree on direct settlement.

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please **revert within 2 working days** if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

1) AJAX Inspection Services Pte Ltd Tel: 6255 0808 Fax: 6849 9155	2) Automobile Inspection Services Pte Ltd Tel: 6286 0155 Fax: 6284 1539 Contact Person: Sophia
3) LBS Automotive Appraisal Pte Ltd L.B.S. Auto Consultants Pte Ltd Tel: 6281 6690 / 62832866 Fax: 6281 8748 Contact Person: Amy/ Grace	4) Priority Services Tel: 62934822 Fax: 62963283 Contact Person: Sharon
5) RT Appraisal Pte Ltd Tel: 67486076 Fax: 67480361 Contact Person: Elson/Elgene	6) LKK Auto Consultants Pte Ltd Tel: 6256-3561 Fax: 6741-4108
7) Kelvin Automotive Appraising Services Tel: 81825263 Fax: 67461148 Contact Person: Kelvin	8) Automotive Appraiser & Surveying Services Tel: 96623655 Fax: 67655662 Contact Person: Mr Chee
9) JP Knights Pte Ltd Tel: 63450068 Fax: 63445328	10) Appraisals Associates Pte Ltd Tel : 67472822 Fax: 67470070

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Regards,

Janet Tan
 Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: PBSP [<mailto:pml-pbsp@simedarby.com.sg>]
Sent: Wednesday, August 15, 2018 6:50 PM
To: Janet Tan <janet.tan@eqinsurance.com.sg>; Joel Goh <joel.goh@eqinsurance.com.sg>
Subject: Re: REQ FOR DIRECT SETTLEMENT - SLX414X & SKW2733D ON 12.08.2018

Dear Sirs,

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Sunday, 10 March 2019 1:34 PM
To: 'Janet Tan'
Cc: Admin A
Subject: <Seek Mandate> EQ ref : TBA *LKK ref : CC4/EQ18015234/T1pa3q2 [ACCIDENT INVOLVING SKW2733D(EQ-OI) AND SLX414X(TP) ON 12/08/2018]
Attachments: LKK Survey Report & Photos.pdf; TP LOD_SLX414X.pdf

EQ ref : TBA
LKK ref : CC4/EQ18015234/T1pa3q2

Dear Sirs/Madam,

ACCIDENT INVOLVING SKW2733D(EQ-OI) AND SLX414X(TP) ON 12/08/2018

We refer to the above matter.

The accident occurred when our insured driver came out from parking lot and collided onto third party parked vehicle. Liability is not in our insured driver's favour.

We seek your approval to offer Third Party repairer "**PERFORMANCE MOTORS LTD**" at **\$12,510.39(all-in)**.

The summary is as follows: -

	Claimed Amount	Revised Amount
1. Cost of Repair (w/GST)	\$ 15,326.04	\$ 12,108.39
2. Loss of Use (4days x \$100.00)	\$ 400.00	\$ 400.00 (4days x \$100.00)
3. LTA/ GIA Search Fee	\$ 2.00	\$ 2.00
Total	\$ 15,728.04	<u>\$ 12,510.39</u>

**4days recommendation for repair.

Enclosed here with all the relevant documents for your perusal.

Kindly let us have your approval/Instruction.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Wednesday, 13 March 2019 8:18 AM
To: PBSP
Cc: Admin A
Subject: RE: LOD REMINDER - SLX414X & SKW2733D ON 12/08/2018 - TP EQ INSURANCE
*** LKK REF: CC4/EQ18015234/T1pa3q2

Without Prejudice

Dear Sirs/Mdm,

We confirm settlement as follows: -

1. Cost of Repair (w/GST)	\$ 12,108.39
2. Loss of Use (4days x \$100.00)	\$ 400.00
3. LTA / GIA Search Fee	\$ 2.00
Total	\$12,510.39

We will proceed to close file.

"Please note that our above settlement is made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured/driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAuto)
Sent: Wednesday, 20 February 2019 4:30 PM
To: PBSP <pml-pbsp@simedarby.com.sg>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Cc: CS A Team <cs-a@lkkauto.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>
Subject: RE: LOD REMINDER - SLX414X & SKW2733D ON 12/08/2018 - TP EQ INSURANCE *** LKK REF: CC4/EQ18015234/T1pa3q2

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir / Madam,

Thank you for your email.

Please note that this case has been re-assigned to **Hsiao Tong**.

Our respective case handler will look into the matter and revert to you in due course.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@simedarby.com.sg>

Sent: Wednesday, 20 February, 2019 3:52 PM

To: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>

Subject: LOD REMINDER - SLX414X & SKW2733D ON 12/08/2018 - TP EQ INSURANCE

Dear LKK

Please assist to look into the attached LOD dated 2 Nov 2018.

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

Certificate of Insurance**MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)**

Cert No./Policy No. : D18MTPV01003358
Insured : LEE JIM CHIAP EDWIN
Motor Car (Registration No.) : SLX414X
Cover : Comprehensive - ExcelDrive PRESTIGE
Policy Commencement Date : 08 FEBRUARY 2018 10.44
Policy Expiry Date : 07 FEBRUARY 2019 23.59
Maximum Liability (Section I) : Market value at time of loss
Excess* : \$1500 - Section I
(Waived up to S\$1,000 if accident repair is done at ExcelDrive Workshops for the first claim per policy year)
Voluntary Excess* : N.A
Windscreen Excess* : S\$100.00 - Waived if Repair at ExcelDrive Workshop
Loss of Use : Per Policy Schedule

* Subject to GST wherever applicable

Persons or Classes of Persons entitled to drive*

1. The Insured.
2. Any other person who is driving on the Insured's order or with his permission.
3. In the event of the death of the insured,
 - a. any member of the insured's family, or a paid driver who has been driving the Motor Car during the life of the insured and permission to drive had not been withdrawn prior to the death of the insured; and
 - b. any other person who has been given permission to drive the Motor Car prior to the death and such permission had not been withdrawn by the insured.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Car or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Car. And provided further that the Motor Car is registered under the Road Traffic Act (Chapter 276) and its registration under the Road Traffic Act (Chapter 276) has not been cancelled at the time of the accident, loss or damage.

Limitations As To Use

Use only for social, domestic and pleasure purpose and for the Insured's business. The Policy does not cover use for hire or reward, racing, pace-making, speed testing, reliability trial, the carriage of goods other than samples in connection with any trade or business or use for any purposes in connection with the Motor Trade.

ExcelDrive Workshops and Accident Reporting


It is a condition precedent to liability that the Insured shall call at the Company's Accident Reporting Center with the Motor Car within 24 hours of the accident or by the next working day thereof.

All accident repairs to the Motor Car must be carried out at ExcelDrive Workshops, otherwise the claim is not payable under the Policy. For ExcelDrive Prestige Plan, accident repairs to the Motor Car can be carried out at any workshop other than ExcelDrive Workshops.

For the list of Accident Reporting Centres and ExcelDrive Workshops, please visit our website at www.sompo.com.sg or call our Emergency Hotline: (65) 6226 3323.

(We HEREBY CERTIFY that the policy to which this Certificate relates is issued in accordance with (1) the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia), and (2) the Policy terms, conditions and exceptions of the Private Car Policy ref MTP 27

Sompo Insurance Singapore Pte. Ltd.



Authorised Signatory

Date/Time of Issue : 07 FEBRUARY 2018 15:16

IMPORTANT NOTICE

- Keep the Certificate in your Motor Car.
- Under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189), it shall be unlawful for any person to use or cause to permit any other person to use a motor vehicle without a valid policy of insurance under the Act.
- On the sale of the Motor Car or if for any reason the insurance is terminated during its currency, the Insured must surrender the Certificate of Insurance and the Policy to the insurance company, if the Certificate of Insurance has been lost or destroyed, a statutory declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).
- This Policy will cease to be valid once the Motor Car has been sold to another person. The Policy is not transferable to the new owner of the Motor Car.

Intermediary Code & Name : 11M05507 & MMS SERVICES PTE LTD | CI Code : 22A 4QZZ04KJNY0QJAN

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1300955D



Name

EDWIN LEE JIM CHIAP

李任捷

Race

CHINESE

Date of birth

22-04-1958

Sex

M

S1300955D

Country of birth

SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number S1300955D

Name

EDWIN LEE JIM CHIAP

Birth Date 22 Apr 1958

Issue Date 03 Nov 2003



4886411



NRIC No. S1300955D

Date of issue

20-09-2012

Address

6 LINCOLN ROAD
#04-11
SINGAPORE 308345

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(IES)

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

30 Nov 1977



NP 425A



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 28/03/2019

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	SLX 414X (Insd Veh)	Your Ref. No. : DM18HO02131/JT
	SKW 2733D (TP Veh)	Our Ref. No. : CC4/EQI18015234/T1pa3q2
Date of Accident	12/8/2018	

Liability	100%	
Final Repair Cost	: \$ 12,108.39	
Loss of Use	: \$ 400.00	4 days
Rental (If any)	: \$	days
Others:	: \$ 2.00	
	: \$	
	12,510.39	
Final Settlement Sum	: \$ 12,510.39	
Remarks	:	

<u>Payment Instruction: Payee's Breakdown</u>		
1)	PERFORMANCE MOTORS LIMITED	: \$ 12,510.39
		: \$

JOANNE LEE

LKK Auto Consultants Pte Ltd



EQ Insurance Company Limited
 5 Maxwell Road
 #17-00 Tower Block
 MND Complex
 Singapore 069110
 Attention: Motor Claims

"Without Prejudice"

Your Ref:

Our Ref:

Date:

02 November 2018

Subject:

ACCIDENT INVOLVING VEHICLES SLX414X & SKW2733D ON 12.08.2018

Dear Sirs

We refer to the above matter.

The accident was caused solely by the negligence on the part of your insured. As a result of the said accident, our client has suffered losses which are set out hereunder as follows:-

Cost of repair	: S\$ 12108.39
Loss of use	: S\$ 400.00 (S\$ 100.00 x 4 days)
GIA search fee	: S\$ 2.00
Total	: S\$ 12510.39

A copy of each of the following supporting documents is enclosed:

1. Copy of Accident Report
2. Copy of Final Repair bill & GIA search slip
3. Copy of Certificate of Insurance
4. Copy of Identification Card & Driving License
5. Copy of Letter of Authorisation

Performance Motors
 Limited
 1800-Call-BMW
 (1800-2255-269)

www.pml.com.sg

303 Alexandra Road
 Sime Darby
 Performance Centre
 Singapore 159941
 Tel Sales 6319 0100
 Tel Aftersales:
 6319 0111
 Fax 6474 7770

215 Alexandra Road
 #01-01
 Sime Darby
 Business Centre
 Singapore 159944
 Tel Sales 6319 0511
 Tel Aftersales:
 6319 0527
 Fax 6479 6624

280
 Kampong Arang Rd
 East Coast Centre
 Singapore 438180
 Tel Aftersales:
 6319 0888
 Fax 6344 1332

Registered office
 305 Alexandra Road
 #02-01
 Vantage
 Automotive Centre
 Singapore 159942

Co. Reg. No.
 197401559W

Please note that you or your insured should send us an acknowledgement of receipt of this letter within fourteen (14) days from the date of this letter, failing which our client will have no alternative but to commence legal proceedings against you without any further notice to you or your insured.

Should you have a counterclaim against our client arising out of the accident, you are also required to send a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

For any correspondence, please contact Ms Caroline Tan at 6319-0174 / Fax. 6479-4601 or email to pml-pbsp@simeдарby.com.sg.

Yours sincerely

Teng Wai Khan
 Customer Service Manager, Body & Paint



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC4/EQI18015234/T1ua3

07 SEPT 2018

NG SWEE KIM KAREN EUNICE
BLK 216 LORONG 8 TOA PAYOH
#22-605
SINGAPORE 310216

Dear Sir/Madam,

ACCIDENT INVOLVING SKW 2733D AND SLX 414X ON 12/08/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, EQ Insurance Company Ltd to deal with the third party claim against your policy.

Based on the accident report and accident scenario, liability is not in your favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

THIN THIN HLAING
Case Handler
DID: 6841 2360
FAX: 6741 4108
EMAIL: thinthin@lkkauto.com

c.c. *EQ INSURANCE COMPANY LIMITED*
(Motor Claims Dept)

LETTER OF AUTHORISATION

ACCIDENT INVOLVING SLX414X & SKW2733D ON 12/8/18

I, Edwin Lee Jim Chia owner of Vehicle Registration No. SLX414X hereby authorise Performance Motors Limited to submit, correspond, negotiate and settle my claim for cost of repair and/or uninsured losses arising from the above accident.

I further authorise Performance Motors Limited to execute, sign, seal and deliver all documents whatsoever in relation to this matter and to accept and receive any payment due to me in respect of my claim above.

I hereby declare that all acts and documents done by virtue of this Letter of Authorisation on my behalf shall be good valid and effectual to all intents and purposes whatsoever as if the same had been done or executed by me in person.

I further confirm that the acceptance by Performance Motors Limited of the settlement amount in respect of such claim shall constitute the full discharge of my claim in respect of such loss and damage.

Signed by:



Name: EDWIN LEE JIM CHIA

NRIC No.: S1300953D

3/9/2018

In the presence of:

Han Kwang Yong

Name:

(Date)

3/9/2018

NRIC No.:

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770380, Kampong Arang Road
East Coast Centre
Singapore 438182
Tel. 63190888 (AfterSales)
Fax. 63449773115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/330 (Motorrad)
Fax. 64796401 (AfterSales)
64796424 (Motorrad)**SERVICE TAX INVOICE**Repair Order No. : **B1 1295926**Date IN : **03/09/2018**Cust. Svc. Advisor: **Han Kwan Yong**Page No. : **1 of 2**Invoice Number : **2024361 / WSB**Invoice Date : **31/10/2018**Payment Terms : **30 Days From Invoice**Invoice By : **Sharon Heng****- CUSTOMER INFORMATION -**Mr Edwin Lee Jim Chiap
6 Lincoln Road
#04-11

Singapore 308345

- INVOICE TO - 45912EQ Insurance Company Limited
5 Maxwell Road, #17-00 Tower Block
MND Complex
Singapore 069110

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLX414X	BC98672	08/02/2018	640I XDRIVE GT	9329

--- LABOUR 1 ---

	NETT
To replace front bumper panel including to make good the front right fender and knock out dented area caused by the accident. To remove and install body parts in order to carry out painting job.	1,700.00
To respray front bumper and front right fender	1,730.00
To replace right LED AHL High headlight including program and conduct tests for proper function.	451.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150.00
Sundries.	150.00
INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.	0.00
DATE OF ACCIDENT: 12.8.2018. 3RD PARTY CAR : SKW2733D.	
YOUR REF NO : NIL.	
VEHICLE WAS SURVEYED BY MR TAUFIKH FROM LKK AUTO CONSULTANTS PTE LTD ON 3.9.2018 AT 12.20 PM. AUTHORISED REPAIR BY MS JANET TAN FROM EQ INSURANCE ON 16.8.2018 VIA E-MAIL.	
PROPOSE LOSS OF USE = \$100X4. THE AMOUNT IS SUBJECTED TO INSURANCE COMPANY CONFIRMATION.	0.00
GIA SEARCH FEE = \$2.00.	0.00

Total Labour 1: **4,181.00****--- PARTS ---**

	Qty	Retail Price	NETT
FRT BUMPER PANEL PRIMED (M/PDC/PMA)	1	1,870.60	1,870.60
EMBLEM (M)	1	79.95	79.95
RH HEADLIGHT LED AHL HIGH (ICON LIG	1	5,174.20	5,174.20
PLUG	10	1.05	10.50

Total Parts : **7,135.25**

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559M GST Reg. No. M2-0020881-s



101, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

190, Kampung Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/330 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1295926	Page No. : 2 of 2
Date IN : 03/09/2018	Invoice Number : 2024361 / WSB
Cust. Svc. Advisor: Han Kwan Yong	Invoice Date : 31/10/2018
	Payment Terms : 30 Days From Invoice
	Invoice By : Sharon Heng

Labour Charges : 4,031.00	Total Labour & Parts Charges : S\$ 11,316.25
Parts Charges : 7,135.25	Less Insurance Excess : S\$ 0.00
Lubricant/Misc : 150.00	Invoice Total Amount Exclude GST : S\$ 11,316.25
	GST @ 7% : S\$ 792.14
	Invoice Total Amount Include GST : S\$ 12,108.39

Computer generated invoice. No signature is required. Amount Payable Include GST : **S\$ 12,108.39**

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.





RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
 Phone: +65 6224 0010 Fax: +65 6224 0030
 Operating Hours: Monday to Friday 9am to 5pm
 GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-123852

Date of Request: 13/08/2018

Your Ref No: Online Purchase

Performance Motors Limited
 303 Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941

Dear Sir/Madam,

Enquiry Date 13/08/2018

Enquiry By Caroline Tan Shirui

TP Vehicle No. SKW2733D

Accident Date 12/08/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SKW2733D	EQ Insurance Company Ltd	23/10/2017-22/10/2018	6223 9433

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
 Phone: +65 6224 0010 Fax: +65 6224 0030
 Operating Hours: Monday to Friday 9am to 5pm
 GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-123852
 Date of Request: 13/08/2018

Your Ref No: Online Purchase

Performance Motors Limited
 303 Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941

Dear Sir/Madam,

Enquiry Date 13/08/2018
 Enquiry By Caroline Tan Shirui
 TP Vehicle No. SKW2733D
 Accident Date 12/08/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

GIRO Cash Cheque

Hsiao Tong (LKKAuto)

From: Janet Tan <janet.tan@eqinsurance.com.sg>
Sent: Monday, 11 March 2019 10:02 AM
To: Hsiao Tong (LKKAuto)
Subject: FW: <Seek Mandate> EQ ref : TBA *LKK ref : CC4/EQI18015234/T1pa3q2 [ACCIDENT INVOLVING SKW2733D(EQ-DM18HO02131/JT) AND SLX414X(TP) ON 12/08/2018]
Attachments: LKK Survey Report & Photos.pdf; TP LOD_SLX414X.pdf

Dear Hsiao Tong

Please proceed to offer up to \$12,510.39.

Regards,

Janet Tan
Senior Executive | Claims



EQ Insurance Company Limited
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]
Sent: Sunday, March 10, 2019 1:34 PM
To: Janet Tan <janet.tan@eqinsurance.com.sg>
Cc: Admin A <admin-a@lkkauto.com>
Subject: <Seek Mandate> EQ ref : TBA *LKK ref : CC4/EQI18015234/T1pa3q2 [ACCIDENT INVOLVING SKW2733D(EQ-OI) AND SLX414X(TP) ON 12/08/2018]

EQ ref : **TBA**
LKK ref : CC4/EQI18015234/T1pa3q2

Dear Sirs/Madam,

ACCIDENT INVOLVING SKW2733D(EQ-OI) AND SLX414X(TP) ON 12/08/2018

We refer to the above matter.

The accident occurred when our insured driver came out from parking lot and collided onto third party parked vehicle. Liability is not in our insured driver's favour.

We seek your approval to offer Third Party repairer "**PERFORMANCE MOTORS LTD**" at **\$12,510.39(all-in)**.

The summary is as follows: -

	Claimed Amount	Revised Amount
1. Cost of Repair (w/GST)	\$ 15,326.04	\$ 12,108.39
2. Loss of Use (4days x \$100.00)	\$ 400.00	\$ 400.00 (4days x \$100.00)
3. LTA/ GIA Search Fee	\$ 2.00	\$ 2.00
Total	\$ 15,728.04	\$ 12,510.39

**4days recommendation for repair.

Enclosed here with all the relevant documents for your perusal.

Kindly let us have your approval/instruction.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CC4/EQ18015234/T1pa3q2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 28-03-2019	
		Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKW 2733D	Veh. Inspected	SLX 414X
Policy No.	DMPPHQ17-005299	Coverage (\$)	0.00
Claim No.	DM18HO02131/JT	Excess (\$)	0.00
Assign From	JANET	Assign Date	20/08/2018
2. Vehicle Particulars & Condition			
Make & Model	B.M.W. 640I	c.c	2998
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	WBAJV62090BC98672	Colour	GREY
Odometer	9329	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	245/40 R20	PIRELLI	6 mm
L/H Front Tyre	245/40 R20	PIRELLI	6 mm
R/H Rear Tyre	245/40 R20	PIRELLI	6 mm
L/H Rear Tyre	245/40 R20	PIRELLI	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	12/08/2018	Inspection Date	03/09/2018
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 414X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SUNDRIES (SN)	NECESSARY	150.00	150.00
1	FRT RH GRILLE (SPORT) (SN)	NOT NECESSARY	151.80	-
1	GUIDE BUMPER RH (SN)	NOT NECESSARY	17.00	-
1	GUIDE TOP RH (SN)	NOT NECESSARY	33.50	-
1	FRT BUMPER BOTTOM CARRIER (ACC) (SN)	NOT NECESSARY	441.55	-
1	AIR INLET FIT (SN)	NOT NECESSARY	69.95	-
1	RH GRILLE AIR INLET OPEN (M) (SN)	NOT NECESSARY	70.85	-
1	RH COVER GRILLE (M) (SN)	NOT NECESSARY	56.50	-
1	RH FOG LAMP SUPPORT (M) (SN)	NOT NECESSARY	71.15	-
1	FRT BUMPER PANEL PRIMED (M/PDC/PMA) (SN)	DEFORMED	1,870.60	1,870.60
1	GRILLE ,AIR I (SN)	NOT NECESSARY	99.70	-
1	AIR FLAPS TOP (SN)	NOT NECESSARY	273.65	-
1	EMBLEM (M) (SN)	NECESSARY	79.95	79.95
10	PLUG (SN)	NECESSARY	10.50	10.50
1	RH HEADLIGHT MOUNTING (SN)	NOT NECESSARY	134.30	-
1	RH BRAKE AIR DUCT (SN)	NOT NECESSARY	51.50	-
1	RH HEADLIGHT LED AHL HIGH (ICON LIG) (SN)	CUT	5,174.20	5,174.20
1	ULTRASONIC S (SN)	NOT NECESSARY	380.65	-
1	DECOUPLING RING PDC TORQUE CONVERTER (SN)	NOT NECESSARY	5.05	-
			9,142.40	7,285.25
LABOUR				
TO REPLACE FRONT BUMPER & ATTACHMENTS ,RIGHT HEADLIGHT INNER SUPPORT INCLUDING TO KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT.			2,550.00	1,700.00
TO RESPRAY FRONT BUMPER AND FRONT RIGHT FENDER.			1,923.00	1,730.00
TO REPLACE RIGHT HEADLIGHT INCLUDING PROGRAM AND CONDUCT TESTS FOR PROPER FUNCTION.			531.00	451.00
TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS .			177.00	150.00
			5,181.00	4,031.00

Report Ref No. CC4/EQ118015234/T1pa3q2



GRAND TOTAL		14,323.40	11,316.25
RECOMMENDED COST OF REPAIRS			11,316.25

Report Ref No. CC4/EQ18015234/T1pa3q2

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automotive Assessor

HO LEONG CHUAN
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Joanne Lee (LKK Auto)

From: Joanne Lee (LKK Auto) <report@lkkauto.com>
Sent: Friday, 29 March 2019 2:22 PM
To: 'janet.tan@eqinsurance.com.sg'
Subject: TP Direct Settlement - Accident Involving SKW 2733D (OI) and SLX 414X (TP) on 12/08/2018
Attachments: LKK REPORT & PHOTO.pdf; TP DS SUPPORTING DOCUMENT.pdf

Dear Sir/Madam,

Please be informed that the above-mentioned case had been settled.

Enclose herewith final report & relevant documents for your necessary action please.

Thank you.

Best Regards,

JOANNE | Reports

LKK Auto Consultants Pte.Ltd.

Phone: 6256-3561 Ext.111 Fax: 6741-4108 email: report@lkkauto.com

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 Singapore 408933