

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 17:36

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014540 Date : 03/12/2019 Order : SLN7819T Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SLN7819T (V 33618) Regn Date: 17/05/2017 Mileage: 19376 WIP No.: 21388

Model: A3 SPORTSBACK 1.0 TFSI 8VFANG Chassis: WAUZZZ8V2HA122394 Engine: CHZ 351321 Dept: U

You have been assisted by :- UB-Tony Foong (33)

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE	25.00	1.00	25.00
S	SUBLET	M: TO INSTALL IN-CAR CAMERA.	900.00	1.00	900.00
S	SUBLET	M: TO INSTALL REAR WINDSCREEN SOLAR FILM	400.00	1.00	400.00
S	BODYWORK	M: TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION	280.00	1.00	280.00
S	BODYWORK	M: TO RENEW LHS 1/4 GLASS AND REAR WINDSCREEN TO FACILITATE FENDER RENEWAL	600.00	1.00	600.00
S	BODYWORK	M: TO REMOVE AND REINSTALL REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS AND REAR WIPER ASSY	480.00	1.00	480.00
S	BODYWORK	M: TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS,BATTERY MANAGER,FUSE AND RELAY TRAYS,ELECTRICAL AND AUDIO EQUIPMENT.INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	1400.00	1.00	1,400.00
S	BODYWORK	M: TO REMOVE AND REINSTALL REAR SEAT,BACK REST, HAT TRAY,ABCD PILLAR TRIM,LUGGAGE COMPARTMENT TRIMS.DISLODGE ROOF LINER AND DISENAGEGE CURTAIN AIRBAG	1400.00	1.00	1,400.00
S	BODYWORK	M: TO DISMANTLE AND REINSTALL CENTRE CONSOLE. RENEW AIRBAG CONTROL UNIT AND BOTH FRONT SEATBELT	1800.00	1.00	1,800.00
S	BODYWORK	M: TO REMOVE AND REINSTALL EXHAUST SYSTEM AND REAR SUSPENSION ASSEMBLY,INCLUDING REAR AXLE AND PROPELLOR SHAFT.RENEW ACCORDINGLY	2800.00	1.00	2,800.00

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 2 17:36

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014540	Account: A0006 (T 0)
	Date : 03/12/2019	AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
	Order : SLN7819T	
	Term : 30	

Regn No: SLN7819T (V 33618)	Regn Date: 17/05/2017	Mileage: 19376	WIP No.: 21388
Model: A3 SPORTSBACK 1.0 TFSI 8VFANG	Chassis: WAUZZZ8V2HA122394	Engine: CHZ 351321	Dept: U
You have been assisted by :- UB-Tony Foong (33)			

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE AND REINSTALL FUEL TANK ASSY	600.00	1.00	600.00
S	BODYWORK	M: TO SET UP VEHICLE ON CAR O LINER FOR REPAIR	1200.00	1.00	1,200.00
S	BODYWORK	M: TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID.REPAIR AND STRAIGHTEN LHS REAR CHASSIS FRAME TO SPECIFICATION OF ORIGIN.CUT OUT AND WELD REAR END PANELLING,SPARE WHEEL HOUSING AND LHS REAR FENDER.REPAIR RHS REAR FENDER.REORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL PARTS REMOVED	9000.00	1.00	9,000.00
S	BODYWORK	M: TO CARRY OUT STONE CHIP PRIMER WORK ON REAR PANELLING AND SPARE WHEEL HOUSING	780.00	1.00	780.00
S	BODYWORK	M: TO RESPRAY REAR BUMPER,REAR LID,BOTH REAR FENDER,LHS REAR DOOR AND LHS SILL PANEL. TO CARRY OUT STONE CHIP TREATMENT,CAVITY PRESERVATION AND JOINT SEALER WORKS	4950.00	1.00	4,950.00
S	BODYWORK	M: TO CARRY OUT WHEEL ALIGNMENT	240.00	1.00	240.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	384.00	1.00	384.00
S	BODYWORK	M: TO SUPPLY ACRYLIC SEALANT,CAVITY WAX,STONE CHIP TREATMENT,METAL FILLER POWDER,REAR WINDSCREEN SEALANT AND 1/4 GLASS SEALANT	1080.00	1.00	1,080.00
X	A8V4807083D	(A) (Ger) ADAPTER (28/8 Less 020%	1.00	31.70	25.36
X	A8V4807084D	(A) (SK) ADAPTER (02/10 Less 020%	1.00	31.70	25.36
X	A8V0945105	(A) (SK) REFLECTOR (28/ Less 020%	1.00	25.10	20.08
X	A8V4807739C	(AIR) (SK) CATCH (27/08 Less 020%	1.00	11.00	8.80
X	A8V4807740C	(AIR) (SK) CATCH (27/08 Less 020%	1.00	11.00	8.80
X	A8V4807377D	(AIR) (SK) GUIDE (27/08 Less 020%	1.00	56.60	45.28
X	A8V4807378D	(AIR) (SK) GUIDE (27/08 Less 020%	1.00	56.60	45.28

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 3 17:36

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014540 Date : 03/12/2019 Order : SLN7819T Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SLN7819T (V 33618) Regn Date: 17/05/2017 Mileage: 19376 WIP No.: 21388

Model: A3 SPORTSBACK 1.0 TFSI 8VFANG Chassis: WAUZZZ8V2HA122394 Engine: CHZ 351321 Dept: U

You have been assisted by :- UB-Tony Foong (33)

		Details	Qty	Unit Price	Amount
X	A8V3807329A	(AIR) (SK) BRACKET (27/	Less 020%	1.00	22.50
X	A8V3807330A	(AIR) (SK) BRACKET (27/	Less 020%	1.00	23.90
X	A8V4827705	(AIR) (SK) WTHRSTRIP (2	Less 020%	1.00	175.50
X	A8V4827520	(A) (SK) CAP (30/8/18)	Less 020%	1.00	6.10
X	A8V4827933B GRU	006423/ (V) (Ger) SPOIL	Less 020%	1.00	1467.00
X	A3B9998754	(A) (Ger) BUSH (28/8/18	Less 020%	1.00	45.70
X	A8V4867979E 4PK	(AIR) (SK) TRIM PANEL (	Less 020%	1.00	499.50
X	A8V4867973D 4PK	006423/ (V) (Ger) TRIM	Less 020%	1.00	249.50
X	A8V0813561	(AIR) (SK) PLATE (27/08	Less 020%	1.00	35.20
X	A8V0813562	(AIR) (SK) PLATE (27/08	Less 020%	1.00	35.20
X	A8V0809347	006423/ (V) (Ger) PLATE	Less 020%	1.00	48.20
X	A8V4853345 2ZZ	(AIR) (SK) MOLDING (27/	Less 020%	1.00	226.00
X	A8V5857705E V04	(AIR) (SK) SEAT BELT (2	Less 020%	1.00	956.00
X	A8V5857706E V04	(AIR) (SK) SEAT BELT (2	Less 020%	1.00	956.00
X	A8V4813331TB	(AIR) (SK) REINFORCEM(	Less 020%	1.00	644.50
X	A8V3827299B	(AIR) (SK) HINGE (27/08	Less 020%	2.00	134.50
X	A8V4945091	(AIR) (SK) TAIL LIGHT (	Less 020%	1.00	730.00
X	A8V4945093C	(AIR) (SK) TAIL LIGHT (	Less 020%	1.00	730.00
X	A8V0955711B	(AIR) (SK) MOTOR (27/08	Less 020%	1.00	402.50
X	A8V4863471H 4PK	(AIR) (SK) TRIM PANEL (	Less 020%	1.00	134.50
X	A8V4863879R FIK	(AIR) (GER) LINING (27/	Less 020%	1.00	914.00
X	A8V4867245B MG6	(AIR) (GER) LINING (27/	Less 020%	1.00	140.50
X	A8V4253609E	(AIR) (GER) SILENCER (2	Less 020%	1.00	556.00
X	A5Q0959655AR	(AIR) (SK) MODULE (27/0	Less 020%	1.00	1525.00
X	A8W9827239	(A) (SK) BUMPER (28/8/1	Less 020%	2.00	16.00
X	A5M0955875	(A) (SK) COUPLPIECE (28	Less 020%	2.00	22.60
X	A8V3955407 1P9	(A) (SK) WIPER ARM (28/	Less 020%	1.00	72.30
X	A8V0805673A	(A) (Ger) GROMMET (28/8	Less 020%	4.00	14.80
X	A5Q0813115	(A) (SK) FLOORPLATE (30	Less 020%	1.00	1603.00
X	A5Q0813528	(A) (SK) MEMBER (30/8/1	Less 020%	1.00	190.00
X	A5Q0803274B	(A) (SK) RETAINER (30/8	Less 020%	1.00	44.60
X	A8V4861529 GW8	(A) (SK) LINING (30/8/1	Less 020%	1.00	875.00
X	A8V4867769B RY9	(A) (SK) COVER (30/8/18	Less 020%	1.00	393.50
X	A8V3012635B	(A) (SK) BRACKET (30/8/	Less 020%	1.00	156.00

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 4 17:36

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014540 Date : 03/12/2019 Order : SLN7819T Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SLN7819T (V 33618) Regn Date: 17/05/2017 Mileage: 19376 WIP No.: 21388

Model: A3 SPORTSBACK 1.0 TFSI 8VFANG Chassis: WAUZZZ8V2HA122394 Engine: CHZ 351321 Dept: U

You have been assisted by :- UB-Tony Foong (33)

		Details	Qty	Unit Price	Amount
X	A8V3863697D	(A) (SK) PLAS BASIN(30	Less 020%	1.00	252.50
X	A8V0863423A 4PK	(A) (SK) COVER(3/9/18)	Less 020%	1.00	55.30
X	A8V4810205A	006428/(V) (Ger) SUPPO	Less 020%	1.00	560.50
X	A8V4817475	006428/(V) (Ger) PLATE	Less 020%	1.00	329.50
X	A5Q0803501AL	006431/(V) (G) SIDE ME	Less 020%	1.00	1164.00
X	A5Q0813127	006432/(V) (G) REINFOR	Less 020%	1.00	11.90
X	A8V4810197TA	006446/(V) (Ger) SIDE	Less 020%	1.00	660.00
X	AB 000750M3	BRAKEFLUID	Less 020%	1.00	28.00
X	A8V4827025D	(A) (SK) LID(28/8/18)	Less 020%	1.00	1782.00
X	A8V4809837	SUBPART	Less 020%	1.00	1938.00
X	A8V4845299A NVB	(AIR) (SK) SIDE WINDO(	Less 020%	1.00	224.50
X	A8V0810171A	WHEEL HOUS	Less 020%	1.00	214.50
X	A5Q0825701E	PLATE	Less 020%	1.00	146.00
X	A8V3807521K 9B9	(AIR) (Ger) SPOILER(27	Less 020%	1.00	205.50
X	A8V4813307	REAR APRON	Less 020%	1.00	216.00
X	A8V4845501 NVB	REARWINDOW	Less 020%	1.00	675.00
X	A8V4807067L GRU	(AIR) (GER) COVER(27/0	Less 020%	1.00	1619.00
X	A8V4807309	BEAM	Less 020%	1.00	500.50
X	A8V0098629A	ATT. PARTS	Less 020%	1.00	48.80
X	A8V4853742 2ZZ	AUDI SIGN	Less 020%	1.00	107.50
X	A8X0853737A 2ZZ	INSCRIPTION 'TFSI'	Less 020%	1.00	82.70
X	A8P0853741 2ZZ	INSCRIPTION 'A3'	Less 020%	1.00	82.70
X	A8V0857819	(AIR) (SK) ADJUSTER(27	Less 020%	2.00	171.50
X	A8R0827505A	LATCH	Less 020%	1.00	156.50
X	A8V0827507E	PLATE	Less 020%	1.00	75.90
X	A8V4810569A	(A) (Ger) DEADENER(28/	Less 020%	1.00	17.60
X	A8D0853419F	PACKING	Less 020%	1.00	14.50
X	A1K0253141L	CLAMP	Less 020%	1.00	52.30
X	A5Q0253144D	BRACKET	Less 020%	2.00	35.70
X	A4G9819181B	TRIM	Less 020%	1.00	28.60
X	A8J8827439	BALL PIN	Less 020%	2.00	17.70
X	A8J8827439	BALL PIN	Less 020%	2.00	17.70
X	A8T0827310	NUT	Less 020%	2.00	1.50
X	A1K0803583B	006423/(V) (G) PLUG(31	Less 020%	4.00	2.60

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 5 17:36

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014540 Date : 03/12/2019 Order : SLN7819T Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SLN7819T (V 33618) Regn Date: 17/05/2017 Mileage: 19376 WIP No.: 21388
Model: A3 SPORTSBACK 1.0 TFSI 8VFANG Chassis: WAUZZZ8V2HA122394 Engine: CHZ 351321 Dept: U
You have been assisted by :- UB-Tony Foong (33)

		Details		Qty	Unit Price	Amount
X	A8P4827249D	(A) (SK) BUMPER(28/8/1	Less 020%	2.00	17.10	27.36
X	A8P4827951A	PLUG	Less 020%	2.00	1.70	2.72
X	A8V0827566	BUTTON	Less 020%	1.00	1181.00	944.80
X	A8E0945246A	FASTENING	Less 020%	2.00	9.80	15.68
X	A311601361	RUBBER VAL	Less 020%	8.00	2.80	17.92
X	A5NA943021	LIC PL LIG	Less 020%	2.00	93.30	149.28
X	A4G9955205	CAP	Less 020%	1.00	16.10	12.88
X	A000979992A	(A) (SK) SLEEVE(28/8/1	Less 020%	2.00	131.00	209.60
X	A5Q0959651B	SENSOR	Less 020%	1.00	238.50	190.80
X	A2D0955962	(A) (SK) HOSE(28/8/18)	Less 020%	3.00	15.90	38.16
X	A1J0955751D	TUBING	Less 020%	1.00	72.30	57.84
X	A5Q0919275B GRU	SENSOR	Less 020%	4.00	210.50	673.60
X	A8V0945147A	(A) (SK) ADJUSTPART(30	Less 020%	2.00	16.70	26.72
X	A3B0955875	COUPLPIECE	Less 020%	2.00	22.40	35.84
X	A8V3955985	NOZZLE	Less 020%	1.00	24.50	19.60
X	A5Q0919133 704	WASHER	Less 020%	4.00	3.40	10.88
X	AD 00920002	PRIMER (DG)	Less 020%	2.00	18.20	29.12
X	A8K0973702G	HOUSING	Less 020%	1.00	8.10	6.48
X	A5Q0962131	AERIAL	Less 020%	1.00	64.10	51.28
X	AWHT006918	POP-RIVET	Less 020%	4.00	1.00	3.20
X	AN 105835019B9	RIVET	Less 020%	2.00	1.40	2.24
X	AN 90511505	NUT	Less 020%	2.00	1.60	2.56
X	AWHT002258	NUT	Less 020%	4.00	1.30	4.16
X	AN 90155703	WASHER	Less 020%	4.00	1.00	3.20
X	A8V3955425	WIPERBLADE REAR	Less 020%	1.00	22.80	18.24
X	A8V4827552	GASFILSTRU	Less 020%	1.00	88.20	70.56
X	A8V4853763 2ZZ	WINDOW SLO	Less 020%	1.00	233.50	186.80
X	A8V4853703A 2ZZ	MOLDING	Less 020%	1.00	509.00	407.20

Parts 24,206.88
Labour 0.00
Sublet 28,319.00
Menus 0.00
Lubricant 0.00

Sub-Total 52,525.88

7% GST 3,676.81

Grand Total 56,202.69



Received by

For & on behalf of
Premium Automobiles Pte Ltd