



金興(龔)汽車私人有限公司
 160 Sin Ming Drive, #02-18/19/20/21,
 Sin Ming AutoCity, Singapore 575722
 Tel: 6452 7018 Fax: 6458 3895
 Email: service@kkimhin.com.sg

TP INSURER: India International Insurance Pte Ltd (HQ)
 NIL

Singapore

Claimant Insurer: AXA Insurance Pte Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	19/08/2018
Vehicle Reg. No.:	SJL7929T	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	GOH CHYE HOCK, IVAN	Driver (Insured):	TAN ENG KWANG
Make/Model:	HYUNDAI AVANTE, 1.6 HD (M)	Vehicle Reg. Date:	12/12/2008
Vehicle Colour:	SILVER		
Engine No:	G4FC8U543764	Chassis No:	KMH DU41BR9U623456
Odometer:	0 KM		
Paint Type:			<i>Not known</i>
Total Loss?	NO		<i>LIB 87</i>
Est. Duration of Repair (day)	<i>2 days</i>		<i>Resumy After Pain</i>
Description of Accident/Loss	PLEASE REFER TO SKETCH PLAN.		
Remarks:	VEHICLE IS NOT IN YET, WE WILL ARRANGE FOR SURVEY ONCE READY. KINDLY ADVISE LIABILITY. THANK YOU.		
Present Location:	K KIM HIN AUTO PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	1,113.12
Miscellaneous Items	10.00
Labour	880.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,003.12
+ GST 7.00% (S\$)	140.22
Nett Amount (S\$)	2,143.34

This claim is handled by: WONG SHU MAN

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Aug 2018)

Parts: 143 HYUNDAI AVANTE 1.6 HD (M) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: K Kim Hin Auto Pte Ltd/SJL7929T/21/08/2018 10:43

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*REAR BUMPER	0.00	0.00	*489.10 F	✓
2	1		*REAR BUMPER SPONGE	0.00	0.00	*109.90 F	?
3	1		*REAR BUMPER REINFORCEMENT	0.00	0.00	*270.00 F	?
4	2		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	0.00	0.00	*134.60 F	X
5	2		*REAR BUMPER TOP BRACKET	0.00	0.00	*48.00 F	?
6	3		*REAR BUMPER BOTTOM BRACKET	0.00	0.00	*64.80 F	?
7	1		*REVERSE SENSOR	0	0.00	*220.00 FS	X
Sub Total (\$\$)						1,336.40	
- Add. Disc. on L,N Items 20.00% (\$\$)						223.28	
Total Parts (\$\$)						1,113.12	

F=Franchise part. S=SpcNett.

K Kim Hin Auto Pte Ltd/SJL7929T/21/08/2018 10:43. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND TO RENEW AFFECTED PARTS.	New	<i>200</i> 350.00
2	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New	<i>200</i> 450.00
3	TO REMOVE AND REFIT REVERSE SENSOR ASSY.	New	<i>50</i> 80.00
Gross Labour Cost (S\$)			880.00

K Kim Hin Auto Pte Ltd/SJL7929T/21/08/2018 10:43. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >