

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 9067Z

MAKE :

MODEL : HYUNDAI i40

AXA

DATE 21/8/2018 10:32

DOA: 17.08.2018

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Bumper Cover <i>X Rep</i>			\$ 562.30	
	Front Bumper Bracket (LH) <i>X</i>			\$ 24.60	
	Headlamp (LH) <i>X</i>			\$ 1,388.00	
	Frt & Rear Wheel Hub Cap, LH <i>✓</i>		\$ 150.70	\$ 301.40	
	<i>Front Pwr (LH) X Rep</i>				
	<i>Rear Pwr (LH) X Rep</i>				
	<i>Rear Fender (LH) X Rep</i>				
	<i>Rear Bumper (LH) X Rep</i>				
	<i>Rear Panel Bump (LH) X Rep</i>				
	<i>Front Fender (LH) X Rep</i>				
	SUB TOTAL			\$ 2,276.30	
	LESS 20%			\$ 455.26	
	DISCOUNTED TOTAL			\$ 1,821.04	
	Rear Bumper Rubber Mat <i>X</i>			\$ 50.00	Nett
	Rear Door Comfortdelgro & Apps Sticker (LH) <i>✓</i>			\$ 80.00	Nett
	Frt Door Color Comfort Logo (LH) <i>✓</i>			\$ 75.00	Nett
				\$ 205.00	
	Labour Charge				
	Panel Beating			\$ 650.00 <i>400</i>	
	Spray Painting Charge			\$ 1,750.00 <i>1400</i>	
	Four Wheel Alignment			\$ 120.00 <i>X</i>	
	TOTAL LABOUR			\$ 2,520.00	
	ESTIMATE TOTAL			\$ 4,546.04	
<i>Kalve' (LH)</i> <i>21/8/18 1520 hr</i> <i>3 Rep.</i> <i>4,</i> <i>After Rep't p Lh</i> UKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					