

RA | CC 4, ASM 180 15306, N fab 9/ | LKK: 14856
 IDVC:
 Surveyor: Ngz | DOI: 23/8/2018 | Date/Time: 23/8/2018
 Registered in Merimen: -

Pre-assign / CCU / FTE
 Insured Vehicle No.: SJK 8916 S | Claim No.: 58M0054J
 Name of Insured: MS CAR2 LEASING PTE | Policy No.: VEX/PL857572 *Car*
 Insured Tel No.: _____ | HP: _____ | Make / Model: Toyota
 Excess Sec II :SS _____ | D.O.A.: 20/08/2018 | Place of Accident: Victoria St.
 Is driver the owner? (YES / NO) _____ | Nature of Accident: _____
 If NO, Driver Name / Age: Lee Chin Cheng | OI GIA REPORT: YES () NO () ; TP GIA REPORT: YES () NO ()
 Driver Tel No.: 96927068 (V/L: YES / NO) | Insured Liability: % _____ Final? Yes / No _____

SLL 192Z → → → →
 INSRs: WSP: World Auto. | INSRs: WSP: _____ | INSRs: WSP: _____ | INSRs: WSP: _____
 Tel: _____ | Tel: _____ | Tel: _____ | Tel: _____
 Liability: _____ | Liability: _____ | Liability: _____ | Liability: _____
 RMKS: _____ | RMKS: _____ | RMKS: _____ | RMKS: _____

Date/Time		STAGE	DATE / PIC
<u>2/8/18</u>	<u>SLL192Z-X; SJK8916S-X</u>	Non-Reporting ltr (1st):	
		Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
<u>4/8/18</u>	<u>Rental company, send letter to OI</u>	Call OI:	
<u>14/8/18</u>	<u>proceed OI</u>	After call ltr to OI: <u>10/9/18</u>	<u>John 17/9</u>
		Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	<input type="checkbox"/>
		After call ltr to OI:	<input checked="" type="checkbox"/>
		Authorisation To Act:	<input checked="" type="checkbox"/>
		Release Voucher:	<input checked="" type="checkbox"/>
		Final Repair Bill:	<input checked="" type="checkbox"/>
		Car Rental Invoice:	<input type="checkbox"/>
		Towing Invoice:	<input type="checkbox"/>
		LTA / GIA:	<input checked="" type="checkbox"/>
		Medical Bill:	<input type="checkbox"/>
		PIR:	<input type="checkbox"/>
		Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
		LOD:	<input checked="" type="checkbox"/>
		Payment Breakdown Form:	<input type="checkbox"/>
		Post-Repair Photos:	<input type="checkbox"/>
		Others:	<input type="checkbox"/>
	<u>before print photo</u>		

PRELIMINARY ADVICE Date/Time: 2/10/18 Sent By: CAK

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____

Repair Cost: S\$ 7,136.40 (8 days) Reduction: 47.39 % Email Call

FINAL SETTLEMENT Date/Time: 28/8/18 Confirm with: baseline Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 27 If NO or B 28, Ass. Lia: _____
 Repair Cost: (w/ GST) S\$ 8,277.95
 Loss of Rental (LOR): SS - (_____ days)
 Loss of Use (LOU): SS 480.00 (560.00 x 8 days)
 Loss of Income (LOI): SS - (5 x _____ days)
 LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search: SS 2.00
 Medical: SS -
 Disbursement: SS - (e.g. Tow/ Independent)
 Legal Cost: SS -
 Total: SS 8,759.95 Global Sum SS: _____

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email Call

Payee 1: SS 8,759.95 Name 1: World Auto Pte Ltd
 Payee 2: (Strike if N.A.) SS - Name 2: _____
 Payee 3: (Strike if N.A.) SS - Name 3: _____

Front to rear
 7/3/19

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD
 143 Cecil Street #01-01 GB Building
 069542

Attention : Motor Claim Department
 Contact : 338 7288 Fax No. : 880 4828

Estimate : ES000299

Date : 23/08/2018
 Vehicle Num. : SLL 192Z (LCR)
 Make/Model : HONDA VEZEL HYBRID
 Chassis/Eng# : 2431223570
 Accident Date : 20/08/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR BOOT LID	1,200	1,300.00 / DD
2.	1	REAR BOOT HYBRID EMBLEM (VEZEL)		89.00 / K C
3.	1	REAR BOOT VEZEL EMBLEM (VEZEL)		89.00 / K C
4.	2/RH,LH	REAR BOOT REFLECTOR LAMP	900.00	1,800.00 / XSVL
5.	1	REAR NUMBER PLATE LAMP GARNISH		290.00 / X SVL
6.	1	REAR WINDSCREEN GLASS MOULDING		250.00 / M L
7.	1	REAR BOOT HAND GRIP COVER		60.00 / X SVL
8.	1	REAR BOOT LOCK ASSY		300.00 / not working
9.	1	REAR BOOT LOCK SWITCH		289.00 / X SVL
10.	1	REAR BOOT INNER TRIM BOARD		280.00 / X SVL
11.	1	REAR BOOT WEATHER STRIP		180.00 / TOCEN
12.	1	REAR BUMPER		900.00 / CRA
13.	2/RH,LH	REAR BUMPER REFLECTOR LENS	250.00	500.00 / CRA
14.	1	REAR END PANEL		860.00 / CRT
15.	1	REAR END PANEL TOP GARNISH		260.00 / QLA
16.	1	REAR FLOOR BOARD		350.00 / X SVL
17.	1	REAR FLOOR PANEL		800.00 / DD
18.	1	REAR COMPARTMENT BOX		280.00 / CRA
19.	2/RH,LH	REAR TAIL LAMP	700.00	1,400.00 / X SVL
20.	1	SMART BUZZER SENSOR		188.00 / PASSE
21.	1	REAR ANTENNA SENSOR		190.00 / X SVL
22.	2/RH,LH	REAR BUMPER RETAINER	89.00	178.00 / X SVL
List Total S\$:			5,208	10,833.00
20.00% Discount S\$:			4,166.40	2,166.60
				8,666.40
SPECIAL NETT ITEMS :				
1.	1	REAR NUMBER PLATE LAMP GARNISH CLIP		40.00 / X/N

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD
 143 Cecil Street #01-01 GB Building
 069542

Attention : Motor Claim Department
 Contact : 338 7288 Fax No. : 880 4638

Estimate : ES000299

Date : 23/08/2018
 Vehicle Num. : SLL 192Z (LCR)
 Make/Model : HONDA VEZEL HYBRID
 Chassis/Eng# :
 Accident Date : 20/08/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
2.	1	REAR WINDSCREEN SEALANT		100.00 / 122
3.	1	REAR BOOT INNER TRIM BOARD CLIP		40.00 x 2 = 80
4.	1	REAR BUMPER CLIP		40.00 / 220
5.	1	REAR END PANEL TOP GARNISH CLIPS		40.00 / 122
6.	2/RH, LH	REAR TAILLAMP CLIPS	40.00	80.00 x 2 = 160
7.	1	REVERSE SENSOR		280.00 / 122
Special Nett Total S\$:			420	620.00
LABOUR :				
TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES				480.00 80
REMOVE & REFIT REAR WINDSCREEN GLASS				180.00 120
TO APPLY RUSTPROOFING/ TUFFCOATING TREATMENT TO REPLACED PARTS.				180.00 300 60
REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING CUT/WELD, PANEL BEAT, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS				-2200.00 1,400
PUTTY AND SPRAY PAINT ALL AFFECTED AREAS (INNER&OUTER)				4,800.00 1,100
TO CHECK WIRES, CONNECTORS, REPLACE DAMAGED LAMPS AND REVERSE SENSORS.				420.00 30
TO REMOVE AND INSTALL HIGH VOLTAGE HYBRID BATTERY AS A REQUIREMENTS FOR SAFETY PRECAUTIONS.				380.00 240
TO CONDUCT A STANDARD OF OPEARTING PROCEDURE POST REPAIRS DIAGNOSTIC SCAN TEST A REQUIREMENT FOR HYBRID				380.00 120
			3150	

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD
 143 Cecil Street #01-01 GB Building
 069542

Attention : Motor Claim Department
 Contact : 338 7288 Fax No. : 880 4838

Estimate : ES000299

Date : 23/08/2018
 Vehicle Num. : SLL 192Z (LCR)
 Make/Model : HONDA VEZEL HYBRID
 Chassis/Eng# :
 Accident Date : 20/08/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

CARS UPON COMPLETION OF COLLISION REPAIRS.

Labour Total S\$:	5,420.00
--------------------	----------

LKK Auto Consultants hence notify the Repainer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repainer
 Signature:
 Date:

NAZ LKK
 23/8/18 1500

PIP

8 DAYS

BEFORE PAINT PHOTO

E. & O.E.

Total S\$: 14,706.40

for WORLD AUTO PTE LTD

PARTS \$5208
 LESS 20% \$4166.40
 \$NETT \$420
 LABOUR \$3150
 TOTAL \$7,736.40 / 8 DAYS

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD

143 Cecil Street #01-01 GB Building
 069542

Attention : Motor Claim Department
 Contact : 338 7288 Fax No. : 880 4838

Estimate : ES000299

Date : 23/08/2018
 Vehicle Num. : SLL 192Z (LCR)
 Make/Model : HONDA VEZEL HYBRID
 Chassis/Eng# :
 Accident Date : 20/08/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR BOOT LID		1,300.00 / DD
2.	1	REAR BOOT HYBRID EMBLEM (VEZEL)		89.00 / ACC
3.	1	REAR BOOT VEZEL EMBLEM (VEZEL)		89.00 / ACC
4.	2/RH,LH	REAR BOOT REFLECTOR LAMP	900.00	-1,800.00 ?
5.	1	REAR NUMBER PLATE LAMP GARNISH		290.00 ?
6.	1	REAR WINDSCREEN GLASS MOULDING		250.00 / ACC
7.	1	REAR BOOT HAND GRIP COVER		60.00 X SUC
8.	1	REAR BOOT LOCK ASSY		300.00 / not working
9.	1	REAR BOOT LOCK SWITCH		289.00 X SUC
10.	1	REAR BOOT INNER TRIM BOARD		280.00 X SUC
11.	1	REAR BOOT WEATHER STRIP		180.00 X SUC
12.	1	REAR BUMPER		900.00 X TOCAN
13.	2/RH,LH	REAR BUMPER REFLECTOR LENS	250.00	-500.00 / CRA
14.	1	REAR END PANEL		860.00 / GT
15.	1	REAR END PANEL TOP GARNISH		260.00 / CRA
16.	1	REAR FLOOR BOARD		350.00 X SUC
17.	1	REAR FLOOR PANEL		800.00 / DD
18.	1	REAR COMPARTMENT BOX		280.00 / CRA
19.	2/RH,LH	REAR TAIL LAMP	700.00	1,400.00 ?
20.	1	SMART BUZZER SENSOR		188.00 ?
21.	1	REAR ANTENNA SENSOR		190.00 X SUC
22.	2/RH,LH	REAR BUMPER RETAINER	89.00	178.00 ?
List Total S\$:				10,833.00
20.00% Discount S\$:				2,166.60
				8,666.40
SPECIAL NETT ITEMS :				
1.	1	REAR NUMBER PLATE LAMP GARNISH CLIP		40.00 ?

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD

143 Cecil Street #01-01 GB Building
 069542

Attention : Motor Claim Department
 Contact : 338 7288 Fax No. : 880 4838

Estimate : ES000299

Date : 23/08/2018
 Vehicle Num. : SLL 192Z (LCR)
 Make/Model : HONDA VEZEL HYBRID
 Chassis/Eng# :
 Accident Date : 20/08/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
2.	1	REAR WINDSCREEN SEALANT		100.00 / 100
3.	1	REAR BOOT INNER TRIM BOARD CLIP		40.00 x 10 = 400
4.	1	REAR BUMPER CLIP		40.00 ?
5.	1	REAR END PANEL TOP GARNISH CLIPS		40.00 / 100
6.	2/RH,LH	REAR TAILLAMP CLIPS	40.00	80.00 x SW
7.	1	REVERSE SENSOR		280.00 / 100
Special Nett Total S\$:				620.00
LABOUR :				
TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES				180.00 50
REMOVE & REFIT REAR WINDSCREEN GLASS				180.00 120
TO APPLY RUSTPROOFING/ TUFFCOATING TREATMENT TO REPLACED PARTS.				180.00 320 60
REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING CUT/WELD, PANEL BEAT, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS				2,200.00 1,400
PUTTY AND SPRAY PAINT ALL AFFECTED AREAS (INNER&OUTER)				1,800.00 1,100
TO CHECK WIRES, CONNECTORS, REPLACE DAMAGED LAMPS AND REVERSE SENSORS.				120.00 30
TO REMOVE AND INSTALL HIGH VOLTAGE HYBRID BATTERY AS A REQUIREMENTS FOR SAFETY PRECAUTIONS.				380.00 240
TO CONDUCT A STANDARD OF OPEARTING PROCEDURE POST REPAIRS DIAGNOSTIC SCAN TEST A REQUIREMENT FOR HYBRID				380.00 120

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD
 143 Cecil Street #01-01 GB Building
 069542

Attention : Motor Claim Department
 Contact : 338 7288 Fax No. : 880 4838

Estimate : ES000299

Date : 23/08/2018
 Vehicle Num. : SLL 192Z (LCR)
 Make/Model : HONDA VEZEL HYBRID
 Chassis/Eng# :
 Accident Date : 20/08/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

CARS UPON COMPLETION OF COLLISION REPAIRS.

Labour Total S\$: -----
5,420.00

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

NAZ LKK

23/8/18 1500

PIP

8 DAYS

BEFORE PAINT PHOTO

E. & O.E.

Total S\$: 14,706.40
=====

for WORLD AUTO PTE LTD

Poh Kin (LKKAuto)

From: geraldine@worldauto.com.sg
Sent: Thursday, 28 February 2019 1:50 PM
To: Poh Kin (LKKAuto)
Cc: tggtan@worldauto.com.sg; daniel@worldauto.com.sg; Asher Sng (LKKAuto); Admin A
Subject: RE: ACCIDENT CLAIMS - AXA INSURANCE (SLL 192Z)
Categories: clear

Dear Poh Kin,

Offer herein accepted with thanks!

Will forward executed DV & LOA to you in due course.

Regards,
Geraldine

From: Poh Kin (LKKAuto) <pohkin@lkkauto.com>
Sent: Thursday, 28 February, 2019 1:45 PM
To: geraldine@worldauto.com.sg
Cc: tggtan@worldauto.com.sg; daniel@worldauto.com.sg; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: ACCIDENT CLAIMS - AXA INSURANCE (SLL 192Z)
Importance: High

WITHOUT PREJUDICE
SAVE AS TO COSTS

Our Ref: CC4/ASM18015306/Nfa3
Your Ref: TP/2190/2018

Dear Geraldine,

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SLL 192Z AND SJR 89165 ON 20.08.2018

We refer to the above matter and your letter of demand dated 12/01/2019.

We hereby confirmed settlement as per your letter of demand:-

1. Cost of Repair (w/GST)	S\$ 8,277.95
2. Loss of Use (\$60.00 x 8 days)	S\$ 480.00
3. LTA search fee	S\$ 2.00
	S\$ 8,759.95

Please duly sign the DV attached and return with your Authorization to ACT to us (LKK) for payment processing.

Your prompt action will be very much appreciated.

Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Thursday, 28 February 2019 1:45 PM
To: geraldine@worldauto.com.sg
Cc: tgttan@worldauto.com.sg; daniel@worldauto.com.sg; Asher Sng (LKKAuto); Admin A
Subject: RE: ACCIDENT CLAIMS - AXA INSURANCE (SLL 192Z)
Attachments: DV SLL 192Z.pdf
Importance: High

WITHOUT PREJUDICE SAVE AS TO COSTS

Our Ref: CC4/ASM18015306/Nfa3
Your Ref: TP/2190/2018

Dear Geraldine,

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SLL 192Z AND SJR 8916S ON 20.08.2018

We refer to the above matter and your letter of demand dated 12/01/2019.

We hereby confirmed settlement as per your letter of demand:-

1. Cost of Repair (w/GST)	S\$ 8,277.95
2. Loss of Use (\$60.00 x 8 days)	S\$ 480.00
3. LTA search fee	S\$ 2.00
	S\$ 8,759.95

Please duly sign the DV attached and return with your Authorization to ACT to us (LKK) for payment processing.

Your prompt action will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

Poh Kin (LKKAuto)

From: Naz (LKKAuto)
Sent: Wednesday, 26 December 2018 4:26 PM
To: tgttan@worldauto.com.sg
Cc: Poh Kin (LKKAuto); CS A Team
Subject: Re: SLL 192Z FINALIZATION
Attachments: FINALIZATION.pdf

Categories: clear

Dear Ms Tan,

Apologies for the late reply. Attached herewith is the amended marked estimate following a check on the part prices. We will proceed to finalize if you are agreeable with the amended COR;

PARTS - \$5208
LESS 20% - \$4166.40
SPECIAL NET ITEMS - \$420
LABOUR - \$3150
TOTAL - \$7736 / 8 REPAIR DAYS

Thank you.

Best Regards,

Naz | Technical Investigator

LKK Auto Consultants

Phone: 6841-2157 | Email: Naz@lkkauto.com | Fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Poh Kin (LKKAuto)

From: Mei Kwan (LKKAuto)
Sent: Thursday, 28 February 2019 11:54 AM
To: Poh Kin (LKKAuto)
Cc: CS A Team
Subject: FW: New message for service request 64856, vehicle number SLL192Z

Categories: clear

Report Remarks Entry - CC4/ASM18015306/Nfa3

Remarks

28/2/19 9:47 AM *** Message Hi, please
proceed as per mandate. TY. - ANG Richard

Remarks

Add

New remarks Added

Remarks 1	By	On
<input type="checkbox"/> SLL 192Z ; SJR 8916S	HMK	23/8/20 3:11:40
<input type="checkbox"/> EST : \$ — SUR : NAZ — WKSP : WORLD AUTO PTE LTD	HMK	23/8/20 3:11:49
<input type="checkbox"/> S8M00SYJ // 64856 // RA	HMK	23/8/20 3:11:56

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Admin-D (LKKAuto)

Sent: Thursday, 28 February, 2019 9:52 AM

To: Admin A <admin-a@lkkauto.com>

Subject: FW: New message for service request 64856, vehicle number SLL192Z

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

<< <S8M00SYJ> Revise IA with mandate uploaded

Type

🔔 Question

Message

Liability: Insured driver collided into the rear of third party vehicle. Liability is down against our insured. Send letter to OI on 10th September 2018. Immediate Advice (with mandate) have been uploaded in SMART CLAIM. We hereby seek your approval to offer Third Party repairer M/s "World Auto Pte Ltd" is as follows: -
1)COR(w/gst) : \$8,277.95 + 2) Loss of Use (8days x \$60.00): \$480.00 + 3) GIA Search: \$2.00 =Total: \$8,759.95.
**8days recommendation for repair. **All the relevant documents had been uploaded in SMART CLAIM. For your approval please. PohKin - 27/02/2019

[Reply](#)

<< < S8M00SYJ > IA with mandate uploaded

Type

🔍 Question

Message

Liability: Insured driver collided into the rear of third party vehicle. Liability is down against our insured. Send letter to OI on 10th September 2018. Immediate Advice (with mandate) have been uploaded in SMART CLAIM. Propose settlement amount is between \$9,259.76 to \$12,602.99. All the relevant documents had been uploaded in SMART CLAIM. For your kind attention and instruction. Thank you- Pohkin 02/10/2018

[Reply](#)



Immediate Advice

To : AXA Insurance Pte Ltd

Date: 2/10/2018

Survey Details:

Date of loss	20-Aug-18
Date of appointment	23-Aug-18
Date of survey	23-Aug-18
Location of survey	WORLD AUTO PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SLL 1922
Make and Model	HONDA VEZEL HYBRID 1.5X - 1496cc
Date of registration	10-Feb-17
Excess	
Market Value	\$ 85,000.00
Parf Rebate	\$ 50,072.00
Nett Loss	\$ 34,928.00

Repair details:

Initial Estimate	\$ 14,706.40
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 4,562.40
Check items (estimate)	\$ 3,124.80
Labour	\$ 3,150.00
Total	\$ 10,837.20
Lump Sum(if applicable)	\$ -

Number of days for repair	8 days
---------------------------	---------------



Remarks:

****Item by item

Mandate:

Liability(TP)	100%	100%
	with check item	no check item
Proposed repair cost(w/gst)	\$11,595.50 (\$10,837.20+7% GST)	\$8,252.27 (\$7,712.40+7% GST)
Loss of use	\$ -	\$ -
Loss of rental (estimate)	\$ 1,000.00	\$ 1,000.00
Loss of income	\$ -	\$ -
LTA search fees	\$ 7.49	\$ 7.49
Others	\$ -	\$ -
Proposed Total	\$ 12,602.99	\$ 9,259.76



WORLD AUTO PTE LTD

47 JALAN PEMIMPIN #01-02/03

HALCYON 2

SINGAPORE 577200

12/01/2019

Your Ref :

Our Ref : TP/2190/2018

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY #24-01 AXA TOWER
SINGAPORE 06811

Attn : Motor Claim Dept – Third Party

Dear Sirs,

ACCIDENT INVOLVING VEH.NO. SLL192Z / SJR8916S ON 20/08/2018

Reference is made to the aforesaid matter (on behalf of our client M/S LCRF PL)

Enclosed herewith are the following documents for your information and necessary actions only :-

- a) Our Final Repair Bill

Please assist in our claims of :

Final Bill	\$ 7736.40	(already finalised)
GST 7%	\$ 541.55	
Search Fee	\$ 2.00	
Loss of Use (\$60x 8 days)	\$ 480.00	

Amount \$ 8759.95

Kindly let us have your reply and payment as soon as possible.

Thank you for your kind attention and much appreciated assistance.

Yours faithfully,



10th September 2018

MS CARZ LEASING PTE LTD

255 Lavender Street
Singapore 338791.

Dear Sir,

OUR REF : CC4/ASM18015306/Nfb3

YOUR REF : SJR 8916S

**ROAD TRAFFIC ACCIDENT INVOLVING SJR 8916S AND SLL 192Z ALONG
VICTORIA STREET TOWARDS LAVENDER STREET ON 20.08.2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party Property Damage claim against your policy.

We have received a claim from M/s World Auto Pte Ltd, acting on behalf of the owner of SLL 192Z against your motor insurance policy.

Based on the accident report, accident scenario, it was reported that your vehicle had collided into rear of Third Party vehicle SLL 192Z. As such, liability is down against us.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to pohkin@lkkauto.com within 7 days from the date of this letter **if not provided at AXA's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6841 2132 or email us at pohkin@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Poh Kin, Chong
Case Handler
DID: 6841 2132
FAX: 6741 4108
Email: pohkin@lkkauto.com

c.c. *AXA Insurance Pte Ltd (AXA)*
(Motor Claims Dept)

LETTER OF AUTHORISATION

In the matter of the following accident:-

DATE OF ACCIDENT : 20-08-2018

CLIENT'S VEHICLE NO : SLL192Z

PLACE OF ACCIDENT : JUNC OF KALLANG RD TWDS CRAWFORD ST

THIRD PARTY VEHICLE NO : SJR8916S

I/We, LCRF PTE LTD

ADDRESS: 29 PAYA LEBAR ROAD, PAYA LEBAR OFFICE CENTRE

UEN/NRIC/FIN NO : 201624597K

Tel. (O) _____ (H) _____ (MOBILE) _____

I/We hereby authorize and appoint World Auto Pte Ltd to act for me/us in respect of the above matter up to the final conclusion of the said matter.

I/We hereby authorize and appoint World Auto Pte Ltd to act for me/us for the purpose of negotiating and enter into settlement with the tortfeasor, their insurers or solicitors appointed by the tortfeasor/insurers without the need to commence action.

I/We hereby authorize World Auto Pte Ltd to receive on my/our behalf all settlement sums and disbursements including loss of use/rental to pay to yourselves all costs you may at any time receive in connection with the above mention matter.

DATED THIS 21TH DAY OF August YEAR 2018



A handwritten signature in black ink, consisting of several loops and a long horizontal stroke extending to the right.

Name: LCRF PTE LTD
UEN No: 201624597K



redefining / insurance



CLAIM REF : S8M00SYJ ✓
INSURED : MS CARZ LEASING PTE LTD ✓

DISCHARGE VOUCHER

We/I LCRF PTE LTD, Co Reg No. 201624597/K hereby agree to accept the sum of dollars [Eight Thousand Seven Hundred Fifty-Nine and Cents Ninety-Five only] (S\$ 8,759.95) paid to us/me by **AXA INSURANCE PTE LTD** as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said **AXA INSURANCE PTE LTD** or their Insured or the driver of motor vehicle no. SJR 8916S as a result of an accident along Lavender Street on 20th August 2018 of which we/I were/was the driver/ owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. SLL 192Z.

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. SJR 8916S in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify **AXA INSURANCE PTE LTD** against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. SJR 8916S.

Dated this 5th day of March 2019

Claimant's Signature : _____
NRIC no./ Company Stamp : _____
Occupation/ Business : _____
Address : _____
Telephone No. : _____
Witness's Name : Kevinine Foong
Witness's Signature : _____
Witness's NRIC No. : S7002184F



WORLD AUTO PTE LTD
 47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG
 S'PORE 577200
 Tel No. : 64513933 Fax No. : 64557576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD
 8 SHENTON WAY #24-01 AXA TOWER
 S'PORE 068811

Attention : Motor Claim Department
 Contact : 68804888 Fax No. : 68804838

Tax Invoice : F189099

Date : 11/01/2019
 Vehicle Num. : SLL 192Z
 Make/Model : HONDA VEZEL HYBRID
 Chassis/Eng# :
 Accident Date : 20/08/2018
 Claim No. : TP/2190/2018
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		LIST ITEMS :		
1.	1	BOOTLID		1,200.00
2.	1	BOOTLID 'HYBRID' EMBLEM		89.00
3.	1	BOOTLID 'VEZEL' EMBLEM		89.00
4.	1	REAR WINDSCREEN GLASS MOULDING		250.00
5.	1	REAR BOOT LOCK		300.00
6.	1	REAR BOOT WEATHERSTRIP		180.00
7.	1	REAR BUMPER		900.00
8.	1	REAR END PANEL		860.00
9.	1	REAR END PANEL TOP GARNISH		260.00
10.	1	REAR FLOOR PANEL		800.00
11.	1	REAR COMPARTMENT BOX		280.00
		List Total S\$:		5,208.00
		20.00% Discount S\$:		1,041.60
				4,166.40
		SPECIAL NETT ITEMS :		
1.	1	REAR WINDSCREEN SEALANT		100.00
2.	1SET	REAR END PANEL TOP GARNISH CLIPS		40.00
3.	1	REVERSE SENSOR		280.00
		Special Nett Total S\$:		420.00
		LABOUR :		
		TRANSFER REAR BOOTLID MECHANISM & ACCESSORIES		80.00
		REMOVE & REPLACE REAR WINDSCREEN GLASS		120.00
		APPLY RUSTPROOFING/TUFFCOATING TREATMENT TO REPLACED PARTS		60.00
		REMOVE & REPLACE ACCIDENT DAMAGED PARTS FOR REPAIRS INCLUDING CUT/WELD, PANEL BEAT, STRAIGHTEN CHASSIS		1,400.00
		PUTTY & SPRAY PAINT ON ALL AFFECTED AREAS		1,100.00

CONTINUE / ...

WORLD AUTO PTE LTD
 47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG
 S'PORE 577200
 Tel No. : 64513933 Fax No. : 64557576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD
 8 SHENTON WAY #24-01 AXA TOWER
 S'PORE 068811

Attention : Motor Claim Department
 Contact : 68804888 Fax No. : 68804838

Tax Invoice : F189099

Date : 11/01/2019
 Vehicle Num. : SLL 192Z
 Make/Model : HONDA VEZEL HYBRID
 Chassis/Eng# :
 Accident Date : 20/08/2018
 Claim No. : TP/2190/2018
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		CHECK WIRINGS & CONNECTORS, REPLACE DAMAGED LAMPS & REVERSE SENSORS		30.00
		REMOVE & INSTALL HV HYBRID BATTERY FOR SAFETY PRECAUTIONS		240.00
		CONDUCT SOP POST REPAIRS DIAGNOSTIC SCAN TEST FOR HYBRID CARS UPON COMPLETION OF COLLISION REPAIRS		120.00
		Labour Total S\$:		3,150.00

Total S\$: 7,736.40
 GST 7% S\$: 541.55
 Amount Due S\$: 8,277.95


 WORLD AUTO PTE LTD



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

 6 Raffles Quay #18-00, Singapore 048580
 Phone: +65 6224 0010 Fax: +65 6224 0030
 Operating Hours: Monday to Friday 9am to 5pm
 GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-128613

Date of Request: 21/08/2018

Your Ref No:

Online Purchase

 World Auto Pte Ltd
 47 Jln Pemimpin
 #01-02/03 Halcyon 2
 Singapore 577200

Dear Sir/Madam,

 Enquiry Date 21/08/2018
 Enquiry By Kalah Varatharajoo
 Vehicle No. SJR8916S
 Accident Date 20/08/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SJR8916S	AXA Insurance Pte Ltd	17/07/2018-16/07/2019	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.


**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
 Phone: +65 6224 0010 Fax: +65 6224 0030
 Operating Hours: Monday to Friday 9am to 5pm
 GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-128613

Date of Request: 21/08/2018

Your Ref No:

Online Purchase

World Auto Pte Ltd
 47 Jln Pemimpin
 #01-02/03 Halcyon 2
 Singapore 577200

Dear Sir/Madam,

Enquiry Date 21/08/2018
 Enquiry By Kalah Varatharajoo
 Vehicle No. SJR8916S
 Accident Date 20/08/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

GIRO Cash Cheque



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18015306/Nfa3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:RICHARD ANG

Date : 12-03-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJR 8916S	Veh. Inspected	SLL 192Z
Policy No.	VFX/P1857572	Coverage (\$)	0.00
Claim No.	S8M00SYJ	Excess (\$)	0.00
Assign From		Assign Date	23/08/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL HYBRID	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	RU31223570	Colour	SILVER
Odometer	91289	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	GITI	5 mm
L/H Front Tyre	215/60 R16	GITI	5 mm
R/H Rear Tyre	215/60 R16	DUNLOP	5 mm
L/H Rear Tyre	215/60 R16	DUNLOP	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION,
DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/08/2018	Inspection Date	23/08/2018
Survey held at	WORLD AUTO PTE LTD 47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG SINGAPORE 577200		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 192Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT LID (CONSISTENT)	DENTED	1,300.00	1,200.00
1	REAR BOOT HYBRID EMBLEM (VEZEL) (CONSISTENT)	NECESSARY	89.00	89.00
1	REAR BOOT VEZEL EMBLEM (VEZEL) (CONSISTENT)	NECESSARY	89.00	89.00
2	RH,LH REAR BOOT REFLECTOR LAMP @\$900.00 (CONSISTENT)	SERVICEABLE	1,800.00	-
1	REAR NUMBER PLATE LAMP GARNISH (CONSISTENT)	SERVICEABLE	290.00	-
1	REAR WINDSCREEN GLASS MOULDING (CONSISTENT)	NECESSARY	250.00	250.00
1	REAR BOOT HAND GRIP COVER (CONSISTENT)	SERVICEABLE	60.00	-
1	REAR BOOT LOCK ASSY (CONSISTENT)	NOT WORKING	300.00	300.00
1	REAR BOOT LOCK SWITCH (CONSISTENT)	SERVICEABLE	289.00	-
1	REAR BOOT INNER TRIM BOARD (CONSISTENT)	SERVICEABLE	280.00	-
1	REAR BOOT WEATHERSTRIP (CONSISTENT)	TORN	180.00	180.00
1	REAR BUMPER (CONSISTENT)	CRACKED	900.00	900.00
2	RH,LH REAR BUMPER REFLECTOR LENS @\$250.00 (CONSISTENT)	SERVICEABLE	500.00	-
1	REAR END PANEL (CONSISTENT)	BENT	860.00	860.00
1	REAR END PANEL TOP GARNISH (CONSISTENT)	CRACKED	260.00	260.00
1	REAR FLOOR BOARD (CONSISTENT)	SERVICEABLE	350.00	-
1	REAR FLOOR PANEL (CONSISTENT)	DENTED	800.00	800.00
1	REAR COMPARTMENT BOX (CONSISTENT)	CRACKED	280.00	280.00
2	RH,LH REAR TAIL LAMP @\$700.00 (CONSISTENT)	SERVICEABLE	1,400.00	-
1	SMART BUZZER SENSOR (CONSISTENT)	SERVICEABLE	188.00	-
2	RH,LH REAR BUMPER RETAINER @\$89.00 (CONSISTENT)	SERVICEABLE	178.00	-
1	REAR ANTENNA SENSOR (CONSISTENT)	SERVICEABLE	190.00	-
	LESS 20% DISCOUNT		-2,166.60	-1,041.60
			8,666.40	4,166.40
SPECIAL NETT ITEMS				
1	REAR NUMBER PLATE LAMP GARNISH CLIP (SN) (CONSISTENT)	NOT NECESSARY	40.00	-
1	REAR WINDSCREEN SEALANT (SN) (CONSISTENT)	NECESSARY	100.00	100.00

Report Ref No. CC4/ASM18015306/Nfa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BOOT INNER TRIM BOARD CLIP (SN) (CONSISTENT)	NOT NECESSARY	40.00	-
1	REAR BUMPER CLIP (SN) (CONSISTENT)	NOT NECESSARY	40.00	-
1	REAR END PANEL TOP GARNISH CLIPS (SN) (CONSISTENT)	NECESSARY	40.00	40.00
2	RH,LH REAR TAILLAMP CLIPS @\$40.00 (SN) (CONSISTENT)	SERVICEABLE	80.00	-
1	REVERSE SENSOR (SN) (CONSISTENT)	NECESSARY	280.00	280.00
			620.00	420.00
	LABOUR			
	TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES.		180.00	80.00
	REMOVE & REFIT REAR WINDSCREEN GLASS.		180.00	120.00
	TO APPLY RUSTPROOFING /TUFFCOATING TREATMENT TO REPLACED PARTS.		180.00	60.00
	REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING CUT/WELD ,PANEL BEAT ,STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS.		2,200.00	1,400.00
	PUTTY AND SPRAY PAINT ALL AFFECTED AREAS (INNER & OUTER).		1,800.00	1,100.00
	TO CHECK WIRES, CONNECTORS ,REPLACE DAMAGED LAMPS AND REVERSE SENSORS.		120.00	30.00
	TO REMOVE AND INSTALL HIGH VOLTAGE HYBRID BATTERY AS A REQUIREMENTS FOR SAFETY PRECAUTIONS.		380.00	240.00
	TO CONDUCT A STANDARD OF OPEARTING PROCEDURE POST REPAIRS DIAGNOSTIC SCAN TEST A REQUIREMENT FOR HYBRID CARS UPON COMPLETION OF COLLISION REPAIRS.		380.00	120.00
			5,420.00	3,150.00
GRAND TOTAL			14,706.40	7,736.40
RECOMMENDED COST OF REPAIRS				7,736.40

Report Ref No. CC4/ASM18015306/Nfa3q2

MUHAMMAD NAZRIL BIN ABDULLAH
Automotive Assessor

HO LEONG CHUAN
Automotive Assessor

DISCLAIMER OF LIABILITY TO THRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.

