

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/GAI18015333/Gz4d3e2 GREAT AMERICAN INSURANCE COMPANY Ref: 3 TEMASEK AVENUE #16-01 CENTENNIAL Date: 29-08-2018 **TOWER SINGAPORE 039190** Code: GAI 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **SGW 797E** Veh. Inspected **SLA 8788K** Policy No. Coverage (\$) 0.00 CLMOMVP00000823 Excess (\$) 0.00 Claim No. **Assign From** KELVYNA NGIAN 23/08/2018 **Assign Date** 2. **Vehicle Particulars & Condition** Make & Model HONDA VEZEL 1496 c.c **Engine No. HIDDEN** Year of Reg. 2016 Chassis No. RU11112914 Colour **BLACK** 48579 KM Odometer **IN ORDER** Steering Brakes **IN ORDER Modification** SPORTS RIM GOOD General 3. **Conditions of Tyres** Size Make **Balance** DUNLOP 6 mm R/H Front Tyre 215/60 R16 **DUNLOP** L/H Front Tyre 215/60 R16 6 mm R/H Rear Tyre 215/60 R16 **DUNLOP** 6 mm 215/60 R16 DUNLOP 6 mm L/H Rear Tyre 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. **General Information** 5. 16/08/2018 23/08/2018 (01:00 PM) **Accident Date** Inspect Date / Time Survey held at YAP LEE MOTOR BLK 1 KAKI BUKIT AVE 6 #01-26 AUTOBAY@KAKI BUKIT SINGAPORE 417883 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days

Report Ref No. CS3/GAI18015333/Gz4d3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A
Automotive Assessor

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.