

Shiau Chan (LKKAUTO)

From: Carrine Leong <carrine.leong@premiumauto.com.sg>
Sent: Wednesday, 24 April 2019 5:21 PM
To: Shiau Chan (LKKAUTO); Adrian Ling (LKKAUTO); SUR; Denise Tay (LKKAUTO)
Cc: jayee.yap@premiumauto.com.sg; 'Chang Chee Sing'
Subject: RE: FINAL REVISION - SLM8682T - OD AIG - SURVEYED 23 AUG 18 - BY TAUFIK

Dear Shiau Chan,

Confirm.

Thanks & Best Regard
Carrine Leong
Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183
e. carrine.leong@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Shiau Chan (LKKAUTO) [mailto:siewsc@lkkauto.com]
Sent: Tuesday, 23 April, 2019 2:51 PM
To: Carrine Leong <carrine.leong@premiumauto.com.sg>; Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; SUR <sur@lkkauto.com>; Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Cc: jayee.yap@premiumauto.com.sg; 'Chang Chee Sing' <claims@premiumauto.com.sg>
Subject: RE: FINAL REVISION - SLM8682T - OD AIG - SURVEYED 23 AUG 18 - BY TAUFIK

Dear Carrine,

WITHOUT PREJUDICE

Offer final fig \$12,105.80 before excess \$0/- & GST and 11 repair days.

Kindly confirm.

Best Regards,
Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	20 Aug 2018 14:33	Cim Veh Model Changed		[I] Merimen Administrator
2	20 Aug 2018 14:33	Cim Created	Reg No: SLM8682T, Policy No: 2100503943, Acct Date: 2018/08/20, Claim Type: S C, Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG), Ins.Status => Notification, Created from SAS:MPA118107489	[I] Merimen Administrator
3	24 Aug 2018 11:09	Cim Registration Modified	Setl.Type:3->0, Claim Type:SC->OD.	[I] Nivitha Govindasamy
4	24 Aug 2018 11:09	Adj Cim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[I] Nivitha Govindasamy
5	24 Aug 2018 11:09	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Nivitha Govindasamy
6	24 Aug 2018 11:09	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/09/04	[A] Nivitha Govindasamy
7	24 Aug 2018 11:09	Adj Mandate Set	Approved:8000.00,Reinsp:Adj decides.	[A] Nivitha Govindasamy
8	24 Aug 2018 11:09	Cim Registration Modified	Rep:1137->200611.	[A] Nivitha Govindasamy
9	24 Aug 2018 11:09	Cim Veh Model Changed	(204293) AUDI A1 SPORTBACK 1.0 TFSI S-tronic (A).	[A] Nivitha Govindasamy
10	24 Aug 2018 11:09	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID	[A] Nivitha Govindasamy
11	24 Aug 2018 16:00	Adj Rpt Initiated		[A] SHIAU CHAN
12	24 Aug 2018 16:00	Insured Phone No Updated	[None] -> [+6587771947]	[A] SHIAU CHAN
13	24 Aug 2018 16:00	Cim Dtl Modified	JPJ Reg. Date: -> 2017/03/17.	[A] SHIAU CHAN
14	24 Aug 2018 16:00	Cim Details Notified		[A] SHIAU CHAN
15	24 Aug 2018 16:01	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/09/04	[A] SHIAU CHAN
16	24 Aug 2018 16:02	Adj Mandate Request	Cur.Req:13034.00:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
17	27 Aug 2018 15:14	Cim Registration Modified	Init.Est.->5,000 - 6,000. Excess: -> 0.00, 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Loo, Tong Shing
18	27 Aug 2018 15:14	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
19	28 Aug 2018 11:46	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/09/04. Mandate Remarks: Kindly advise why the labour at \$2,600.00? Re-inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-CK
20	28 Aug 2018 11:46	Adj Mandate Set	Approved:10563.00:Kindly advise why the labour at \$2,600.00? Re-inspection to be done for damage check and supplementary items / labour.Reinsp:Yes.	[I] Koh, Victor-CK
21	06 Sep 2018 16:48	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/09/04	[A] SHIAU CHAN
22	06 Sep 2018 16:49	Adj Mandate Request	Cur.Req:14297.00:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL. KINDLY AP PROVE ON SUPPLEMENTARY.	[A] SHIAU CHAN
23	07 Sep 2018 13:32	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2018/09/04. Mandate Remarks: Kindly breakdown why the labour at \$2,100.00, Re-inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-CK
24	07 Sep 2018 13:32	Adj Mandate Set	Approved:11826.00:Kindly breakdown why the labour at \$2,100.00. Re-inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-CK
25	26 Oct 2018 15:16	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/09/04	[A] SHIAU CHAN
26	26 Oct 2018 15:17	Adj Mandate Request	Cur.Req:12755.80:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL. KINDLY AP PROVE REPAIR COST OF \$12,755.80.	[A] SHIAU CHAN
27	31 Jan 2019 09:37	Adj Mandate Set	Approved:12755.80.Reinsp:Adj decides.	[I] Koh, Victor-CK

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1896736	24/08/2018 16:00	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLM8682T		10.70

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Tuesday, 4 December 2018 12:00 PM
To: TongShing.Loo@aig.com
Cc: SUR
Subject: Re: Alert - Adj Mandate Approved (\$\$11826.00) - SLM8682T - Claim Handler: Loo, Tong Shing

This mail is associated with :
***SLM8682T (9550393961SG)**
OD
Aug 20 2018 8:30AM
[MR LIEW WEI LIANG]
Premium Automobiles Pte Ltd

Hi Shiau Chan,

Labour at \$500.00 per day why is there \$550.00?
Bonnet not damage, front door only spray painting why is there labour for it?
Bumper, fender, healamp only 2 days. Labour at \$1,000.00.
Labour \$2100.00 not justify.
Submit survey report in merimen

Regards
Victor Koh

<-- Original Message -->

From: LKK_HQ
To: AIG_SG; Victor_KohCK; TongShing.Loo@aig.com
CC: sur@lkkauto.com
Sent On: 12/10/2018 01:33 PM
Subject: Re: Alert - Adj Mandate Approved (\$\$11826.00) - SLM8682T - Claim Handler: Loo, Tong Shing

Dear Sir,

According to our surveyor, the breakdown of the labour \$2,100.00 are as below:

To replace front bumper \$550.00,
front RH fender & RH headlamp \$550.00,
front bonnet \$500.00 & front RH door \$500.00

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561

<-- Original Message -->

From: AIG_SG
To: LKK_HQ
Sent On: 07/09/2018 01:32 PM
Subject: Alert - Adj Mandate Approved (\$\$11826.00) - SLM8682T - Claim Handler: Loo, Tong Shing

98197818

1 Bumper 1 day

1 Fender 1 day

1 Headlamp 1/2 day

2500 x 2500

= 1250

remove & install mirror 300

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Loo, Tong Shing

Date: 26 Oct 2018

Preliminary Advice

Vehicle No	: SLM8682T	Accident Date	: 20/08/2018
Make	: AUDI A1 SPORTBACK	Policy No.	: 2100503943
Assignment Date	: 24/08/2018	Excess	: S\$0.00
Date of Inspection	: 23/08/2018	Est. Duration of Repair	: 11.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,622.00	
Revised Amount	:S\$	12,755.80	(INCLUSIVE OF CHECK ITEMS)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	12,755.80	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	85,000.00
COE / PARF Rebate	:S\$	48,518.00
Salvage Value	:S\$	
Margin for Repair	:S\$	36,482.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON REPAIR COST OF \$12,755.80.

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	20 Aug 2018 14:33	Clim Veh Model Changed		[I] Merimen Administrator
2	20 Aug 2018 14:33	Clim Created	Reg No: SLM8682T, Policy No: 2100503943, Acct Date: 2018/08/20, Claim Type: S C. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG), Ins.Status => Notification. Created from SAS:MPA118107489	[I] Merimen Administrator
3	24 Aug 2018 11:09	Clim Registration Modified	Setl.Type:3->0, Claim Type:SC->OD.	[I] Nivitha Govindasamy
4	24 Aug 2018 11:09	Adj Clim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[I] Nivitha Govindasamy
5	24 Aug 2018 11:09	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Nivitha Govindasamy
6	24 Aug 2018 11:09	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/09/04	[A] Nivitha Govindasamy
7	24 Aug 2018 11:09	Adj Mandate Set	Approved:8000.00,Reinsp:Adj decides.	[A] Nivitha Govindasamy
8	24 Aug 2018 11:09	Clim Registration Modified	Rep:1137->200611.	[A] Nivitha Govindasamy
9	24 Aug 2018 11:09	Clim Veh Model Changed	(204293) AUDI A1 SPORTBACK 1.0 TFSI S-tronic (A).	[A] Nivitha Govindasamy
10	24 Aug 2018 11:09	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID	[A] Nivitha Govindasamy
11	24 Aug 2018 16:00	Adj Rpt Initiated		[A] SHIAU CHAN
12	24 Aug 2018 16:00	Insured Phone No Updated	[None] -> [+6587771947]	[A] SHIAU CHAN
13	24 Aug 2018 16:00	Clim Dtl Modified	JPJ Reg. Date: -> 2017/03/17.	[A] SHIAU CHAN
14	24 Aug 2018 16:00	Clim Details Notified		[A] SHIAU CHAN
15	24 Aug 2018 16:01	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/09/04	[A] SHIAU CHAN
16	24 Aug 2018 16:02	Adj Mandate Request	Cur.Req:13034.00:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
17	27 Aug 2018 15:14	Clim Registration Modified	Init.Est.->5,000 - 6,000. Excess: -> 0.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Loo, Tong Shing
18	27 Aug 2018 15:14	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
19	28 Aug 2018 11:46	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/09/04, Mandate Remarks: Kindly advise why the labour at \$2,600.00? Re-inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-CK
20	28 Aug 2018 11:46	Adj Mandate Set	Approved:10563.00:Kindly advise why the labour at \$2,600.00? Re-inspection to be done for damage check and supplementary items / labour.Reinsp:Yes.	[I] Koh, Victor-CK
21	06 Sep 2018 16:48	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/09/04	[A] SHIAU CHAN
22	06 Sep 2018 16:49	Adj Mandate Request	Cur.Req:14297.00:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL. KINDLY APPROVE ON SUPPLEMENTARY.	[A] SHIAU CHAN
23	07 Sep 2018 13:32	Adj Next Rpt Changed	Cur Rpt:Final Rpt, Cur Due Date:2018/09/04, Mandate Remarks: Kindly breakdown why the labour at \$2,100.00, Re-inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-CK
24	07 Sep 2018 13:32	Adj Mandate Set	Approved:11826.00:Kindly breakdown why the labour at \$2,100.00. Re-inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-CK

Date From



Date To



Audit Type

None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1896736	24/08/2018 16:00	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLM8682T		10.70

To replace front bumper, front RH headlamp and front RH fender. To repair front bonnet and front RH door.

To replace front bumper - \$550

To replace front RH fender & RH headlamp - \$550

To repair front bonnet & front RH door - \$500 each

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Loo, Tong Shing

Date: 06 Sep 2018

Preliminary Advice

Vehicle No	: SLM8682T	Accident Date	: 20/08/2018
Make	: AUDI A1 SPORTBACK	Policy No.	: 2100503943
Assignment Date	: 24/08/2018	Excess	: S\$0.00
Date of Inspection	: 23/08/2018	Est. Duration of Repair	: 7.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,622.00	(ESTIMATE \$14,359.00 + SUPPLEMENTARY \$1,263.00)
Revised Amount	:S\$	11,826.00	(INCLUSIVE OF SUPPLEMENTARY)
Check Items (Estimated)	:S\$	2,471.00	
Total	:S\$	14,297.00	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	85,000.00
COE / PARF Rebate	:S\$	48,518.00
Salvage Value	:S\$	
Margin for Repair	:S\$	36,482.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 28 August 2018 3:13 PM
To: 'Claims'; SUR
Subject: RE: OD claim for SLM 8682 T on 20/08/2018

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLM 8682T (Excess \$0.00/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>
Sent: Monday, 20 August 2018 2:42 PM
To: SUR <sur@lkkauto.com>
Cc: 'Claims' <claims@premiumauto.com.sg>
Subject: RE: OD claim for SLM 8682 T on 20/08/2018

Good afternoon all ,

Here is the attachment of GIA report for your kind reference .

We will forward to you the estimate once available .

Thank you .

Best Regards,
Phua
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 109902273W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Thursday, 6 September 2018 5:00 PM
To: do-not-reply@merimen.com
Cc: SUR
Subject: Re: Alert - Adj Mandate Approved (S\$10563.00) - SLM8682T - Claim Handler: Loo, Tong Shing

This mail is associated with :
***SLM8682T (9550393961SG)**
OD
Aug 20 2018 8:30AM
[MR LIEW WEI LIANG]
Premium Automobiles Pte Ltd

Dear Victor,

The labour should be \$2,100.00 instead of \$2,600.00.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561

<-- Original Message -->

From: AIG_SG
To: LKK_HQ
Sent On: 28/08/2018 11:46 AM
Subject: Alert - Adj Mandate Approved (S\$10563.00) - SLM8682T - Claim Handler: Loo, Tong Shing

Approved:10563.00:Kindly advise why the labour at \$2,600.00? Re-inspection to be done for damage check and supplementary items / labour.

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)

View Received Message

This mail is associated with :

***SLM8682T (95503939615G)**

OD

Aug 20 2018 8:30AM

[MR LIEW WEI LIANG]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 28/08/2018 11:46 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$10563.00) - SLM8682T - Claim Handler: Loo, Tong Shing

Approved:10563.00:Kindly advise why the labour at \$2,600.00? Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 24 Aug 2018

Preliminary Advice

Vehicle No	: SLM8682T	Accident Date	: 20/08/2018
Make	: AUDI A1 SPORTBACK	Policy No.	: 2100503943
Assignment Date	: 24/08/2018	Excess	: S\$0.00
Date of Inspection	: 23/08/2018	Est. Duration of Repair	: 7.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,359.00
Revised Amount	:S\$	10,563.00
Check Items (Estimated)	:S\$	2,471.00
Total	:S\$	13,034.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	85,000.00
COE / PARF Rebate	:S\$	48,518.00
Salvage Value	:S\$	
Margin for Repair	:S\$	36,482.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7175A
Vehicle Details	
Vehicle No.:	SLM8682T
Vehicle to be Exported:	No
Intended De-registration Date:	24 Aug 2018
Vehicle Make:	AUDI
Vehicle Model:	A1 SB 1.0 TFSI (PI)
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	CHZ150154
Chassis No.:	WAUZZZ8X8HB032436
Maximum Power Output:	70.0 kW (93 bhp)
Open Market Value:	\$21,256.00
Original Registration Date:	17 Mar 2017
First Registration Date:	17 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$6,759.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Mar 2027
PARF Rebate Amount:	\$5,069.00
Intended COE Rebate Details	
COE Expiry Date:	16 Mar 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,789.00
COE Rebate Amount:	\$43,449.00
Total Rebate Amount:	\$48,518.00

The information contained herein is correct as at 24 Aug 2018

OK

Post FREE Ad to Sell Your Used Items!

Have preloved items cluttering around your house?
Sell it on Marketplace. Posting an advertisement is FREE!

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

Toyota Estima Hybrid 2.4A (New 10 Years Old)



Accident Free, Good Condition, Well Maintained, West & Teer Registered, Fuel Efficiency, Direct Owner, Standard



Browse by Category

Sort by Date Posted 20 results/page

4 vehicles

AUDI A1

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	AUDI A1	Any	Any	2017	Any	Any	Any	Available
	Audi A1 Sportback 1.0A TFSI S-tronic	\$88,888	\$9,270 /yr	10-Oct-2017	999 cc	6,000 km	Hatchback	Available
With Only \$9,480 Down Payment, Monthly Of Only \$1,370, Drive This Perfect City Car With No Hassle At All! Diligently Serviced With Agent, Warranty Till 2019. Free Servicing With Agent. Always Parked U...								
Audax Auto Pte Ltd								
Posted: 24-Aug-2018 Tags: 2017 Audi A1, Audi A1, Audi, A1, Used Audi								
	Audi A1 Sportback 1.0A TFSI S-tronic	\$85,800	\$9,260 /yr	15-Jun-2017	999 cc	19,000 km	Hatchback	Available
Free 3 Time Servicing! Unit Still Under Agent Warranty! Low Mileage, Powerful/Responsive Turbocharged Engine. Fuel Economy Of 22km/L. Cheapest Unit In The Market. Please Whatsapp/Call Or Message Us For...								
Posted: 21-Aug-2018 Tags: 2017 Audi A1, Audi A1, Audi, A1, Used Audi								
	Audi A1 Sportback 1.0A TFSI S-tronic	\$85,000	\$9,630 /yr	14-Feb-2017	999 cc	16,900 km	Hatchback	Available
5 Years Of Warranty From Premium Auto (Audi Centre Singapore) Until Feb 2022, And 3 Years / 45,000km Of Free Servicing. All Servicing And Checks Duly Done With Premium Auto And All Records Are Availab...								
Carro								
Posted: 29-Jul-2018 Tags: 2017 Audi A1, Audi A1, Audi, A1, Used Audi								
	Audi A1 Sportback 1.0A TFSI S-tronic	\$90,666	\$9,310 /yr	21-Nov-2017	999 cc	2,902 km	Hatchback	Available
Mileage Only 2,900km, 1 Owner, Just Like Brand New But So Much Cheaper. In House Loan Avail. Drive This Perfect City Car With No Hassle At All! Diligently Serviced With Agent, Warranty Till 2019. Free...								
Creative Auto								
Posted: 13-Jul-2018 Tags: 2017 Audi A1, Audi A1, Audi, A1, Used Audi								

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

Home New Cars Used Cars Sell My Car Directory Products Insurance Article Forum Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, lock up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used AUDI A1, AUDI A1 Singapore, used AUDI A1, used vehicles Singapore or even buy used AUDI A1 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

Compare

Logout Us Careers Contact Us Sitemap Terms of Service Privacy Policy Personal Data Protection Statement

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/08/2018 13:41
Date Of Accident	20/08/2018 08:30
Exact Location Of Accident	DEPOT ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLM8682T
Insured/Policyholder	
Name Of Registered Owner	MR LIEW WEI LIANG
NRIC No	S8737175A
Email Address	WEILIANG.LIEW@GMAIL.COM
Mobile Phone No	(LOCAL) +65-87771947
Alternative Phone No	OTHERS-87771947

Vehicle Particulars

Manufacturer	AUDI
Model	A1 1.0 SB TFSI S TRO
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100503943
Cover Note Number	

Driver

Name of Driver	SONYA CHAN CHUI SHAN
NRIC No	S8990204E
Date Of Birth	05/06/1989
Occupation	INDOOR
Date Of Driving Pass	18/05/2015
Driving Experience	3 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91386228
Fax Number	
Contact Number	
Email Address	SONYACHANCS@GMAIL.COM

Address	BLK 286A COMPASSVALVE CRESCENT #05-73
Postcode	541286
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	YES
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : LIEW WEI LIANG GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

GOING STRAIGHT DOWN DEPOT ROAD. TAXI DRIVER TURNED OUT OF HIS LANE TO CUT INTO MY LANE AND RESULTED IN A CRASH.


Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA2285G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

SKETCH PLAN



A = SLM8682T

B = SHA 2285G

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


Going straight down Depot Road. taxi driver turned out of his lane to cut into my lane and resulted in a crash

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature

Date & Time: 20/8/18


Driver's Signature

(If driver is not the policyholder)

Date & Time: 20/08/18



Reporting Centre Personnel's Signature

Name: Tony Fong

NRIC/FIN No.: G2040197X

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time:

20/8/18



Driver's Signature

(If driver is not the policyholder)

Date & Time: 20/08/18



Reporting Centre Personnel's Signature

Name: Tan Fong

NRIC/FIN No.: 62040171

Accident Photo



Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0959/2018/PH
Date	:	21-Aug-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Liew Wei Liang
Address	:	BLK 286A Compassvale Crescent #05-73 Singapore 541286
Telephone	:	HP +65 87771947
Type of Claim	:	Own Damage Claims
Policy No.	:	2100503943
Vehicle No	:	SLM 8682 T
Model Code	:	A1 SB 1.0 TFSI S
Model / Year	:	Mar-17
Engine No	:	CHZ 150154
Chassis No	:	WAUZZZ8X8H032436
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	20-Aug-18
Place of Accident	:	Depot Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLM 8682 T.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
2	To dismantle and reinstall rhs front door panel trim. To remove and reinstall rhs wing mirror assy.	S/N \$ 300.00 ✓ <i>all</i>	
3	To dismantle and renew front bumper, rhs front fender and rhs headlight. Repair bonnet and rhs front door. Re-	<i>800</i> <i>800</i> <i>550</i> S \$ 2,700.00 <i>2800</i> <i>1250</i>	
4	To respray front bumper, bonnet, rhs front fender and rhs front door. <i>550</i>	<i>550</i> \$ 2,700.00 <i>2300</i> <i>2200</i>	
5	To renew rhs front rim and carry out wheel alignment.	S/N \$ 280.00 ✓	
6	To carry out diagnostic check	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: <u>\$ 6,532.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLM 8682 T.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER	\$ 1,336.00	de ✓ 1068.20
2	FIXING PARTS FOR FRONT BUMPER	\$ 212.00	rec ✓ 83
3	HINGE BRACKET - LH/RH	2 \$ 58.00	? x an
4	ADAPTER WHEEL HOUSING LINER - RH	\$ 14.00	her ✓ 11.20
5	GRILLE - CENTER	\$ 171.00	? x an
6	CLOSING ELEMENT	\$ 143.00	? x an
7	AIR GUIDE GRILLE SATIN BLACK - RH	\$ 353.00	mis ✓ 282
8	RADIATOR GRILLE	\$ 833.00	? x } x
9	FOAM FILLER PIECE	\$ 101.00	? x } an
10	SIDE REINFORCEMENT	\$ 605.00	? x }
11	FRONT FENDER - RH	\$ 778.00	bt ✓ 622.40
12	ATTACHMENT PARTS FOR FENDER	\$ 38.00	rec ✓ x an
13	BRACKET - RH FRONT	\$ 52.00	rec ✓ 41.12
14	BRACE - RH FRONT	\$ 47.00	rec ✓ x an
15	WHEEL HOUSING LINER - RH	\$ 151.00	de ✓ 120.80
16	ATTACHMENT PARTS WHEEL HOUSING LINER	\$ 34.00	? x an
17	HEADLIGHT FOR GAS DISCHARGE LAMP	\$ 1,705.00	ant ✓ 1364
18	MOUNTING FOR MAIN BEAM HEADLIGHT - RH	\$ 103.00	? x } x
19	LIFT CYLINDER	\$ 123.00	? x } an
20	ALUMINIUM RIM - RH FRONT	\$ 645.00	ant ✓ 516
SUB TOTAL SPARE PARTS CHARGES		\$ 7,502.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLM 8682 T.

S/N		Parts Description		Damaged Parts & Prices	
				S/Nett	Remark
21		CAR PLATE - FRONT	S/N	\$ 25.00	X n/a
22		SUNDRIES		\$ 300.00	? 1296 ✓
TOTAL SPARE PARTS CHARGES			:	\$ 7,827.00	
TOTAL LABOUR CHARGES			:	\$ 6,532.00	
GRAND TOTAL			:	\$ 14,359.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

17760.92

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Tanjiluh 97495749
Surveyed Date : 23/2/18 @ 1430
Authorised Date : Not Authorise
Excess Cost : to be advise.
Liability :
Remarks :

7 days.
Resurvey before paint
sure@lkkauto.com

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dep Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0959/2018/PH 30-Aug-18 CHANG 1 of 1 SLM 8682 T Audi A1 SB 1.0 TFSI
Quantity	Description	Unit Price	Amount
Labours			
1	To dismantle front suspension assy. Inspect for damage and renew accordingly. S/N	\$ 2,400.00	✓
Parts			
1	FRONT CONTROL ARM - RH	\$ 248.00	PA - 198.40
2	FRONT GUIDE JOINT - RH	\$ 101.00	PA - 81.40
3	FRONT WHEEL BEARING HOUSING - RH	\$ 356.00	PA - 284.80
4	FRONT WHEEL BEARING - RH	\$ 327.00	PA - 261.20
5	FRONT TRACK ROD - RH	\$ 70.00	PA - 55.36
6	TIE ROD END - RH	\$ 84.00	PA - 66.48
7	BOLTS & NUTS	\$ 77.00	PA - 54.88
GRAND TOTAL :		\$ 1,263.00	

For Premium Automobiles Pte Ltd



Authorised Signature

R9541
31/8/18

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0959/2018/PH
Date	:	21-Aug-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian, Taufik

11 days with added repairs.

jb 12 Oct 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Liew Wei Liang
Address	:	BLK 286A Compassvale Crescent #05-73 Singapore 541286
Telephone	:	HP +65 87771947
Type of Claim	:	Own Damage Claims
Policy No.	:	2100503943
Vehicle No	:	SLM 8682 T
Model Code	:	A1 SB 1.0 TFSI S
Model / Year	:	Mar-17
Engine No	:	CHZ 150154
Chassis No	:	WAUZZZ8X8HB032436
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	20-Aug-18
Place of Accident	:	Depot Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLM 8682 T .

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	\$ 360.00
2	To dismantle and reinstall rhs front door panel trim. To remove and reinstall rhs wing mirror assy.	S/N \$ 300.00	
3	To dismantle and renew front bumper, rhs front fender and rhs headlight. Repair bonnet and rhs front door. Re- <i>2 1/2 days</i> install front crash management components. Reinstall all	\$ 2,700.00	\$ 2,100.00 <i>1250 ✓</i>
4	To respray front bumper, bonnet, rhs front fender and rhs front door. <i>4 panels</i> <i>850/pnl</i>	\$ 2,700.00	\$ 2,300.00 <i>2200 ✓</i>
5	To renew rhs front rim and carry out wheel alignment.	S/N \$ 280.00	\$ 280.00
6	Added labour charges - see attached	S/N \$ 2,400.00	\$ 2,400.00
7	To carry out diagnostic check	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		\$ 8,932.00	\$ 7,632.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLM 8682 T.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER	\$ 1,336.00	\$ 1,068.80
2	FIXING PARTS FOR FRONT BUMPER	\$ 212.00	\$ 83.00
3	HINGE BRACKET - LH/RH	2 \$ 58.00	
4	ADAPTER WHEEL HOUSING LINER - RH	\$ 14.00	\$ 11.20
5	GRILLE - CENTER	\$ 171.00	
6	CLOSING ELEMENT	\$ 143.00	
7	AIR GUIDE GRILLE SATIN BLACK - RH	\$ 353.00	\$ 282.00
8	RADIATOR GRILLE	\$ 833.00	
9	FOAM FILLER PIECE	\$ 101.00	
10	SIDE REINFORCEMENT	\$ 605.00	
11	FRONT FENDER - RH	\$ 778.00	\$ 622.40
12	ATTACHMENT PARTS FOR FENDER	\$ 38.00	
13	BRACKET - RH FRONT	\$ 52.00	\$ 41.12
14	BRACE - RH FRONT	\$ 47.00	
15	WHEEL HOUSING LINER - RH	\$ 151.00	\$ 120.80
16	ATTACHMENT PARTS WHEEL HOUSING LINER	\$ 34.00	
17	HEADLIGHT FOR GAS DISCHARGE LAMP	\$ 1,705.00	\$ 1,364.00
18	MOUNTING FOR MAIN BEAM HEADLIGHT - RH	\$ 103.00	
19	LIFT CYLINDER	\$ 123.00	
20	ALUMINIUM RIM - RH FRONT	\$ 645.00	\$ 516.00
SUB TOTAL SPARE PARTS CHARGES		\$ 7,502.00	\$ 4,109.32

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLM 8682 T .

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remark
				\$ 4,109.32
21	CAR PLATE - FRONT	S/N	\$ 25.00	
22	SUPPLEMENTARY		\$ 1,263.00	\$ 1,001.52
23	SUNDRIES		\$ 300.00	\$ 12.96
	TOTAL SPARE PARTS CHARGES	:	\$ 9,090.00	\$ 5,123.80
	TOTAL LABOUR CHARGES	:	\$ 8,932.00	\$ 7,632.00
	GRAND TOTAL	:	\$ 18,022.00	\$ 12,755.80

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-VV

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0959/2018/PH 30-Aug-18 CHANG 1 of 1 SLM 8682 T Audi A1 SB 1.0 TFSI
Quantity	Description	Unit Price	Amount
Labours			
1	To dismantle front suspension assy. inspect for damage and renew accordingly. S/N	\$ 2,400.00	\$ 2,400.00
Parts			
1	FRONT CONTROL ARM - RH	\$ 248.00	\$ 198.40
2	FRONT GUIDE JOINT - RH	\$ 101.00	\$ 80.40
3	FRONT WHEEL BEARING HOUSING - RH	\$ 356.00	\$ 284.80
4	FRONT WHEEL BEARING - RH	\$ 327.00	\$ 261.20
5	FRONT TRACK ROD - RH	\$ 70.00	\$ 55.36
6	TIE ROD END - RH	\$ 84.00	\$ 66.48
7	BOLTS & NUTS	\$ 77.00	\$ 54.88
GRAND TOTAL :		\$ 1,263.00	\$ 1,001.52

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dep Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/00/0959/2018/PH 30-Aug-18 CHANG 1 of 1 SLM 8682 T Audi A1 5B 1.0 TFSI
Quantity	Description	Unit Price	Amount
Labours			
1000 1	To dismantle front suspension assy. Inspect for damage and renew accordingly. S/N	\$ 2,400.00	2400.00
Parts			
1	FRONT CONTROL ARM - RH	\$ 248.00	248.00
2	FRONT GUIDE JOINT - RH	\$ 101.00	101.00
3	FRONT WHEEL BEARING HOUSING - RH	\$ 356.00	356.00
4	FRONT WHEEL BEARING - RH	\$ 327.00	327.00
5	FRONT TRACK ROD - RH	\$ 70.00	70.00
6	TIE ROD END - RH	\$ 84.00	84.00
7	BOLTS & NUTS	\$ 77.00	77.00
GRAND TOTAL :		\$ 1,263.00	1001.52

For Premium Automobiles Pte Ltd



Authorised Signature

Rasul
31/8/18

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLM 8682 T

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0959/2018/MAS

30 April 2019

Dear Sir,

RE: INSURANCE CLAIM FOR SLM 8682 T, Audi A1 SB 1.0 TFSI S-Tro

With reference to the above-mentioned vehicle, no. **SLM 8682 T**, claimant, **Mr. Liew Wei Liang**, please find the related document per attached.

1. A copy of the Original invoice no. 85013716 – S\$12,953.21
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLM 8682 T

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119938
Main Telephone: 6346 2222
Main Telefax: 6471 9773

Alexandra Service Centre
281 Alexandra Road
Singapore 119938
Telephone: 6346 2222
Telefax: 6471 1023

Ubi Service Centre
15 Ubi Road 1
Singapore 408720
Telephone: 6346 2222
Telefax: 6471 1023

Customer Service
Service Appointment
Service Breakdown Service
Email: customer.care@premiumauto.com.sg

6346 2222
6346 1253

INSURANCE INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 1 11:33

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013716 Date : 26/04/2019 Order : SLM8682T Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLM8682T (V 32147) Regn Dates: 17/03/2017 Mileage: 47444 WIP No.: 21830
Model: AI SB 1.0 TFSI 5 tronic 8XFCSE Chassis: WAUZZZ8X8H8032436 Engine: CHZ 150154 Dept: U
USB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. REPAIR BONNET AND RHS FRONT DOOR. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	1550.00	1.00	1,550.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER, BONNET, RHS FRONT FENDER AND RHS FRONT DOOR	2200.00	1.00	2,200.00
S	BODYWORK	M: TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	280.00	1.00	280.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
S	BODYWORK	M:	2400.00	1.00	2,400.00
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159908
Main Telephone: 6384 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159908
Telephone: 6388 2223
Telefax: 6473 1033

Ubi Service Centre
55 Ubi Road 1
Singapore 408722
Telephone: 6861 1151
Telefax: 6861 1151

Customer Service
Service Appointment
Service Breakdown Service
6264 2223
6628 1233
customer.care@premiumauto.com.sg

INS TAX INVOICE

Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 2 11:33

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013716 Date : 26/04/2019 Order : SLM8682T Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLM8682T (V 32147) Regn Date: 17/03/2017 Mileage: 47444 WIP No.: 21830
Model: AI SB 1.0 TFSI S tronic 8XFCSG Chassis: WAUZZZ8X8HB032436 Engine: CHZ 150154 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount	
		TO DISMANTLE FRONT SUSPENSION ASSY. INSPECT FOR DAMAGE AND RENEW ACCORDINGLY				
X	ABXA601025E	006419/(V) (SK) RIM 16	Less 020%	1.00	645.00	516.00
X	AN 91217701	(A) (SK) BOLT (TECH) (30	Less 020%	2.00	11.20	17.92
X	AN 90954503	(A) (SK) NUT (TECH) (30/	Less 020%	1.00	4.90	3.92
X	A150423812A	(A) (SK) TIEROD END (TE	Less 020%	1.00	83.10	66.48
X	A6C0423933	(A) (SK) CLIP (TECH) (30	Less 020%	1.00	5.50	4.40
X	A150423933	(A) (SK) CLIP (TECH) (30	Less 020%	1.00	4.90	3.92
X	ABXA941044A	HEADLAMP	Less 020%	1.00	1705.00	1,364.00
X	ABXA809962A	006419/(V) (SK) WHEEL	Less 020%	1.00	151.00	120.80
X	ABX0821106A	FENDER	Less 020%	1.00	776.00	622.40
X	ABXA807065A GRU	COVER	Less 020%	1.00	1336.00	1,068.00
X	AN 90942902	NUT (TECH)	Less 020%	2.00	2.40	3.84
X	A06K10915885	FIX. PARTS	Less 020%	1.00	103.75	83.00
X	ABXA807084A	006419/(V) (SK) ADAPTE	Less 020%	1.00	14.00	11.20
X	ABX06214728	BRACKET	Less 020%	1.00	51.40	41.12
X	A6R0407152F	CONTR ARM (TECH)	Less 020%	1.00	248.00	198.40
X	A6C0407621	WHEEL HUB (TECH)	Less 020%	1.00	326.50	261.20
Sub-Total						
7% GST						
Grand Total						



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119938
Mobile Telephone: 6836 2721
Fax: 6471 1133

Alexandra Service Centre
281 Alexandra Road
Singapore 119938
Telephone: 6388 2223
Telefax: 6475 1023

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Customer Service
11 (1) Appointment
24-hour Breakdown Service
Email: customer.care@premiumauto.com.sg
6564 2223
9628 1233

Page 3 of 3

Invoice: 85013716	Account: 80005 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD	AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT	MOTOR CLAIM DEPT
AIG BUILDING	AIG BUILDING
78 SHENTON WAY	78 SHENTON WAY
#07-16	#07-16
SINGAPORE 079120 079120	SINGAPORE 079120
Date : 26/04/2019	
Order : SLM8682T	
Term : 30	

Regn No.: SLM8682T (V 32147)	Regn Date: 17/03/2017	Mileage: 47444	WIP No.: 21830
Model: A1 SB 1.0 TFSI S tronic 8XFCSE	Chassis: WAUZZZ8X6H0032436	Engine: CHZ 150154	Dept: U
USD No.:			
You have been assisted by :- UB-Jiayee	(33)		

		Details		Qty	Unit Price	Amount
X	A6D0407396B	(A) (SK) NUT (TECH) (30/	Less 020%	1.00	13.90	11.12
X	A6R0407366B	JOINT (TECH)	Less 020%	1.00	100.50	80.40
X	A6C0423810C	TIE ROD (TECH)	Less 020%	1.00	69.20	55.36
X	A6D0407256AC	HOUSING (TECH)	Less 020%	1.00	356.00	284.80
X	A8XA807682B 9B9	GRILL	Less 020%	1.00	352.50	282.00
X	AWHT003684	NUT (REQ2) (TECH)	Less 020%	1.00	4.60	3.68
X	AN 0161857	POP-RIVET	Less 020%	2.00	2.90	4.64
X	AN 10106402	NUT (TECH)	Less 020%	2.00	2.60	4.16
X	AN 10332002	NUT (TECH)	Less 020%	3.00	2.10	5.04
X	AN 90954002	BOLT (TECH)	Less 020%	1.00	6.50	5.20

Parts	5,123.00	Sub-Total	12,105.00
Labour	0.00	7% GST	847.41
Sublet	6,982.00	Grand Total	12,953.21
Menus	0.00		
Lubricant	0.00		



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLM 8682 T

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0959/2018/JT
September 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A1 SB 1.0 TFSI S-tronic
Vehicle Chassis No. : WAUZZZ8X8HB032436
Vehicle Regn No. : **SLM 8682 T**
Vehicle Mileage : 31998km
Vehicle Owner : Mr. Liew Wei Liang
Certificate No : 2100503943
Policy Excess : NIL
Accident Date : 20th August 2018
Place : **Depot Road**
Repair Cost : \$ 12,953.21
WIP No. : 21830
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :



Time :

Date :

8/9/18

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8990204E



Name

SONYA CHAN CHUI SHAN
(SONYA CHEN CUISHAN)

陈翠珊

Race

CHINESE

Date of birth

05-06-1989 F

Country of birth

UNITED STATES

S8990204E

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S8990204E

SONYA CHAN CHUI SHAN
(SONYA CHEN CUISHAN)

Birth Date: 05 Jun 1989

Issue Date: 04 Feb 2017



002653448H

3888501



NRIC No: S8990204E



Date of issue

21-06-2004

APT BLK 208A COMPASSVALE CRESCENT #05-73
SINGAPORE 641286

NRIC No: S8990204E

Date: 22/12/2016

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3A Motor cars without clutch pedals (Auto) with unladen weight $\leq$ 3000kg with $\leq$ 7 passengers, exclusive of driver; and other motor vehicles without clutch pedals with unladen weight $\leq$ 2500kg 18 May 2015

NP 428A



Licence No: S8990204E

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8737175A



Name

LIEW WEI LIANG



劉 韋 良

Race

CHINESE

Date of birth

13-11-1987

Sex

M

Country of Birth

SINGAPORE

S8737175A



A8283712

NRIC No: S8737175A



Blood Group

Date of issue

14-11-2002

APT BLK 288A COMPASSVALE CRESCENT #05-13
SINGAPORE 541285

NRIC No: S8737175A

Date: 22/12/2010

COVER NOTE

Cover Note No. 2100503943		Date 11 Mar 2017	
The following risk described in the Schedule is hereby HELD COVERED in the terms of the applicable Company's policy issued to the Policyholder.			
SCHEDULE			
Policyholder	LIEW WEI LIANG ✓	Registration No.	SLM 8632J
Age Condition	All Age Condition	Make/Model	AUDI A1 Sportback 1.0 TFSI S
Policy Type	AUDI AUTO PROTECTOR	CC/Ton	999.00
Effective Date	17 Mar 2017	Engine No	CHZ150154 ✓
Expiry Date	16 Mar 2018	Chassis No	WAUZZZ8X8HB032436 ✓
Excess	S\$600.00	Year of Registration	2017 ✓
		Hire Purchase Company	HONG LEONG FINANCE LTD ✓

This policy is subject to driver's age condition. The policy will indemnify the insured or any authorised driver only if he/she meets the age condition. Please refer to policy terms and conditions.

In addition to the Policy Excess, a Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00 (before GST) will apply to You or Your Authorised Driver who is below the age of 23 (in case of All Age Condition policies) and/or has less than 2 years' driving experience. The YIDR Excess is not applicable to Named Driver policies.

Usage of vehicle only for the following purposes:

1. Use only for social, domestic and pleasure purposes and for the Policyholder's business.
2. Use in connection with the Policyholder's business. Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business and use for social, domestic or pleasure purposes.

Please note that acceptance of the risk is subject to our final acceptance and terms and conditions applicable to the policy. Should you require any change to the insurance, please contact us immediately. Otherwise, any change will not be covered under the policy.

The Company may cancel this cover by notice in writing and the insurance will be terminated and a proportionate part of the annual premium for the insurance will be charged for the time the Company has been on risk.

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

CERTIFICATE OF INSURANCE

I/We hereby certify that this cover note is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Issued in SINGAPORE

AIG Asia Pacific Insurance Pte. Ltd.

IMPORTANT NOTICE

THIS COVER NOTE IS VALID FOR 60 DAYS FROM THE FIRST DAY OF THE POLICY PERIOD. APPLICABLE TO CORPORATE POLICIES ONLY.

AUTHORISED REPRESENTATIVE

ORIGINAL

PRLYCQ

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Aug 2018 16:00		24 Aug 2018 11:09 Edit Adj Rpt	S\$12,105.80 Edit Estimates	S\$12,105.80 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured: MR LIEW WEI LIANG , ID: S8737175A, Tel: +6587771947									
Vehicle Reg. No.: SLM8682T		Date of Loss: 20/08/2018 08:00 - :59 [17 Months and 3 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 9550393961SG		Policy/Cover Note No.: 2100503943 (Comprehensive)							
		Excess: S\$0.00							
Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing] TongShing.Loo@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 04/09/2018]									
Driver/Custodian: SONYA CHAN CHUI SHAN (29 / Female), NRIC: S8990204E, Tel: +6591386228 Email: SONYACHANCS@GMAIL.COM									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (31/01/2019): Alert - Adj Mandate Approved (S\$12755.80) - SLM8682T - Claim Handler: Loo, Tong ... - AIG_SG (04/12/2018): Re: Alert - Adj Mandate Approved (S\$11826.00) - SLM8682T - Claim Handler: Loo, T... - AIG_SG (07/09/2018): Alert - Adj Mandate Approved (S\$11826.00) - SLM8682T - Claim Handler: Loo, Tong ... - AIG_SG (28/08/2018): Alert - Adj Mandate Approved (S\$10563.00) - SLM8682T - Claim Handler: Loo, Tong ...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLM8682T (9550393961SG)
 OD
 Aug 20 2018 8:30AM
 [MR LIEW WEI LIANG]
 Premium Automobiles Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Video											1 per page		☒	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)									Thumbnail	Print		
1	20/08/18 14:32	Video - Accident [Linked Accident Report Documents]									Load MP4			
Assessment Reports											1 per page		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)									Thumbnail	Print		
1	24/08/18 16:01	Adjuster Immediate Advice									Load HTM			
2	06/09/18 16:48	Adjuster Immediate Advice									Load HTM			
3	26/10/18 15:16	Adjuster Immediate Advice									Load HTM			
Photos/Images											3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)									Thumbnail	Print		
1	24/08/18 15:57	General View									Load JPG	☒		
2	24/08/18 15:57	General View									Load JPG	☒		
3	24/08/18 15:57	General View									Load JPG	☒		
4	24/08/18 15:57	Odometer Reading									Load JPG	☒		
5	24/08/18 15:57	General View									Load JPG	☒		
6	24/08/18 15:57	General View									Load JPG	☒		
7	24/08/18 15:57	General View									Load JPG	☒		
8	24/08/18 15:57	General View									Load JPG	☒		
9	24/08/18 15:57	General View									Load JPG	☒		
10	24/08/18 15:57	General View									Load JPG	☒		
11	24/08/18 15:57	General View									Load JPG	☒		
12	24/08/18 15:57	General View									Load JPG	☒		
13	24/08/18 15:57	General View									Load JPG	☒		
14	24/08/18 15:57	General View									Load JPG	☒		
15	24/08/18 15:57	General View									Load JPG	☒		
16	24/08/18 15:57	General View									Load JPG	☒		
17	24/08/18 15:57	General View									Load JPG	☒		
18	24/08/18 15:57	General View									Load JPG	☒		
19	24/08/18 15:57	General View									Load JPG	☒		
20	24/08/18 15:57	General View									Load JPG	☒		
21	24/08/18 15:57	General View									Load JPG	☒		
22	24/08/18 15:57	General View									Load JPG	☒		
23	24/08/18 15:57	General View									Load JPG	☒		
24	24/08/18 15:57	General View									Load JPG	☒		
25	24/08/18 15:57	General View									Load JPG	☒		
26	24/08/18 15:57	General View									Load JPG	☒		
27	24/08/18 15:57	General View									Load JPG	☒		
28	24/08/18 15:57	General View									Load JPG	☒		
29	24/08/18 15:57	General View									Load JPG	☒		
30	24/08/18 15:57	General View									Load JPG			

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
				☒
31	24/08/18 15:57	General View	 Load JPG	☒
32	24/08/18 15:57	General View	 Load JPG	☒
33	24/08/18 15:57	General View	 Load JPG	☒
34	24/08/18 15:57	General View	 Load JPG	☒
35	24/08/18 15:57	General View	 Load JPG	☒
36	24/08/18 15:57	General View	 Load JPG	☒
37	24/08/18 15:57	General View	 Load JPG	☒
38	24/08/18 15:57	General View	 Load JPG	☒
39	24/08/18 15:57	General View	 Load JPG	☒
40	24/08/18 15:57	General View	 Load JPG	☒
41	24/08/18 15:57	General View	 Load JPG	☒
42	24/08/18 15:57	General View	 Load JPG	☒
43	24/08/18 15:57	General View	 Load JPG	☒
44	24/08/18 15:57	General View	 Load JPG	☒
45	24/08/18 15:57	General View	 Load JPG	☒
46	24/08/18 15:57	General View	 Load JPG	☒
47	24/08/18 15:57	General View	 Load JPG	☒
48	24/08/18 15:57	General View	 Load JPG	☒
49	24/08/18 15:57	General View	 Load JPG	☒
50	24/08/18 15:57	General View	 Load JPG	☒
51	24/08/18 15:57	General View	 Load JPG	☒
52	06/09/18 16:44	Reinspection Photo	 Load JPG	☒
53	06/09/18 16:44	Reinspection Photo	 Load JPG	☒
54	06/09/18 16:44	Reinspection Photo	 Load JPG	☒
55	06/09/18 16:44	Reinspection Photo	 Load JPG	☒
56	06/09/18 16:44	Reinspection Photo	 Load JPG	☒
57	06/09/18 16:44	Reinspection Photo	 Load JPG	☒
58	06/09/18 16:44	Reinspection Photo	 Load JPG	☒
59	06/09/18 16:44	Reinspection Photo	 Load JPG	☒
60	06/09/18 16:44	Reinspection Photo	 Load JPG	☒
61	06/09/18 16:44	Reinspection Photo	 Load JPG	☒
62	06/09/18 16:44	Reinspection Photo	 Load JPG	☒
63	06/09/18 16:44	Reinspection Photo	 Load JPG	☒
64	06/09/18 16:44	Reinspection Photo	 Load JPG	☒
65	06/09/18 16:44	Reinspection Photo	 Load JPG	☒
66	06/09/18 16:44	Reinspection Photo	 Load JPG	☒
67	06/09/18 16:44	Reinspection Photo	 Load JPG	☒
68	06/09/18 16:44	Reinspection Photo	 Load JPG	☒
69	06/09/18 16:44	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/08/18 15:56	Singapore Accident Statement	 Load PDF	
2	24/08/18 15:56	ESTIMATE	 Load PDF	
3	27/08/18 12:12	CORRECT SKETCH PLAN	 Load PDF	
4	27/08/18 13:02	AMENDED GIA REPORT	 Load PDF	
5	27/08/18 14:57	DRIVING LICENSE AND NIRC	 Load PDF	
6	06/09/18 16:45	SUPPLEMENTARY LIST	 Load PDF	
7	26/10/18 15:13	REVISED ESTIMATE	 Load PDF	
8	10/05/19 17:30	Workshop Invoice	 Load PDF	
9	10/05/19 17:30	Discharge Voucher	 Load PDF	

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
10	10/05/19 17:34	Supplementary	 Load PDF	

Linked Accident Report Documents

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	20/08/18 14:32	Video - Accident	 Load MP4	
2	20/08/18 14:34	Video - Accident	 Load MP4	
Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	20/08/18 14:33	Accident Statement	 Load HTM	
2	27/08/18 12:50	Addendum Sheet	 Load JPG	☒
3	27/08/18 12:54	Accident Statement Addm. #1	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	20/08/18 14:16	Accident Photo	 Load JPG	☒
2	20/08/18 14:16	Accident Photo	 Load JPG	☒
3	20/08/18 14:16	Accident Photo	 Load JPG	☒
4	20/08/18 14:16	Accident Photo	 Load JPG	☒
5	20/08/18 14:16	Accident Photo	 Load JPG	☒
6	20/08/18 14:16	Accident Photo	 Load JPG	☒
7	20/08/18 14:16	Accident Photo	 Load JPG	☒
8	20/08/18 14:16	Accident Photo	 Load JPG	☒
9	20/08/18 14:16	Accident Photo	 Load JPG	☒
10	20/08/18 14:16	Accident Photo	 Load JPG	☒
11	20/08/18 14:16	Accident Photo	 Load JPG	☒
12	20/08/18 14:16	Accident Photo	 Load JPG	☒
13	20/08/18 14:16	Accident Photo	 Load JPG	☒
14	20/08/18 14:16	Accident Photo	 Load JPG	☒
15	20/08/18 14:16	Accident Photo	 Load JPG	☒
16	20/08/18 14:16	Accident Photo	 Load JPG	☒
17	20/08/18 14:16	Accident Photo	 Load JPG	☒
18	20/08/18 14:16	Accident Photo	 Load JPG	☒
19	20/08/18 14:16	Accident Photo	 Load JPG	☒
20	20/08/18 14:16	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	27/08/18 12:50	Sketch Plan	 Load JPG	☒
2	27/08/18 12:50	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note:

Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18015387/T1QD3

Date: 10/05/2019

REFERENCE

Insured/Claimant: MR LIEW WEI LIANG Policy No: 2100503943
Date of Loss: 20/08/2018 Nature of Claim: OD Claim No: 9550393961SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLM8682T**
Make & Model: AUDI A1 SPORTBACK, 1.0 TFSI S-tronic (A) Engine No: CHZ150154
Reg. Date: 17/03/2017 (Man. Year: 2016) Chassis No: WAUZZZ8X8HB032436
Colour: White Odometer: 31968 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$85,000.00
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45 R16 Rear Tyre Size: 215/45 R16
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,828.52	5,123.80	3,704.72	41.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,932.00	6,982.00	1,950.00	21.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	17,760.52	12,105.80	5,654.72	31.84
+ GST 7.00/7.00% (\$\$)	1,243.24	847.41	395.83	31.84
Nett Amount (\$\$)	19,003.76	12,953.21	6,050.55	31.84

INSPECTION

Date of Assignment: 24/08/2018
Date Inspected: 23/08/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 11.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,336.00 FS	*1,068.80 FS
2	1		*FIXING PARTS FOR FRONT BUMPER	Necessary	212.00 FS	*83.00 FS
3	2		*HINGE BRACKET - LH/RH	Not Necessary	58.00 FS	*- FS
4	1		*ADAPTER WHEEL HOUSING LINER - RH	Necessary	14.00 FS	*11.20 FS
5	1		*GRILLE - CENTER	Not Necessary	171.00 FS	*- FS
6	1		*CLOSING ELEMENT	Not Necessary	143.00 FS	*- FS
7	1		*AIR GUIDE GRILLE SATIN BLACK - RH	Missing	353.00 FS	*282.00 FS
8	1		*RADIATOR GRILLE	Not Necessary	833.00 FS	*- FS
9	1		*FOAM FILLER PIECE	Not Necessary	101.00 FS	*- FS
10	1		*SIDE REINFORCEMENT	Not Necessary	605.00 FS	*- FS
11	1		*FRONT FENDER - RH	Bent	778.00 FS	*622.40 FS
12	1		*ATTACHMENT PARTS FOR FENDER	Not Necessary	38.00 FS	*- FS
13	1		*BRACKET - RH FRONT	Necessary	52.00 FS	*41.12 FS
14	1		*BRACE - RH FRONT	Not Necessary	47.00 FS	*- FS
15	1		*WHEEL HOUSING LINER - RH	Deformed	151.00 FS	*120.80 FS
16	1		*ATTACHMENT PARTS WHEEL HOUSING LINER	Not Necessary	34.00 FS	*- FS
17	1		*HEADLIGHT FOR GAS DISCHARGE LAMP	Cut	1,705.00 FS	*1,384.00 FS
18	1		*MOUNTING FOR MAIN BEAM HEADLIGHT - RH	Not Necessary	103.00 FS	*- FS
19	1		*LIFT CYLINDER	Not Necessary	123.00 FS	*- FS
20	1		*ALUMINIUM RIM - RH FRONT	Cut	645.00 FS	*516.00 FS
21	1		*CAR PLATE - FRONT	Not Necessary	25.00 FS	*- FS
22	1		*SUNDRIES	Necessary	300.00 FS	*12.96 FS
23	1		*FRONT CONTROL ARM - RH	Bent	198.40 FS	*198.40 FS
24	1		*FRONT GUIDE JOINT - RH	Bent	80.40 FS	*80.40 FS
25	1		*FRONT WHEEL BEARING HOUSING - RH	Bent	284.80 FS	*284.80 FS
26	1		*FRONT WHEEL BEARING - RH	Necessary	261.20 FS	*261.20 FS
27	1		*FRONT TRACK ROD - RH	Bent	55.36 FS	*55.36 FS
28	1		*TIE ROD END - RH	Bent	66.48 FS	*66.48 FS
29	1		*BOLTS & NUTS	Necessary	54.88 FS	*54.88 FS
Total Parts (\$\$)					8,828.52	5,123.80

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY.	New	300.00	300.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. REPAIR BONNET AND RHS FRONT DOOR.	New	2,700.00	1,250.00
3	TO RESPRAY FRONT BUMPER, BONNET, RHS FRONT FENDER AND RHS FRONT DOOR.	New	2,700.00	2,200.00
4	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	New	280.00	280.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
6	TO DISMANTLE FRONT SUSPENSION ASSY. INSPECT FOR DAMAGE AND RENEW ACCORDINGLY.	New	2,400.00	2,400.00
7	TO REMOVE AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	New	360.00	360.00
Gross Labour Cost (S\$)			8,932.00	6,982.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >