

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dep Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0959/2018/PH 30-Aug-18 CHANG 1 of 1 SLM 8682 T Audi A1 SB 1.0 TFSI
Quantity	Description	Unit Price	Amount
Labours			
1	To dismantle front suspension assy. Inspect for damage and renew accordingly. S/N	\$ 2,400.00	✓
Parts			
1	FRONT CONTROL ARM - RH	\$ 248.00	PA ✓ 198.40
2	FRONT GUIDE JOINT - RH	\$ 101.00	PA ✓ 80.40
3	FRONT WHEEL BEARING HOUSING - RH	\$ 356.00	PA ✓ 284.00
4	FRONT WHEEL BEARING - RH	\$ 327.00	PA ✓ 261.20
5	FRONT TRACK ROD - RH	\$ 70.00	PA ✓ 55.36
6	TIE ROD END - RH	\$ 84.00	PA ✓ 66.48
7	BOLTS & NUTS	\$ 77.00	PA ✓ 54.88
GRAND TOTAL :		\$ 1,263.00	

For Premium Automobiles Pte Ltd

Rasul
31/8/18



Authorised Signature