

1552000

INS. CASE OWNER

BENNER

CC 4/AIG1801

5296, N 463

LJK:

IDAC:

Surveyor:

NAE

DOI:

ASSIGNMENT

24100118

Date / Time:

21/8/18

Registered in Meriton:

21/8/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

GBG 4439G

Claim No.:

52495182464

Name of Insured:

FEDERAL EXPRESS (S) PH

Policy No.:

100824969

Insured Tel No.:

HP:

21/8/18

Make / Model:

Toyota

Excess Sec II : \$5

D.O.A.:

Place of Accident:

HEMENTI RD

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

MUHAMMAD IZUDIN BIN KAHABU

GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

Final? Yes / No

SIS 4722C



INSRS:

WSP:

Tel:

Liability:

RMKS:

CYS



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

21/8/18
vic

SIS 4722C-X

GBG 4439G-X

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call Of:

After call Itr to Of:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup):

After call Itr to Of:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

21/8/18 - uc

21/8/18 - uc

21/8/18 - uc

21/8/18 - uc

21/8/18 - uc

21/8/18 - uc

21/8/18 - uc

21/8/18 - uc

21/8/18 - uc

21/8/18 - uc

21/8/18 - uc

21/8/18 - uc

21/8/18 - uc

21/8/18 - uc

21/8/18 - uc

21/8/18 - uc

21/8/18 - uc

21/8/18 - uc

21/8/18 - uc

PRELIMINARY ADVICE		Date/Time:	Sent By:
FINALIZATION		Date/Time:	Confirm with:
Repair Cost:	L19	SS 6,600.00 / 8	days/Reduction:
FINAL SETTLEMENT		Date/Time:	Confirm with:
Final Liability:	% 100	(Assessed / Assessed)	BOLA S/N No.:
Repair Cost:	6,600.00	SS 7,062.00	
Loss of Rental (LOR):	SS -	(days)	
Loss of Use (LOU):	SS 1,000.00	100 x 11	days
Loss of Income (LOI):	SS -	(5 x days)	
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/>	<input checked="" type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LO <input type="checkbox"/>	[Tick only one]	
GIA/LTA Search	SS 7.45		
Medical:	SS -		
Disbursement:	SS -	(e.g. Tow/Independent)	
Legal Cost	SS -		
Total:	SS 8,109.45	Global Sum SS:	8,000.00
FINAL PAYMENT		Date/Time:	Confirm with:
Payee 1:	SS 8,000.00	Name 1:	CYS AUTOMOBILE SERVICES PTE LTD
Payee 2: (Strike if N.A.)	SS -	Name 2:	-
Payee 3: (Strike if N.A.)	SS -	Name 3:	-

SENT

1) Claim status: Normal/Reject/Private Settle
2) Report Format:
3) Survey fee: \$310.00

REF:

Surveyor

N/A

REF:

A/G

h

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLS4732L Yr Regn: 23 APR 2008
 Type: M.Cycle / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: HONDA (RV) C.C. 2354
 Colour: WHITE A/C: Insured / Std / Nil /
 Sp. Reading: 222, 294 T/Radio: Insured / Std / Nil /
 Eng/No: _____
 C/No: JHLR48508207409
 Gen. Cond: Good / Poor / Burnt
 Steering: In Op / Jammed / Leaked / Burnt or
 Brake: In Op / Jammed / Leaked / Burnt or
 Modl: Nil / S/Rim / STD / R/Rim or
 Tyre Size: F: 225/60R18
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 21/8/18 D.O.I. 24/8/18
 Survey held at CYS AUTO
 Des. of Damages: Fr / Rev / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
27/12/18	FINALIZED LUMP SUM REPAIR + 6,600.00 / 8 DAYS COST: 9,194.68 (32%)

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1) _____

Date/Time, File Return to?

2) _____

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

) \$ = R\$ \$

) Photos

) Others

Report Format :

Lump Sum / I.B.I. (\$)

TOTAL

5a.

Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
 B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



進友成汽車服務私人有限公司

CYS Automobile Services Pte Ltd

ROC Reg. No. A05041/2001E

GST Reg. NO: 20-0105041-E

MR HOE YONG SOON CONSTRUCTION PTE LTD
8B ADMIRALTY STREET #04-15
8B@ADMIRALTY. (S) 757440

POLICY NO

YOUR REF

OUR REF

VEHICLE NO

MAKE/MODEL

DATE OF ACCIDENT

THIRD PARTY CLAIMS

GBG4439G (AIG)

TP5931

SLS4732C

Honda CRV 2.4

21.Aug.18

SURVEY BY

DATE : 23.Aug.18

1 PC TAILGATE		S\$	931.20	DD
1 PC TAILGATE " CRV" EMBLEM			29.40	NEE
1 PC TAILGATE OUTER CHROME			238.40	NEE
1 PC TAILGATE CENTRE EMBLEM			24.10	NEE
1 PC TAILGATE GARNISH			368.80	CRV
4 PCS TAILGATE GLASS MOUDLING			98.50	NEE
1 PC TAILGATE OUTER LOCK			151.80	BROKEN
1 PC TAILGATE TOP LOCK			178.50	BROKEN
1 PC TAILGATE INNER TRIM BOARD			175.10	CRV
1 PC TAILGATE WEATHERSTRIP			133.70	BT
1 PC TAILGATE WIPER MOTOR			255.30	?
2 PCS TAILGATE ABSORBER	151.8		303.60	?
2 PCS TAILGATE HINGES	68.10		136.20	?
1 PC REAR END PANEL			535.40	?
1 PC REAR END PANEL TOP GARNISH			85.40	CRV
1 PC SPARE TYRE FLOOR PANEL			1,045.50	DD
1 PC SPARE TYRE FLOOR PANEL SCREW			17.00	NEE
2 PCS SPARE TYRE SIDE GARNISH	80.80		161.60	?
1 PC SPARE TYRE HARDBOARD			462.10	BT
2 PCS REAR FENDER INNER TRIM BOARD			189.30	?
1 PC REAR BUMPER			599.50	BT
2 PCS REAR BUMPER SIDE	153.40		306.80	LIT RA?
2 PCS REAR BUMPER SIDE RETAINERS	17.40		34.80	LH RIT?
1 PC TAILLAMP ASSY L/H			420.60	CRV
		S\$	6,882.60	
			1,376.52	
		S\$	5,506.08	
		S\$	120.00	S/NETT
			33.60	NEE
			80.00	NEE
			35.00	NEE
			350.00	200 NEE
		S\$	618.60	
		S\$	30.00	20
			80.00	60
			80.00	60
			60.00	30
			140.00	20
			80.00	60
			1,600.00	1,400
			1,600.00	1,400
		S\$	9,794.68	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed

is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TO CHECK WIRING FUNCTION

TO APPLY RUST PROOFING ON REPLACED/ REPAIRED PANEL

TO TRANSFER TAILGATE

TO REMOVE AND REFIX CAMERA

TO REMOVE AND REFIX TAILGATE GLASS

TO REMOVE AND REFIX CUSHION SEAT

LABOUR CHARGES

TO PUTTY AND SPRAY PAINTING CHARGES

SIN DOLLARS: NINE THOUSAND SEVEN HUNDRED NINETY-FOUR AND CENTS SIXTY-EIGHT ONLY.

YOUR FAITHFULLY, 38 Woodlands Industrial Park East 1 #07-17 Admiralty Industrial Park Singapore 757700
Tel: 6219 2098 (3 Lines) Fax: 6219 2096 E-mail: cysauto@singnet.com.sg

CYS AUTOMOBILE SERVICES PTE LTD

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Vehicle Details

Vehicle No.:

Vehicle to be Exported:

Intended De-registration Date:

Vehicle Make:

Vehicle Model:

Primary Colour:

Manufacturing Year:

Engine No.:

Chassis No.:

Maximum Power Output:

Open Market Value:

Original Registration Date:

First Registration Date:

Transfer Count:

Actual ARF Paid:

Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebate Amount:

Intended COE Rebate Details

COE Expiry Date:

COE Category:

COE Period(Years):

PQP Paid:

COE Rebate Amount:

Total Rebate Amount:

Company

8036M

SLS4732C

Yes

25 Aug 2018

HONDA

HONDA CRV 2.4LAT

White

2008

K24Z12752853

JHLRE48508C207409

125.0 kW (167 bhp)

\$30,328.00

23 Apr 2008

23 Apr 2008

2

\$30,328.00

Forfeited

\$0.00

22 Apr 2028

B - Car (1601cc & above)

10

\$40,881.00

\$39,493.00

\$39,493.00

The information contained herein is correct as at 23 Aug 2018

OK

Vic (LKKAUTO)

From: Tan, Bennie-WZ <Bennie-WZ.Tan@aig.com>
Sent: Monday, 4 March, 2019 12:56 AM
To: Vic (LKKAUTO)
Cc: Admin A
Subject: RE: <SEEK MANDATE> Your Ref: 5749877824SG-003 _ACCIDENT INVOLVING VEHICLES GBG 4439G (OI) AND SLS 4732C (TP) ON 21/08/2018 LKK RFE CC4/AIG18015396/Nhb3

Hi Vic

Referring to your email below.

Kindly let us have your further comments on your recommendation on the following parts:

1. TAILGATE WIPER MOTOR — working intermittently when tested during the first survey.
2. SPARE TYRE FLOOR PANEL — Detail - Refer photo 27 and 28.
3. TAILLAMP ASSY L/H — cut / Sander - Refer photo 14. Edge of tailgate hit against

Also, please advise on the breakdown on labour cost as well as the recommended repair days.

Thank you.

Best Regards

Bennie Tan
AIG
Senior Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1718

Bennie-WZ.Tan@aig.com | www.aig.sg

Let's see need to cut a weld and find panel and spare spare tyre panel.

Painting 8 working days of repair. No recommended.

From: Vic (LKKAUTO) [mailto:vicalpeh@lkkauto.com]
Sent: Tuesday, January 29, 2019 11:26 AM
To: Tan, Bennie-WZ
Cc: Admin A; Vic (LKKAUTO)
Subject: <SEEK MANDATE> Your Ref: 5749877824SG _ACCIDENT INVOLVING VEHICLES GBG 4439G (OI) AND SLS 4732C (TP) ON 21/08/2018 LKK RFE CC4/AIG18015396/Nhb3

Your Ref: 5749877824SG

Our Ref: CC4/AIG18015396/Nhb3

Dear Bennie,

ACCIDENT INVOLVING VEHICLES GBG 4439G (OI) AND SLS 4732C (TP) ON 21/08/2018

We refer to the subject matter.

It was reported that Insured vehicle had rear-ended TP vehicle.

Vic (LKKAuto)

From: Tan, Bennie-WZ <Bennie-WZ.Tan@aig.com>
Sent: Sunday, 10 March, 2019 9:24 AM
To: Vic (LKKAuto)
Cc: Admin A
Subject: RE: <SEEK MANDATE> Your Ref: 5749877824SG-003 _ACCIDENT INVOLVING VEHICLES GBG 4439G (OI) AND SLS 4732C (TP) ON 21/08/2018 LKK RFE CC4/AIG18015396/Nhb3

Hi Vic

Panel Baiting 06 Hrs.
Spray Painting 02 Hrs.

Referring to your email below.

Per our previous email, we also requested for a breakdown to the recommended days.

Best Regards

Bennie Tan
AIG

Senior Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1718

Bennie-WZ.Tan@aig.com | www.aig.sg

3 days - ~~remove and cut~~ Remove and cut vinyl trimmings.
New bumper & tailgate wiring etc.
2 days - remove and cut / weld back end Panel and spare tyre Panel
2 days - spray painting Panel

From: Vic (LKKAuto) [mailto:vicalpeh@lkkauto.com]

Sent: Thursday, March 07, 2019 4:06 PM

To: Tan, Bennie-WZ

Cc: Admin A; Vic (LKKAuto)

Subject: RE: <SEEK MANDATE> Your Ref: 5749877824SG-003 _ACCIDENT INVOLVING VEHICLES GBG 4439G (OI) AND SLS 4732C (TP) ON 21/08/2018 LKK RFE CC4/AIG18015396/Nhb3

Dear Bennie,

We refer to your below email.

Please refer to the below comments with regards to your queries:

1. TAILGATE WIPER MOTOR – it was working intermittently when tested during the first survey
2. SPARE TYRE FLOOR PANEL – it was dented. Please refer to photos 27-28 in merimen.
3. TAILLAMP ASSY L/H – cut/scratch was observed. Please refer to photo 14. The edge of the tailgate hit against the lamp cover during the impact.

With regards to the labour cost, there is a need to cut and weld the end panel and spare tyre panel. A total of 8 repair days were recommended.

Meanwhile, TP had proposed and agreed to settle the claim in full at a global sum of \$8,000.00 (all in).

Thank you.

Print Received Message

This mail is associated with :

***SLS4732C (5749877824SG)
[GBG4439G]**

TP

HOE YONG SOON CONSTRUCTION PTE LTD

Aug 21 2018 2:00PM

[FEDERAL EXPRESS (SINGAPORE)]

CYS Automobile Services Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 21/03/2019 14:15 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$8000.00) - SLS4732C - Claim Handler: Tan, Bennie-WZ

Approved:8000.00:Pls do your utmost to negotiate settlement from \$7,800 - \$8,000 (All-in)

Vic (LKKAUTO)

From: CYSAUTO <cysauto@singnet.com.sg>
Sent: Friday, 21 December, 2018 4:16 PM
To: Vic (LKKAUTO)
Cc: Naz (LKKAUTO); SUR
Subject: FW: OUR REF: SLS4732C YOUR INSURED: GBG4439G - ***LKK
REF:CC4/AIG18015396/Nhb3 - DEMAND LETTER
Attachments: LTA RECEIPT.tif; LTA FEES.jpg
Importance: High

Dear Mr Naz,

WITHOUT PREJUDICE

I wish to inform you that we are agreed the repair cost at \$6,600.00

Dear Mr Vic,

We have instruction to accept as follow:

Cost of Repair	\$ 7,062.00(inclusive GST)
Loss of Use (13daysX\$100)	\$ 1,300.00(recommend 10days+arrangement+2 weekends)
LTA Fees	\$ 7.45(as claimed)
TOTAL	\$ 8,369.45

Kindly let us have your confirmation on this claim asap. Thanks and look forward for your reply.

Warm regards,
Ms Tee Wee Sin



CYS AUTOMOBILE SERVICES PTE LTD

38 Woodlands Industrial Park E1 #07-17 S(757700)

Tel: 62192098 Fax: 62192096

Email: cysauto@singnet.com.sg

From: Shu Pei

(LKKAUTO) [mailto:shupe@lkkauto.com]
Sent: Friday, August 24, 2018 2:38 PM
To: CYSAUTO <cysauto@singnet.com.sg>
Cc: Admin A <admin-a@lkkauto.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>
Subject: RE: OUR REF: SLS4732C YOUR INSURED: GBG4439G - KINDLY CHECK LIABILITY ***LKK
REF:CC4/AIG18015396/Nhb3

Dear Ms Tee,

We refer to the above matter.

Please be informed that we are currently **pending for OI GIA report.**

Please note that for liability, claim negotiation and settlement, please contact Vic at 6841 2096.

Our respective case handler will look into the matter and revert to you in due course.

Thank you

To check availability of the case handler, you may contact the undersigned.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CYSAUTO <cysauto@singnet.com.sg>

Sent: Friday, 24 August 2018 1:35 PM

To: Admin A <admin-a@lkkauto.com>

Subject: OUR REF: SLS4732C YOUR INSURED: GBG4439G - KINDLY CHECK LIABILITY

Importance: High

Dear Sir,

WITHOUT PREJUDICE

Attached herewith estimate surveyed by Mr Nazril and GIA report for your attention.

Kindly check liability for this claim. Thanks and look forward for your reply.

Warm regards,

Ms Tee Wee Sin



CYS AUTOMOBILE SERVICES PTE LTD

38 Woodlands Industrial Park E1 #07-17 S(757700)

Tel: 62192098 Fax: 62192096

Email: cysauto@singnet.com.sg

From:
AIG
SGP,

Claims-Survey [mailto:AIGSGP_ClaimsSurvey@aig.com]

Sent: Thursday, August 23, 2018 2:25 PM

To: CYS Auto, Woodlands <cysauto@singnet.com.sg>

Subject: RE: ARRANGE FOR THIRD PARTY SURVEY FOR VEHICLE SLS4732C AGAINST GBG4439G

Without Prejudice

Hi Esther,

We'll appoint AIG in-house surveyor to inspect the vehicle, kindly confirm acceptance.

Thanks.

AIG Claims Survey

From: CYS Auto, Woodlands [<mailto:cysauto@singnet.com.sg>]
Sent: Thursday, August 23, 2018 1:34 PM
To: AIG SGP, Claims-Survey
Subject: ARRANGE FOR THIRD PARTY SURVEY FOR VEHICLE SLS4732C AGAINST GBG4439G

Dear Officer,

ACCIDENT INVOLVING SLS4732C & GBG4439G ON 21.AUG.18

Kindly arrange for a survey for my client's vehicle SLS4732C against your insured GBG4439C.

Vehicle is in 38, WOODLANDS INDUSTRIAL PARK E1 #07-17 (S) 757700.

Kindly let me have the officer in charge and also the liability of this case.

I've attached the GIA report and ESTIMATE for your reference.

Thanks.

Regards,
Esther Lim
CYS AUTOMOBILE SERVICES PTE LTD
TEL: 62192098
FAX: 62192096



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

31 AUGUST 2018

**FEDERAL EXPRESS 9(SINGAPORE) PTE LTD
90 ALPS AVENUE
SINGAPORE 498746
ATTN: THE MANAGEMENT**

Dear Sir/Madam,

**OUR REF : CC4/AIG18015396/Nhb3
YOUR REF : GBG 4439G
ACCIDENT INVOLVING GBG 4439G AND SLS 4732C ALONG CLEMENTI ROAD ON
21.08.2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Body Repairer/Workshop acting on behalf of the owner of SLS 4732C against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had collided to the Third-Party vehicle SLS 4732C. As such, liability may not be on your favour.

Please be informed that your No Claim Discount (NCD – if any) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defense, please reply to us within 10 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 10 days from the date of this letter **if not provided at AIG's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AIG's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AIG of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AIG shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Vic Alpeh
Case Handler
DID: 6841 2096
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

WITHOUT PREJUDICE to:

(a) Insurers' Subrogated Claim any/or

(b) Any Personal Injury Claims

(Note: This Notice supersedes and inconsistent with any other notice found in this Discharge Voucher)

AUTHORISATION TO ACT


(AIG Express Third Party Claim)

I, Hue Yeng Soon Construction ^{Ac. No.} (the third party claimant) of 88 Admiralty Street
#04-15 88@ Admiralty Spire ⁷⁸⁷⁴²⁰ (address), owner of SL54732C (vehicle no.)
hereby authorize CYS AUTOMOBILE SERVICES PTE LTD ("the workshop") to act for me
with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle
no. SL54732C that was damaged pursuant to the accident which occurred on 21.8.18
(date) along Upper Bukit Timah Road (location) involving vehicle no/s
GEE 4439G ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit
and the workshop is further authorized to receive payment further to settlement of my claim with
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 24 (day) of Aug (month) 2018 (year)


Signed by "the third party claimant"
(with chop if applicable)



退友成汽車服務私人有限公司
CYS Automobile Services Pte Ltd
38 Woodlands Industrial Park East 1
#07-17 Admiralty Industrial Park
Singapore 757700
Tel: 6214 2098 (toll-free) Fax: 6219 2096
Signed by "the workshop"
(with chop)

WITHOUT PREJUDICE to :

(a) Insurers' Subrogated Claim any/or

(b) Any Personal Injury Claims

[Note: This Notice supersedes and inconsistencies found in this Discharge Voucher]

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **CYS AUTOMOBILE SERVICES PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$8,000.00** (Global Sum – all in) for vehicle no. **SLS 4732C** that was damaged pursuant to the accident which occurred on **21/08/2018** (date) along **CLEMENTI ROAD** (location) involving vehicle no/s **GBG 4439G** This is pursuant to the inspection conducted on **24/08/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **HOE YONG SOON CONSTRUCTION PTE LTD** ("the third party claimant") of vehicle no. **SLS 4732C** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SLS 4732C** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 21/08/18



Signed by appointed surveyor


CYS Automobile Services Pte Ltd
38 Woodlands Industrial Park East-1
#07-17 Admiralty Industrial Park
Singapore 757700
Tel: 6219 2096 (3lines) Fax: 6219 2096

Signed by "the workshop" (with chop)



進友成汽車服務私人有限公司

CYS Automobile Services Pte Ltd

ROC Reg. No :A05041/2001E

GST Reg. NO: 20-0105041-E

TAX INVOICE

Invoice No

7767

M/S AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16 SINGAPORE 079120
ATTN: MOTOR CLAIMS DEPT.

POLICY NO	:	THIRD PARTY CLAIM
OUR REF	:	TP 5931
VEHICLE NO	:	SLS 4732 C
MAKE/MODEL	:	HONDA CRV
DATE OF ACCIDENT	:	21-Aug-18
DATE	:	21-Mar-19

SURVEY BY

TO AGREE AT THE SUM OF

	S\$	6,600.00
GST 7%		462.00
	<u>S\$</u>	<u>7,062.00</u>

SIN DOLLARS, SEVEN THOUSAND AND SIXTY-TWO ONLY

YOURS FAITHFULLY,


FOR CYS AUTOMOBILE SERVICES PTE LTD

> Back to OneMotoring



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 23 Aug 2018 / 09:24:08

Receipt Date/Time : 23 Aug 2018 / 09:24:08

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180823-000208

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - GBG4439G				
As at 21 Aug 2018/14:20:00				
Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - GBG4439G Enquiry Fee 20180823092256072767	7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
Paid By				
	20180823092312723	Direct Debit: eNETS Debit (Internet Banking)		7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

[> Back to OneMotoring](#)**Vehicle Insurance Particulars Result**

Vehicle No.

GBG4439G

Incident Date/Time

21 Aug 2018 / 14:20:00

Insurance Company Name

AIG ASIA PACIFIC INSURANCE PTE. LTD.

[Print](#)[OK](#)[Save as PDF](#)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Aug 2018 Edit Reg		23 Aug 2018 00:00 Edit Adj Rpt	S\$6,600.00 Edit Estimates	S\$6,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	FEDERAL EXPRESS (SINGAPORE) PTE LTD, Co. Reg. No.: NA								
Main Claimant:	HOE YONG SOON CONSTRUCTION PTE LTD, Co. Reg. No.: 200008036M								
Vehicle Reg. No.:	SLS4732C	Date of Loss:	21/08/2018 14:00 - :59 [123 Months and 29 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 5749877824SG	Policy/Cover Note No.:	0999994900 (Third Party Only)						
Vehicle Reg. No. (Insured):	GBG4439G	Policy No. (Claimant):	5094747033						
		Excess:							
Repairer:	CYS Automobile Services Pte Ltd (Woodlands) 38 Woodlands Industrial Park East 1, #07-17, Admiralty Industrial Park, 757700 Woodlands - Tel: 6219 2098								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 04/09/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG_EXPRESS (21/03/2019): Alert - Adj Mandate Approved (S\$8000.00) - SLS4732C - Claim Handler: Tan, Bennie... AIG_SG_EXPRESS (10/03/2019): Alert - Adj Mandate Maintained - SLS4732C - Claim Handler: Tan, Bennie-WZ AIG_SG_EXPRESS (04/03/2019): Alert - Adj Mandate Maintained - SLS4732C - Claim Handler: Tan, Bennie-WZ 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLS4732C (5749877824SG)**
[GBG4439G]
TP
HOE YONG SOON CONSTRUCTION PTE LTD
Aug 21 2018 2:00PM
[FEDERAL EXPRESS (SINGAPORE) PTE LTD]
CYS Automobile Services Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser	
Letters/Correspondences						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	(Draft)	Third Party Express Settlement - Payment Breakdown	1	Edit			
Photos/Images						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	28/08/18 18:27	General View	1	Load JPG	<input checked="" type="checkbox"/>		
2	28/08/18 18:27	General View	1	Load JPG	<input checked="" type="checkbox"/>		
3	28/08/18 18:27	General View	1	Load JPG	<input checked="" type="checkbox"/>		
4	28/08/18 18:27	General View	1	Load JPG	<input checked="" type="checkbox"/>		
5	28/08/18 18:27	General View	1	Load JPG	<input checked="" type="checkbox"/>		
6	28/08/18 18:27	General View	1	Load JPG	<input checked="" type="checkbox"/>		
7	28/08/18 18:27	General View	1	Load JPG	<input checked="" type="checkbox"/>		
8	28/08/18 18:27	General View	1	Load JPG	<input checked="" type="checkbox"/>		
9	28/08/18 18:27	General View	1	Load JPG	<input checked="" type="checkbox"/>		
10	28/08/18 18:27	General View	1	Load JPG	<input checked="" type="checkbox"/>		
11	28/08/18 18:27	General View	1	Load JPG	<input checked="" type="checkbox"/>		
12	28/08/18 18:27	General View	1	Load JPG	<input checked="" type="checkbox"/>		
13	28/08/18 18:27	General View	1	Load JPG	<input checked="" type="checkbox"/>		
14	28/08/18 18:27	General View	1	Load JPG	<input checked="" type="checkbox"/>		
15	28/08/18 18:27	General View	1	Load JPG	<input checked="" type="checkbox"/>		
16	28/08/18 18:27	General View	1	Load JPG	<input checked="" type="checkbox"/>		
17	28/08/18 18:27	General View	1	Load JPG	<input checked="" type="checkbox"/>		
18	28/08/18 18:27	General View	1	Load JPG	<input checked="" type="checkbox"/>		
19	28/08/18 18:27	General View	1	Load JPG	<input checked="" type="checkbox"/>		
20	28/08/18 18:27	General View	1	Load JPG	<input checked="" type="checkbox"/>		
21	28/08/18 18:27	General View	1	Load JPG	<input checked="" type="checkbox"/>		
22	28/08/18 18:27	General View	1	Load JPG	<input checked="" type="checkbox"/>		
23	28/08/18 18:27	General View	1	Load JPG	<input checked="" type="checkbox"/>		
24	28/08/18 18:27	General View	1	Load JPG	<input checked="" type="checkbox"/>		
25	28/08/18 18:27	General View	1	Load JPG	<input checked="" type="checkbox"/>		
26	28/08/18 18:27	General View	1	Load JPG	<input checked="" type="checkbox"/>		
27	27/12/18 16:04	Dismantled Parts	1	Load JPG	<input checked="" type="checkbox"/>		
28	27/12/18 16:04	Dismantled Parts	1	Load JPG	<input checked="" type="checkbox"/>		
29	27/12/18 16:04	Dismantled Parts	1	Load JPG	<input checked="" type="checkbox"/>		
30	27/12/18 16:04	Dismantled Parts	1	Load JPG	<input checked="" type="checkbox"/>		
31	27/12/18 16:04	Dismantled Parts	1	Load JPG	<input checked="" type="checkbox"/>		
32	27/12/18 16:04	Dismantled Parts	1	Load JPG	<input checked="" type="checkbox"/>		
33	27/12/18 16:04	Dismantled Parts	1	Load JPG	<input checked="" type="checkbox"/>		
34	27/12/18 16:04	Dismantled Parts	1	Load JPG	<input checked="" type="checkbox"/>		

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	27/12/18 16:04	Dismantled Parts		<input checked="" type="checkbox"/>
36	27/12/18 16:04	Dismantled Parts		<input checked="" type="checkbox"/>
37	27/12/18 16:05	Dismantled Parts		<input checked="" type="checkbox"/>
38	27/12/18 16:05	Dismantled Parts		<input checked="" type="checkbox"/>
39	27/12/18 16:05	Dismantled Parts		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/08/18 13:57	EMAIL FROM AIG DD 23082018		
2	24/08/18 13:57	TP ESTIMATE		
3	24/08/18 13:57	TP GIA REPORT		
4	30/08/18 09:56	TP ESTIMATE- MARKED		
5	31/08/18 14:32	LETTER TO OI		
6	23/01/19 10:25	LTA SEARCH		
7	12/04/19 10:42	WORKSHOP INVOICE		
8	12/04/19 10:42	AUTHORISATION TO ACT FORM		
9	12/04/19 10:42	Release Voucher		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	27/08/18 09:08	OI GIA REPORT		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer. <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	GBG4439G (Insd veh)	Model:	HONDA CR-V 2.4 L (A)
	SLS4732C (TP veh)		
Date of Accident:	21/08/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	10,480.31
Final Repair Cost	:	\$	8,000.00
Loss of Use	:	\$	11.00 days at \$100.00 per day
Rental (if any)	:	\$	days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	8,000.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop**: Agreed Liability ____ 100 ____ (%)

B) For **GIA Registered Workshop**: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	CYS Automobile Services Pte Ltd	:	\$ 8,000.00
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

12 Apr
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18015396/NHB3Q2

Date: 12/04/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994900
Claimant Vehicle No : SLS4732C **Insured Vehicle No :** GBG4439G
 Date of Loss: 21/08/2018 Nature of Claim: TP Claim No: 5749877824SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLS4732C**
 Make & Model: HONDA CR-V, 2.4 L (A) Engine No: K24Z12752853
 Reg. Date: 23/04/2008 (Man. Year: 2008) Chassis No: JHLRE48508C207409
 Colour: White Odometer: 222294 km
 Engine Capacity: 2354 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60 R18 Rear Tyre Size: 225/60 R18
 Front Left Side: Sumitomo 6 mm Rear Left Side: Sumitomo 6 mm
 Front Right Side: Sumitomo 6 mm Rear Right Side: Sumitomo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,124.68	5,002.28	1,122.40	18.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,670.00	3,150.00	520.00	14.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,794.68	8,152.28	1,642.40	16.77
Approved Total (Overridden) (S\$)		6,600.00		
(S\$)	9,794.68	6,600.00	3,194.68	32.62
+ GST 7.00/7.00% (S\$)	685.63	462.00	223.63	32.62
Nett Amount (S\$)	10,480.31	7,062.00	3,418.31	32.62
+ Loss of Use (11.0 x S\$100.00/day) (S\$)		1,100.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		8,169.45		
Global Sum Settlement (S\$)		8,000.00		

INSPECTION

Date of Assignment: 23/08/2018
 Date Inspected: 24/08/2018 Inspected At:

CYS Automobile Services Pte Ltd
(Woodlands)
38 Woodlands Industrial Park East 1, #07-
17, Admiralty Industrial Park
Singapore 757700

Estimated Period of Repair: 8.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	931.20 FL	*750.00 FL
2	1		*TAILGATE CRV EMBLEM	Necessary	29.40 FL	*29.40 FL
3	1		*TAILGATE OUTER CHROME	Necessary	238.40 FL	*238.40 FL
4	1		*TAILGATE CENTRE EMBLEM	Necessary	24.10 FL	*24.10 FL
5	1		*TAILGATE GARNISH	Cracked	368.80 FL	*300.00 FL
6	1		*TAILGATE GLASS MOULDING (4 PCS)	Necessary	98.50 FL	*98.50 FL
7	1		*TAILGATE OUER LOCK	Broken	151.80 FL	*151.80 FL
8	1		*TAILGATE TOP LOCK	Broken	178.50 FL	*178.50 FL
9	1		*TAILGATE INNER TRIM BOARD	Cracked	175.10 FL	*100.00 FL
10	1		*TAILGATE WEATHERSTRIP	Bent	133.70 FL	*133.70 FL
11	1		*TAILGATE WIPER MOTOR	Not Working	255.30 FL	*200.00 FL
12	2		*TAILGATE ABSORBER	Serviceable	303.60 FL	*- FL
13	2		*TAILGATE HINGES	Serviceable	136.20 FL	*- FL
14	1		*REAR END PANEL	Deformed	535.40 FL	*535.40 FL
15	1		*REAR END PANEL TOP GARNISH	Cracked	85.40 FL	*85.40 FL
16	1		*SPARE TYRE FLOOR PANEL	Dented	1,045.50 FL	*1,000.00 FL
17	1		*SPARE TYRE FLOOR PANEL SCREW	Necessary	17.00 FL	*17.00 FL
18	2		*SPARE TYRE SIDE GARNISH	Serviceable	161.60 FL	*- FL
19	1		*SPARE TYRE HARDBOARD	Bent	462.10 FL	*462.10 FL
20	2		*REAR FENDER INNER TRIM BOARD	Cracked	189.30 FL	*189.30 FL
21	1		*REAR BUMPER	Bent	599.50 FL	*599.50 FL
22	1		*REAR BUMPER SIDE	O/S Cracked	306.80 FL	*153.40 FL
23	2		*REAR BUMPER SIDE RETAINERS	Serviceable	34.80 FL	*- FL
24	1		*TAILLAMP ASSY L/H	Cracked	420.60 FL	*420.60 FL
25	1		*INSULATOR PADDING	Cracked	120.00 FS	*120.00 FS
26	8		*TAILGATE GARNISH CLIPS	Necessary	33.60 FS	*33.60 FS
27	2		*SEALANT	Necessary	80.00 FS	*80.00 FS
28	1		*SET REAR BUMPER CLIPS	Necessary	35.00 FS	*35.00 FS
29	1		*SET REVERSE SENSOR	Necessary	350.00 FS	*200.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc

Sub Total (\$\$) 7,501.20 6,135.70

- List Item Discount on L Items 20.00/20.00% (\$\$) 1,376.52 1,133.42

Total Parts (\$\$) 6,124.68 5,002.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING FUNCTION	New	30.00	20.00
2	TO APPLY RUST PROOFING ON REPLACED/ REPAIRED PANEL	New	80.00	60.00
3	TO TRANSFER TAILGATE	New	80.00	60.00
4	TO REMOVE AND REFIX CAMERA	New	60.00	30.00
5	TO REMOVE AND REFIX TAILGATE GLASS	New	140.00	120.00
6	TO REMOVE AND REFIX CUSHION SEAT	New	80.00	60.00
7	LABOUR CHARGES	New	1,600.00	1,400.00
8	TO PUTTY AND SPRAY PAINTING CHARGES	New	1,600.00	1,400.00
Gross Labour Cost (S\$)			3,670.00	3,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >