

# SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT  
SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD  
59 SENOKO ROAD  
SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002578

Date : 21/08/2018

Vehicle Num. : GBE4683C

Make/Model : FIAT DOBLO 1.6MJTD-2015

Chassis/Eng# : ZFA26300006B30556/263A50007454

Accident Date : 19/08/2018

Claim No. :

Reference : GBC8068S

Policy No. : 29004183

| S/N          | Quantity | Particular                           | Unit Price        | Amount S\$         |
|--------------|----------|--------------------------------------|-------------------|--------------------|
| LIST ITEMS : |          |                                      |                   |                    |
| 1.           | 1        | FRONT BUMPER                         |                   | 864.07 <i>DE</i>   |
| 2.           | 2        | BUMPER SIDE BRACKET                  | 69.80 <i>RH #</i> | 139.60 <i>X</i>    |
| 3.           | 1        | MUDGUARD, RHS                        |                   | 377.46 <i>bt</i>   |
| 4.           | 1        | MUDGUARD GARNISH, RHS                |                   | 195.20 <i>DE</i>   |
| 5.           | 1        | MUDGUARD INNER GARNISH               |                   | 265.10 <i>DE</i>   |
| 6.           | 1        | FRONT DOOR, RHS                      |                   | 2,615.62 <i>BT</i> |
| 7.           | 2        | DOOR HINGE                           | 195.20            | 390.40 <i>DE</i>   |
| 8.           | 1        | RUNCHANNEL                           |                   | 395.20 <i>DE</i>   |
| 9.           | 1        | DOOR GLASS                           |                   | 398.20 <i>DE</i>   |
| 10.          | 1        | DOOR LOCK                            |                   | 298.50 <i>BT</i>   |
| 11.          | 1        | DOOR HANDLE OUTER                    |                   | 215.60 <i>DE</i>   |
| 12.          | 1        | DOOR TRIM                            |                   | 895.20 <i>cut</i>  |
| 13.          | 1        | DOOR REGULATOR                       |                   | 368.50             |
| 14.          | 1        | WEATHERSTRIP, FR DOOR BELT, OTR, RHS |                   | 195.20 <i>cut</i>  |
| 15.          | 1        | WEATHERSTRIP, FR DOOR BELT, INR, LH  |                   | 175.50 <i>cut</i>  |
| 16.          | 1        | MOULDING ASSY                        |                   | 198.20 <i>cut</i>  |
| 17.          | 1        | HANDLE, FR DOOR INSIDE RH            |                   | 105.20 <i>X</i>    |
| 18.          | 1        | DOOR CHECK                           |                   | 125.20 <i>BT</i>   |
| 19.          | 1        | HARNESS                              |                   | 195.20             |
| 20.          | 1        | SIDE MIRROR, RHS                     |                   | 795.40 <i>DE</i>   |
| 21.          | 1        | SIDE MIRROR COVER                    |                   | 105.20 <i>DE</i>   |
| 22.          | 1        | FRONT WINDSCREEN                     |                   | 817.82 <i>DE</i>   |
| 23.          | 1        | FRONT WINDSCREEN MOULDING            |                   | 368.20 <i>DE</i>   |

CONTINUE / ...

# SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002578

Date : 21/08/2018

Vehicle Num. : GBE4683C

Make/Model : FIAT DOBLO 1.6MJTD-2015

Chassis/Eng# : ZFA26300006B30556/263A50007454

Accident Date : 19/08/2018

Claim No. :

Reference : GBG8068S

Policy No. : 29004183

| S/N                   | Quantity | Particular                              | Unit Price | Amount S\$             |
|-----------------------|----------|-----------------------------------------|------------|------------------------|
| 24.                   | 1        | SIDE MIRROR CONTROL SWITCH              |            | 125.20 X               |
| 25.                   | 1        | WEATHERSTRIP, FR DOOR OPENING, INR, RHS |            | 145.20 <i>re</i>       |
| 26.                   | 1        | PILLAR, RHS                             |            | 695.20 <i>repair</i>   |
| 27.                   | 1        | PILLAR, CTR                             |            | 495.50 <i>repair</i>   |
| 28.                   | 1        | SLIDING DOOR, RH                        |            | 2,863.50 <i>st</i>     |
| 29.                   | 1        | SLIDING LOCK                            |            | 268.20 <i>st</i>       |
| 30.                   | 1        | SLIDING DOOR HANDLE, OTR, RH            |            | 245.30 <i>Bo</i>       |
| 31.                   | 1        | SLIDING DOOR ROLLER, LWR, RH            |            | 298.20 X               |
| 32.                   | 1        | SLIDING DOOR ROLLER, CTR, RH            |            | 245.20 X               |
| 33.                   | 1        | SLIDING DOOR TRIM                       |            | 468.20 ?               |
| 34.                   | 1        | SLIDING DOOR WEATHERSTRIP               |            | 275.20 27,520.00 X     |
| 35.                   | 1        | SIDE PANEL, RH                          |            | 2,152.10 <i>repair</i> |
| 36.                   | 1        | REAR LAMP, RHS                          |            | 462.67 <i>ca</i>       |
| 37.                   | 1        | REAR BUMPER                             |            | 734.34 <i>re</i>       |
| 38.                   | 2        | BUMPER SIDE BRACKET RH                  | 95.20      | 190.40 X               |
| 39.                   | 2        | TYRE, HUP KIT                           | 165.20     | 330.40 <i>sch</i>      |
| 40.                   | 1        | WIPER PANEL                             |            | 368.20 <i>DE</i>       |
| 41.                   | 1        | SLIDING DOOR MOULDING                   |            | 178.20 <i>re</i>       |
| List Total S\$ :      |          |                                         |            | 48,285.78              |
| 15.00% Discount S\$ : |          |                                         |            | 7,242.87               |
|                       |          |                                         |            | 41,042.91              |
| NETT ITEMS :          |          |                                         |            |                        |
| 1.                    | 1        | WINDSCREEN SEALANT                      |            | 40.00 <i>re</i>        |

CONTINUE / ...

# SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT  
SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD  
59 SENOKO ROAD  
SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002578

Date : 21/08/2018

Vehicle Num. : GBE4683C

Make/Model : FIAT DOBLO 1.6MJTD-2015

Chassis/Eng# : ZFA26300006B30556/263A50007454

Accident Date : 19/08/2018

Claim No. :

Reference : CBC8068S

Policy No. : 29004183

| S/N                                       | Quantity | Particular                   | Unit Price | Amount S\$                      |
|-------------------------------------------|----------|------------------------------|------------|---------------------------------|
| 2.                                        | 1        | ERP BRACKET                  |            | 26.00 <i>me</i>                 |
| 3.                                        | 1        | LOGO                         |            | <del>480.00</del> <i>300</i>    |
| 4.                                        | 1        | COMPANY REGISTRATION STICKER |            | 20.00 <i>me</i>                 |
| Nett Total S\$ :                          |          |                              |            | 566.00                          |
| 10.00% Discount S\$ :                     |          |                              |            | 56.60                           |
|                                           |          |                              |            | 509.40                          |
| LABOUR :                                  |          |                              |            |                                 |
| TO DISMANTLE/REPLACE FRONT WINDSCREEN     |          |                              |            | <del>150.00</del> <i>120</i>    |
| TO PANEL BEAT/REPAIR RH BODY              |          |                              |            | <del>1,800.00</del> <i>1500</i> |
| TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS |          |                              |            |                                 |
| SPRAY PAINTING                            |          |                              |            | <del>1,500.00</del> <i>1300</i> |
| TO APPLY NEW LOGO                         |          |                              |            | <del>150.00</del> <i>80</i>     |
| TO APPLY TUFF KOTE                        |          |                              |            | <del>150.00</del> <i>100</i>    |
| TO CHECK WIRING                           |          |                              |            | <del>120.00</del> <i>60</i>     |
| TOWING CHARGES                            |          |                              |            | 70.00                           |

CONTINUE / ...

# SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002578

Date : 21/08/2018

Vehicle Num. : GBE4683C

Make/Model : FIAT DOBLO 1.6MJTD-2015

Chassis/Eng# : ZFA26300006B30556/263A50007454

Accident Date : 19/08/2018

Claim No. :

Reference : GBC8068S

Policy No. : 29004183

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

LOSS OF USE : 14 DAYS @ \$ 120/DAY

Labour Total S\$ :

3,940.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total S\$ : 45,492.31

=====

SIN SHENG ENGINEERING SERVICES

# SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Supplementary Estimate : ES002581

Date : 24/08/2018

Vehicle Num. : GBE4683C

Make/Model : FIAT DOBLO 1.6MJTD-2015

Chassis/Eng# : ZFA26300006B30556/263A50007454891

Accident Date : 19/08/2018

Claim No. :

Reference : GBG8068S

Policy No. : 29004183

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

|    |   |                               |  |                   |
|----|---|-------------------------------|--|-------------------|
| 1. | 1 | LIST ITEMS :<br>HEADLAMP, RHS |  | 862.30 <i>CRA</i> |
|    |   | List TotalS\$ :               |  | 862.30            |
|    |   | 15.00% Discount S\$ :         |  | 129.35            |
|    |   |                               |  | 732.95            |

Total S\$ : 732.95

=====

Susan

SIN SHENG ENGINEERING SERVICES