

AUTOWORX HOUSE

C/O.176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 64520715 FAX: 64529250

ESTIMATE

UNIQUE TOURIST SERVICE PTE LTD
c/o 46 Lenton Plain
Singapore 786548

Not Authorised
61 Lm & ?
Resurvey After Painting
4 days Date: 23/8/2018

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE: NISSAN TEANA / SJN 5145 R	
	rear door lower chrome garnish	<i>CM</i> 376.40 ✓
	rear door outer channel garnish	356.70 ?
	rear door glass regulator	<i>R</i> 566.20 X
	sub-total	1,299.30
	less 30%	389.79
	sub-total(a)	909.51 <i>767.48</i>
	rear door net	<i>B</i> 867.40 ✓
	rear door lock net	<i>R</i> 78.60 ✓
	rear door hinge <u>nett@</u>	<i>Dir</i> 193.40 ✓
	rear door stay rod net	<i>Dir</i> 175.00 ✓
	front door net	<i>R</i> 765.40 X
	B' pillar outer panel net	<i>R</i> 674.00 X
	sub-total	2,753.80
	less 10%	275.38
	sub-total(b)	2,478.42 <i>1182.96</i>
	sub-total for (a) + (b)	3,387.93
	To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.	<i>400</i> 1,300.00
	To check wiring system.	<i>200</i> 60.00
	To transfer door(s) accessories.	60.00 ✓
	sub-total	4,807.93

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

	balance b/f	4,807.93
	To remove trimming and seats to enable repair.	<i>in</i> 120.00 <i>X</i>
	To apply putty & spray painting on affected areas.	<i>600</i> 800.00
	To bench mount to align frame.	<i>in</i> 400.00 <i>X</i>
	To apply rust proofing on affected areas.	<i>30%</i> 100.00
	Total	<u>6,227.93</u>