LIU'S BROTHER AUTO ENGINEERING WORKSHOP Invoice/Ref No: XD4791T180729 No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883 ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbro@ymail.com Estimate Customer Name: AXA Insurance Singapore Pte Ltd Date: 21-08-18 Address Motor Claims Department Vehicle No: XD4791T 8 Shenton Way #27-01 Model/Make: Mercedes Benz **AXA** Tower Singapore 068811 2632/6X4 Revised Original Item Quotation / **Descriptions Of Parts** Quotation / No. Cost Of Estimation Repair MIC Front Rh Bumper 121 720.00 2 Signal Lamp 210.00 Bumper Inner Panel 11 3 343.00 4 Bumper Lower Garnish 17 470.00 Corner Panel (M 5 575.00 6 Step Panel \$1,840.00 7 Step Panel Outer Garnish 11 490.00 8 Wheel Fender Inner 670.00 Side Mirror Completed 9 \$ 1,930.00 "2632" Emblem 10 nn 142.00 11 "Corporate" Advertisement & Artwork 11 200,00 To check all wiring & electrical component for proper function 50.00 Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etcs \$ 1,000.00 To putty & spray painting & including touch up paint on accident affecte \$ 1,000.00 Total Parts & Labour of estimate for damaged vehicle \$ 9,640.00 Total amount in Lump Sum Basis for repaired vehicle SDLS: 23/8/6 23/8/6 2/3 \$ 2200 M/s Liu's Brother Auto Engrg Wks LKK A to Consultants hence notify the Repairer of the following: · To resurvey efore/after pray painting . To display damaged part(s) during resurvey · Paris prices are subject to confirmation The sarty survey is on a "Without Prejudice" basis · No illegal modification(s) is allowed · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: Date: