



Ethicarz Pte. Ltd. 56 Loyang Way, Singapore (508775) #04-04

Loyang Enterprise Building, Email: kelvinwo@ethicarz.sg

Tel: 63844404, FAX: 63840444

VEHICLE NUM:

MAKE & MODEL:

MILEAGE:

TYRE:

CHASSIS NUM:

SJT8492L

NISSAN LATIO

JN1BAAC11Z0021365

ATTN:		
QTY	DESCRIPTION - PARTS	PRICE
	BOOTLID ✓ Bue	\$787.50 N
	BOOTLID LOCK ?	\$115 N
	BOOTLID WEATHERSTRIP ✓ NEC	\$82 N
	BOOTLID CENTER CHROME MOULDING No. plate chrome ? Garnish ?	\$185 N
	BOOTLID CENTER CHROME MOULDING CLIPS No. plate chrome Garnish, clip	\$121.20 N
	BOOTLID INSULATOR Insulator X SVC	\$215.50 N
	BOOTLID INSULATOR CLIPS X SVC	\$20
	BOOTLID SENSOR slw	\$125. N
	BOOTLID EMBLEM - LATIO ✓ NEC	\$52.60 N
	BOOTLID LOGO ✓ NEC	\$59.70 N
	BOOTLID HINGE L+R ? NEC ?	\$76.20 N
	NUMBER PALTE LAMP L+R X	\$42.30 N
	REAR BUMPER ✓ DD	\$533.40 N
	REAR BUMPER CLIPS ✓ NEC	\$50.00
	REAR BUMPER SIDE RETAINER L+R ✓ NEC	\$86.00
	REAR BUMPER BRACKET L+R ✓ DD	\$24.00
	REAR BUMPER SPONGE ?	\$76 N
	REAR BUMPER SENSOR ✓ cut / sc	\$250 s/n
	TAILLAMP L+R ✓ CRA.	\$279 N
	TAILLAMP PANEL L+R ?	\$
	TAILLAMP CLIPS L+R ?	\$20
*	REAR FENDER L+R X SVC	\$486.20 N
	REAR FENDER COWLING L+R X SVC	\$95 N
	REAR FEDDER COWLING CLIPS L+R X SVC	\$10
	REAR FENDER INNER TRIM L+R ?	\$8
	REAR FENDER INNER TRIM CLIPS L+R ?	\$8
	REAR END PANEL ✓ DD	\$442.60 N
	REAR END PANEL TOP GARNISH ✓ CRA / WP	\$73 N
	REAR END PANEL TOP GARNISH CLIPS ?	\$50
*	SPARE WHEEL PANEL X NN	\$676.20 N
	SPARE WHEEL QUARTER PANEL L+R X NN	\$187. N.
	SPARE WHEEL BOARD X NN ✓ Brr / WP	\$495 N
	REAR FENDER L+R X NN	\$562 N
	REAR FENDER INNER TRIM L+R X RPT	\$X
	REAR FENDER INNER TRIM CLIPS L+R X RPT	\$X
	REAR FENDER COWLING L+R X NN	\$10
	REAR FENDER COWLING CLIPS L+R X NN.	\$8
	EXHAUST PIPE X R	\$504 N

	EXHAUST PIPE GASKET	X NN	\$ 60
	EXHAUST PIPE HEATSHEID	X NN	\$ 115 N
	EXHAUST PIPE MOUNTING	X NN	\$ 40 N
	WINDSCREEN MOULDING	X NN	\$ 95 N
	BONNET	X SVC ✓ DD	\$ 893.90 N
	BONNET SEAL L+R	X NN	\$ 10 N
	BONNET SEAL CLIPS L+R	X NN	\$ 8 N
	BONNET HINGE L+R	X SVC	\$ 48 N
	BONNET LOCK	?	\$ 68 N
	FRONT GRILLE BASE L+R	chrome ✓ drip - 8#	\$ 388.20 N
	FRONT GRILLE LOGO	✓ NEC	\$ 59.70 N
	FRONT GRILLE CHROME MOULDING TOP - L+R	X NS	\$ 60 N
	FRONT GRILLE CHROME MOULDING MID - L+R	X NS	\$ 60 N
	FRONT GRILLE LOWER CHROME MOULDING	X NS	\$ 80 N
	FRONT GRILLE TRIM	X NS	\$ 100 N
	FRONT GRILLE TRIM CLIPS	✓ NEC	\$ 8
	FRONT BUMPER	✓ DD	\$ 456.30 N
	FRONT BUMPER CLIPS	✓ NEC	\$ 50.00 N
	FRONT BUMPER SIDE RETAINER L+R	✓ NEC	\$ 24.00 N
	FRONT BUMPER BRACKET L+R	X SVC	\$ 94.00 N
	FRONT BUMPER SPONGE	?	\$ 215.30 N
	FRONT BUMPER REINFORCEMENT	?	\$ 446.30 N
	FRONT SUPPORT PANEL	?	\$ 308.50 N
	FRONT BRACE PANEL	?	\$ 90. N
	FRONT BUMPER LOWER GRILLE	?	\$ ✓
	FRONT BUMPER UNDERCOVER	X NN	\$ 159.30 N
	FRONT BUMPER UNDERCOVER CLIPS	X NN	\$ 8
	HEADLAMP ASSY L+R	?	\$ 450.90 N
	HEADLAMP LOWER BRACKET L+R	?	\$ 25. N
	FOG LAMP L+R	X SVC	\$ 85 N
	FOG LAMP BRACKET L+R	X NN	\$ 42 N
	AIR DUCT INTAKE PIPE	✓ ?	\$ 96 N
	A/C CONDENSOR ASSY	?	\$ 554 N
	A/C LOW PRESUSRE PIPE	X NN	\$ 210 N
	A/C HIGH PRESSURE PIPE	X NN	\$ 180 N
	A/C DISCHARGE PIPE	X NN	\$ 160 N
	RADIATOR ASSY	?	\$ 687.70 N
	FAN MOTOR ASSY	?	\$ 456.30 N
		SUBTOTAL	\$ -
		LESS 10%	\$ -
		PARTS TOTAL	\$ -
QTY	SPECIAL NETT	PRICE	
	FRONT NUMBER PLATE	\$	80.00
	REAR NUMBER PLATE	\$	80.00

	REVERSE SENSOR X RPT	\$ 300.00
	REVERSE CAM X SVC	\$ 400.00
	REAR END PANEL SEALANT ✓ NEC	\$ 80.00
	SPARE WHEEL PANEL SEALANT X NN	\$ 80.00
	RADIATOR COOLANT X NN	\$ 120.00
	SPARE WHEEL INSULATOR X NN	\$ 150.00
	WINDSCREEN SEALANT X NN	\$ 80.00
	SPECIAL NETT TOTAL	\$ 1,370.00
QTY	LABOUR	PRICE
	TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD ,KNOCK&REALIGN (F)	\$ 1,800.00 600
	TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD ,KNOCK&REALIGN (R)	\$ 2,500.00
	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA (F)	\$ 1,800.00 400
	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA (R)	\$ 2,400.00 1200
	TO RUST PROOF ACCIDENT AFFECTED AREA	\$ 300.00 80
	TO RNR REAR WINDSCREEN	\$ 180.00
	TO RNR REAR BOOT MECHANISM	\$ 200.00 60
	TO RNR REAR LUGGAGE COMPARTMENT	\$ 200.00 80
	TO RNR REVERSE SENSOR & CHECK FUNCTION.	\$ 150.00 60
	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	\$ 300.00 80
	TO RNR A/C CONDENSOR ASSY AND REFILL GAS	\$ 200.00 X
	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS	\$ 150.00 60
	TO DO DIAGNOSIS AND RESET , REPROGRAM OR CODING FAULT CODE.	\$ 150.00 80
	TO DO WATER LEAK TEST .	\$ 150.00 X
	TO RNR RADIATOR ASSY AND HOSES TO ASSIST WORK LOAD	\$ 200.00 X
	TO RNR FUEL TANK TO ASSIST WORK LOAD	\$ 200.00 X
	LABOUR TOTAL	\$ 10,880.00
	GRAND TOTAL COST	\$ 12,250.00

With Prejudice
 Lump Sum Repair
 Part Price Subject To
 Part / Dismantling / After Paint
 - Resurvey
 Wilson To.
 LKK Auto.
 Tel: 67418434 / 96404178
 Wilson @ lkkauto.com.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey 2 OF 2
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: