



2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. F/20180823/2075

VEHICLE, MY VEHICLE CAUGHT ON FIRE, I WANTED TO PARK THE CAR HOWEVER THE ACCELERATOR WAS NOT FUNCTIONING PROPERLY. I COULD NOT MOVE FORWARD, SO I STOPPED MY VEHICLE AND GOT OUT,I CALLED SCDF AND ALSO TOLD MY BROTHER IN LAW. HE TOOK THE FIRE HYDRANT FROM THE CARPARK, HOWEVER, IT WAS NOT ENOUGH TO PUT THE FIRE OUT, SCDF CAME AND IT TOOK THEM ABOUT 15 MIINUTES TO PUT THE FIRE OUT. POLICE WAS AT THE SCENE AS WELL

Subjects Involve	
Victim	
Person Name	HANIS BINTE BAHARIN (Informant)

Signature Of Officer Recording The Report:

TP / KHALED AMR HASSAN MOHSSEN

Signature Of Interpreter: Not applicable

Officer In-Charge Of Case: F / Ang Mo Kio Police Divisional Investigation Branch / Sr Staff Sgt LIN BAOLONG Contact No.: 62180000

Signature Of Informant:

Date/Time: 23/08/2018 13:46

Classification Of Case:

Authentication Stamp



POLICE CASE CARD



SINGAPORE POLICE FORCE CASE CARD Report Number 19 19 80 872 / 0135 Classification Value in Sc

Actions Taken

Police Advisory Issued Community Mediatron Magistrate's Complaint Investigation Branch

Others:

Officer's Name :

Contact Number (ZIS WWW



Magazinate's Complaint Into Vigos gl/HDR IDq



Modistion Reterral http://goo.gk/60/7 POCI



SINGAPORE POLICE FORCE

Report Number: F 120180822 0135
Classification: Vehicle of fie.

Actions Taken

Police Advisory Issued Community Mediation

Magistrate's Complaint Investigation Branch

Others:

Officer's Name:

Contact Number:



Magistrate's Complaint http://goo.gl/40RIZq



Mediation Referral http://goo.gl/9U7P0C





YOU AND CONSTRUCTED BRIVE MEHICLES IN THE FOLLOWING CLASSIES!

Class 3A Motor cars without clutch pedals (Auto) =< 3000kg with =< 7 passengers, exclusive of the driver; and other motor vehicles without clutch pedals =< 2500kg

PASS DATE

Licence No: S8628105H

01 Sep 2009

REPUBLIC OF SINGAPORE IDENTITY CARD NO. \$8628105H



HANIS BINTE BAHARIN

حانس بنت بحارين

Name



MALAY Date of birth 09-10-1986

Country/Place of birth SINGAPORE

5732992





22-04-2017

APT BLK 710 BEDOK RESERVOIR ROAD #09-3126 SINGAPORE 470710

REPUBLIC OF SINGAPORE IDENTITY CARD NO. \$1124313D





BAHARIN BIN BAKAR

بحارین بن بکر Race

MALAY Date of birth 15-02-1955

S1124313D

Country/Place of birth SINGAPORE

5994507



NRIC No. S1124313D



Date of issue 04-08-2018

APT BLK 710 BEDOK RESERVOIR ROAD #09-3126 SINGAPORE 470710



MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807 Tel +65 6827 7888, Fax +65 6827 7800 Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA) THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)

THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)

(REPUBLIC OF SINGAPORE)

THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE) OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.1

ULTIMATE CAR PROTECTOR-PREMIER

Comprehensive

Certificate No. S 28933206 SMF

Excess: SGD1,500

1. Index Mark and Registration Number of Vehicle

SKB1182K

Individual Ownership

2. Name of Policyholder

Baharin bin Bakar

3. Effective Date of the Commencement of Insurance for the purposes of the Act 28/04/2018

4. Date of Expiry of Insurance

27/04/2019

5. Persons or Classes of Persons entitled to drive*

Baharin bin Bakar

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

- * Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
- Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business. The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR CAN BE CARRIED OUT AT ANY WORKSHOP OF YOUR CHOICE OR AT ANY MSIG AUTHORISED WORKSHOP LISTED IN THE ATTACHED.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.

Approved Insurers

for Chief Executive Officer

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 The AIG Building Singapore 079120 Attn: Motor Claims Dept

Tel: 6419 1993

Your Ref: SKB 1182 K

Norah Khai 6768 9828 6841 1183

Nora.khai@premiumauto.com.sg

Body & Paint Dept PA/OD/TL14/2018

August 2018

Dear Sir/Mdm,

RE: ACCIDENT INVOLVING VEHICLE NO: SKB 1182 K

VEHICLE MODEL: Audi A8 L D4 3.0 TFSI qu

LOCATION: Sengkang Rivervale Crescent Carpark

DOA: 22 August 2018

We refer to the above-mentioned vehicle.

We have visually inspected the vehicle and would like to inform you the car was involved in a Fire Incident.

The accident has caused intensive damages to the engine compartment.

Kindly arrange for survey.

We recommend for a Total Loss on this vehicle.

Premium Automobiles Pte Ltc Showroom

9 Leng Kee Road Singapore 159090

Telephone (65) 6566 1111

Telefax (65) 6471 3733

Service & Parts Centres 55 Ubi Rd 1 Singapore 408699

Telephone (65) 6336 2323 Telefax (65) 684 11183

Thank you,

Norah Khai Claims Manager

27/08/20 @ 1500m

TAN LOSS. HASE

Exus iBH

2kt And

2

...CLAIM SUBFOLDER...(Pending for Survey Report) Total Loss

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status	
Main	23 Aug 2018		24 Aug 2018 10:16 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Su Report Cancel Case	rvey
	Main	R	eference	Claim Det	tails	Documents	Sho	W All
CLAIM S	Main SUBFOLDER DE		eference	Claim Det		Documents by insurer]	Sho	IIA wo

Mi	ain [Reference		Claim Details		Documents		Snow All
CLAIM SUB	FOLDER DETAILS				[Create	ed by insurer]		
Insured:	BAHARIN BIN BA	KAR, ID: S11243	13D, Tel: +65	96352207				
Vehicle Reg. No.:	SKB1182K			Date of Loss:		018 11:00 - :59 oths and 25 Days From	LTA Reg Date	(Man Yr)]
Claim Type:	OD / 568114	Policy/Cover Note No.:	S28933206SMF (Comprehensive) Coverage: 28/04/2018 - 27/04/2019					
				Excess:	s: S\$0.00			
Repairer:	Premium Automo	biles Pte Ltd (UB	I) 55 Ubi Road 1	, 408699 Ubi - Tel:	6768982	8/9827/9911		
Handling Insurer:	MSIG Insurance	(Singapore) Pte.	Ltd. (HQ) - Tel:	+65 6827 7888	[Handled	by Jocelyn Ng Shin I	Bun]	
Adjuster:	LKK Auto Consult	tants Pte Ltd (HQ) - Tel: 6256-356	51 [Handled by B	RYAN TA	NI] [Final Rpt	due 23/09/20	18]
Driver/Custo dian:				105H, Tel: +6590				
Adj Asg. Remarks:	Please appoint LKK	to survey the vehi	cle and investiga	te caused of fire. Ple	ease appl	y fire report from SCD	F. Thank you.	
ASSOCIATE	D MAIL RECEIVED)				View	All Compos	se Case Ma
	mail for this case.						_	
There are no								
	IATED TASKS				/iew All	Search Tasks Cre	eate New Task	Complete

Claim Documents

*SKB1182K (568114)
OD
Aug 22 2018 11:00AM
[BAHARIN BIN BAKAR]
Premium Automobiles Pte Ltd

Ass	essment Reports		1 per	page 🔻	~
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	23/08/18 15:14	Accident Statement	0	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	28/08/18 13:48	Adjuster Immediate Advice	0	Load HTM	
2	28/08/18 13:53	Adjuster Immediate Advice	0	Load HTM	
Pho	otos/Images		3 per	page 🗸	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	14/09/18 09:24	General View	0	Load JPG	V
2	14/09/18 09:24	General View	0	Load JPG	~
3	14/09/18 09:24	General View	0	Load JPG	V
4	14/09/18 09:24	General View	0	Load JPG	~
5	14/09/18 09:24	General View	0	Load JPG	4
6	14/09/18 09:24	General View	0	Load JPG	✓
7	14/09/18 09:24	General View	0	Load JPG	~
8	14/09/18 09:24	General View	0	Load JPG	V
9	14/09/18 09:24	General View	0	Load JPG	✓
10	14/09/18 09:24	General View	0	Load JPG	✓
11	14/09/18 09:24	General View	0	Load JPG	✓
12	14/09/18 09:24	General View	0	Load JPG	✓
13	14/09/18 09:24	General View	0	Load JPG	✓
14	14/09/18 09:24	General View	0	Load JPG	~
15	14/09/18 09:24	General View	0	Load JPG	✓
16	14/09/18 09:24	General View	0	Load JPG	✓
Doc	cumentation		1 per	page V	V
	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	I per	Thumbnail	-
No 1	23/08/18 19:16	Transfer Fee Details	0	Load PDF	
2	23/08/18 19:16	PARF COE	0	Load PDF	
3	24/08/18 09:21	Email from Premium Auto (Jeffery Tan) - to arrange survey	0	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	28/08/18 13:52	ESTIMATE	0	Load PDF	
2	17/09/18 11:10	Investigation Report	0	Load PDF	
3	17/09/18 11:10	Fire Report	0	Load PDF	

Linked Accident Report Documents

View View			View in Brows	er	
Ass	sessment Reports 1 per page		ige 🗸	~	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	23/08/18 15:14 Accident Statement		1 Load HTM		
Pho	tos/Images		3 per pa	ige 🗸	V

Merimen e-Claims Page 2 of 2

Ass	essment Reports		1 per i	page 🔻	V
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Prin
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	23/08/18 15:05	Police Report	0	Load JPG	✓
2	23/08/18 15:05	Police Report	0	Load JPG	V
3	23/08/18 15:05	POLICE CASE CARD	0	Load JPG	✓
4	23/08/18 15:08	Accident Photo	0	Load JPG	~
5	23/08/18 15:08	Accident Photo	0	Load JPG	✓
6	23/08/18 15:08	Accident Photo	0	Load JPG	✓
7	23/08/18 15:08	Accident Photo	Ð	Load JPG	✓
8	23/08/18 15:08	Accident Photo	0	Load JPG	~
9	23/08/18 15:08	Accident Photo	0	Load JPG	✓
10	23/08/18 15:08	Accident Photo	0	Load JPG	✓
11	23/08/18 15:08	Accident Photo	0	Load JPG	✓
12	23/08/18 15:08	Accident Photo	0	Load JPG	✓
13	23/08/18 15:08	Accident Photo	0	Load JPG	V
14	23/08/18 15:08	Accident Photo	0	Load JPG	✓
Doc	cumentation		1 per	page 🔻	✓
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	23/08/18 15:04	Sketch Plan	0	Load JPG	✓
2	23/08/18 15:04	Sketch Plan #2	•	Load JPG	~

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save Print
There are no document checklists configured.		
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)		
		/
		_
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.		

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way, #21-01 SGX Centre 2

Singapore 068807

Our File No:

CS/MSG18015450/DQD3E2

Date:

OD

17/09/2018

REFERENCE

Date of Loss:

Insured/Claimant:

BAHARIN BIN BAKAR

Policy No: Nature of Claim: S28933206SMF

Claim No:

568114

DESCRIPTION & IDENTIFICATION OF VEHICLE

22/08/2018

Reg No:

SKB1182K

Make & Model:

AUDI A8 L, 3.0 TFSI QU (A)

Engine No:

CGW005534

0 km

Reg. Date:

28/04/2011 (Man. Year: 2011)

Chassis No: Odometer:

WAUZZZ4H7BN014675

Colour: Engine Capacity: Black

2995 cc

Market Value/New Car Price: S\$84,000.00 Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES

255/45 R19

Rear Tyre Size:

No

255/45 R19

Front Tyre Size: Front Left Side: Front Right Side:

Pirelli 5 mm

Rear Left Side: Rear Right Side:

Pirelli 5 mm Pirelli 5 mm

Pirelli 5 mm The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:

24/08/2018

Date Inspected:

27/08/2018 Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair:

0.0 days

Adjuster: BRYAN TANI

SHIAU CHAN Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Page 2 of 4 Adjuster Report

TOTAL LOSS ASPECT

Market Value : \$84,000.00

OMV:

\$82,593.00

PARF Rebate (1): \$49,555.00

Quota Premium Paid: \$56,801.00

COE Rebate (2): \$15,145.00

Total Rebate (1) + (2) = : \$64,700.00

The total amount incurred will be Market Value \$84,000.00 minus Total Rebate \$64,700 = \$19,300.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 17 Sep 2018)

Parts:

143

AUDI A8 L 3.0 TFSI QU (A) (Catalogue:Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKB1182K)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >