

KIM CHWEE AUTO PTE LTD

1 Kakit Bukit Ave 6

#01-46,48,50 Autobay

SINGAPORE 417883

not authorized
2/6/18
2/5/17,000
647.

VEHICLE NO: SKZ 297T

QTY	PARTICULAR		
1 PCS	BOOTLID	4070	but/buc \$6,070.00 ✓
1 PCS	BOOTLID REAR LOGO	107.80	rec \$166.00 ✓
1 PCS	BOOTLID '3.0' EMBLEM	83.60	rec \$95.00 ✓
1 PCS	BOOTLID 'A8' EMBLEM	83.60	rec \$105.00 ✓
1 PCS	BOOTLID 'QUATTRO' EMBLEM	81.00	rec \$102.00 ✓
2 PCS	BOOTLID REFLECTORS @\$1500.00	1270.60 x 2 = 2541.20	one \$3,000.00 ✓
1 PCS	BOOTLID REVERSE CAMERA		see \$1,185.00 X
1 PCS	BOOTLID INNER TRIM		17 \$820.00 X
1 PCS	BOOTLID INNER LOCK	121	tail/shld \$210.00 ✓
1 PCS	BOOTLID LOCK STRIKER		17 \$150.00 X
1 PCS	BOOTLID LOCK MOTOR ASSY		17 \$1,696.00 X
2 PCS	BOOTLID HINGES @\$377.00		17 \$674.00 X
1 PCS	BOOTLID WEATHERSTRIP	356.40	twi \$356.40 ✓
2 PCS	TAILLAMPS @\$1600.00	1339 x 2 = 2678	one \$3,200.00 ✓
2 PCS	TAILLAMP SIDE COVERS @\$26.40		17 \$52.80 X
1 PCS	REAR BUMPER TOP	3211	dis \$3,888.00 ✓
1 PCS	REAR BUMPER BOTTOM	1-94	dis \$594.00 ✓
1 PCS	REAR BUMPER CHROME MOULDING	792	one \$792.00 ✓
2 PCS	REAR BUMPER REVERSE SENSORS @\$215.60		shld \$431.20 ✓
2 PCS	REAR BUMPER SIDE GUIDES @\$28.60		shld \$57.20 ✓
1 PCS	REAR BUMPER CENTRE GUIDE		one \$105.00 ✓
1 PCS	REAR BUMPER CENTRE BRACKET		one \$108.00 ✓
1 PCS	REAR BUMPER REINFORCEMENT	1315	dis \$1,515.00 ✓
2 PCS	TAILLAMP HOUSING PANELS @\$115.00		17 \$230.00 X
1 PCS	REAR END PANEL OUTER	497.20	body \$697.20 ✓
1 PCS	REAR END PANEL INNER	457.00	body \$499.00 ✓
1 PCS	REAR END PANEL FILLER PLATE		17 \$499.00 X
1 PCS	REAR END PANEL TOP GARNISH	435.60	twi \$488.00 ✓
1 PCS	REAR FLOOR PANEL		17 \$1,016.00 X
1 PCS	REAR FLOOR PANEL TOP BORAD		no/ueph \$899.00 ✓
1 PCS	REAR FLOOR PANEL WELL	906.00	one \$1,016.00 ✓
1 PCS	REAR EXHAUST ASSY		17 \$2,880.00 X
1 PCS	REAR EXHAUST HEAT SHIELD		17 \$411.00 X
1 PCS	REAR BUMPER LOWER UNDER COVER	311	17 \$392.00 ✓
2 PCS	REAR FENDER INNER TRIMS @\$805.00		17 \$1,610.00 X
			\$36,009.80

(57)

70240.2
19228.19

LABOUR CHARGES:

TO CHECK WIRING	\$80.00	30
TO DISMENTLE & REPLACING REVERSE SENSOR	\$80.00	50
TO DISMENTLE & REFIX SEAT, CUSHION UPHOLSTREY	\$150.00	80
TO DISMENTLE & REFIX REAR EXHAUST	\$200.00	100
TO DISMENTLE & REFIX BOOTLID MECHANISM	\$180.00	80
TO DISMENTLE & REFIX PETROL TANK	11 \$150.00	X
TO SPRAY RUST PROOFING	\$150.00	60
TO DISMENTLE & REFIX REAR WINDSCREEN	11 \$150.00	X
LABOUR FOR PANEL BEATING, CUT, WELD STRAIGHTENED	\$2,200.00	1000
REPLACING PARTS		
TO PUTTY & SPRAY PAINTING	\$1,800.00	1000
TOTAL	\$41,149.80	

21628-M
17302

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: