



Your Ref: 18.24926 PD-O

Date: 10th Sep 2018

Our Ref: CS3/ASM18011977/Bvbe2-1

M/s AXA Insurance Pte Ltd
C/O: Seah Ong & Partners LLP
36 Robinson Road
#12-03 City House
Singapore 068877
(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLA 8549J
INSURED VEHICLE: FBL 3881S
ACCIDENT DATE: 27/06/2018

We thank you for your instruction on 25/08/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLA 8549J from M/s C L Appraiser Pte Ltd.
- b) Singapore Accident Statement of Vehicles SLA 8549J.
- c) Colour damaged vehicle photographs of SLA 8549J.

Pre-Repair Inspection Date : 03/07/2018 at M/s Teamwork Garage Pte Ltd, 53 Ubi Avenue 1#01-24 Singapore 408934.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLA 8549J
Make & Model	: Toyota Estima Aeras
Chassis Number	: ACR500116793
Engine Capacity	: 2362 cc

2. We recommend that the repairs of the entire damage require about 8(Eight) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.