

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT			
SOMPO INSURANCE SINGAPORE PL		Ref: CS3/SMO1801559	96/Gz4d3e2
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWER SINGAPORE 048623		Date: 30-08-2018 8623	
		Code: SMO	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Ve	<b>h.</b> SKN 6533K	Veh. Inspected	FBC 5700R
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1803132/AGC	Excess (\$)	0.00
Assign Fro	m GRACE TEO	Assign Date	27/08/2018
2. Vehicle Particulars & Condition			
Make & Mo	del HONDA ANF 125MSS	c.c	125
Engine No.	. HIDDEN	Year of Reg.	2008
Chassis No	NF125MM5000689	Colour	BLACK
Odometer	18801 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front 1	<b>Tyre</b> 70/90-17	MICHELIN	5 mm
L/H Front T	Tyre		mm
R/H Rear T	yre 80/90-17	DUNLOP	5 mm
L/H Rear T	yre		mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S PORTION.		THE O/S BODY AND FRONT	
5. General Information			
Accident D	Pate 20/07/2018	Inspect Date / Time	28/08/2018 ( 05:20 PM )
Survey hel	d at MCS AUTO	•	
	NO. 1100 SERANGOON ROAD SINGAPORE 328195		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000			
5b. Estimate Days of Repair			
ESTIMATED	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days		

Report Ref No. CS3/SMO18015596/Gz4d3e2

Inspected By

**XING GUO QIANG** 

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A
Automotive Assessor

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.