



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :	Customer :
PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : QUAY SIEW TENG Tel : Email :	GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No. :

Quotation No. : QO18/08-1317	Quotation Date : 25/08/2018	Terms : 30 DAYS
Vehicle No. : SLP4866R	Chassis No. : MHFB29F3202012104	Third Party Insurer : III
Model : VIOS		Date of Accident : 30/07/2018
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	REAR BUMPER	1	505.0000 DE ✓	505.00
2	REAR BUMPER SIDE RETAINER LONG	2	120.0000 ?	240.00
3	REAR BUMPER SIDE RETAINER SHORT	2	45.0000 ?	90.00
4	REAR BUMPER CLIPS	10	10.0000 New ✓	100.00
5	REAR BUMPER REFLECTOR	2	215.0000 X	430.00
6	REAR REINFORCEMENT	1	135.0000 ?	135.00
7	REAR END PANEL	1	725.0000 repair ✓	725.00
8	REAR END PANEL TOP GARNISH	1	255.0000 ?	255.00
9	REAR END PANEL TOP GARNISH CLIPS	10	5.0000 ?	50.00
10	BOOTLID COVER	1	825.0000 repair ✓	825.00
11	BOOTLID HINGE	2	60.0000 X	120.00
12	BOOTLID LOCK	1	125.0000 X	125.00
13	BOOTLID 'TOYOTA' EMBLEM	1	60.0000 New ✓	60.00
14	BOOTLID 'VIOS' BADGE	1	55.0000 New ✓	55.00
15	BOOTLID 'E' BADGE	1	50.0000 New ✓	50.00
16	BOOTLID OUTER PROTECTOR	1	290.0000 X	290.00
17	BOOTLID INNER TRIM BOARD COVER	1	535.0000 X	535.00
18	BOOTLID INNER TRIM BOARD COVER CLIPS	10	3.5000 X	35.00
19	REAR TAILLAMP	2	325.0000 X	650.00
20	REAR TAILLAMP CLIPS	6	5.0000 X	30.00
21	REAR FENDER	2	915.0000 X	1,830.00
22	REAR FENDER SPLASH SHIELD	2	65.0000 X	130.00
23	REAR FENDER SPLASH SHIELD CLIPS	20	3.5000 X	70.00

C/F 0.00



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : QUAY SIEW TENG Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No :
--	--

Quotation No. : QO18/08-1317	Quotation Date : 25/08/2018	Terms : 30 DAYS
Vehicle No. : SLP4866R	Chassis No. : MHFB29F3202012104	Third Party Insurer : III
Model : VIOS	Date of Accident : 30/07/2018	
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
24	REAR SPARE TYRE PANEL	1	795.0000	795.00
25	REAR SPARE TYRE PANEL FLOOR BOARD	1	265.0000	265.00
26	LESS 20% (ITEM 1-26)	1	-1,735.0000	-1,735.00
27	REAR REVERSE SENSOR	2	280.0000	560.00
28	TO REMOVE AND REINSTALL REAR TRIMS, FLOOR CARPET AND SEAT TO FACILITATE REPAIR	1	150.0000	150.00
29	TO APPLY RUST PROOFING/TUFFICATING TREATMENT TO REPLACE PARTS	1	120.0000	120.00
30	TO REMOVE & REPLACED REAR BUMPER SENSOR	1	120.0000	120.00
31	TO REMOVE, REPLACED DAMAGED BODYPARTS, REPAIR & REALIGN BODYWORK & WHERE CONSISTENT TO THE ACCIDENT	1	1,200.0000	1,200.00
32	TO PUTTY & SPRAY PAINT ON THE AFFECTED AREAS.	1	1,200.0000	1,200.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
H/ 90010068
4 days
P/P
27/08/18 @ 1745
Resy by paint

Sub Total 10,010.00
GST(7.00%) 700.70
Total (SGD) 10,710.70

Please conduct the survey at
Pegasus Engineering @ 74 Kian Teck Road Singapore 628800