Veron Chen (LKKAuto)

From: Mastura <mastura@premiumauto.com.sg>
Sent: Tuesday, 19 February 2019 7:34 PM
To: Veron Chen (LKKAuto); SUR; 'Claims'

Subject: LOD - FINAL REVISION - SDS9809C - OD AIG - SURVEYED 28 AUG 18

Attachments: SAftersales19021919080.pdf

Dear Claims team,

Above attachment is for your perusal. We will pass the LOD to Adrian by hand shortly.

Thank you.

Best Regards,

Mastura

Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 **d.** +65 6768 9828 **f.** +65 6841 1183

e. mastura@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Veron Chen (LKKAuto) < veronchen@lkkauto.com>

Sent: Wednesday, 30 January 2019 9:58 AM

To: Boo seng yak <boojohnny@gmail.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: FINAL REVISION - SDS9809C - OD AIG - SURVEYED 28 AUG 18

Dear Mr Boo,

Confirm repair cost of \$6,813.76 before excess \$1600 and GST @ 6 days of repairs.

Kindly send us invoice and discharge voucher for us to close file.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak < boojohnny@gmail.com > Sent: Wednesday, 23 January 2019 4:06 PM

To: Adrian Ling (LKKAuto)
SUR <sur@lkkauto.com; Carrine Leong
carrine.leong@premiumauto.com.sg; jiayee.yap@premiumauto.com.sg; Chang Chee Sing

<claims@premiumauto.com.sg>

Subject: FINAL REVISION - SDS9809C - OD AIG - SURVEYED 28 AUG 18

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$6813.76 @ 6 days of repairs.

Photographs of roof liner removed is attached.

Your early closure is well appreciated.

Best regards - jb