

AUTOWORX HOUSE

C/O176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7423

ESTIMATE

TUNG SAI MENG
c/o 46 Lentor Plain
Singapore 786548

Not Authorized
11 Sep @?
Murray After Paint
4 days

Date: 28/8/2018

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE: VOLVO S60 / SKQ8039S	
1 pc	front fender	<i>Pr</i> 1,108.60 ✓
1 pc	front fender dust cover	<i>Pr</i> 316.00 X
1 pc	front bumper	1,613.70 ?
1 pc	front bumper side retainer	<i>Pr</i> 69.00 ✓
1 pc	front bumper fog lamp	<i>Pr</i> 578.00 ✓
1 pc	front bumper fog lamp garnish	<i>Pr</i> 262.00 X
1 pc	front head lamp	<i>Pr</i> 1,654.00 ✓
1 pc	front knuckle arm	<i>Pr</i> 897.20 X
1 pc	front wheel bearing	<i>Pr</i> 467.90 X
1 pc	front shock absorber	<i>Pr</i> 965.70 X
1 pc	front lower arm	<i>Pr</i> 857.80 X
1 pc	alloy rim	<i>Pr</i> 1,260.00 X
	sub-total	10,049.90
	less 5%	502.50
	sub-total	9,547.41
	To remove and replace all the parts mentioned above, panel beat and realign the necessary affected areas.	<i>4000</i> 700.00
	To check wiring system.	<i>200</i> 50.00
	To spray painting on affected areas.	<i>4500</i> 600.00
	To replace alloy rim & perform wheel balancing.	<i>200</i> 40.00
	To remove and install front undercarriage parts to enable repair.	<i>un</i> 200.00 X
	To perform 4 wheels computerised alignment.	<i>600</i> 80.00
	To apply rust proofing on affected areas.	<i>300</i> 180.00
	Total	11,397.41

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

(*Pr*)
sub-total
less 5%
sub-total