

ASS. REC. BY:

REP

CS/FCI18015676/Tlsd3ⁿ²

Special Instruction

SALES/INT

cws

Taufitch

ASSIGNMENT (Office)

From (Person)

May chua

of

FCI

Date/Time

28/8/18 @ 209pm

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SCP 1123C

Insured:

SHA7040M

at Workshop m/s

Weemmes

Tel:

98187217

of

45 lang Kee

Policy No:

Claim No:

D18006355MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

22/08/2018

(Client's Record)

Insp: 219 Alexander Rd

CA / REV / RET. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

3:06pm @ 28/8/18

Person Contacted:

Derek

Vehicle

IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SCP1123C - C03/AIG1500801/Rq bk3 DOA: 10/01/2015
	SHA7040M - C5/MSG15008322/Gq bk3 DOA: 24/02/13
30/08/18	@ 15:42 p.m. revised PA to May via email.
11/09/18	Confirmed plp \$8,180.16 @ 4 days with Taufitch (\$3,898.24 Red - 32%)

11/11/18

typist

REF.

FC1

ASSIGNMENT

From:

Date:

Estimated Cost

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No

at Workshop runs

of

Insured

Policy No.

Claims No

Sum Insured

Excess

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value

IDAC Accident Rpt:

Consistent? Yes or No

GIA / PR Seen

Consistent? Yes or No

Est. Repairs:

days

Res:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

wp

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date

Person Contacted

Val Reg:

SCP1123C

Val Reg:

2014 Dec.

Type: ☒ M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

VW 580

CC 1560

Colour:

Grey

A/C

Insured / Std / NI / NA

Sp Reading:

9/1096

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

yv17584 ABF1188 385

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 225/50K17

R:

~ ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTS / ☒ PIR / SUMI /

TOYO / YOKO or

Front

R/Bal:

6

mm

Rear

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A.

D.O.I.

28/8/18 @ 4:50pm

Survey held at

Womersley Alconeta

Des. of Damages: Frt / Rear ☒ O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

RECEIVED 14 SEP 2018

Date/Time File Pass to?

14/09/18

1) *Typist*

Date/Time File Return to?

2)

☐

: Preli. Report

☒

: Final Report

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

3 - P.C. 34

1 Shoes

1 Other:

Add Fee:

☐

Site Insp. £5

☐

Interview £5

☐

Tech. Insp. £5

☐

Witness £5

Report Format:

Lump Sum / LB £

8,180.16 P/R

2x15= 30

170+30
50

30

280



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18015678/T1sd3

36 ROBINSON ROAD

#16-01 CITY HOUSESINGAPORE 068877

Date : 28-08-2018

Code : FCI2



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 7040M	Veh. Inspected	SCP 1123C
Policy No.		Coverage (\$)	0.00
Claim No.	D18006355MFSH	Excess (\$)	0.00
Assign From	CWS (MAY CHUA)	Assign Date	28/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	22/08/2018	Inspection Date	28/08/2018
Survey held at	249 ALEXANDRA ROAD		
Repairer	WEARNES AUTOMOTIVE PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED THE



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18006355MFSH

Date: 30 August 2018

Our Ref: CS/FCI18015676/T1sd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SCP 1123C .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 28/08/2018 at the premises of M/s Wearnes Automotive Pte Ltd and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 12,078.40</u> .
Revised Estimate Amount	: <u>S\$ 8,728.40</u> .
"Check" Items Amount	: <u>S\$</u> .
Market Value	: <u>S\$</u> .
LTA Reimbursement Value	: <u>S\$</u> .
Nett Value	: <u>S\$</u> .

Description of Damage:

The vehicle sustained damages at the o/s body.



Comments/ Present Status:

Damages Consistent.

Repair days: 4 Days

Yours faithfully,
Mohamad Taufikh
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	24-08-2018	Our Ref No. D18006355MFSH
Accident Date	22-08-2018	Claim Type. Third Party
Insured Vehicle	SHA7040M	Third Party Vehicle. SCP1123C
Survey Location	45 LENG KEE ROAD	
Contact Person.	DEREK OH	
Contact No.	63789336/ 98187217	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	WEARNES AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 13 September 2018 3:34 PM
To: 'Richmond Ho'
Cc: 'Derek Oh Siong Wee'; 'SUR'
Subject: RE: Final Bill For SCP1123C

Hi Richmond,

Confirmed final fig of \$8,180.16 (part by part) @ 4 days of repairs before GST.

Final invoice and all supporting documents sent over to First Capital Ins Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]
Sent: Thursday, 6 September 2018 10:40 AM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>; Richmond Ho (richmond.ho@wearnes.com) <richmond.ho@wearnes.com>
Cc: Derek Oh Siong Wee <derek.oh@wearnes.com>
Subject: FW: Final Bill For SCP1123C
Importance: High

Dear Shirley,

FYNA-CS/FCII8015676/T1sd3

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Richmond Ho <richmond.ho@wearnes.com>
Sent: Wednesday, 5 September 2018 5:37 PM
To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Cc: Derek Oh Siong Wee <derek.oh@wearnes.com>
Subject: Final Bill For SCP1123C
Importance: High

Hi,

Please refer to above attachment for the final bill.

Richmond Ho
Senior Service Consultant
Body & Paint – Insurance Claim



Wearnes Automotive Pte Ltd
249 Alexandra Road Singapore 159935
D (65) 6430 4890 M (65) 9176 8543
www.wearnesauto.com richmond.ho@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 30 August 2018 3:42 PM
To: MAYCHUA@MSFIRSTCAPITAL.COM.SG; 'Claim Workflow System'
Cc: 'SUR'; 'Nivitha (LKK Auto)'; ASSIGNMENTS@LKKAUTO.COM
Subject: RE: SURVEY ASSESSMENT - D18006355MFSH/1
Attachments: SCP 1123C - Preli Advise.pdf

Dear May,

Enclosed herewith preliminary advice of SCP 1123C.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 28 August 2018 4:55 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; ASSIGNMENTS@LKKAUTO.COM
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; 'SUR' <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006355MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Tuesday, 28 August 2018 2:09 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; MAYCHUA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18006355MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.


Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

WEARNES AUTO PROTECTOR (VOLVO) PRIVATE VEHICLE

Name of Policyholder : MOK HEI WANG, PETER
 Period of Insurance : 26 Dec 2017 To 25 Dec 2018
 Engine No. : D4162T4173434
 Chassis No. : YV1AS84ABF1188385

Vehicle No. : SCP1123C
 Policy No. : 2100397256-03
 Endorsement No. :
 Issued Date : 15 Nov 2017

ABOUT THE COVER

Make/Model : VOLVO S80 D2
 Engine Capacity/Tonnage : 1,560.00 CC
 Driver Restriction : NA
 Sum Insured : Market Value
 Off Peak Car : No
 First Year of Registration : 2014
 Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are as Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition : 40 years old and above

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 2000cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$1000 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

MOK HEI WANG, PETER - \$1000 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Wearn's Automotive Pte Ltd Add: 249 Alexandra Road Singapore 159035 64304890 63789350

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: HONG LEONG FINANCE LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1969 (Malaysia).

0503485704

WEARNES AUTOMOTIVE - GG (V)
 45 LENG KEE ROAD
 SINGAPORE 159103

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

M. J. J. J.

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

SSCNKJ

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S2577655J



Name

MOK HEI WANG, PETER

莫 義 弘

Race

CHINESE

Date of birth

14-01-1962

Country/Place of birth

HONG KONG

Sex

M

S2577655J

REPUBLIC OF SINGAPORE DRIVING LICENCE




S2577655J

MOK HEI WANG, PETER

Valid Until: 14 Jan 1962

Issue Date: 15 Apr 2003



5691184



NRIC No. S2577655J



Date of issue

1B-01-2017

Address

APT BLK 262B COMPASSVALE STREET
#11-101
SINGAPORE 542262

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE

09 Jun 1990



Licence No: S2577655J

NP 428A



WEARNES

SERVICE ESTIMATE

78955 - C00001 SL: SERVICE SALES - PC

Mr Mok Hei Wang, Peter
Block 262b, Compassvale Street
#11-101

Singapore 542262

GST Reg.No: M28920628X

Inv.No. : B&P 0 Page 1

Inv.date : 24/08/2018

WIP No. : 23487

Veh.In/Out: 23/08/2018

*Tel.No. : Mobile: 97263450

Reg.No. : SCP1123C

Reg.date : 26/12/2014

Mileage : 0

Chassis No: YV1AS84ABF1188385

Closed by : Derek Oh Siong Wee

Svc Consultant :

Remarks : Mr Mok Hei Wang, Pet

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE FRONT RH DOOR, FRT RH DOOR TRIM, FRT RH DOOR SEAL, FRT RH WING MIRROR, FRT RH FENDER ETC	0	2400.00	0		2,400.00	S
-----	---	---	---------	---	--	----------	---

1600

800	TO PUTTY SPRAY PAINT ON FRT RH DOOR, FRT RH COVER, FRT RH FENDER, ETC	0	2800.00	0		2,800.00	S
-----	---	---	---------	---	--	----------	---

1000

802	TO TRANSFER FRONT RH DOOR PART	0	250.00	0		250.00	S
280	TO CHECK WIRING INCLUDE	0	450.00	0		450.00	S

RESETTING OF ALL ELECTRICAL MODULES

DOOR MIRROR RH S80 L	1.0 EA	581.90	505.71	581.90	S	mis
MIRROR GLASS RH S60	1.0 EA	210.50	189.45	210.50	S	mis
MIRROR BACK COVER RH	1.0 EA	285.90	257.31	285.90	S	mis
DOOR PANEL FRT RH S8	1.0 EA	2824.90	2594.42	2824.90	S	ad
FLANGE SCREW M05x14x	10.0 EA	2.60	2	26.00	S	new
DOOR SEAL PRIMARY FR	1.0 EA	230.90	217.31	230.90	S	rec

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanglim 97495749

WP

28/8/18 @ 1630

Resurvey before print

Sur @ lkkauto.com

4 days.

SERVICE ESTIMATE

78955 - C00001 SL: SERVICE SALES - PC

Mr Mok Hei Wang, Peter

Block 262b, Compassvale Street

#11-101

Singapore 542262

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 2

Inv.date : 24/08/2018

WIP No. : 23487

Veh.In/Out: 23/08/2018

*Tel.No. : Mobile: 97263450

Reg.No. : SCP1123C

Reg.date : 26/12/2014

Mileage : 0

Chassis No: YV1AS84ABFL188385

Closed by : Derek Oh Siong Wee

Svc Consultant :

Remarks : Mr Mok Hei Wang, Pet

Op.No	Description	Hech Qty	Price	Disc%	Pkg	Amount	g
	DOOR GUIDE CHROME RH	1.0 EA	394.50	355.05		394.50	3 at
	DOOR WAIST CHROME RH	1.0 EA	320.60	299.54		320.60	S ant
	DOOR HANDLE OUTER XC	1.0 EA	500.00			500.00	S Ry
	SOUND DEADENING PAD	1.0 EA	250.00	225.25		500.00	S nee
	ADHESIVE TUBE CHEMIC	4.0 EA	75.80	272.88		303.20	S nee

Gross Total. 12,078.40

Labour Total 5,900.00
 Parts Total 6,178.40
 Package Total 0.00

Net..... 12,078.40
 GST @ 7.0% 845.49
 Total..... 12,923.90
 Paid..... 0.00
 Please Pay.. 12,923.90

GST: S=StdRated; 0=OutOfScope; Z=ZeroRated

mcs

SERVICE ESTIMATE

O - F00003 SL: FIRST CAPITAL INSURANCE LTD
 FIRST CAPITAL INSURANCE LTD
 36 ROBINSON ROAD
 #16-01, CITY HOUSE
 SINGAPORE
 Singapore 068877

GST Reg.No: M28920628X
 Inv.No. : B&P 0 Page 1
 Inv.date : 05/09/2018
 WIP No. : 23487
 Veh.In/Out: 23/08/2018 05/09/2018
 *Tel.No. :
 Reg.No. : SCP1123C
 Reg.date : 26/12/2014
 Mileage : 0
 Chassis No: YV1AS84ABF1188385

Closed by : Richmond Ho
 Svc Consultant :
 Remarks : Mr Mok Hei Wang, Pet

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRONT RH DOOR, FRT RH DOOR TRIM, FRT RH DOOR SEAL, FRT RH WING MIRROR, FRT RH FENDER ETC	0	1600.00	0		1,600.00	S
800	TO PUTTY SPRAY PAINT ON FRT RH DOOR, FRT RH COVER, ETC	0	1000.00	0		1,000.00	S
802	TO TRANSFER FRONT RH DOOR PART	0	250.00	0		250.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	450.00	0		450.00	S
	DOOR MIRROR RH S80 ①	1.0 EA	581.90	10		523.71	S
	MIRROR GLASS RH S60 ②	1.0 EA	210.50	10		189.45	S
	MIRROR BACK COVER RH ③	1.0 EA	285.90	10		257.31	S
	DOOR PANEL FRT RH S8 ④	1.0 EA	2824.90	10		2,542.41	S
	DOOR SEAL PRIMARY FR ⑤	1.0 EA	230.90	10		207.81	S
	DOOR GUIDE CHROME RH ⑥	1.0 EA	394.50	10		355.05	S
	DOOR WAIST CHROME RH ⑦	1.0 EA	320.60	10		288.54	S

SERVICE ESTIMATE

0 - F00003 SL: FIRST CAPITAL INSURANCE LTD
 FIRST CAPITAL INSURANCE LTD
 36 ROBINSON ROAD
 #16-01, CITY HOUSE
 SINGAPORE
 Singapore 068877

GST Reg.No: M28920628X
 Inv.No. : B&P 0 Page 2
 Inv.date. : 05/09/2018
 WIP No. : 23487
 Veh.In/Out: 23/08/2018 05/09/2018
 *Tel.No. :
 Reg.No. : 3CP1123C
 Reg.date. : 26/12/2014
 Mileage : 0
 Chassis No: YV1AS84ABF1198385

Closed by : Richmond Ho
 Svc Consultant :
 Remarks : Mr Mok Hei Wang, Pet

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	SOUND DEADENING PAD 	1.0 EA	250.00	10		225.00	S
	ADHESIVE TUBE CHEMIC 	4.0 EA	75.80	10		272.88	S
	SEMS SCREW 	10.0 EA	2.00	10		18.00	S

				Gross Total.	8,180.16
Labour Total	3,300.00	Net.....		8,180.16	
Parts Total	4,880.16	GST @ 7.0%		572.61	
Package Total	0.00	Total.....		8,752.77	
				Paid.....	0.00
				Please Pay..	8,752.77

GST: S=StdRated; D=OutOfScope; Z=ZeroRated



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18015676/T1sd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 18-09-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 7040M	Veh. Inspected	SCP 1123C	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006355MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	28/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	VOLVO S80	c.c	1560	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	YV1AS84ABF1188385	Colour	GREY	
Odometer	91696	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R17	PIRELLI	6 mm	
L/H Front Tyre	225/50 R17	PIRELLI	6 mm	
R/H Rear Tyre	225/50 R17	PIRELLI	6 mm	
L/H Rear Tyre	225/50 R17	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/08/2018	Inspection Date	28/08/2018	
Survey held at	249 ALEXANDRA ROAD			
Repairer	WEARNES AUTOMOTIVE PTE LTD			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR.		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCP 1123C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	DOOR MIRROR RH S80 1 (SN)	MISSING	581.90	523.71
1	MIRROR GLASS RH S60 (SN)	MISSING	210.50	189.45
1	MIRROR BACK COVER RH (SN)	MISSING	285.90	257.31
1	DOOR PANEL FRT RH S8 (SN)	DENTED	2,824.90	2,542.41
10	FLANGE SCREW M05X14X (SN)	NECESSARY	26.00	18.00
1	DOOR SEAL PRIMARY FR (SN)	NECESSARY	230.90	207.81
1	DOOR GUIDE CHROME RH (SN)	CUT	394.50	355.05
1	DOOR WAIST CHROME RH (SN)	CUT	320.60	288.54
1	DOOR HANDLE OUTER XC (SN)	TO REPAIR SEE LABOUR	500.00	-
2	SOUND DEADENING PAD (SN)	NECESSARY (1 PC ONLY)	500.00	225.00
4	ADHESIVE TUBE CHEMIC (SN)	NECESSARY	303.20	272.88
			6,178.40	4,880.16
LABOUR				
	TO REPLACE FRONT RH DOOR, FRT RH DOOR TRIM, FRT RH DOOR SEAL, FRT RH WING MIRROR, FRT RH FENDER ETC. INCLUSIVE OF THE REPAIR OF DOOR HANDLE OUTER XC.		2,400.00	1,600.00
	TO PUTTY SPRAY PAINT ON FRT RH DOOR, FRT RH COVER, FRT RH FENDER, ETC.		2,800.00	1,000.00
	TO TRANSFER FRONT RH DOOR PART.		250.00	250.00
	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.		450.00	450.00
			5,900.00	3,300.00
GRAND TOTAL			12,078.40	8,180.16
RECOMMENDED COST OF REPAIRS				8,180.16

Report Ref No. CS/FC118015676/T1sd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.