


FALCON-AIR AUTO SERVICES PTE LTDCO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D**FALCON-AIR**AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way
#27-01 AXA Tower SINGAPORE 069542

Attention : Motor Claim Department

Contact : 63387288/68804625 Fax No. : 68804838

Estimate : ES707150

Date : 29/08/2018
Vehicle Num. : SJK 1476C
Make/Model : HYUNDAI AVANTE
Chassis/Eng# : KMHDU41BR8U573158
Accident Date : 27/08/2018
Claim No. :
Reference : 3PTY
Policy No. :

S/N Quantity Particular Unit Price Amount \$S

- LIST ITEMS :
1. 1 PC REAR BUMPER
 2. 1 PC N/S REAR BUMPER SIDE RETAINER
 3. 12 PC REAR BUMPER CLIPS
 4. 1 PC REAR BUMPER REINFORCEMENT
 5. 1 PC BOOT LID LOGO EMBLEM
 6. 1 PC BOOT LID AVANTE EMBLEM

List Total \$S :
20.00% Discount \$S :*50%?**Not Allowed
d/s \$1250/-
3 day.
Wh-ple. Hh-ry-*

245	756.00
24	24.00
5.00	60.00
11	342.00
11	58.00
11	55.00

1,295.00
259.00
1,036.00

1. 1 SET SPECIAL NETT ITEMS:
REVERSE SENSOR

Special Nett Total \$S :

11	250.00
250.00	

LABOUR :

TO CHECK LIGHT SYSTEM AND WIRING

INSTALL REVERSE SENSOR

TO REMOVE INNER TRIM, GARNISH AND ETC TO FACILITATE REPAIR AND TO FIX BACK

20	50.00
50	100.00
60	180.00

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7-840

29%

672

1602


FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

FALCON-AIR AUTO SERVICES PTE LTDCO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D**FALCON-AIR**AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way
#27-01 AXA Tower SINGAPORE 069542

Attention : Motor Claim Department

Contact : 63387288/68804625 Fax No. : 68804838

Estimate : ES707150

Date : 29/08/2018

Vehicle Num. : SJK 1476C

Make/Model : HYUNDAI AVANTE

Chassis/Eng# : KMHU41BR5U573158

Accident Date : 27/08/2018

Claim No. :

Reference : 3PTY

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

TO REMOVE NECESSARY PARTS TO REPAIR INNER PANEL, REPLACE
ACCIDENT DAMAGED PARTS AND ALIGN THE SAME
TO PUTTY AND RESPRAY ACCIDENT DAMAGED AREAS

300 500.00
500 600.00

Labour Total S\$:

1,430.00

930

E. & O.E.

Total S\$:

2,716.00

for FALCON AIR AUTO SERVICES PTE LTD

(TAMPINES BRANCH)

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg