

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9516D**AAD1808-223**

Not Authorised
61 Sep 8135d

Vehicle No.:

SHD 9516D

Chassis No.:

KL1LA69RJB091132

Vehicle Make:

CHEVROLET

Vehicle Model:

EPICA 2.0

Date of Accident :

27.8.2018

Third Party Insurer :

AIG**PART****LIST**

1	1	Rear Fender RH	\$	<i>R</i> 1,145.00 <i>X</i>
2	1	Rear Fender Inner Trim RH	\$	<i>SL</i> 418.44 <i>X</i>
3	1	Rear Bumper	\$	<i>Bu</i> 1,202.00 <i>✓</i>
4	1	Rear Bumper Beam	\$	<i>R</i> 239.94
5	1	Rear Bumper Centre Absorber	\$	<i>SL</i> 260.00
6	1	Rear Bumper Side Retainer RH	\$	<i>SL</i> 68.76
7	1	Rear Bumper Side Retainer LH	\$	<i>SL</i> 68.76
8	1	Rear Bumper Reflectors RH	\$	<i>SL</i> 119.74
9	1	Rear Bumper Reflectors LH	\$	<i>SL</i> 119.74
10	1	Rear Bumper Tow Hook Cover	\$	<i>SL</i> 93.00
11	1	Rear End Panel Outer	\$	<i>R</i> 623.76
12	1	Rear End Panel Inner Trim	\$	<i>SL</i> 263.84
13	1	Rear Tail Lamp RH	\$	<i>SL</i> 479.30
14	1	Rear Tail Lamp Inner Panel RH	\$	<i>R</i> 359.00

TOTAL	\$	5,461.28
10%	\$	546.13
	\$	4,915.15

Special Nett

1Set Rear Fender Inner Trim Clip RH

\$ *nn* 30.00 *X*

TOTAL	\$	30.00
--------------	-----------	--------------

TOTAL PARTS	\$	4,945.15
--------------------	-----------	-----------------

Trans-cab Auto Services Pte Ltd

AAD1808-223

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9516D

LABOUR

To Check Electrical Lighting Concerned.	\$	nn 170.00 X
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,100.00 2001
Putty and spray painting of the affected portion.	\$	2,100.00 4001
To check steering geometry and computer wheel alignment	\$	nn 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00 X
To rust-proofing of the affected areas.	\$	nn 170.00 X
To transfer of fender fittings, attachment and perform water seepage test.	\$	nn 170.00 X

TOTAL \$ **5,100.00****Over All Total** \$ **10,045.15****Repair Days (Lump Sum)****7 DAYS**

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: