

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 27 AUGUST 2018

Third Party Insurer: AIG

Vehicle No: SFE8129M

Third Party Veh No: SGT7519L

Model: MERCEDES BENZ GLC250

Date of Accident: 27 AUGUST 2018

Chassis: WDC2539462F135431

Not Ashark
1-B.1
Murray B. 6pm
4-5 days

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE <i>B1 ✓</i>		
1	REAR TAILGATE WEATHER STRIP <i>in X</i>		
1	REAR TAILGATE EMBLEM 'GLC 250' <i>in</i>		
1	REAR TAILGATE EMBLEM 'AMG' <i>in</i>		
1	REAR TAILGATE EMBLEM LOGO <i>in</i>		
3	REAR TAILGATE EMBLEM LOGO CLIPS <i>in</i>		
1	REAR TAILLAMP LOWER BRACKET RH <i>in X</i>		
1	REAR BUMPER <i>B1 ✓</i>		
1	REAR BUMPER REFLECTOR RH <i>?</i>		
2	REAR BUMPER REVERSE SENSOR <i>?</i>		
2	REAR BUMPER REVERSE SENSOR RUBBER SEAL <i>?</i>		
1	REAR BUMPER REVERSE SENSOR WIRE HARDNESS <i>?</i>		
1	REAR BUMPER SIDE RETAINER RH <i>in X</i>		
1	REAR BUMPER TOW HOOK COVER <i>in</i>		
1	REAR BUMPER REINFORCEMENT <i>?</i>		
1	REAR BUMPER LOWER BRACKET CENTRE <i>?</i>		
1	REAR BUMPER LOWER BRACKET RH <i>?</i>		
6	REAR BUMPER CLIPS <i>in</i>		
8	REAR BUMPER RIVETS <i>in</i>		
1	REAR BUMPER LOWER DIFFUSER <i>in</i>		
1	REAR BUMPER LOWER DIFFUSER SIDE RETAINER LH <i>?</i>		
1	REAR BUMPER LOWER DIFFUSER CHROME MOULDING <i>in</i>		
1	REAR EXHAUST END CHROME PIPE RH <i>in</i>		
1	REAR EXHAUST END CHROME PIPE BRACKET RH <i>?</i>		
1	REAR EXHAUST ALUMINIUM HEAT SHIELD <i>?</i>		
SUB TOTAL			\$0.00
Less 10%			\$0.00
PARTS TOTAL			\$0.00

QTY	SPECIAL NETT	UNIT S\$	AMOUNT S\$
1	REAR BUMPER TOP CHROME PAD <i>in</i>		
1	REAR BUMPER COATING <i>?</i>		
1	REAR TAILGATE COATING <i>?</i>		
S/N TOTAL			\$0.00

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date:	27 AUGUST 2018	Third Party Insurer:	AIG
Vehicle No:	SFE8129M	Third Party Veh No:	SGT7519L
Model:	MERCEDES BENZ GLC250	Date of Accident:	27 AUGUST 2018
Chassis:	WDC2539462F135431		

ESTIMATE

LABOUR CHARGES:

TO REMOVE & REPLACE WITH PANEL BEATING ALL ACCIDENT PORTION	\$1,000.00	5001
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	\$800.00	481
TO DIAGNOSTIC CHECK & RESET MEMORY TO IDENTIFICATION STANDARD	\$250.00	7
TO DISMANTLE & REPLACE REAR BUMPER REVERSE SENSOR	\$80.00	601
TO CHECK WIRING WITH WATER LEAKAGE TEST	\$60.00	201

LABOUR TOTAL	\$2,190.00
--------------	------------

PUI THENG

TOTAL