



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE PERFORMANCE

Company Registration No. 201118055N

ESTIMATE

Gallop Human Resource
Blk317 Jurong East Street 31 #02-32 Singapore
600317

Contact : 93632266

Code : C101825

Date in : 29/08/2018

Vehicle Num. : GBE5929M

Model : Mercedes Benz Citan 109 CDI Van E

xtra-Long - 2 Seaters

Chassis/Eng# : WDF4156052U166052/K9KB608D548661

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
Front Bumper Fog Lamp Garnish LH	1	192.00	192.00 ✓
Front Bumper Fog Lamp LH	1	135.00	135.00 ✗
Front Bumper Lower Centre Grille	1	116.80	116.80 ?
Front Bumper Side Bracket LH	1	152.00	152.00 ?
Front Bumper with Inner Bracket	1	1615.00	1,615.00 —
Front Grille 'Logo' Emblem	1	72.50	72.50 ?
Front Grille 'Logo' Emblem Small	1	68.50	68.50 ✓
Front Grille Base	1	225.80	225.80 ✗
Front Grille Chrome Moulding Set	1	483.80	483.80 ?
Front Grille Cover	1	332.50	332.50 ✓
Front Headlamp LH	1	368.30	368.30 ?
Subtotal before discount			3,762.20
Percentage discount	0%	10%	0.00
Sub-total 1			3,762.20
Front Bumper Clips (Set)(SN)	1	50.00	50.00 ✓
Front Bumper No. Plate (SN)	1	25.00	25.00 ✗
Front Bumper No. Plate Garnish (SN)	1	50.00	50.00 ✗



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE PERFORMANCE Company Registration No. 201118055N

Subtotal before discount	125.00
Percentage discount 0%	0.00
Sub-total 2	125.00
Parts-total	3,887.20

LABOUR

Description	Price
Diagnose, replace and/or repair to rectify front portion electrical system for proper functioning.	100.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	500.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	500.00
Labour Total	1,100.00
Parts & Labour Total	4,987.20

page 2

not Allowed
wku
30/8/18
3 dy.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: