

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

Ref: CS3/FCI18015809/Gz4d3s2 MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD

26-11-2018 Date:

Page No.:1 of 1

#16-0	1 CITY HOUSES						
			Code: FCI2				
1. Policy Particulars :- (THIRD PARTY CLAIM)							
	Insured Veh.	SHC 7273Y	Veh. Inspected	SKT 3170L			
	Policy No.		Coverage (\$)	0.00			
	Claim No.	D18006436MFSH	Excess (\$)	0.00			
	Assign From	SITHARA	Assign Date	29/08/2018			
2. Vehicle Particulars & Condition							
	Make & Model	TOYOTA AXIO	c.c	1496			
	Engine No.	HIDDEN	Year of Reg.				
	Chassis No.	NZE1617104151	Colour	SILVER			
	Odometer	211288 KM	Steering	IN ORDER			
	Brakes	IN ORDER	Modification	SPORTS RIM			
	General	GOOD					
3. Conditions of Tyres							
		Size	Make	Balance			
	R/H Front Tyre	195/60R15	DUNLOP	6 mm			
	L/H Front Tyre	195/60R15	DUNLOP	6 mm			
	R/H Rear Tyre	195/60R15	DUNLOP	6 mm			
	L/H Rear Tyre	195/60R15	DUNLOP	6 mm			
l.	. Description of Damages						
	THE VEHICLE SUS						
5. General Information							
	Accident Date	28/08/2018	Inspect Date / Time	30/08/2018 (04:15 PM)			

5.	General Information					
	Accident Date	28/08/2018	Inspect Date / Time	30/08/2018 (04:15 PM)		
	Survey held at	APEX MOTORING				
		25 KAKI BUKIT ROAD 4 #01-55 SYNERGY @ KB SINGPORE 417800.				

5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

D)MARKET VALUE:\$26,000.00

Report Ref No. CS3/FCI18015809/Gz4d3s2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

Automotive Assessor

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.