

INS. CASE OWNER:

CC 5, A16 180 15813, Axtas

INS. IDAC:

STORY

Wup

ASSIGNMENT

DOI: 19/1/18

Date / Time:

29/8/18
29/8/18

Registered in Merimen:

Pre-assign / CCU / FTE

SLE 53054



Insured Vehicle No.

Name of Insured

My Pit zhen

Insured Tel No.

HP: 84999896

Excess Sec II : S\$

D.O.A: 29/8/2018

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SLE 13926



INSRS:

WSP:

Tel:

Liability:

RMKS:

Premium



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

29/8/18

SLE 13926, X, SLE 53054, X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call Of:

After call ltr to OI:

2018-4-19

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

X

After call ltr to OI:

/

Authorisation To Act:

/

Release Voucher:

/

Final Repair Bill:

/

Car Rental Invoice:

X

Towing Invoice:

X

LTA / GIA:

X

Medical Bill:

X

PIR:

X

Mandate/Reject Instruction:

X

LOD:

/

Payment Breakdown Form:

Post-Repair Photos:

/

Others:

/

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

8-4-19

Confirm with:

NORA

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

22

Email

Call

Repair Cost:

S\$

3,257.72

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

200

(S100 x 2

days)

Loss of Income (LOI):

S\$

-

(S

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

-

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost:

S\$

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

S\$

3,457.72

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

3,457.72

Name 1:

PREMIUM AUTOMOBILES PTE LTD

Payee 2: (Strike if N/A)

S\$

X

Name 2:

✓

Payee 3: (Strike if N/A)

S\$

-

Name 3:

✓

COPY SENT 10/9/19

REF:

ASS. REC. BY Adrian Ling

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 hrs. days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLQ1392E Yr Regn: 2017 / JulyType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Audi A5 cc 1984Colour: White A/C: Insured / Std / NI / NASp. Reading: 28688 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZ2F5SHA033714Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 245/40R18R: 245/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 04/09/18Survey held at PremiumDes. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

QDA TP ALG.25.2.19 \$ 3,044.60R (\$ 1,590.40/34%)

Date/Time, File Pass in?

☐

: Prefi. Report

ii)

☐

: Final Report

Date/Time, File Return in?

iii)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ = RSL 59

) Fines:

) Other:

TOTAL

Report Format :

Lump Sum / L.B.I: (\$)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1020/2018/GW
Date : 1-Sep-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian
2 days - ok - jb - 13 Nov 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : MR Wee Qui-Cheng, Perlita
Address : 92 Hillview avenue
#03-01
Singapore 669592
Telephone : HP +65 93870777
Type of Claim : Third Party Claims
Policy No. : 2100510363-01
Vehicle No : **SLQ 1392 E**
Model Code : Audi A5 SB 2.0 TFSI
Model / Year : Jun-17
Engine No : CVK 034638
Chassis No : WAUZZZF55HA033714
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 29-Aug-18
Place of Accident : 51 Scotts Road Prudential @Scotts S228241 Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLQ 1392 E.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER GRILLE	\$ 171.00	
2	RADIATOR GRILLE	\$ 2,022.00	\$ 1,617.60
3	RADIATOR GRILLE COVER	\$ 165.00	
4	FRONT CAR PLATE	S/N \$ 25.00	\$ 25.00
5	SUNDRIES	\$ 300.00	
TOTAL SPARE PARTS		\$ 2,683.00	\$ 1,642.60
TOTAL LABOUR CHARGES		\$ 1,952.00	\$ 1,402.00
GRAND TOTAL		\$ 4,635.00	\$ 3,044.60

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

L&K Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLQ 1392 E

S/N	Nature of Jobs	Estimated Charges			
1	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N	\$ 480.00	\$	480.00
2	To dismantle front bumper. Re-organize front crash management components. Reinstall all parts removed.		\$ 1,050.00	\$	500.00
3	To reapply coating on front radiator grille.	S/N	\$ 230.00	\$	230.00
3	To carry out diagnostic check.	S/N	\$ 192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 1,952.00	\$	1,402.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLQ 1392 E

S/N	Nature of Jobs	Estimated Charges
1	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓
2	To dismantle front bumper. Re-organize front crash management components. Reinstall all parts removed.	\$ 1,050.00 500
3	To reapply coating on front radiator grille.	S/N \$ 230.00 ✓
3	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ 1,952.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLQ 1392 E.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER GRILLE <i>Not on</i>	\$ 171.00	+
2	RADIATOR GRILLE <i>Good</i>	\$ 2,022.00	✓ <i>K17.60</i>
3	RADIATOR GRILLE COVER <i>Not on</i>	\$ 165.00	+
4	FRONT CAR PLATE <i>New</i>	S/N \$ 25.00	✓
5	SUNDRIES <i>? NN</i>	\$ 300.00	+
TOTAL SPARE PARTS		:	\$ 2,683.00
TOTAL LABOUR CHARGES		:	\$ 1,952.00
GRAND TOTAL		:	\$ 4,635.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 04/09/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 02 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

QUOTATION

BILL TO :

Name : ANDY TEO
 Contact Number :
 Vehicle Make/Model/Colour : AUDI A5 SPORTBACK WHITE
 Vehicle Registration Number : SLQ 1392 E

DATE : 31/8/2018
 QUOTATION : Q 1808065
 VALID : 30 DAYS

DESCRIPTION	AMOUNT (SGD)
Re-application - Front Grill	230.00
Invoice paid for initial application - Date : 5/7/2017 Invoice : 175786 Warranty - TR120174163 Package - Extreme	

ESTIMATE : S 230.00

BILL TO :

Name : ANDY TEO
 Contact Number : 9387 0777

DATE : 5 July 2017

INVOICE : 175786

Vehicle Make/Model/Colour : AUDI A5 SPORTBACK WHITE

Vehicle Registration Number : SLQ 1392 E

Payment Mode : CASH / NETS / CREDIT

DESCRIPTION	AMOUNT
Extreme Packages	\$ 1,908.00
Discount on Package - 20%	\$ (381.60)
Booking Deposit Paid - Invoice: 175759	\$ (200.00)
Promotion Inclusive Ceramic PRO Umbrella Ceramic PRO Leather	
Warranty Number - 20174163 ◆ Ceramic PRO Care - Newly Applied ◆ ✓ Do not use Shampoo for the 1st 3 days ✓ Keep the surface dry. If surface get wet, Dab the surface dry with a lightly damp Microfiber towel. Do Not use Wiping motion. ✓ In event any substances land on the surface, clean up as soon as possible ◆ Basic Care for Owners ◆ ✓ Weekly wash with Quality Shampoo and dry with clean chamois cloth. ✓ Remove bird dropping, tree saps as soon as possible. Soften the substances with tissue soaked with water. Gently lift the substances off. Do not rub or use force. ✓ Apply Ceramic PRO SPORT after shampoo wash every fortnightly Ceramic PRO Prestige card will be mailed to the address provided on warranty registration. * Please register your warranty online to be effective within 14 days http://www.ceramicpro.com.sg/warranty-register/	
TOTAL :	\$ 1,326.40
TOTAL DUE AFTER 3% DISCOUNT ON FINAL BILL :	1,286.61
Parking Rebate :	\$ (9.00)
Total Paid :	\$ 1,277.61

9 Yishun Industrial Street 1 #01-69/70 North Spring Bizhub Singapore 768163

T: +65 6710 7793 | E: info@sppaintprotection.com

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: CC3/AIG18015813/ua3

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/TP/1020/2018/MAS

26 March 2019

Dear Sir,

RE: INSURANCE CLAIM FOR SLQ 1392 E, Audi A5 SB 2.0 TFSI S-Tro

With reference to the above-mentioned vehicle, no. **SLQ 1392 E**, claimant, **Ms. Wee Qui-Cheng, Perlita**, please find the related document as per attached.

1. A copy of the Original invoice no. 85013556 – S\$3,257.72
2. A copy of Authorization to Act duly signed by client
3. A copy of the Release Voucher attached
4. A copy of Breakdown of Payment attached
5. Loss of Use – S\$200.00 (S\$100.00 x 2 working days)

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – SLQ 1392 E

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

BREAKDOWN OF PAYMENT

Vehicle No: SLQ 1392 E

Accident on 29/08/2018 at 51 Scotts Road Prudential @ Scotts

Involving vehicle/s SLE 5305 E

1) Repair cost \$ 3,257.72

Payable to: Premium Automobiles Pte Ltd

2) GIA/LTA search fee \$ —

Payable to: Premium Automobiles Pte Ltd

3) Loss of Use or
Rental Car \$ 200.00

Payable to: Perlita Wee Qui-Cheng

4) Medical fees \$

Payable to:

5) Others \$

Payable to:

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7336065Z



Name
TEO SIN KUAN, ANDY LUKE
(ZHANG XINGGUANG)
张星光

Race
CHINESE

Date of birth
05-10-1973

Sex
M

Country of birth
SINGAPORE




REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number S7336065Z

Name
TEO SIN KUAN
(ZHANG XINGGUANG)

Birth Date 05 Oct 1973

Issue Date 13 May 2003





3488214



APRIC No. S7336065Z



Date of issue
03-02-2004

92 HILLVIEW AVENUE #03-01
HILLBROOKS SINGAPORE 669592


APRIC No. S7336065Z Date: 26/08/2009 No: 6177897

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

PASS DATE
20 May 1997

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

Licence No: S7336065Z



NP 426A

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : WEE QUI-CHENG, PERLITA
Period of Insurance : 28 Jun 2018 To 27 Jun 2019
Engine No. : CVK034838
Chassis No. : WAUZZZF55HA033714

Vehicle No. : SLQ1392E
Policy No. : 2100510363-01
Endorsement No. :
Issued Date : 25 Jun 2018

ABOUT THE COVER

Make/Model : AUDI A5 Sportback 2.0TFSI S Tronic (Design)
Engine Capacity/Tonnage : 1,984.00 CC **Sum Insured** : Market Value **First Year of Registration** : 2017
Driver Restriction : NA **Off Peak Car** : No **Insuring with COE/PAF** : Yes

Person or Classes of Persons Entitled to Drive* :

- a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$0 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

WEE QUI-CHENG, PERLITA

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662223

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125261

PREMIUM LEASING -CYS

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

50PMUJ

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Monday, 8 April 2019 5:30 PM
To: dennynngpz@yahoo.com
Cc: Admin A
Subject: ACCIDENT INVOLVING SLE 5305U AND SLQ 1392E ON 29/08/2018

Our ref: CC6/AIG18015813/Aja3

NG PIT ZHEN

Policy Holder

Dear Sir/Madam,

ACCIDENT INVOLVING SLE 5305U AND SLQ 1392E ON 29/08/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us.

We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

AUTHORISATION TO ACT
(AIG Express Third Party Claim)

I, Perlita Wee Qui-Cheng (the third party claimant) of 92 Hillview Avenue
#03-01 Singapore 669592 (address), owner of SLQ 1392 E (vehicle no.)
hereby authorize Premium Automobiles Pte Ltd ("the workshop") to act for me
with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle
no. SLQ 1392 E that was damaged pursuant to the accident which occurred on 29/08/2018
(date) along 51 Scotts Road Prudential @ Scotts (location) involving vehicle no/s
SLE 5305 E ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit
and the workshop is further authorized to receive payment further to settlement of my claim with
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 13 (day) of Oct (month) 2018 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)

RELEASE VOUCHER
(AIG Express Third Party Claim)

"We/I, Premium Automobiles Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$ 3,157.72 (Repair Cost), S\$ 200.00 (Loss of ~~rental~~ use), S\$ - (Disbursement), for vehicle no. SLQ 1392 E that was damaged pursuant to the accident which occurred on 29/08/2018 (date) along 51 Scotts Road Prudential @ Scotts (location) involving vehicle no/s SLE 5305 E. This is pursuant to the inspection conducted on 04/09/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Perlita Wee Qui-Cheng ("the third party claimant") of vehicle no. SLQ 1392 E make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLQ 1392 E (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 10 (day) of 04 (month) 2019 (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)



Premium Automobiles Pte Ltd

Audi Centre Singapore
201 Alexandra Road
Singapore 119938
Main Telephone: 6816 2223
Main Telefax: 6471 5733

Alexandra Service Centre
201 Alexandra Road
Singapore 119938
Telephone: 6388 2223
Telefax: 6471 1033

Ubi Service Centre
55 Ubi Road 1
Singapore 408809
Telephone: 6388 2223

Customer Service
Service Appointment
Service Breakdown Service
Email: customer.care@premiumauto.com.sg

6388 2223
6828 1233

INSURANCE INVOICE

Company Reg. No. 099902271W
GST Reg. No. 199902271W

Page 1 14:45

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice: 85013556
Date: 07/03/2019
Order: SLD1392E
Term: 30

Account: A0006 IT 01
AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No.: SLD1392E (V 33759) Regn Dates: 28/06/2017 Mileages: 35450 WIP No.: 22856
Model: A5 SPORTBACK 2.0 TFSI S tronic Chassis: WAUZZZF55HA033714 Engine: CVK 034838 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE	25.00	1.00	25.00
S	BODYWORK	M: TO REMOVE AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	488.00	1.00	488.00
S	BODYWORK	M: TO DISMANTLE FRONT BUMPER, REORGANISE CRASH MANAGEMENT COMPONENTS, REINSTALL ALL PARTS REMOVED	500.00	1.00	500.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
Q	OTHERS	M: TO REAPPLY COATING ON FRONT RADIATOR GRILLE	238.00	1.00	238.00
X	RAW6853651R RAW	(A) (GER) GRILLE (13/09) Less 020%	1.00	2022.00	1,617.60

Parts 1,617.60
Labour 238.00
Sublet 1,197.00
Menus 0.00
Lubricant 0.00

Sub-Total 3,044.60
7% GST 213.12
Grand Total 3,257.72

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Aug 2018 Edit Reg		04 Sep 2018 00:00 Edit Adj Rpt	\$53,044.60 Edit Estimates	\$53,044.60 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: Ng Pit Zhen , ID: 58338407G									
Main Claimant: WEE QUI-CHENG, PERLITA , ID: 57721461E									
Vehicle Reg. No.:	SLQ1392E	Date of Loss:	29/08/2018 09:00 - :59 [14 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 6639005351SG	Policy/Cover Note No.:	2100478620 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLE5305U	Policy No. (Claimant):	2100510363-01						
		Excess:							
Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com									
Claimant's Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 07/09/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLQ1392E (6639005351SG)
[SLE5305U]
TP
WEE QUI-CHENG, PERLITA
Aug 29 2018 9:00AM
[Ng Pit Zhen]
Premium Automobiles Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences			1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	1	Edit
Photos/Images			3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	25/02/19 18:53	General View	1	Load JPG <input checked="" type="checkbox"/>
2	25/02/19 18:53	General View	1	Load JPG <input checked="" type="checkbox"/>
3	25/02/19 18:53	General View	1	Load JPG <input checked="" type="checkbox"/>
4	25/02/19 18:53	General View	1	Load JPG <input checked="" type="checkbox"/>
5	25/02/19 18:53	General View	1	Load JPG <input checked="" type="checkbox"/>
6	25/02/19 18:53	General View	1	Load JPG <input checked="" type="checkbox"/>
7	25/02/19 18:53	General View	1	Load JPG <input checked="" type="checkbox"/>
8	25/02/19 18:53	General View	1	Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	29/08/18 19:47	TP GIA REPORT	1	Load PDF
2	03/09/18 13:15	TP ESTIMATE	1	Load PDF
3	05/09/18 17:27	TP ESTIMATE - MARKED	1	Load PDF
4	12/04/19 15:11	WORKSHOP INVOICE	1	Load PDF
5	12/04/19 15:11	AUTHORISATION TO ACT FORM	1	Load PDF
6	12/04/19 15:11	Release Voucher	1	Load PDF
7	12/04/19 15:11	LETTER TO OI	1	Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	30/08/18 08:46	OI GIA REPORT	1	Load PDF

Documents Checklist

DOCUMENTS CHECKLIST		Reset Save Print
There are no document checklists configured.		
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>		
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>		

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLE5305U (Insd veh)	Model:	AUDI A5 2.0 (A)
	SLQ1392E (TP veh)		
Date of Accident:	29/08/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$	4,959.45	
Final Repair Cost	:	\$	3,257.72	
Loss of Use	:	\$	200.00	2.00 days at \$100.00 per day
Rental (if any)	:	\$	0.00	days
LTA / GIA Search Fee	:	\$	0.00	
Others:	:	\$	0.00	
	:	\$		
Final Settlement Sum	:	\$	3,457.72	

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop:** Agreed Liability _____ (%)

B) For **GIA Registered Workshop:** BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Premium Automobiles Pte Ltd	:	\$ 3,457.72
2)		:	\$

JOANNE LEE KHANG MIN

12 Apr
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18015813/AJA3Q2

Date: 12/04/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100478620
Claimant Vehicle No : SLQ1392E **Insured Vehicle No :** SLE5305U
 Date of Loss: 29/08/2018 Nature of Claim: TP Claim No: 6639005351SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLQ1392E**
 Make & Model: AUDI A5, 2.0 (A) Engine No: CVK034838
 Reg. Date: 28/06/2017 (Man. Year: 2017) Chassis No: WAUZZZF55HA033714
 Colour: White Odometer: 28688 km
 Engine Capacity: 1984 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18
 Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
 Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,683.00	1,642.60	1,040.40	38.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,952.00	1,402.00	550.00	28.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,635.00	3,044.60	1,590.40	34.31
+ GST 7.00/7.00% (S\$)	324.45	213.12	111.33	34.31
Nett Amount (S\$)	4,959.45	3,257.72	1,701.73	34.31
+ Loss of Use (2.0 x S\$100.00/day) (S\$)		200.00		
Nett Liability (S\$)		3,457.72		

INSPECTION

Date of Assignment: 04/09/2018
 Date Inspected: 04/09/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
 55 Ubi Road 1
 Singapore 408699
 Estimated Period of Repair: 2.0 days

Adjuster: ADRIAN LING

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER GRILLE	Not Necessary	171.00 FS	*- FS
2	1		*RADIATOR GRILLE	Cracked	2,022.00 FS	*1,617.60 FS
3	1		*RADIATOR GRILLE COVER	Not Necessary	165.00 FS	*- FS
4	1		*FRONT CAR PLATE	Necessary	25.00 FS	*25.00 FS
5	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
Total Parts (S\$)					2,683.00	1,642.60

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE FRONT BUMPER .RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
3	TO REAPPLY COATING ON FRONT RADIATOR GRILLE	New	230.00	230.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			1,952.00	1,402.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >