

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1020/2018/GW
Date : 1-Sep-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : MR Wee Qui-Cheng, Perlita
Address : 92 Hillview avenue
#03-01
Singapore 669592
Telephone : HP +65 93870777
Type of Claim : Third Party Claims
Policy No. : 2100510363-01
Vehicle No : **SLQ 1392 E**
Model Code : Audi A5 SB 2.0 TFSI
Model / Year : Jun-17
Engine No : CVK 034838
Chassis No : WAUZZZF55HA033714
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 29-Aug-18
Place of Accident : 51 Scotts Road Prudential @Scotts S228241 Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLQ 1392 E

S/N	Nature of Jobs	Estimated Charges
1	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00
2	To dismantle front bumper. Re-organize front crash management components. Reinstall all parts removed.	\$ 1,050.00
3	To carry out diagnostic check.	S/N \$ 192.00
TOTAL LABOUR CHARGES		: \$ 1,722.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLQ 1392 E.

S/N	Parts Description	<u>Damage Parts & Prices</u>	
		S/NETT	REMARKS
1	FRONT BUMPER GRILLE	\$ 171.00	
2	RADIATOR GRILLE	\$ 2,022.00	
3	RADIATOR GRILLE COVER	\$ 165.00	
4	FRONT CAR PLATE	S/N \$ 25.00	
5	SUNDRIES	\$ 300.00	
TOTAL SPARE PARTS		: \$ 2,683.00	
TOTAL LABOUR CHARGES		: \$ 1,722.00	
GRAND TOTAL		: \$ 4,405.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant