


SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHD6225M
Ref. No : TAX/08/18/2107
Reg. Date : 05/10/2015
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS
Name of Driver : FOO CHENG HUAT JACK
Type of Accident : SIDE SWIPE
Date / Time of Accident : 29/08/2018 12:20:00 PM
Accident Reported Date / Time : 29/08/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024097734
Special Instruction to ARC,if any :
SJC318A
Prepared Date : 29/08/2018 01:41:26 PM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U305766183

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 845.00	0.00
Total Spray Painting Charges	: 2,052.00	0.00
Total Material Charges	: 4,789.93	4,789.93
Other Charges	: 1,413.76	0.00
TOTAL	: 9,100.69	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 5.00	0.00 4
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 29/08/2018 06:55:42 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 29/08/2018 06:55:42 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	845.00	0.00
Total Labour	845.00 <i>800</i>	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR RH	378.00 <i>200</i>	0.00
TO RESPRAY REAR DOOR RH	378.00 <i>200</i>	0.00
TO RESPRAY FRONT FENDER RH	378.00 <i>200</i>	0.00
TO REPSRAY FRONT BUMPER	378.00 <i>200</i>	0.00
TO RESPRAY ROCKER PANEL MOULDING	180.00 <i>80</i>	0.00
TO RESPRAY RIM	180.00 <i>80</i>	0.00
TO RESPRAY DOOR HANDLE	180.00 <i>20</i>	0.00
Total Spray Painting & Panel Beating	2,052.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00 <i>20</i>	0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00 <i>40</i>	0.00
TO TRANSFER DOOR MECHANISM	240.00 <i>X 110 11</i>	0.00
TO REPLACE SUNDRY PARTS	100.00 <i>X 11</i>	0.00
TO WASH AND VACUUM	60.00 <i>X 11</i>	0.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	593.76 <i>/ net</i>	0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00 <i>20</i>	0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00 <i>X 11</i>	0.00
Total Other Costs	1,413.76	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
67001-47070		6505528	DOOR FRT/RH	1	894.40	25.00	670.80	Replace	Replace	No <i>x R</i>
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace	No <i>rec</i>
75851-47900			MOULDING BODY, RH	1	673.60	25.00	505.20	Replace	Replace	No <i>x R</i>
67003-47080		6505486	DOOR RR/RH	1	954.50	25.00	715.87	Replace	Replace	No <i>x R</i>
			PIXEL STICKER	1	60.00	0.00	60.00	Replace	Replace	No <i>rec</i>
53801-47050		6505557	FENDER FRT/RH	1	723.40	25.00	542.55	Replace	Replace	No <i>x R</i>
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No <i>rec</i>
53875-47030		6505553	FENDER LINER FRT/RH	1	171.70	25.00	128.77	Replace	Replace	No <i>x s v</i>
53851-47040			FENDER LINER PAD, FR WHEEL. RH	1	49.30	25.00	36.97	Replace	Replace	No <i>x s v</i>
42611--47140 (Frt)		6505658	WHEEL DISC. FRONT	1	1,484.20	25.00	1,113.15	Replace	Replace	No <i>x R</i>
52119-47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace	No <i>x R</i>
69210-74030			DOOR OUTER HANDLE FRT/RH	1	370.80	25.00	278.10	Replace	Replace	No <i>sc</i>
TOTAL MATERIALS							4,511.85	4,511.83		
TOTAL MATERIALS(Discounted)							4,789.93	4,789.93		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

NA2 LKIC
 4/9/18 1630
 PIP
 4 Days
 BEFORE PAINT PHOTO

LK Auto Consultants hence notify the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer
 Signature:
 Date: