

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9134Y**AAD1808-217***Not Authorised
L1 Sing 86006*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 9134Y

KL1LA69RJBB055347

CHEVROLET

EPICA 2.0

26.8.2018

AXA**PART****LIST**

1	1	Rear Fender RH	\$	<i>R</i>	1,145.00	<i>X</i>
2	1	Rear Fender Inner Trim RH	\$	<i>Sm</i>	418.44	
3	1	Rear Bumper	\$	<i>R</i>	1,202.00	
4	1	Rear Bumper Beam	\$	<i>R</i>	239.94	
5	1	Rear Bumper Centre Absorber	\$	<i>Sm</i>	260.00	
6	1	Rear Bumper Side Retainer RH	\$	<i>Sm</i>	68.76	
7	1	Rear Bumper Side Retainer LH	\$	<i>Sm</i>	68.76	
8	1	Rear Bumper Reflectors RH	\$	<i>Sm</i>	119.74	
9	1	Rear Bumper Reflectors LH	\$	<i>Sm</i>	119.74	
10	1	Rear Bumper Tow Hook Cover	\$	<i>Sm</i>	93.00	
11	1	Rear End Panel Outer	\$	<i>R</i>	623.76	
12	1	Rear End Panel Inner Trim	\$	<i>Sm</i>	263.84	
13	1	Rear Tail Lamp RH	\$	<i>CM</i>	479.30	<i>X</i>
14	1	Rear Tail Lamp Inner Panel RH	\$	<i>R</i>	359.00	

TOTAL	\$	5,461.28
10%	\$	546.13
	\$	4,915.15

Special Nett1Set Rear Fender Inner Trim Clip RH \$ *nn* 30.00 *X*

TOTAL	\$	30.00
--------------	-----------	--------------

TOTAL PARTS	\$	4,945.15
--------------------	-----------	-----------------

Trans-cab Auto Services Pte Ltd

AAD1808-217

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9134Y

LABOUR

To Check Electrical Lighting Concerned.	\$	170.00	201
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,100.00	801
Putty and spray painting of the affected portion.	\$	2,100.00	2001
To check steering geometry and computer wheel alignment	\$	220.00	nn X
To transfer of tire, rim and on wheel balancing.	\$	170.00	nn X
To rust-proofing of the affected areas.	\$	170.00	nn X
To transfer of fender fittings, attachment and perform water seepage test.	\$	170.00	nn X

TOTAL	\$	5,100.00
--------------	-----------	-----------------

Over All Total	\$	10,045.15
-----------------------	-----------	------------------

Repair Days (Lump Sum)**7 DAYS****1 day**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: