

ESTIMATED ACCIDENT REPAIR COST



ACCIDENT TIME REPORTED	0815HRS
ACCIDENT DATE	28-Aug-18
BUS CAPTAIN NAME	MOHD TALMEZEE BIN OTHMAN
EMPLOYEE NUMBER	

BUS REGISTRATION NUMBER	SBS6370T
BUS TYPE (SD/DD)	SD
BUS ROUTE NUMBER	
BUS ADVERTS (Y/N)	N

SECTION 1: PARTS & CONSUMABLE ITEMS (MATERIAL COST)

Part No.	Part or Item Description	Quantity	Total Cost
77200607	FRONT BUMPER	1	CRA / \$701.56
77200122	BUMPER FRONT O/S	1	CRA / \$784.55
77201196	HEADLAMP RH	1	820 / \$369.20
77014639	BLINKER LAMP O/S	1	720 / \$54.80
77201026	LOCK FOR O/S BUMPER	1	PA / \$41.60
77201028	FASTENER (FRONT O/S BUMPER)		14 / \$12.35
		7% GST	\$137.48
		FINAL TOTAL COST	\$2,101.54

SECTION 2: ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)	TOTAL COST
TO REPLACE/REPAIR THE DAMAGED PARTS (INCLUDING SPRAY PAINTING)	3300 / \$4,380.00
	7% GST
	\$304.50
	FINAL TOTAL COST
	\$4,654.50

ESTIMATED ACCIDENT REPAIR COST



SECTION 5: REPAIRS TO BUS ADVERTISEMENT VINYL/PANELS (ADVERTISEMENT COST)

TOTAL ADVERTISEMENT REPAIR COST	-
---------------------------------	---

SECTION 6: RECOVERY OF ACCIDENT BUS (TOWING COST)

TOTAL TOWING COST	-
-------------------	---

SECTION 7: NUMBER OF DAYS UNDER ACCIDENT REPAIR (LOSS OF USE COST)

		Date In For Repairs	31/8/2018
		Date Out From Repairs	5/9/2018
		Number of Days Under Repair	5
BUS TYPE (SD / DD)	SD		
LOSS OF USE COST		\$1,500.00	

SUMMARY	
SECTION NO.	COST
1	\$2,101.54
2	\$4,654.50
3	-
4	-
5	\$1,500.00
ESTIMATED ACCIDENT REPAIR COST (1+2+3+4+5)	\$8,256.04

Rashid
Hp 90010068
5 days
31/08/18 @ 1415 hrs