

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623 Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No SG1104R

Ref. No BUS/08/18/1024

Reg. Date 01/01/1900 2/6/2016

Vehicle Type **BUS-12M**

Model Make MB CITARO 0530

MB CITARO MERCEDES

Name of Driver Quek Kim Hooi

Type of Accident HEAD-ON

ISIMIZ 🙈

Date / Time of Accident 18/08/2018 09:56:00 AM

Accident Reported Date / Time: 20/08/2018 12:00:00 AM

Surveyor is Required? Yes

Survey by

Vehicle is Towed Back? N_O

Towed Back Date/Time

Replacement Vehicle issued? : Z₀


Accident Repair Job Card No

Special Instruction to ARC, if any

BUS RIGHT REAR PORTION DAMAGED TP: SKW5696H (FWD INSURANCE)

Prepared Date

21/08/2018 11:41:02 AM



Work Shop : Chassis No : Mileage Repair Completed Date / Time : 0

Summary of Repair Estimates

Total Labout Charges : 1,060.00 0.00 Total Spray Painting Charges : 432.00 0.00 Total Material Charges : 0.00 0.00			Quotation from ARC	Adjusted by Surveyor, if applicable
arges : 432.00 : 0.00	Total Labout Charges	• •	1,060.00	0.00
0.00	Total Spray Painting Charges	• •	432.00	0.00
	Total Material Charges		0.00	0.00

Prepared / Adjusted By No. of Repair Days Lum Sum Total 0.00

TOTAL

Other Charges

0.00

1,492.00

Arc / Surveyor Sing Off Date

3.00 7.00

0.00

0.00 0.00

RA

0.00

01/01/1900 12:00:00 AM

: 30/08/2018 09:12:54 AM

Prepared / Adjusted Date

Remarks

Prepared Date : 30/08/2018 09:12:54 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Invoice No

Invoice Date

Quotation Date Invoice Amount :

Quotation No

Prepared Date:

BUS/08/18/1024

Page:

N

		וטנמו במשטמי
0.00	1,060.00 \$30	
		TO KETAIX XII XELY TO TO TO
0.00	1,060.00	TO SEE DIE DE LA BORTION
8		Job Scope
Adjusted by Surveyor, it applicable	Quotation from ARC	
older: I a series of the serie		

Part 2 - Spray Painting & Panel Beating Related Works

		Clare all clares
0.00	432.00 300	
		AND KINTKAY ADOVE SEE SINCE
		TEMS
0.00	432 00	
		JOB OCOPE
	Muoration Hom Six	
Adjusted by Surveyor, if applicable		
		0
		- 1:

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Total Other Costs	Job Scope	
		Quotation from ARC
		Adjusted by Surveyor, if applicable

PIP 2 DAY ATTER REPAIR PHOTO 3018/18 1600

LICK Auto Consultants hence notify

- the Repairer of the following:
- To resurvey before/after spray painting
- To diaplay damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

1

Added Spare Parts / Material Usage After Surveyor Signed off

TOTAL SUPPLEMENTARY MATERIALS	N. Salah	Activature ක්රමුණ විදු පිළඳුකැණ.			ILS	TERIA	TAL SUPPLEMENTARY MAT	TO	
Part Name Qty List Price Discount Final Price ARC Check Surveyor LT (\$) (\$) (\$) Check Check	1	Check	(\$)	(%)	List Price (\$)	Qty	Part Name	Portion	Part Number