

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHD6111H
Ref. No : TAX/08/18/2109
Reg. Date : 23/10/2015
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS
Name of Driver : NGAN FOOK LAM
Type of Accident : HEAD TO REAR
Date / Time of Accident : 29/08/2018 01:20:00 PM
Accident Reported Date / Time : 29/08/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024097735
Special Instruction to ARC, if any :
SJS895R - AIG - LKK
Prepared Date : 29/08/2018 03:26:16 PM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U805766471

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	676.00	0.00
Total Spray Painting Charges :	936.00	0.00
Total Material Charges :	2,340.32	2,340.32
Other Charges :	876.88	0.00
TOTAL :	4,829.20	0.00
Lum Sum Total :	0.00	0.00
No. of Repair Days :	5.00 <i>2,00</i>	0.00
Prepared / Adjusted By :		
Arc / Surveyor Sing Off Date :	29/08/2018 07:31:26 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 29/08/2018 07:31:26 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 8/29/2018 7:34:09 PM

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH REAR PORTION	676.00	0.00
Total Labour	676.00 400	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00 200	0.00
TO RESPRAY REAR FENDER RH	378.00 200	0.00
TO RESPRAY TAIL LAMP PANEL RH	180.00 100	0.00
Total Spray Painting & Panel Beating	936.00 500	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	0.00
TO CHECK WIRING AND SYSTEM FUNCTION	80.00 20	0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00 40	0.00
TO REPLACE SUNDRY PARTS	100.00 Xnn	0.00
TO WASH AND VACUUM	60.00 Xnn	0.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00 Xnn	0.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00 20	0.00
Total Other Costs	876.88	0.00

NALKK
P/R
30/8/18 1445
P/P
2 Days
AFTER REPAIR PHOTO
BEFORE PAINT PHOTO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace	No <i>x R</i>
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No <i>/ nec</i>
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace	No <i>?</i>
90467-07211			BUMPER CLIPS	10	2.10	25.00	15.75	Replace	Replace	No <i>?</i>
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace	Replace	No <i>?</i>
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Replace	No <i>?</i>
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No <i>x s v c</i>
81551-47180		6505462	TAIL LAMP RH	1	557.80	10.00	502.02	Replace	Replace	No <i>/ CR</i>
52562-47010			TAIL LAMP BRACKET, RH	1	30.70	25.00	23.02	Replace	Replace	No <i>?</i>
76087-47020		6505618	BUMPER LIP COVER RR/RH	1	118.10	25.00	88.57	Replace	Replace	No <i>/ SR</i>
52591-47021			BUMPER SEAL, RR RH	1	65.70	25.00	49.27	Replace	Replace	No <i>?</i>
61604-47090			FENDER RR/RH	1	766.80	25.00	575.10	Replace	Replace	No <i>x R</i>
			STICKER DECAL SMRT	1	7.80	0.00	7.80	Replace	Replace	No <i>/ nec</i>
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No <i>/ nec</i>
61621-47030			TROUGH, BACK DOOR	1	110.90	25.00	83.17	Replace	Replace	No <i>R X</i>
TOTAL MATERIALS								2,340.35	2,340.32	
TOTAL MATERIALS(Discounted)							2,340.32	2,340.32		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									