REF: CC3 | AIG18015908 / Afd3n2

ASSIGNMENT

minun	ASSIGNMENT	
From: Date:	Veh No: SFG2321C · Yr Regn: 2018 /Fe	b
Estimated Cost:	Type: M.Car/ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /	
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or	
To Inspect Vehicle No:	Make: Audi A4 cc 1984	
at Workshop m/s	Colour While A/C: Insured / Std / NI /	
of	Sp.Reading 8429, T/Radio: Insured / Std / NI	/ NA
Insured:	Eng/No:	
Policy No.	C/No: WAUZZEF48JAOS2934	
Claims No.	Gen. Cond: Good/ Fair / Poor / Burnt	
Sum Insured: Excess: \$1600	Steering: Inorder / Jammed / Leaked / Burnt or	
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or	
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or	
	Tyre Size: F: 245/35 R-19-	
(Policy Condition)	R: 245/35R19.	
Remark: The veh had commenced its N/S	O/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC FOHTSU / PIR / SUMI /	
repair at the time of inspection.	TOYO / YOKO or	
Bal. or Market Value: 150K '	Front Rear	
DAC Accident Rport: Consistent? : Yes or No	R/Bal. 06 mm R/Bal. 06	mm
GIA / PR Seen: Consistent? ; Yes or No	L/Bal. 06 mm L/Bal. 96	mm
Est Repairs: 04 % days Res.: Yes or No	D.O.A. D.O.I. 30/08/18	
Lum Sum: % 3 Val.: Yes or No	Survey held at Rolling.	
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or	
Vehicle: IN	CONTRACTOR OF THE PROPERTY OF	
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to col	tision.
Date / Time Action / Instruction	100	
8FG 2321C -NALINC130151	610/el DUA: 28/8/13	
Part by Part \$5366.08	(Red: 9649.92:62%)	
4		
RECE	EIVED 1 0 JAN 2019	
	1	
late/Time, File Pass to? : Preli. Report	Days Of Repair:	
Ibli Typist : Final Report	Resurvey No. of Trip: Survey Fee:	
Date/Time, File Return to?	Transportation: 200	
Add	Fee:)
Lance Comment	Interview (\$) Photos	
Report Format :	Tech. Invs (\$) Others	
Jump Sum / LB.I: (3	:Weekend (\$)	
	21	

MPA118111298 / Premium Automobiles Pte Ltd - UBI ENTRY DATE & TIME: 28/08/2018 12:14 SUBMITTED BY: Mastura Binte Osman Basah

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

anorodaid.		
Marie Control of the	ACCIDENT STATEMENT	
Date Of Report	28/08/2018 12:14	
Date Of Accident	27/08/2018 14:30	
Exact Location Of Accident	SIDE LANE ALONG THONG BEE ROAD	
Country/State of Loss	SINGAPORE	
STOP IN THE STORY OF THE SERVICE	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SFG2321C	
Insured/Policyholder		
Name Of Registered Owner	TAN HAN WEI	

NRIC No S7927982Z Email Address NOEMAIL

Mobile Phone No (LOCAL) +65-96925550 Alternative Phone No HOME-64579209

Vehicle Particulars

Manufacturer AUDI

Model A4 SEDAN 2.0 TFSI 8W

Exact Purpose for which vehicle was being used at PRIVATE USE time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

YES

If No, Please state action to be taken

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company

AIG ASIA PACIFIC INSURANCE PTE, LTD.

Type Of Coverage

COMPREHENSIVE

Fleet Policy

NO

Policy Number

1800016196

Cover Note Number

Driver

Name of Driver KWAN SOW YEE

NRIC No S7124554C Date Of Birth 12/07/1971 Occupation **INDOOR** Date Of Driving Pass 14/07/1993

Driving Experience 25 YEARS AND 1 MONTH

Gender MALE

Mobile Number (LOCAL) +65-97837272

Fax Number

Contact Number

EMail Address NOEMAIL Address

BLK 334 HOUGANG AVE 5

#12-264

Postcode

530334

1 0310000

die Comment NO

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle OTHER - BROTHER-IN-LAW

-

Insurance Company of Driver's Own Vehicle

•

General Information of the Accident

Type Of Accident

COLLIDED INTO PARKED VEHICLE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

0

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

ON 27 AUGUST 2018, AT ABOUT 2.30 PM, MY FAMILY WAS ALERTED THAT MY BROTHER-IN-LAW'S CAR (AUDI A4 SFG2321C), HAD BEEN KNOCKED BY A SCDF VEHICLE (YP4752G). UPON INSPECTION, WE NOTICED DENT & SCRATCHES ON THE FRONT LEFT AREA, JUST ABOVE THE LEFT FRONT TYRE. MY BROTHER-IN-LAW VEHICLE, HAD BEEN PARKED ALONG THE SIDE LANE ALONG THONG BEE ROAD OVER THE LAST COUPLE OF DAYS SINCE HE WAS OVERSEAS LAST WEEK. THE VEHICLE WAS PARKED AND STATIONERY AT THE TIME OF ACCIDENT.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

YP4752G

Vehicle Make/Model/Colour

SCDF VEHICLE

Details Of Properties

Vehicle Category

Name of Driver

COMMERCIAL VEHICLE

LIBIOR

MUHD SAUFI

NRIC/Passport Number

S9314618B

Contact Number

96507024

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims:
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents[including their lawyers/law firms], which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

Driver's Signature, (If driver is not the policyholder)

Date & Time: 28/8


Reporting Centre Personnel's Signature Name Tony toury

NRIC/FIN No.

G2040197X

Sketch Plan #2

SKETCH PLAN



A= SFG 23 21C B= YP 4752G

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 27 Aug 2018 @ about 2 - soper, my tamily was
alented that my mother in law's car (Andi AY SFG 13210)
had been lawched by a scot veh. (49 475) E). upon
regreening, we noticed dend & suntones on the front
left area, just above the lift front type.
they broother in law un had been partied along
the side lane along Those for Road over the
lass comple of days to be a sure he was overseen
100 w 0.0 V.
The vali was parted and stationary @ the
tim of accident.

DECLARATION

t/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:


Driver's Signature

(If driver is not the policyholder)
Date & Time: 28/1

Reporting Centre Personnel's Signature Name: Tasky Fagry

NRIC/FIN NO 6-20401474









KWAN SOW YEE

关守义

CHINESE Dwa of Berth

12-07-1971 M Country of Birth SINGAPORE



Blood Group Date of lessur 0 • 02-11-1992

APT BLK 334 HOUGANG AVENUE 5 #12-264 SINGAPORE 530334 NRIC No: S7124554C Date: 10-06-2001 No: 3998269



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3

Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

14 Jul 1993

NP 428A



JTO PROTECTOR PRIVATE VEHICLE

Policyholder

: TAN HAN WEL

of Insurance

: 01 Feb 2018 To 31 Jan 2019

ie No.

: CVK074894

ssis No.

: WAUZZZF48JA052934

Vehicle No.

: SFG2321C

Policy No.

Issued Date

: 1800016196

Endorsement No.

: 01 Mar 2018

ABOUT THE COVER

Make/Model

: AUDI A4 Sedan 2.0 TFSI S tronic

Engine Capacity/Tonnage : 1,984.00 CC Driver Restriction

Sum Insured : Market Value

First Year of Registration : 2018

Off Peak Car : No

Insuring with COE/PARF

Person or Classes of Persons Entitled to Drive*:

b) Any other person who is driving on the Policyholder's order or with his/her permission

: NA

This Policy will indemnify the Policyholder or any authorised driver only if he/site meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience

Age Condition

: 35 years old and above

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving button, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rundered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be

EXCESS

Section 1

Fire - \$0 Own Damage - \$1600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen: \$100

Named Driver and Excess (where applicable)

TAN HAN WEI - \$1600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

di Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other, Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download 'AIG SG' from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: OCBC Bank Ltd

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189). Part I/V of the Road Transport Act. 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules. 1959 (Malaysia).

0504125259

PREMIUM LEASING -PSHS

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd. AUTHORISED REPRESENTATIVE

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate Workshop Contact No

Accident Repairs Ubi Road 1 6366 2323 : 6841 1183

Fax No Reference

: PA/OD/0988/2018/PH

Date

: 29-Aug-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315

Owner's Name

Mr Tan Han Wei

Address

: Blk 334 Hougang Ave 5

: #12-264

Singapore 530334

Telephone Type of Claim (HP) +65 96925550 Own Damage Claim

Policy No.

1800016196

Vehicle No Model Code

SFG 2321 C : Audi A4 2.0 TFSI

Model / Year

Feb-18 : CVK 047894

Engine No

: WAUZZZF48JA052934

Chassis No

Mileage

: Date In :

Liability Excess Cost : +

: -

Estimated By

: Johnny Boo / Allan Wu

Accident Date

: 27-Aug-18

Place of Accident

: Side lane along Thong Bee Road

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFG 2321 C.

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy	S/N	\$ 360.00	
2	To dismantle and renew front bumper, lhs front fender and lhs headlight. Re-organise front crash management components. Reinstall all parts removed.		\$ 2,100.00	1000
3	To respray front bumper and lhs front fender.		\$ 1,500.00	1100 /
4	To renew lhs front rim and carry out wheel slignment	S/N	\$ 280.00	
6	To carry out diagnostic check	S/N	\$ 192.00	//
	TOTAL LABOUR CHARGES		\$ 4,432.00	

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFG 2321 C

S/N	Parts Description		Damaged Parts & Prices S/Nett Remark
1	FRONT BUMPER School	\$	1,849.00 - 1479 70
2	FIXING PARTS FOR FRONT BUMPER 2	\$	245.00 × ×
3	SECURING STRIP	2 \$	60.00 ₹ ⟩
4	AIR GUIDE - LH	\$	73.00 × ×
5	AIR GUIDE GRILLE - LH	\$	118.00
6	GUIDE SECTION - LH	\$	31.00 + X
7	FORNT FENDER - LH Deuted	\$	665.00 532
8	ATTACHMENT PARTS FOR FENDER NAL NEC	\$	45.00 ° Y
9	CLOSING ELEMENT - LH	\$	44.00
10	BRACKET FOR FENDER - LH	\$	31.00 7
11	BRACKET FOR DEFORMATION	\$	43.00 - 34.16
12	BRACKET FOR FENDER	\$	27.00 - 31.60
13	BRACE - LH FRONT The NEw	\$	103.00 ? X
14	COVER - LH Z	\$	27.00 ~ 21.04
15	COVER - LH	\$	20.00 - 15.36
16	WHEEL HOUSING LINER - LH	\$	215.00 ~
17	ATTACHMENT PARTS FOR WHEEL LINER	\$	78.00 ₺
18	WHEEL SPOILER	\$	63.00
19	SPOILER - LH KIR NAL	\$	30.00 €
20	STONE CHIP GUARD - LH New	\$	44.00 / 34.56
20	TOTAL SPARE PARTS CHARGES :	\$	3,811.00
		25	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFG 2321 C

	†ii		Damaged Parts	s & Prices
S/N	Parts Description		S/Nett	Remark
			16±0.007/107/000004 - 102	
21	LED HEADLIGHT - LH NOR MEL	\$	6,973.00 *	K
22	RH FRONT RIM	TBC	the state of the s	780
23	SUNDRIES No.	\$	300.00	: 16.16
	TOTAL SPARE PARTS CHARGES	\$	11,084.00	
	TOTAL LABOUR CHARGES	: \$	4,432.00	
		\$	15,516.00	
	All charges are not inclusive of GST. Legend: Remarks (OK) = Approved, Remarks (X) = Not approved Spare parts are Special Nett.			

16296

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

Authorised Repris, 04 Pays

Signature:

Date:

Acknowledged by Repairer

LKK Auto Consultants hence notify the Repairer of the following: To resurvey before/after spray painting. To display damaged panes, during resurvey

Parts prices are subject to our limiting

Third party survey is on a "Work"
No illegal modification(s) is allow.

To use a basis. Supplementary demiss must be assurveyed and is subject to final approval from insurance Company

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager Allan Wu Claims Consultant

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate

Accident Repairs

Workshop

Ubi Road 1

Contact No

6366 2323

Fax No

6841 1183

Reference

PA/OD/0988/2018/PH

Date

29-Aug-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name

Mr Tan Han Wei

Address

Blk 334 Hougang Ave 5

#12-264

Singapore 530334

Telephone

(HP) +65 96925550

Type of Claim

Own Damage Claim

Policy No.

1800016196

Vehicle No

SFG 2321 C

Model Code

Audi A4 2.0 TFSI

Model / Year

Feb-18

Engine No

CVK 047894

Chassis No

WAUZZZF48JA052934

Mileage

Date In

.

Liability

× 2

Excess Cost

. -

Estimated By

Johnny Boo / Allan Wu

Accident Date

27-Aug-18

Place of Accident

Side lane along Thong Bee Road

Hi Adrian

4 days - ok - jb - 4 Dec 18

Premium Automobiles 55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFG 2321 C.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation		
1	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy	S/N	\$ 360.00	\$	360.00
2	To dismantle and renew front bumper, lhs front fender and lhs headlight. Re-organise front crash management components. Reinstall all parts removed.		\$ 2,100.00	\$	1,000.00
3	To respray front bumper and lhs front fender.		\$ 1,500.00	\$	1,100.00
4	To renew lhs front rim and carry out wheel slignment	S/N	\$ 280.00	\$	280.00
6	To carry out diagnostic check	S/N	\$ 192.00	\$	192.00
	TOTAL LABOUR CHARGES	:	\$ 4,432.00	\$	2,932.00

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFG 2321 C

			Damaged Parts	& Pric	es
. Do	arts Description		S/Nett	R	emark
l Pai	ins Description				
1 FR	RONT BUMPER	\$	1,849.00	\$	1,479.20
311 4530	IXING PARTS FOR FRONT BUMPER	\$	245.00		
	ECURING STRIP	2 \$	60.00		
	IR GUIDE - LH	\$	73.00		
0000	IR GUIDE GRILLE - LH	\$	118.00		
	GUIDE SECTION - LH	\$	31.00		
	ORNT FENDER - LH	\$	665.00	\$	532.00
25-	TTACHMENT PARTS FOR FENDER	\$	45.00		
	CLOSING ELEMENT - LH	s	44.00		
	BRACKET FOR FENDER - LH	\$	31.00		
	BRACKET FOR DEFORMATION	\$	43.00	\$	34.16
2011	BRACKET FOR FENDER	\$	27.00	\$	21.60
	BRACE - LH FRONT	\$	103.00		
	COVER - LH	\$	27.00	\$	21.04
720 SE	COVER - LH	\$	20.00	\$	15.36
	WHEEL HOUSING LINER - LH	\$	215.00		
	ATTACHMENT PARTS FOR WHEEL LINER	\$	78.00		
	WHEEL SPOILER	\$	63.00		
		\$	30.00		
	att Antivati (shirtsa) - Patrikia)	\$	44.00	\$	34.56
attests of		: \$	3,811.00	\$	2,137.92
19 \$	SPOILER - LH STONE CHIP GUARD - LH TOTAL SPARE PARTS CHARGES	\$	44.00	_	

All charges are not inclusive of GST.

Remarks (OK) = Approved, Remarks (X) = Not approved Legend: Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFG 2321 C

				Damaged Parts	& Pri	ces
				S/Nett	F	Remark
S/N	Parts Description	c/f			\$	2,137.92
21	LED HEADLIGHT - LH		S	6,973.00		
	RH FRONT RIM		\$	780.00	\$	780.00
22	A-2010		\$	300.00	\$	16.16
23	SUNDRIES	2	•	11,864.00	\$	2,934.08
	TOTAL SPARE PARTS CHARGES	:	\$	11,004.00		
	TOTAL LABOUR CHARGES	:	\$	4,432.00	\$	2,932.00
	GRAND TOTAL	:	\$	16,296.00	\$	5,866.08

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

Please Note

This estimate is based on visual inspection of the affected vehicle.

Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager Allan Wu Claims Consultant



AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Motor Claims Dept Yr Ref: SFG 2321 C Norah Khai 6768 9911 6841 1183 Nora.khai@premiumauto.com.sg Body & Paint Dept PA/OD/0988/2018/MAS

7 Jan 2019

Telephone +65-Telefax +65-EMail

Our department

Our Ref Your Ref

Date

total pages

Dear Sir,

RE: INSURANCE CLAIM FOR SFG 2321 C Audi A4 Sedan 2.0 TFSI

With reference to the above-mentioned vehicle, no. SFG 2321 C, claimant, Mr. Tan Han Wei, please find the related document per attached.

- A copy of the Original invoice no. 85013308 S\$4,564.71
- A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai Claims Dept

Encls

AIG - SFG 2321 C

Premium Automobiles Pte Ltd Showroom 9 Leng Kee Road Singapore 159090 Telephone (65) 6566 1111 Telefax (65) 6471 3733

Service & Parts Centres 55 Ubi Rd 1 Singapore 408699 Telephone (65) 6336 2323 Telefax (65) 684 11183

...CLAIM SUBFOLDER...(Pending for Survey Report)

			Adi Accioned	Adj	Rpt	Adj Submitted	Ins Auth'ed	Status		
Case Main	Notified 02 Sep 2018	Est Submitted	Adj Assigned 31 Aug 2018 12:34 Edit Adj Rpt	S\$5,8 Edit Est	66.08	\$\$5,866.08 View Rpt		Pending for Survey Report Cancel Case		
	Main	Re	ference	ľ	Claim De	tails	Document	s] .	Show All	
		TATIC	O'TO NAME OF STREET				[Creat	ted by insurer]		
nsured:	subfolder DE	TAN H	AN WEI, ID: S79	927982Z	Date of	LOSS:	[6 Mon Reg Da	2018 14:00 - :59 oths and 26 Days ote (Man Yr)]	From LTA	
Claim Ty	ne:	OD /	o / 1578084930SG			Policy/Cover Note No.: 18000			16196 (Comprehensive)	
Cidiiii 1 y	pe,		Premium Automobiles Pte Ltd			b: Dood 1 408699				
Repairer	:	Premi	um Automobiles	Pte Ltd (UBI) 55 U	- Tel: 65-6419-30	00 [Handled b	y Dally Amri, M	imi Zarina	
Handling	Insurer:									
Adjuster		LKK A due 1	uto Consultants 1/09/2018]	Pte Ltd (6256-3561 [Ha		N LING) [Fill	ai Kpt	
Driver/C	ustodian:	KWAN	SOW YEE (47 / M	lale), NR	IC: S7124	554C, Tel: +6597	1837272			
ASSOC	IATED MAIL RE	CEIVED					View All	Compose (ase Mail	
AIG_	SG (03/09/2018)	: SFG2321C / OI	7 / 27/08/2018	/ Covera	ge & Exce	ss update				
В	SSOCIATED TAS	sks	Group Subje			lew All Search	Tasks Crea	created Or	Complete Done	

Claim Documents

*SFG2321C (1578084930SG)
OD
Aug 27 2018 2:30PM
[TAN HAN WEI]
Premium Automobiles Pte Ltd

			Compose New Letter	Upload Video	Upload Audio	View	Use Viewer	•
į,	Ipload Documents	Upload Photos	Compose New Collect			3 per p	page +	V
Pho	tos/Images						Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consult	tants Pte Ltd (HQ)			0	Load JPG	V
1	17/12/18 11:00	General View				0	Load JPG	V
2	17/12/18 11:00	General View				0	Load JPG	V
3	17/12/18 11:00	General View				0	Load JPG	V
4	17/12/18 11:00	General View				0	Load JPG	(V)
5	17/12/18 11:00	General View				0	Load JPG	V
6	17/12/18 11:00	General View				-		-
7	17/12/18 11:00	General View				0	Load JPG	V
		General View				0	Load JPG	7
8	17/12/18 11:00					0	Load JPG	V
9	17/12/18 11:00	General View				Ð	Load JPG	7
10	17/12/18 11:00	General View				0	Load JPG	V
11	17/12/18 11:00	General View					_	V
12		General View				0	Load JPG	(A)
	1 - 1 - 1 - 1					1 per	page +	V
Do	cumentation						Thumbnai	Prin
No	Relabel/Reorder		itants Pte Ltd (HQ)			Ð	Load PDF	
1	31/08/18 15:07	Singapore Accid				0		
2	31/08/18 15:07	Certificate of In				ō		
3	31/08/18 15:07	Driver's Driving	License			0		8
4	31/08/18 15:07	ESTIMATE				O	The second secon	
5	11/01/19 08:52	WORKSHOP IN				õ		_
6	11/01/19 08:52	DISCHARGE VO	UCHER			_		

Linked Accident Report Documents

			View	Use Viewer	•
	sessment Reports		1 per page		V
sse	ssment Reports	112 (1191)		Thumbnail	Print
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	0	Load HTM	
1	28/08/18 17:47	Accident Statement			
			3 per	page *	V
ho	tos/Images	Premium Automobiles Pte Ltd (UBI)		Thumbnail	
No	Finalized On		0	Load JPG	V
1	28/08/18 17:45	Accident Photo	0	Load JPG	V
2	28/08/18 17:45	Accident Photo	0	Load JPG	V
3	28/08/18 17:45	Accident Photo	0	Load JPG	V
4	28/08/18 17:45	Accident Photo		Load JPG	V
5	28/08/18 17:45	Accident Photo	0	0.0000000000000000000000000000000000000	(V)
6	28/08/18 17:45	Accident Photo	0	Load JPG	V
7	28/08/18 17:45	Accident Photo	0	Load JPG	_
	28/08/18 17:45	Accident Photo	0		V
8		Accident Photo	0	Load JPG	V
9	28/08/18 17:45		0	Load JPG	7
10	28/08/18 17:45	Accident Photo			
			1 per	page •	100.0
Do	cumentation	Premium Automobiles Pte Ltd (UBI)		Thumbna	
No			0	Load JPG	V
1	28/08/18 12:28	Sketch Plan	0	Load JPG	V
2	28/08/18 12:28	Sketch Plan #2			1/4

Documents Checklist

	Reset Save Print
DOCUMENTS CHECKLIST	
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	-
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd. AIG Building, 78 Shenton Way #08-16

Singapore 079120

CC3/AIG18015908/ATD3N2 Our File No:

11/01/2019 Date:

Engine No:

Odometer:

Chassis No:

REFERENCE

Insured/Claimant: Date of Loss:

TAN HAN WEI 27/08/2018

Policy No: Nature of Claim: 1800016196

OD

Claim No:

1578084930SG

WAUZZZF48JA052934

CVK047894

8429 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SFG2321C

Make & Model:

AUDI A4, 2.0 TFSI QU S-TRONIC (A)

01/02/2018 (Man. Year: 2017)

Reg. Date: Colour: **Engine Capacity:**

White 1984 cc

Market Value/New Car

\$\$150,000.00

Price: Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: Front Left Side:

245/35R19 Michelin 6 mm Michelin 6 mm Rear Tyre Size: Rear Left Side: Rear Right Side: 245/35R19 Michelin 6 mm Michelin 6 mm

Front Right Side: The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts Miscellaneous Items	Repairer's 11,864.00 0.00	Adjuster's 2,934.08 0.00	8,929.92 0.00	75.27 33.84
Labour Paintwork Labour	4,432.00 0.00 0.00	2,932.00 0.00 0.00	1,500.00 0.00 0.00	33.04
Towing Calculated Gross Total (S\$ - Excess (S\$	16,296.00	5,866.08 1,600.00	10,429.92 0.00	64.00 0.00
(S\$ + GST 7.00/7.00% (S\$	14,696.00	4,266.08 298.63	10,429.92 730.09	70.97 70.97
Nett Amount (S\$)		4,564.71	11,160.01	70.97

INSPECTION

Date of Assignment: Date Inspected:

31/08/2018

30/08/2018 Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1 Singapore 408699

Estimated Period of Repair:

4.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

10.	Otv	mended Parts Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER *FIXING PARTS FOR FRONT BUMPER	Deformed Not Necessary	1,849.00 FS 245.00 FS	*1,479.20 FS *- FS
2	1		Not Necessary	60.00 FS	*-FS
3	2	*SECURING STRIP	Not Necessary	73.00 FS	*-FS
4	1	*AIR GUIDE-LH	Not Necessary	118.00 FS	*-FS
5	1	*AIR GUIDE GRILLE-LH	Not Necessary	31.00 FS	*-FS
6	1	*GUIDE SECTION-LH	Dented	665.00 FS	*532.00 FS
7	1	*FRONT FENDER-LH	Not Necessary	45.00 FS	*-FS
8	1	*ATTACHMENT PARTS FOR FENDER	Not Necessary	44.00 FS	*-FS
9	1	*CLOSING ELEMENT-LH	Not Necessary	31.00 FS	*-FS
10	1	*BRACKET FOR FENDER-LH	Necessary	43.00 FS	*34.16FS
11	1	*BRACKET FOR DEFORMATION	Necessary	27.00 FS	*21.60 FS
12	1	*BRACKET FOR FENDER	Not Necessary	103.00 FS	
13	1	*BRACE-LH FRONT	Necessary	27.00 FS	*21.04 FS
14	1	*COVER-LH	Necessary	20.00 FS	*15.36 FS
15	1	*COVER-LH	Not Necessary	215.00 FS	*- FS
16	1	*WHEEL HOUSING LINER-LH *ATTACHMENT PARTS FOR WHEEL LINER	Not Necessary	78.00 FS	*- FS
17	1		Not Necessary	63.00 FS	*- FS
18	1	*WHEEL SPOILER	Not Necessary	30.00 FS	*-F8
19	1	*SPOILER-LH	Necessary	44.00 FS	*34.56 FS
20	1	*STONE CHIP GUARD-LH	Not Necessary	6.973.00 FS	*-F8
21	1	*LED HEADLIGHT-LH	Cut	780.00 FS	
22	1	*LH FRONT RIM	Necessary	300.00 FS	
23	1	*SUNDRIES	Necessary		
F=F	F=Franchise part. S=SpcNett.		Total Parts (S\$	11,864.00	2,934.08

Recommended Miscellaneous Items There are no new miscellaneous items selected.

Re No	commended Labour Particulars	Lab.Type	Repairer's	Amount
Lab	our Items	New	360.00	360.00
2	TO REMOVE AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANISE	New	2,100.00	1,000.00
	FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	I Paris Colo	1,500.00	1,100.00
3	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	280.00	280.00
4	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	192.00	192.00
5	TO CARRY OUT DIAGNOSTIC CHECK	ivew		100000000000000000000000000000000000000
	Gross Labo	our Cost (S\$)	4,432.00	2,932.00
	Report was unsubmitted du	ring this print-out.		

< END OF ESTIMATES >