

KIM CHWEE AUTO PTE LTD

1 Kakit Bukit Ave 6

#01-46,48,50 Autobay

SINGAPORE 417883

VEHICLE NO: SKF5489D

QTY	PARTICULAR
1 PCS	BOOTLID 102332
1 PCS	BOOTLID 'H' LOGO
1 PCS	BOOTLID 'HYUNDAI' EMBLEM
1 PCS	BOOTLID 'ELANTRA' EMBLEM
1 PCS	BOOTLID 'ELITE' EMBLEM
1 PCS	BOOTLID INNER LOCK 197.90
1 PCS	BOOTLID LOCK STRIKER
1 PCS	BOOTLID WEATHERSTRIP 212.30
2 PCS	BOOTLID REFLECTORS @\$520.30 420.30 x 2 = 840.60
1 PCS	BOOTLID INNER TRIM 266.60
1 SET	BOOTLID INNER TRIM CLIPS 35
1 PCS	REAR BUMPER 566.00
2 PCS	REAR BUMPER REFLECTORS @\$105.00 85.50
1 PCS	REAR BUMPER REINFORCEMENT 390
2 PCS	REAR BUMPER REINFORCEMENT STAYS @\$201.00 145
2 PCS	REAR BUMPER SIDE RETAINERS @\$66.50
1 SET	REAR BUMPER CLIPS
1 PCS	REAR BUMPER LOWER GARNISH N/S
2 PCS	REAR BUMPER SPLASH SHIELDS @\$150.50
1 PCS	REAR END PANEL 442.80
1 PCS	REAR END PANEL TOP GARNISH 145.00
1 PCS	REAR END PANEL LOCK SENSOR
1 PCS	REAR FLOOR PANEL
1 PCS	REAR FLOOR PANEL TOP BORAD 299.60
1 PCS	REAR FLOOR PANEL TOP TOOLS SPONGE 212.30
2 PCS	REAR FENDERS @\$1807.00
2 PCS	REAR FENDERS INNERS TRIMS @\$405.00 322.20
1 PCS	REAR WINDSCREEN MOULDING
1 PCS	REAR EXHAUST
2 PCS	REAR EXHAUST MOUNTINGS @\$45.00
2 PCS	TAILLAMPS @\$685.30 455.50 x 2 = 911 20%
2 PCS	TAILLAMP HOUSING PANELS @\$295.00
2 PCS	BOOTLID HINGES @\$145.00
1 PCS	REAR END PANEL SEALANT
1 SET	REAR BUMPER REVERSE SENSOR
1 PCS	REAR WINDSCREEN SEALANT

30th Jan	\$1,507.30
run	\$39.90
run	\$48.50
run	\$52.20
run	\$50.00
run	\$291.30
11	\$66.80 X
run/10.1	\$311.30
one	\$1,040.60
del/10.1	\$322.60
run	\$50.00
dis	\$788.20
nt/scn	\$210.00 1pc
dis	\$485.10
nt/scn	\$402.00 1pc
del	\$133.00
run	\$48.00
nt	\$105.60 X
nt/10.1	\$301.00 1pc
30th Jan	\$892.20
run	\$288.30
11	\$250.50 X
run	\$1,680.30 X
nt/scn	\$525.40
del	\$311.20
run	\$3,614.00 X
nt/scn	\$810.00 1pc
11	\$188.20 X
11	\$891.30 X
11	\$90.00 X
one	\$1,370.60
run	\$590.00 X
run	\$290.00 X
run	\$50.00 S.N
shut	\$380.00 200 S.N
11	\$50.00 X
	\$18,525.40

not Authorized
wklr
p/p #8043.77
507.
3-18/18

6617.22
5293.77

LABOUR CHARGES:

TO CHECK WIRING	\$80.00	30
TO DISMENTLE & REPLACING REVERSE SENSOR	\$80.00	50
TO TRANSFER BOOTLID MECHANISM	\$120.00	60
TO DISMENTLE & REFIX SEAT, CUSHION UPHOLSTREY	\$150.00	80
TO DISMENTLE & REFIX REAR EXHAUST	11 \$100.00	X
TO DISMENTLE & REFIX REAR WINDSCREEN	11 \$150.00	X
TO MOUNT VEHICLE ON CAR O-LINER	11 \$380.00	X
TO SPRAY RUST PROOFING	\$150.00	80
LABOUR FOR PANEL BEATING, CUT, WELD STRAIGHTENED	\$1,800.00	1000
REPLACING PARTS		
TO PUTTY & SPRAY PAINTING	\$1,800.00	1200
TOTAL	\$23,335.40	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: