

INS. CASE OWNER:

CC 4, LOR 180

15923, Uwa32

LKK:

IDAC:

ASSIGNMENT

DOI:

31/8/2018

Date/Time:

30/8/18

Registered in Merimen:

31/8/2018

Pre-assign / CCU / FTE



Insured Vehicle No. : SLL2041M

Name of Insured : UM PIC

Insured Tel No. : HP:

Excess Sec II :SS D.O.A: 20/8/18

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age : Hoo Kw Sim 94598662 (V/L: YES / NO)

Claim No. :

Policy No. :

Make / Model : HONDA VIZO

Place of Accident : Lebuhraya Ind 4/18

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

FP500T



INSRS:

WSP: 720

Tel :

Liability : Spry Party

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time

1/9
Uwa

FP500T - X

SLL 2041M - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

50

(Agreed / Assessed) BOLA S/N No. : MIL

If NO or B 28, Ass. Lia :

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

10/4/19

250.00

05/11/13 wel

ASS. REC. BY:

mercan

REF:

ALG

ASSIGNMENT

From:

Date:

31/08/18

Estimated Cost:

ON ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

FP500T

at Workshop m/s

Teo Spray Painting

of

BLK6 Defubene 10-# 01-558

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection

Bal. or Market Value:

22k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

112 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

lup

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

FP500T

Yr Regn:

6.17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha TMAX530

C.C

530

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JYASJ145000004804

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

120/70R15

R:

160/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

R/Bal.

mm

Rear

6

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

20/7/18

D.O.I.

31/8/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S, 1/5 Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LTA 5350

9/4/19

Confirm 2-B.2 # 4576.20 with 5 working days

(Ref-# 1586.55
26/1)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

____ S + RS ____ SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$



張 噴 漆 TEO SPRAY PAINTING

(INCORPORATED IN THE REPUBLIC OF SINGAPORE)

Reg. Address: BLOCK 6, DEFU LANE 10, DEFU INDUSTRIAL PARK C, #01-558
SINGAPORE 539187 TEL: 6283 5474 (2 LINES) FAX: 6287 2012
REG. NO. 275084 / 00X

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building

78 Shenton Way #07-16

Singapore 079120

Tel: 64193000

Fax: 68357416

DATE: 28.08.2018

ABDUL ISMAIL BIN SIMIN

RE: FP500T YAMAHA TMAX530

ACCIDENT ON 20.07.2018 AT TUAS CHECKPOINT MALAYSIA

The damages are:

- 1 FRONT FORK ASSY RH
- 2 FRONT FORK ASSY LH
- 3 UNDERBRACKET COMP
- 4 BOARD FOOTREST (1)
- 5 PANEL CONSOLE (1)
- 6 BOARD FOOTREST (2)
- 7 DAMPER PLATE
- 8 DAMPER PLATE
- 9 PANEL CONSOLE (2)
- 10 MAT (3)
- 11 MAT (4)
- 12 DUCT AIR
- 13 FENDER INNER (2)
- 14 LEG SHIELD (1)
- 15 LID
- 16 LID ASSY
- 17 BOX ASSY
- 18 MOLE (1)
- 19 MOLE (2)
- 20 PANEL (1)
- 21 EMBLEM
- 22 PANEL (2)
- 23 COVER
- 24 PLATE PROTECTOR (2)
- 25 PROTECTOR MUFFLER (1)
- 26 PROTECTOR MUFFLER (3)

2 PCS

Bay	\$ 750.00	2 R 50 s. n
Bed	\$ 750.00	2 R 50 s. n
bat	\$ 375.00	NR 60 s. n
Box	\$ 97.50	✓
con	\$ 67.50	✓
cre	\$ 97.50	✓
dis	\$ 5.00	✓
dis	\$ 12.00	✓
con	\$ 67.50	✓
dis	\$ 18.00	✓
dis	\$ 18.00	X
con	\$ 37.50	✓
con	\$ 52.50	✓
con	\$ 120.00	✓
dis	\$ 15.00	✓
dis	\$ 75.00	✓
dis	\$ 45.00	✓
con	\$ 72.00	✓
con	\$ 72.00	✓
con	\$ 97.50	✓
dis	\$ 45.00	✓
con	\$ 97.50	✓
dis	\$ 27.00	✓
con	\$ 45.00	✓
con	\$ 60.00	✓
dis	\$ 105.00	✓

Not Allowed
Lm
7/7 4576-20
Sdy.
31/8/18
The Mr. Attorney

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before any spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

27 STAY (1) 270
 28 HEADLIGHT ASSY
 29 FENDER FRONT
 30 STAY FENDER (1)
 31 STAY FENDER (2)
 32 FENDER FRONT (2)
 33 HANDLE COMP
 34 BALANCER
 35 CAP HANDLEBAR COVER
 36 COVER HANDLE UPPER (2)
 37 COVER HANDLE UPPER (1)
 38 CAP COVER HANDLE (2)
 ✓ 39 PANEL INNER (1)
 40 BODY COWLING LH
 41 BODY COWLING RH
 42 PANEL INNER (2)
 43 COVER FRONT
 44 SCREEN
 45 REAR VIEW MIRROR ASSY LH
 46 REAR VIEW MIRROR ASSY RH
 47 SIDE COVER LH
 48 COVER SIDE (3)
 49 MOLE SIDE COVER (1)
 ✓ 50 SIGNAL LIGHT FRONT
 51 MAINSTAND
 52 INNER SIDE COVER LH

Sub \$ 27.00 ✓
 Scr \$ 960.00 ✓
 Cur \$ 75.00 ✓
 Sub \$ 22.50 ✓
 Sub \$ 22.50 ✓
 Sub \$ 27.00 ✓
 Sub \$ 67.50 ✓
 Cur \$ 22.50 ✓
 Cur \$ 60.00 ✓
 Cur \$ 15.00 ✓
 Cur \$ 15.00 ✓
 MA \$ 37.50 ✓
 (Re \$ 42.00 ✓
 Cur \$ 180.00 ✓
 Cur \$ 195.00 ✓
 Cur \$ 52.50 ✓
 Cur \$ 112.50 ✓
 Cur \$ 240.00 ✓
 Sub \$ 75.00 ✓
 Sub \$ 75.00 ✓
 Cur \$ 105.00 ✓
 Cur \$ 120.00 ✓
 Cur \$ 82.50 ✓
 Sub \$ 90.00 ✓
 R \$ 180.00 X
 Cur \$ 22.50 ✓

SUB TOTAL
 LESS 10%
 SUB TOTAL

4118

6340.50
 5751.45

ADD NETT

1 LABOUR
 2 NUMBER PLATE
 3 SPRAY

Sub \$ 600.00 450
 Cur \$ 30.00 10 s. N
 380.00 250 140

Total

6761.45

PG 2
 FP500T

1-4118
 102
 2+3706.20
 S.N 170.00
 10km + 700.00
 4576.20

19-NOV-2018 14:36

P. 2 / 2

62564315

Number 27 Price Typing error
is \$270.00

YKK Auto Care Centre hereby notify
the Repairer of the following:

- To resurvey and re-spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and
subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

27 STAY (1)
28 HEADLIGHT ASSY
29 FENDER FRONT
30 STAY FENDER (1)
31 STAY FENDER (2)
32 FENDER FRONT (2)
33 HANDLE COMP
34 BALANCER
35 CAP HANDLEBAR COVER
36 COVER HANDLE UPPER (2)
37 COVER HANDLE UPPER (1)
38 CAP COVER HANDLE (2)
39 PANEL INNER (1)
40 BODY COWLING LH
41 BODY COWLING RH
42 PANEL INNER (2)
43 COVER FRONT
44 SCREEN
45 REAR VIEW MIRROR ASSY LH
46 REAR VIEW MIRROR ASSY RH
47 SIDE COVER LH
48 COVER SIDE (3)
49 MOLE SIDE COVER (1)
50 SIGNAL LIGHT FRONT
51 MAINSTAND
52 INNER SIDE COVER LH

Sub \$ 27.00
scr \$ 980.00
cu \$ 75.00
scr \$ 22.50
scr \$ 22.50
m \$ 27.00
scr \$ 67.50
cu \$ 22.50
cu \$ 60.00
cu \$ 15.00
cu \$ 15.00
m \$ 37.50
m \$ 42.00
cu \$ 180.00
cu \$ 195.00
cu \$ 62.50
cu \$ 112.50
cu \$ 240.00
scr \$ 75.00
scr \$ 75.00
cu \$ 105.00
cu \$ 120.00
cu \$ 82.50
m \$ 90.00
m \$ 180.00
cu \$ 22.50

SUB TOTAL \$6,147.50
LESS 10% \$ 614.75
SUB TOTAL \$5,532.75

ADD NETT

1 LABOUR
2 NUMBER PLATE
3 SPRAY

\$ 600.00 450
\$ 30.00 10
380.00 250

Total 7 6162

PG 2
FP500T



張 噴 漆 TEO SPRAY PAINTING

(INCORPORATED IN THE REPUBLIC OF SINGAPORE)

Reg. Address: BLOCK 6, DEFU LANE 10, DEFU INDUSTRIAL PARK C, #01-558
SINGAPORE 539187 TEL: 6283 5474 (2 LINES) FAX: 6287 2012
REG. NO. 275084 / 00X

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building

78 Shenton Way #07-16

Singapore 079120

Tel: 64193000

Fax: 68357416

DATE: 28.08.2018

ABDUL ISMAIL BIN SIMIN

RE: FP500T YAMAHA TMAX530
ACCIDENT ON 20.07.2018 AT TUAS CHECKPOINT MALAYSIA

The damages are:

1 FRONT FORK ASSY RH		\$ 750.00	?
2 FRONT FORK ASSY LH		\$ 750.00	?
3 UNDERBRACKET COMP		\$ 375.00	?
4 BOARD FOOTREST (1)	500	\$ 97.50	✓
5 PANEL CONSOLE (1)	con	\$ 67.50	✓
6 BOARD FOOTREST (2)	con	\$ 97.50	✓
7 DAMPER PLATE	con	\$ 5.00	✓
8 DAMPER PLATE	con	\$ 12.00	✓
9 PANEL CONSOLE (2)	con	\$ 67.50	✓
10 MAT (3)	con	\$ 18.00	✓
11 MAT (4)	11	\$ 18.00	X
12 DUCT AIR	con	\$ 37.50	✓
13 FENDER INNER (2)		\$ 52.50	?
14 LEG SHIELD (1)	con	\$ 120.00	✓
15 LID		\$ 15.00	?
16 LID ASSY		\$ 75.00	?
17 BOX ASSY		\$ 45.00	?
18 MOLE (1)		\$ 72.00	?
19 MOLE (2)		\$ 72.00	?
20 PANEL (1)	con	\$ 97.50	✓
21 EMBLEM	21	\$ 45.00	✓
22 PANEL (2)	con	\$ 97.50	✓
23 COVER	con	\$ 27.00	✓
24 PLATE PROTECTOR (2)	con	\$ 45.00	✓
25 PROTECTOR MUFFLER (1)	con	\$ 60.00	✓
26 PROTECTOR MUFFLER (3)	Dis	\$ 105.00	✓

2 PCS

Not Allowed
LKR
L/S
5 day.
31/8/18
to the Attorney

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display (damaged part(s)) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

27 STAY (1)
28 HEADLIGHT ASSY
29 FENDER FRONT
30 STAY FENDER (1)
31 STAY FENDER (2)
32 FENDER FRONT (2)
33 HANDLE COMP
34 BALANCER
35 CAP HANDLEBAR COVER
36 COVER HANDLE UPPER (2)
37 COVER HANDLE UPPER (1)
38 CAP COVER HANDLE (2)
39 PANEL INNER (1)
40 BODY COWLING LH
41 BODY COWLING RH
42 PANEL INNER (2)
43 COVER FRONT
44 SCREEN
45 REAR VIEW MIRROR ASSY LH
46 REAR VIEW MIRROR ASSY RH
47 SIDE COVER LH
48 COVER SIDE (3)
49 MOLE SIDE COVER (1)
50 SIGNAL LIGHT FRONT
51 MAINSTAND
52 INNER SIDE COVER LH

\$ 27.00 ?
Scr \$ 960.00 —
C47 \$ 75.00 —
34 \$ 22.50 —
34 \$ 22.50 —
\$ 27.00 ?
\$ 67.50 ?
C47 \$ 22.50 —
\$ 60.00 ?
\$ 15.00 ?
\$ 15.00 ?
\$ 37.50 ?
\$ 42.00 ?
CM \$ 180.00 —
CR \$ 195.00 —
CR \$ 52.50 —
CR \$ 112.50 —
C47 \$ 240.00 —
R20 \$ 75.00 —
34 \$ 75.00 —
CR \$ 105.00 —
CR \$ 120.00 —
\$ 82.50 ?
\$ 90.00 ?
2 \$ 180.00 X
\$ 22.50 ?

SUB TOTAL \$6,147.50
LESS 10% \$ 614.75
SUB TOTAL \$5,532.75

ADD NETT

1 LABOUR
2 NUMBER PLATE
3 SPRAY

\$ 600.00 450
\$ 30.00 10
KIV ?

Total 6162.25



張 噴 漆 TEO SPRAY PAINTING

(INCORPORATED IN THE REPUBLIC OF SINGAPORE)

Reg. Address: BLOCK 6, DEFU LANE 10, DEFU INDUSTRIAL PARK C, #01-558

SINGAPORE 539187 TEL: 6283 5474 (2 LINES) FAX: 6287 2012

REG. NO. 275084 / 00X

TO
ABDUL ISMAIL BIN SIMIN / IRWAN BIN ROSD

TO
AIG Asia Pacific Insurance Pte. Ltd.
AIG Building

19.12.2018

Insurance Claims Repair Amount:

The damages are:

PG 1

1 BOARD FOOTREST	(1)		\$	97.50
2 PANEL CONSOLE	(1)		\$	67.50
3 BOARD FOOTREST	(2)		\$	97.50
4 DAMPER PLATE			\$	5.00
5 DAMPER PLATE			\$	12.00
6 PANEL CONSOLE	(2)		\$	67.50
7 MAT	(3)		\$	18.00
8 DUCT AIR			\$	37.50
9 FENDER INNER	(2)		\$	52.50
10 LEG SHIELD	(1)		\$	120.00
11 MOLE	(1)		\$	72.00
12 MOLE	(2)		\$	72.00
13 PANEL	(1)		\$	97.50
14 EMBLEM		2 PCS	\$	45.00
15 PANEL	(2)		\$	97.50
16 COVER			\$	27.00
17 PLATE PROTECTOR	(2)		\$	45.00
18 PROTECTOR MUFFLER	(1)		\$	60.00
19 PROTECTOR MUFFLER	(3)		\$	105.00
20 STAY	(1)		\$	270.00
21 HEADLIGHT ASSY			\$	960.00
22 FENDER FRONT			\$	75.00
23 STAY FENDER	(1)		\$	22.50
24 STAY FENDER	(2)		\$	22.50
25 HANDLE COMP			\$	67.50
26 BALANCER			\$	22.50
27 CAP HANDLEBAR COVER			\$	60.00
28 COVER HANDLE UPPER	(2)		\$	15.00
29 COVER HANDLE UPPER	(1)		\$	15.00
30 PANEL INNER	(1)		\$	42.00
31 BODY COWLING	LH		\$	180.00
32 BODY COWLING	RH		\$	195.00



張 噴 漆 TEO SPRAY PAINTING

(INCORPORATED IN THE REPUBLIC OF SINGAPORE)

Reg. Address: BLOCK 6, DEFU LANE 10, DEFU INDUSTRIAL PARK C, #01-558

SINGAPORE 539187 TEL: 6283 5474 (2 LINES) FAX: 6287 2012

REG. NO. 275084 / 00X

PG 2

33 PANEL INNER	(2)		\$ 52.50
34 COVER FRONT			\$ 112.50
35 SCREEN			\$ 240.00
36 REAR VIEW MIRROR ASSY	LH		\$ 75.00
37 REAR VIEW MIRROR ASSY	RH		\$ 75.00
38 SIDE COVER	LH		\$ 105.00
39 COVER SIDE	(3)		\$ 120.00
40 MOLE SIDE COVER	(1)		\$ 82.50
41 SIGNAL LIGHT FRONT			\$ 90.00
42 INNER SIDE COVER LH			\$ 22.50
SUB TOTAL			\$ 4,118.00
LESS 10%			\$ 411.80
SUB TOTAL			\$ 3,706.20

NETT ITEM:

1 LABOUR	\$ 450.00
2 NUMBER PLATE	\$ 10.00
3 SPRAY	\$ 250.00
1 FRONT FORK ASSY RH (REPAIR)	\$ 50.00
2 FRONT FORK ASSY LH (REPAIR)	\$ 50.00
3 UNDERBRACKET COMP (REPAIR)	\$ 60.00
SUB TOTAL	
\$ 870.00	
TOTAL	
\$ 4,576.20	

REMARKS :

Please send the cheque payment direct to owner, thank you.

- Pre repair inspection request - FP500T VS SLL2041M (OI) DOA 20/07/2018

From: Mithoosingh, Aashweenjeetkaur
To: admin-a@ikkauto.com, assignments@ikkauto.com
Cc: Tan, Lily (AIG), Fong, Andy-SY, Kaur, Baljit, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Azlan, Syazairdina, Chan, Yoke Shi
Sent: 30/8/2018 2:56:09 PM
Attachments:  tmp6F85.tif

Hi,

Please refer to the enclosed request from **TEO SPRAY PAINTING**.

Claim no : 6818314229SG003
Case Owner : IVY AI VUI YONG

If you have any queries/concerns, please let us know.
Kindly assist to assign Marcus Chua as Single Joint Expert as requested.

Thanks and regards,

Aashweenjeet Kaur (Aashween)
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

From: Irene Suan [mailto:irene@teospraytrading.com.sg]
Sent: Thursday, August 30, 2018 2:15 PM
To: Mithoosingh, Aashweenjeetkaur
Subject: Re: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLL2041M AND FP500T ON 20/07/2018

Good afternoon,

Please arrange Marcus Chua Of LKK.

Thanks
Irene



2018-08-30 8:34 GMT+08:00 Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>:

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยของข้อมูลที่เข้ารหัสลับ เพื่ออ่านมันให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2018-09-06 08:34 +08 to read your message.
After that, open the attachment.

[More Info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Aashweenjeetkaur.Mithoosingh@aig.com
To: irene@teospraytrading.com.sg

Cc: Lily.Tan@aig.com ,Andy-SY.Fong@aig.com ,Baljit Kaur@aig.com ,Lee-Ying.Chin@aig.com ,NoorMariesa.AbuKassim@aig.com ,Imran.Ishak@aig.com ,ShengYang.Lim@aig.com ,Syazairdina.Azlan@aig.com ,yokeshi.chan@aig.com
Subject: AIGENCRYPT - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLL2041M AND FP500T ON 20/07/2018
Date: Thu, 30 Aug 2018 00:34:05 +0000

Dear Sir/Madam,

Reminder for pre-repair survey.

Kindly response to the email below whether agree to the appointment of any of these motor surveyors below as a single joint expert.

Thanks and regards,

Aashweenjeet Kaur (Aashween)

AIG

Express Claims Adjuster II

SG Claims Operations | AIG Shared Services

From: Mithoosingh, Aashweenjeetkaur

Sent: Wednesday, August 29, 2018 8:20 AM

To: Irene Suan

Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Azlan, Syazairdina; Chan, Yoke Shi

Subject: AIGENCRYPT - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLL2041M AND FP500T ON 20/07/2018

Without Prejudice

Your Reference : FP500T

Our Reference : 6818314229SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Fong Soon Yee	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.


Thanks and regards,

Aashweenjeet Kaur (Aashween)

AIG

Express Claims Adjuster II

SG Claims Operations | AIG Shared Services



張 噴 漆
TEO SPRAY PAINTING

(INCORPORATED IN THE REPUBLIC OF SINGAPORE)
Reg. Address: BLOCK 6, DEFU LANE 10, DEFU INDUSTRIAL PARK C, #01-558
SINGAPORE 539187 TEL: 6283 5474 (2 LINES) FAX: 6287 2012
REG. NO. 275084 / 00X

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120
Tel: 64193000
Fax: 68357416

28.08.2018

Attn : Motor Claims Dept

Dear Sir/Madam

RE: THIRD PARTY CLAIMS FOR FP500T AGAINST YOUR
INSURED SLL2041M, ACCIDENT ON 20.07.2018 AT TUAS
CHECKPOINT IN MALAYSIA

With regards to the above, please kindly arrange for your surveyor to come to
TEO SPRAY PAINTING to inspect the damage on the vehicle.

I thank you.

Yours truly,
Teo Spray Painting
Tel: 62835474
Email: irenc@teospraytrading.com.sg

Shuqi

- Pre repair inspection request - FP500T VS SLL2041M (OI) DOA 20/07/2018

From: Mithoosingh, Aashweenjeetkaur
To: admin-a@kkauto.com, assignments@kkauto.com
Cc: Tan, Lily (AIG), Fong, Andy-SY, Kaur, Baljit, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Azlan, Syazairdina, Chan, Yoke Shi
Sent: 30/8/2018 2:56:09 PM
Attachments:  tmp6FB5.tif

Hi,

Please refer to the enclosed request from TEO SPRAY PAINTING.

Claim no : 6818314229SG003
Case Owner : IVY AI VUI YONG

If you have any queries/concerns, please let us know.
Kindly assist to assign Marcus Chua as Single Joint Expert as requested.

Thanks and regards,

Aashweenjeet Kaur (Aashween)
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

From: Irene Suan [mailto:irene@teospraytrading.com.sg]
Sent: Thursday, August 30, 2018 2:15 PM
To: Mithoosingh, Aashweenjeetkaur
Subject: Re: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLL2041M AND FP500T ON 20/07/2018

Good afternoon,

Please arrange Marcus Chua Of LKK.

Thanks
Irene



2018-08-30 8:34 GMT+08:00 Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>:

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ เพื่ออ่านมันให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2018-09-06 08:34 +08 to read your message.
After that, open the attachment.

[More Info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

IMPORTANT NOTICE

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Aashweenjeetkaur.Mithoosingh@aig.com
To: irene@teospraytrading.com.sg

3:36pm @ 30/8/18
person @ Ms. May
vehicle in
amunge 31/8/18

Cc: Lily.Tan@aig.com ,Andy-SY.Fong@aig.com ,Baljit.Kaur@aig.com ,Lee-Ying.Chin@aig.com ,NoorMariesa.AbuKassim@aig.com ,Imran.Ishak@aig.com ,ShengYang.Lim@aig.com ,Syazairdina.Azlan@aig.com ,yokeshi.chan@aig.com
Subject: AIGENCRYPT - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLL2041M AND FP500T ON 20/07/2018
Date: Thu, 30 Aug 2018 00:34:05 +0000

Dear Sir/Madam,

Reminder for pre-repair survey.

Kindly response to the email below whether agree to the appointment of any of these motor surveyors below as a single joint expert.

Thanks and regards,

Aashweenjeet Kaur (Aashween)

AIG

Express Claims Adjuster II

SG Claims Operations | AIG Shared Services

From: Mithoosingh, Aashweenjeetkaur

Sent: Wednesday, August 29, 2018 8:20 AM

To: Irene Suan

Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Azlan, Syazairdina; Chan, Yoke Shi

Subject: AIGENCRYPT - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLL2041M AND FP500T ON 20/07/2018

Without Prejudice

Your Reference : FP500T

Our Reference : 6818314229SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Fong Soon Yee	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.


Thanks and regards,

Aashweenjeet Kaur (Aashween)

AIG

Express Claims Adjuster II

SG Claims Operations | AIG Shared Services



張 噴 TEO SPRAY PAINTING

(INCORPORATED IN THE REPUBLIC OF SINGAPORE)
 Reg. Address: BLOCK 6, DEFU LANE 10, DEFU INDUSTRIAL PARK C, #01-558
 SINGAPORE 539187 TEL: 6283 5474 (2 LINES) FAX: 6287 2012
 REG. NO. 275084 / 00X

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building
 78 Shenton Way #07-16
 Singapore 079120
 Tel: 64193000
 Fax: 68357416

28.08.2018

Attn : Motor Claims Dept

Dear Sir/Madam

RE: THIRD PARTY CLAIMS FOR FP500T AGAINST YOUR
 INSURED SLL2041M . ACCIDENT ON 20.07.2018 AT TUAS
 CHECKPOINT IN MALAYSIA

With regards to the above, please kindly arrange for your surveyor to come to
 TEO SPRAY PAINTING to inspect the damage on the vehicle.

I thank you.

Yours truly,
 Teo Spray Painting
 Tel: 62835474
 Email: irenc@teospraytrading.com.sg

Shuqi

Vivian Lau (LKKAuto)

From: Vivian Lau (LKKAuto)
Sent: Wednesday, 3 April, 2019 12:35 PM
To: 'eyap@lioncityrentals.com.sg'; 'insurance@lioncityrentals.com.sg'
Cc: Hsiao Tong (LKKAuto)
Subject: Accident involving Vehicle SLL 2041M & FP 500T on 20/07/2018

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Our Ref: CC4/LCR18015923/Uwa3

03 April 2019

LION CITY RENTALS PTE LTD

Dear Sir/Madam,

Accident involving Vehicle SLL 2041M & FP 500T on 20/07/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

If you have evidence/information to prove that we should not settle the third party claim, kindly let us have them in writing within 7 days i.e. by **11/04/2019**, after we shall proceed with negotiation with Third Party claimant on the **without prejudice basis** and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Please call us if you have further queries.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Vivian Lau (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Friday, 5 April, 2019 9:53 PM
To: Yong, Ivy-AV; Vivian Lau (LKKAUTO)
Cc: Admin A
Subject: Re: #6818314229SG003#

Hi Ivy,

Noted.

Hi Vivian,

FYNA, CC4/LCR18015923/Uwa3

Best Regards,
Hsiao Tong, Chew | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Yong, Ivy-AV <Ivy-AV.Yong@aig.com>
Sent: Friday, 5 April 2019 2:26 PM
To: Hsiao Tong (LKKAUTO)
Subject: #6818314229SG003#

Hi Hsiao Tong,

Kindly upload your report in merimen.

Thank you

Ivy Yong
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way AIG Building #08-16 Singapore 079120
Tel +64191637

Ivy-AV.Yong@aig.com | www.aig.com.sg

AIG Asia Pacific won General Insurance Company of the Year at the 22nd Asia Insurance Industry Awards.
[Click here to find out more](#)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please

immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Jul 2018 Edit Reg		30 Aug 2018 00:00 Edit Adj Rpt	S\$4,576.20 Edit Estimates	S\$4,576.20 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	LCRF PTE LTD, Co. Reg. No.: 201624597K		
Main Claimant:	ABDUL ISMAIL BIN SIMIN, ID: S7628417B		
Vehicle Reg. No.:	FP500T	Date of Loss:	20/07/2018 00:00 - :59 [13 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 6818314229SG	Policy/Cover Note No.:	0999994808 (Comprehensive)
Vehicle Reg. No. (Insured):	SLL2041M	Policy No. (Claimant):	MT2018TR01093
		Excess:	
Repairer:	Teo Spray Painting (HQ) BLK 6 DEFU LANE 10, DEFU IND PARK C #01-558, 539187 Defu Lane - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Yong, Ivy-AV] Ivy-VA.Yong@aig.com		
Claimant's Insurer:	Great American Insurance Company (HQ) - Tel: 6804 6047		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 11/09/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FP500T (6818314229SG)**
[SLL2041M]
TP
ABDUL ISMAIL BIN SIMIN
Jul 20 2018 12:00AM
[LCRF PTE LTD]
Teo Spray Painting

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

[View](#)
[View in Browser](#)

Assessment Reports			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	04/09/18 10:00	Accident Statement From: SC - Reg. No: SLL2041M, Claimant: LCRF PTE LTD	Load HTM	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/08/18 14:42	General View	Load JPG	☒
2	31/08/18 14:42	General View	Load JPG	☒
3	31/08/18 14:42	General View	Load JPG	☒
4	31/08/18 14:42	General View	Load JPG	☒
5	31/08/18 14:42	General View	Load JPG	☒
6	31/08/18 14:42	General View	Load JPG	☒
7	31/08/18 14:42	General View	Load JPG	☒
8	31/08/18 14:42	General View	Load JPG	☒
9	31/08/18 14:42	General View	Load JPG	☒
10	31/08/18 14:42	General View	Load JPG	☒
11	31/08/18 14:42	General View	Load JPG	☒
12	31/08/18 14:42	General View	Load JPG	☒
13	31/08/18 14:42	General View	Load JPG	☒
14	31/08/18 14:42	General View	Load JPG	☒
15	31/08/18 14:42	General View	Load JPG	☒
16	31/08/18 14:42	General View	Load JPG	☒
17	31/08/18 14:42	General View	Load JPG	☒
18	31/08/18 14:42	General View	Load JPG	☒
19	31/08/18 14:42	General View	Load JPG	☒
20	31/08/18 14:42	General View	Load JPG	☒
21	31/08/18 14:42	General View	Load JPG	☒
22	31/08/18 14:42	General View	Load JPG	☒
23	31/08/18 14:42	General View	Load JPG	☒
24	31/08/18 14:42	General View	Load JPG	☒
25	31/08/18 14:42	General View	Load JPG	☒
26	31/08/18 14:42	General View	Load JPG	☒
27	31/08/18 14:42	General View	Load JPG	☒
28	31/08/18 14:42	General View	Load JPG	☒
29	31/08/18 14:42	General View	Load JPG	☒
30	31/08/18 14:42	General View	Load JPG	☒
31	31/08/18 14:42	General View	Load JPG	☒

Assessment Reports			1 per page ▼	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
32	31/08/18 14:42	General View	 Load JPG	☒
33	31/08/18 14:42	General View	 Load JPG	☒
34	31/08/18 14:42	General View	 Load JPG	☒
35	31/08/18 14:42	General View	 Load JPG	☒
36	31/08/18 14:42	General View	 Load JPG	☒
37	31/08/18 14:42	General View	 Load JPG	☒
38	31/08/18 14:42	General View	 Load JPG	☒
39	31/08/18 14:42	General View	 Load JPG	☒
40	31/08/18 14:42	General View	 Load JPG	☒
41	31/08/18 14:42	General View	 Load JPG	☒
42	31/08/18 14:42	General View	 Load JPG	☒
43	31/08/18 14:42	General View	 Load JPG	☒
44	31/08/18 14:42	General View	 Load JPG	☒
45	31/08/18 14:42	General View	 Load JPG	☒
46	31/08/18 14:42	General View	 Load JPG	☒
47	31/08/18 14:42	General View	 Load JPG	☒
48	31/08/18 14:42	General View	 Load JPG	☒
49	31/08/18 14:42	General View	 Load JPG	☒
50	31/08/18 14:42	General View	 Load JPG	☒
51	31/08/18 14:42	General View	 Load JPG	☒
52	31/08/18 14:42	General View	 Load JPG	☒
53	31/08/18 14:42	General View	 Load JPG	☒
54	31/08/18 14:42	General View	 Load JPG	☒
55	31/08/18 14:42	General View	 Load JPG	☒
56	31/08/18 14:42	General View	 Load JPG	☒
57	31/08/18 14:42	General View	 Load JPG	☒
58	31/08/18 14:42	General View	 Load JPG	☒
59	31/08/18 14:42	General View	 Load JPG	☒
60	31/08/18 14:42	General View	 Load JPG	☒
61	31/08/18 14:42	General View	 Load JPG	☒
62	31/08/18 14:42	General View	 Load JPG	☒
63	31/08/18 14:42	General View	 Load JPG	☒
64	31/08/18 14:42	General View	 Load JPG	☒
65	31/08/18 14:42	General View	 Load JPG	☒
66	31/08/18 14:42	General View	 Load JPG	☒
67	31/08/18 14:42	General View	 Load JPG	☒
68	31/08/18 14:42	General View	 Load JPG	☒
69	31/08/18 14:42	General View	 Load JPG	☒
70	31/08/18 14:42	General View	 Load JPG	☒
71	31/08/18 14:42	General View	 Load JPG	☒
72	31/08/18 14:42	General View	 Load JPG	☒
73	31/08/18 14:42	General View	 Load JPG	☒
74	31/08/18 14:42	General View	 Load JPG	☒
75	31/08/18 14:42	General View	 Load JPG	☒
76	31/08/18 14:42	General View	 Load JPG	☒
77	31/08/18 14:42	General View	 Load JPG	☒
78	31/08/18 14:42	General View	 Load JPG	☒
79	31/08/18 14:42	General View	Load JPG	☒

Assessment Reports			1 per page ▼	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
80	31/08/18 14:42	General View	 Load JPG	☒
81	31/08/18 14:42	General View	 Load JPG	☒
82	31/08/18 14:42	General View	 Load JPG	☒
83	31/08/18 14:42	General View	 Load JPG	☒
84	31/08/18 14:42	General View	 Load JPG	☒
85	31/08/18 14:42	General View	 Load JPG	☒
86	31/08/18 14:42	General View	 Load JPG	☒
87	31/08/18 14:42	General View	 Load JPG	☒
88	31/08/18 14:42	General View	 Load JPG	☒
89	31/08/18 14:42	General View	 Load JPG	☒
90	31/08/18 14:42	General View	 Load JPG	☒
91	31/08/18 14:42	General View	 Load JPG	☒
92	31/08/18 14:43	General View	 Load JPG	☒
93	31/08/18 14:43	General View	 Load JPG	☒
94	31/08/18 14:43	General View	 Load JPG	☒
95	31/08/18 14:43	General View	 Load JPG	☒
96	31/08/18 14:43	General View	 Load JPG	☒
97	31/08/18 14:43	General View	 Load JPG	☒
98	31/08/18 14:43	General View	 Load JPG	☒
99	10/09/18 19:16	Reinspection Photo	 Load JPG	☒
100	10/09/18 19:16	Reinspection Photo	 Load JPG	☒
101	10/09/18 19:16	Reinspection Photo	 Load JPG	☒
102	10/09/18 19:16	Reinspection Photo	 Load JPG	☒
103	10/09/18 19:16	Reinspection Photo	 Load JPG	☒
104	10/09/18 19:16	Reinspection Photo	 Load JPG	☒
105	10/09/18 19:16	Reinspection Photo	 Load JPG	☒
106	10/09/18 19:16	Reinspection Photo	 Load JPG	☒
107	10/09/18 19:16	Reinspection Photo	 Load JPG	☒
108	10/09/18 19:16	Reinspection Photo	 Load JPG	☒
109	10/09/18 19:16	Reinspection Photo	 Load JPG	☒
110	10/09/18 19:16	Reinspection Photo	 Load JPG	☒
111	10/09/18 19:16	Reinspection Photo	 Load JPG	☒
112	10/09/18 19:16	Reinspection Photo	 Load JPG	☒
113	10/09/18 19:16	Reinspection Photo	 Load JPG	☒
114	10/09/18 19:16	Reinspection Photo	 Load JPG	☒
115	10/09/18 19:16	Reinspection Photo	 Load JPG	☒
116	10/09/18 19:16	Reinspection Photo	 Load JPG	☒
117	10/09/18 19:16	Reinspection Photo	 Load JPG	☒
118	10/09/18 19:16	Reinspection Photo	 Load JPG	☒
119	10/09/18 19:16	Reinspection Photo	 Load JPG	☒
120	10/09/18 19:16	Reinspection Photo	 Load JPG	☒
121	10/09/18 19:16	Reinspection Photo	 Load JPG	☒
122	10/09/18 19:16	Reinspection Photo	 Load JPG	☒
123	10/09/18 19:16	Reinspection Photo	 Load JPG	☒
124	10/09/18 19:16	Reinspection Photo	 Load JPG	☒
125	10/09/18 19:16	Reinspection Photo	 Load JPG	☒
126	10/09/18 19:16	Reinspection Photo	 Load JPG	☒
127	10/09/18 19:16	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page ▼	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
128	10/09/18 19:16	Reinspection Photo	 Load JPG	☒
129	10/09/18 19:16	Reinspection Photo	 Load JPG	☒
130	10/09/18 19:16	Reinspection Photo	 Load JPG	☒
131	10/09/18 19:16	Reinspection Photo	 Load JPG	☒
132	10/09/18 19:16	Reinspection Photo	 Load JPG	☒
133	26/09/18 16:57	Reinspection Photo	 Load JPG	☒
134	26/09/18 16:57	Reinspection Photo	 Load JPG	☒
135	26/09/18 16:58	Reinspection Photo	 Load JPG	☒
136	26/09/18 16:58	Reinspection Photo	 Load JPG	☒
137	26/09/18 16:58	Reinspection Photo	 Load JPG	☒
138	26/09/18 16:58	Reinspection Photo	 Load JPG	☒
139	26/09/18 16:58	Reinspection Photo	 Load JPG	☒
140	26/09/18 16:58	Reinspection Photo	 Load JPG	☒
141	26/09/18 16:58	Reinspection Photo	 Load JPG	☒
142	26/09/18 16:58	Reinspection Photo	 Load JPG	☒
143	26/09/18 16:58	Reinspection Photo	 Load JPG	☒
144	26/09/18 16:58	Reinspection Photo	 Load JPG	☒
145	26/09/18 16:58	Reinspection Photo	 Load JPG	☒
146	19/11/18 14:35	Reinspection Photo	 Load JPG	☒
147	19/11/18 14:35	Reinspection Photo	 Load JPG	☒
148	19/11/18 14:35	Reinspection Photo	 Load JPG	☒
149	19/11/18 14:35	Reinspection Photo	 Load JPG	☒
150	19/11/18 14:35	Reinspection Photo	 Load JPG	☒
151	19/11/18 14:35	Reinspection Photo	 Load JPG	☒
152	19/11/18 14:35	Reinspection Photo	 Load JPG	☒
153	19/11/18 14:35	Reinspection Photo	 Load JPG	☒
154	19/11/18 14:35	Reinspection Photo	 Load JPG	☒
155	19/11/18 14:35	Reinspection Photo	 Load JPG	☒
156	19/11/18 14:35	Reinspection Photo	 Load JPG	☒
157	19/11/18 14:35	Reinspection Photo	 Load JPG	☒
158	19/11/18 14:35	Reinspection Photo	 Load JPG	☒
159	19/11/18 14:35	Reinspection Photo	 Load JPG	☒
160	19/11/18 14:35	Reinspection Photo	 Load JPG	☒
161	19/11/18 14:35	Reinspection Photo	 Load JPG	☒
162	19/11/18 14:35	Reinspection Photo	 Load JPG	☒
163	19/11/18 14:35	Reinspection Photo	 Load JPG	☒
164	19/11/18 14:35	Reinspection Photo	 Load JPG	☒
165	19/11/18 14:35	Reinspection Photo	 Load JPG	☒
166	19/11/18 14:35	Reinspection Photo	 Load JPG	☒
167	19/11/18 14:35	Reinspection Photo	 Load JPG	☒
168	19/11/18 14:35	Reinspection Photo	 Load JPG	☒
169	19/11/18 14:35	Reinspection Photo	 Load JPG	☒
170	19/11/18 14:35	Reinspection Photo	 Load JPG	☒
171	19/11/18 14:35	Reinspection Photo	 Load JPG	☒
172	19/11/18 14:35	Reinspection Photo	 Load JPG	☒
173	19/11/18 14:35	Reinspection Photo	 Load JPG	☒
174	19/11/18 14:35	Reinspection Photo	 Load JPG	☒
175	19/11/18 14:35	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page ▼	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
176	19/11/18 14:35	Reinspection Photo	Load JPG	☒
177	19/11/18 14:35	Reinspection Photo	Load JPG	☒
178	19/11/18 14:35	Reinspection Photo	Load JPG	☒
179	19/11/18 14:35	Reinspection Photo	Load JPG	☒
180	19/11/18 14:35	Reinspection Photo	Load JPG	☒
181	19/11/18 14:35	Reinspection Photo	Load JPG	☒
Documentation			1 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/08/18 14:33	EMAIL FROM AIG DD 30.08.2018	Load PDF	
2	31/08/18 14:33	NOTIFICATION FROM WORKSHOP	Load TIF	
3	31/08/18 14:33	ACKNOWLEDGEMENT EMAIL TO AIG DD 31.08.2018	Load PDF	
4	04/09/18 10:37	TP ESTIMATE - MARKED	Load PDF	
5	04/09/18 10:37	TP GIA REPORT	Load PDF	
6	03/04/19 12:40	Email letter to OI Accident involving Vehicle SLL 2041M & FP 500T on 20.07.2018	Load PDF	
7	09/04/19 15:06	Email from AIG to submit WP report 9.4.19	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/LCR18015923/UWA3S2

Date: 22/05/2019

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994808
Claimant Vehicle No :	FP500T	Insured Vehicle No :	SLL2041M
Date of Loss:	20/07/2018	Nature of Claim:	TP
		Claim No:	6818314229SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FP500T	Engine No:	J415E009928
Make & Model:	YAMAHA TMAX530, 530cc (DX)	Chassis No:	JYASJ145000004804
Reg. Date:	08/06/2017 (Man. Year: 2017)	Odometer:	0 km
Colour:	Blue		
Engine Capacity:	530 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	120/70R15	Rear Tyre Size:	160/60R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,781.45	3,876.20	1,905.25	32.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	980.00	700.00	280.00	28.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,761.45	4,576.20	2,185.25	32.32
+ GST 7.00/7.00% (S\$)	473.30	320.33	152.97	32.32
Nett Amount (S\$)	7,234.75	4,896.53	2,338.22	32.32

INSPECTION

Date of Assignment:	30/08/2018	
Date Inspected:	31/08/2018	Inspected At: Teo Spray Painting (HQ) BLK 6 DEFU LANE 10, DEFU IND PARK C #01-558 Singapore 539187
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOARD FOOTREST (1)	Broken	97.50 FL	*97.50 FL
2	1		*PANEL CONSOLE (1)	Cracked	67.50 FL	*67.50 FL
3	1		*BOARD FOOTREST (2)	Cracked	97.50 FL	*97.50 FL
4	1		*DAMPER PLATE	Necessary	5.00 FL	*5.00 FL
5	1		*DAMPER PLATE	Necessary	12.00 FL	*12.00 FL
6	1		*PANEL CONSOLE (2)	Cracked	67.50 FL	*67.50 FL
7	1		*MAT (3)	Twisted	18.00 FL	*18.00 FL
8	1		*MAT (4)	Not Necessary	18.00 FL	*- FL
9	1		*DUCT AIR	Cracked	37.50 FL	*37.50 FL
10	1		*FENDER AIR (2)	Cracked	52.50 FL	*52.50 FL
11	1		*LEG SHIELD (1)	Cracked	120.00 FL	*120.00 FL
12	1		*LID	Not Necessary	15.00 FL	*- FL
13	1		*LID ASSY	Not Necessary	75.00 FL	*- FL
14	1		*BOX ASSY	Not Necessary	45.00 FL	*- FL
15	1		*MOLE (1)	Cut	72.00 FL	*72.00 FL
16	1		*MOLE (2)	Cut	72.00 FL	*72.00 FL
17	1		*PANEL (1)	Cracked	97.50 FL	*97.50 FL
18	2		*EMBLEM	Necessary	45.00 FL	*45.00 FL
19	1		*PANEL (2)	Cracked	97.50 FL	*97.50 FL
20	1		*COVER	Necessary	27.00 FL	*27.00 FL
21	1		*PLATE PROTECTOR (2)	Cut	45.00 FL	*45.00 FL
22	1		*PROTECTOR MUFFLER (1)	Cut	60.00 FL	*60.00 FL
23	1		*PROTECTOR MUFFLER (3)	Distorted	105.00 FL	*105.00 FL
24	1		*STAY (1)	Bent	270.00 FL	*270.00 FL
25	1		*HEADLIGHT ASSY	Scratched	960.00 FL	*960.00 FL
26	1		*FENDER FRONT	Cut	75.00 FL	*75.00 FL
27	1		*STAY FENDER (1)	Bent	22.50 FL	*22.50 FL
28	1		*STAY FENDER (2)	Bent	22.50 FL	*22.50 FL
29	1		*FENDER FRONT (2)	Not Necessary	27.00 FL	*- FL
30	1		*HANDLE COMP	Bent	67.50 FL	*67.50 FL
31	1		*BALANCER	Cut	22.50 FL	*22.50 FL
32	1		*CAP HANDLEBAR COVER	Cut	60.00 FL	*60.00 FL
33	1		*COVER HANDLE UPPER (2)	Cut	15.00 FL	*15.00 FL
34	1		*COVER HANDLE UPPER (1)	Cut	15.00 FL	*15.00 FL
35	1		*CAP COVER HANDLE (2)	Not Necessary	37.50 FL	*- FL
36	1		*PANEL INNER (1)	Cracked	42.00 FL	*42.00 FL
37	1		*BODY COWLING LH	Cracked	180.00 FL	*180.00 FL
38	1		*BODY COWLING RH	Cracked	195.00 FL	*195.00 FL
39	1		*PANEL INNER (2)	Cracked	52.50 FL	*52.50 FL
40	1		*COVER FRONT	Cracked	112.50 FL	*112.50 FL
41	1		*SCREEN	Cut	240.00 FL	*240.00 FL
42	1		*REAR VIEW MIRROR ASSY LH	Broken	75.00 FL	*75.00 FL
43	1		*REAR VIEW MIRROR ASSY RH	Broken	75.00 FL	*75.00 FL
44	1		*SIDE COVER LH	Cracked	105.00 FL	*105.00 FL
45	1		*COVER SIDE (3)	Cracked	120.00 FL	*120.00 FL
46	1		*MOLE SIDE COVER (1)	Cut	82.50 FL	*82.50 FL
47	1		*SIGNAL LIGHT FRONT	Broken	90.00 FL	*90.00 FL
48	1		*MAINSTAND	Repair	180.00 FL	*- FL
49	1		*INNER SIDE COVER LH	Cut	22.50 FL	*22.50 FL
50	1		*FRONT FORK ASSY RH (LOCAL REPAIR)	Bent	675.00 FS	*50.00 FS
51	1		*FRONT FORK ASSY LH (LOCAL REPAIR)	Bent	675.00 FS	*50.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*UNDERBRACKET COMP (LOCAL REPAIR)	Bent	337.50 FS	*60.00 FS
53	1		*NUMBER PLATE	Necessary	30.00 FS	*10.00 FS
F=Franchise part, S=SpcNett, L=ListItemDisc.						
Sub Total (S\$)					6,233.00	4,288.00
- List Item Discount on L Items 10.00/10.00% (S\$)					451.55	411.80
Total Parts (S\$)					5,781.45	3,876.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR.	New	600.00	450.00
2	SPRAY.	New	380.00	250.00
Gross Labour Cost (S\$)			980.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >