

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)Survey on 14/09
only

GST REG. NO : M2 - 0020081 - X

31 AUG 2018

E S T I M A T EEstimate No. : b1 48278
Date Estimated : 31/08/2018
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -Long Lian Ming
80 Li Hwan Drive

Singapore 557103

- ACCOUNT - 121AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDT2132L	5E91640	16/01/2018	216i G TOURER	0

DESCRIPTIONTo replace rear bumper, rear left fender, rear left door,
front left door, side sill left and attachments.Painting rear bumper, rear left fender, rear left door, front
left door, side sill, tail panel and roof panel.To check electrical wiring systems
for proper functionTo remove and install rear hat-tray, rear seat, carpet
and roof top lining to facilitate repairs.To supply and install rear left window glass
solar film.To supply and install front left fixed glass on fender
solar film.

To replace tyre and wheel rim including balancing. (1x).

To check steering geometry and conduct wheel alignment
according to BMW specification (1x)To carry out body cavity preservation.
(Per panel).To carry out body cavity preservation.
(For cut panel).

Sundries.

6800
6375 VALUE
8,500.00

5139 5,710.00

150 177.00

742 873.00

✓ 425.00

✓ 425.00

80 94.00

451 531.00

200 236.00

451 531.00

✓ 150.00

Total Labour 1: 17,652.00

DESCRIPTION

PLASTIC NUT FOR COARSE THREADED PIN

QTY PRIC
6 0.80VALUE
4.80

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 48278
Date Estimated : 31/08/2018
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDT2132L	5E91640	16/01/2018	216i G TOURER	0

DESCRIPTION	QTY	PRIC	VALUE
ALLOY RIM 7JX16 DOUBLE SPK 473	1	738.55	ent 738.55
REAR LH SIDE PANEL	1	1,360.75	bt 1,360.75
Positionieru	1	5.60	nee 5.60
REINFORCEMENT PLATE UNIVERSAL	1	27.75	nee 27.75
Reinforcemen	1	49.20	nee 49.20
Reinforcemen	1	49.20	nee 49.20
Reinforcemen	1	49.20	nee 49.20
T WELD BOLT L=5.4MM	10	2.55	nl 25.50
FRT LH DOOR	1	1,103.65	bt 1,103.65
RR LH DOOR	1	1,103.65	bt 1,103.65
RR BUMPER RH SIDE GUIDE	1	60.00	? 60.00
REAR BUMPER PANEL PRIMED (PDC)	1	966.25	Ry 966.25
SET MOUNTS PDC SENSOR REAR	1	62.95	? 62.95
PLASTIC NUT	4	0.85	? 3.40
LH SILL TRIM PRIMED	1	278.65	Ry 278.65
REAR LH SIDE WINDOW FIXED (ALU HOCH	1	270.25	? 270.25
LH FIXED DOOR WINDOW	1	127.30	? 127.30
REAR DOOR EDGE PROTECTION	1	153.10	? 153.10
FRT DOOR EDGE PROTECTION	1	153.10	? 153.10
REAR LH RETAINING STRIP SILL	1	45.00	? 45.00
CAVITY PROTECTION WAX REMOVER 500ML	1	18.45	nee 18.45
BLIND RIVET AVIBVLB	8	0.55	nee 4.40
SCREW (SF PLUS M5X15)	3	0.55	nee 1.65
(DG/SL) BODY ADHESIVE K5B (195ML)	1	281.55	nee 281.55
(DG) BODYWORK ADHESIVE K5A (50ML)	1	118.35	nee 118.35
(DG) CLEANER R1 (100ML)	1	26.15	nee 26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	1	131.55	nee 131.55
PUNCH RIVET N4	36	0.55	nee 19.80

Total Parts : 7,239.75

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
Date & Time 14/9/18 @ 1430 Excess S\$ _____
Surveyor's Name Tanjiah Sign _____
Surveyor's Tel 92145719 authorised Yes / No _____

Anti-rust Date _____ Time _____

REPAIRER'S PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail tanjiah@lkkauto.com

Surveyor's Working Days Recommend 15 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Labour 1	:	17,652.00
Parts	:	7,239.75
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,742.42

Grand Total : 26,634.17

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **